Raytheon Aircraft

Beech Hawker

Model:

G36

A/C Serial Number:

E-3660

Registration Number:

N610TC

EXTERIOR PAINT:

Desoto White F17865 Sherwin Williams Clarette A07976 Sherwin Williams Gold Metallic R06086 Sherwin Williams Regimental Blue CA8800/F15044

INTERIOR PAINT:

Pewter 070-270

KEY NO. 2R221

STC's

This aircraft has the following STC's incorporated into the production of this unit at build:

1. SA00902WI

Replacement of original landing gear doors

2. SA00719LA

Hartzell PHC-C3YF-1R/F8468A (B, K) -6R constant speed

propeller

3. SA01033WI

Replacement of original landing gear doors

AIRWORTHINESS CERTIFICATE

I have inspected this aircraft and issued a STANDARD Airworthiness Certificate Dated 12-09-2005. Time: 3.6 Landings: 5

Max Workman

For Raytheon Aircraft Company

DOA-230339-CE

Ti	ΛT	-		IME	ENTRIES MAY BE ON MULTIPLE	INSPECTOR'S	LICENS
Υ	M	D		DURS	LINES IF REQUIRED	SIGNATURE	NUMBE
06	1	29	27	7	Drained engine oil and remared		
					engine oil Filer. Replaced with		
					Aerostell 100 15W-50 and mailed		
					engine oil sample to Engine Oil		
			3.0		Analysis. Replaced Oil Filks.	WH Magley	270209
06	2	23	49	1	Robert St. M. Cha		
00	or .	₩.J	71	0	Replaced engine oil and filter W/ Acroshell 100 15W-50 JAN		
					636 Bongaza Mx. Manuel. Meila		1
					oil Sample to Engine Oil Analysis.	DARREL	2702099
					9 = 1 11 19		,
_	oair S	statio	FRQ on GM 2-4184	ZR383E	AVIATION, INC. REG # N610TC S/N E-3660 HM 0107.7 TACH N/A	DAT W/O AFT	M-514
uste	ed ou	tside go do heck	windo or strik satisfa	w frame o ker plate a actory.	f windshield using 890 B2 seal pak as required, nd door seal to allow for easier latching of door.		
		Th	is aircr	raft and/or Arturo To	component is certified to be airworthy for return to service with orres SIGNATURE:	respect to the work perfo	rmed. Page 1 of
					· ·	i .	1

Aircraft Model Se	erial Nu	mber			
Reg #C	Owner's	Name			
		53 			
DATE TIME ENTRIES MAY	BE ON	MULTIPLE	INSPECT	TOR'S L	ICENSE
/ M D HOURS LINES IF	REQUI	RED	SIGNAT	TURE N	IUMBER
RNADO ALLEY TURBO INC.			12	•	
0 AIRPORT RD AIRFRAME LO		(ENTRY 27 JUNE 2006			
)A, OK 74820 110TC BONANZA G36 SN: E-3660 ACFT T			S: 115.3		
M IO-550-B SN: 687094 ENG TSN: 1	15.3				
STALLATION OF "WHIRLWIND SYSTEM II" TURE	30 NOR	MALIZING SYST	EM COVERED	UNDER STC	SA5223NM
ID STC SE5222NM, IN ACCORDANCE WITH INS	TALLAT	TON INSTRUCTION	ONS ETI-B-01 F	REV. H DATEL	03/04/05 AND
ASTER DRAWING LIST TAT-B-MDL REV. K DATE PERATION AND CONTINUED AIRWORTHINESS.					
0944-0029 SERIAL NUMBER JDN00064. INSTAL					
RIAL NUMBER AF0105. INSTALLED NEWLY OV	/ERHAU	ILED WASTEGAT	TE PART NUME	BER 470908-0	011 SERIAL
JMBER JBN00052. INSTALLED NEW TURBOCH					
STALLED LATE MODEL A36 TYPE FUEL FLOW (
JMBER F31 SERIAL NUMBER 3155. INSTALLED STALLATION COMPLETED IN ACCORDANCE W	J. P. IN	SIRUMENIS II	I SLIM LINE DI	SHAL GAGE	ASSEMBLY.
STALLED 6 PLACE SUPPLEMENTAL OXYGEN S					
ASTER DRAWING PACKAGE. COMPONENTS AF					
ECTRICALLY OPERATED ON/OFF SOLENOID M	10UNTE		FILL PORT WIT	'H MECHANIC	AL GAGE
DUNTED INSIDE PASSENGER DOOR ARE. USE					
T OF #6 SEAT. ELECTRICALLY OPERATED ON	WOFF S	WITCH AND PR	ESSURE GAGE	ON INSTRUM	MENT PANEL.
T OF #6 SEAT. ELECTRICALLY OPERATED ON E FLIGHT MANUAL SUPPLEMENT FOR OPERA	WOFF S	WITCH AND PR	ESSURE GAGE	ON INSTRUM	MENT PANEL.
T OF #6 SEAT. ELECTRICALLY OPERATED ON E FLIGHT MANUAL SUPPLEMENT FOR OPERA AK CHECK OK.	WOFF S	WITCH AND PR	ESSURE GAGE	ON INSTRUM	MENT PANEL.
TOF#6 SEAT. ELECTRICALLY OPERATED ON EE FLIGHT MANUAL SUPPLEMENT FOR OPERA AK CHECK OK.	WOFF S	WITCH AND PR	ESSURE GAGE	ON INSTRUM	MENT PANEL.
T OF #6 SEAT. ELECTRICALLY OPERATED ON E FLIGHT MANUAL SUPPLEMENT FOR OPERA AK CHECK OK.	WOFF S	WITCH AND PR	ESSURE GAGE	ON INSTRUM	MENT PANEL.
TOF#6 SEAT. ELECTRICALLY OPERATED ON E FLIGHT MANUAL SUPPLEMENT FOR OPERA AK CHECK OK. MUDICIPAL THE SUPPLEMENT OF THE SUPPLEMENT	WOFF S	WITCH AND PR	ESSURE GAGE	ON INSTRUM	MENT PANEL.
TOF#6 SEAT. ELECTRICALLY OPERATED ON E FLIGHT MANUAL SUPPLEMENT FOR OPERA AK CHECK OK. MUDICIPAL THE SUPPLEMENT OF THE SUPPLEMENT	N/OFF S TION AN	WITCH AND PRI	ESSURE GAGE	ON INSTRUMESS. RUN-UP	MENT PANEL. , OP's, AND
TOF#6 SEAT. ELECTRICALLY OPERATED ON E FLIGHT MANUAL SUPPLEMENT FOR OPERA AK CHECK OK. AVID R. LANDRETH A&P 2651512 IA	N/OFF S TION AN	WITCH AND PR	ESSURE GAGE	ON INSTRUM	MENT PANEL. , OP's, AND
TOF #6 SEAT. ELECTRICALLY OPERATED ON EE FLIGHT MANUAL SUPPLEMENT FOR OPERATE AK CHECK OK. ANID R. LANDRETH A&P 2651512 IA CUTTER AVIATION, INC.	NOFF S TION AN	WITCH AND PRIND CONTINUED	ESSURE GAGE	ON INSTRUMESS. RUN-UP	MENT PANEL. , OP's, AND E 12/16/06 01M-998
T OF #6 SEAT. ELECTRICALLY OPERATED ON SE FLIGHT MANUAL SUPPLEMENT FOR OPERATE AK CHECK OK. AND ALEVALUATION, INC. ALBUQUERQUE	NOFF S TION AT REG # S/N	WITCH AND PRIND CONTINUED N610TC E-3660 202.4	ESSURE GAGE	ON INSTRUMESS. RUN-UP	MENT PANEL. , OP's, AND E 12/16/06 01M-998
T OF #6 SEAT. ELECTRICALLY OPERATED ON SE FLIGHT MANUAL SUPPLEMENT FOR OPERATE AK CHECK OK. AND R. LANDRETH A&P 2651512 IA CUTTER AVIATION, INC. ALBUQUERQUE A Repair Station GMZR383E	REG# S/N HM	WITCH AND PRIND CONTINUED N610TC E-3660 202.4 N/A	ESSURE GAGE AIRWORTHINE	ON INSTRUMESS. RUN-UP DATE W/O AFT	MENT PANEL. , OP's, AND E 12/16/06 01M-998
T OF #6 SEAT. ELECTRICALLY OPERATED ON E FLIGHT MANUAL SUPPLEMENT FOR OPERATE AK CHECK OK. WID R. LANDRETH A&P 2651512 IA WID R. LANDRETH A&P 2651512 IA ALBUQUERQUE A Repair Station GMZR383E 505 842-4184	REG # S/N HM TACH Ta A36 ins	WITCH AND PRIND CONTINUED N610TC E-3660 202.4 N/A	ESSURE GAGE AIRWORTHINE	ON INSTRUMESS. RUN-UP DATE W/O AFT	MENT PANEL. , OP's, AND E 12/16/06 01M-998
T OF #6 SEAT. ELECTRICALLY OPERATED ON E FLIGHT MANUAL SUPPLEMENT FOR OPERATE AK CHECK OK. VID R. LANDRETH A&P 2651512 IA VID R. LANDRETH A&P 2651512 IA ALBUQUERQUE A Repair Station GMZR383E 505 842-4184 1. Completed annual inspection using Raytheon Bonanz	REG # S/N HM TACH Ta A36 ins	WITCH AND PRIND CONTINUED N610TC E-3660 202.4 N/A	ESSURE GAGE AIRWORTHINE	ON INSTRUMESS. RUN-UP DATE W/O AFT	MENT PANEL. , OP's, AND E 12/16/06 01M-998
T OF #6 SEAT. ELECTRICALLY OPERATED ON E FLIGHT MANUAL SUPPLEMENT FOR OPERATE AK CHECK OK. VID R. LANDRETH A&P 2651512 IA VID R. LANDRETH A&P 2651512 IA ALBUQUERQUE A Repair Station GMZR383E 505 842-4184 1. Completed annual inspection using Raytheon Bonanz 2. Resealed windscreen at several areas required with P 3. Reglued L/H wing root rubber seal. 4. Retorqued pilot seat arm rest bolts.	REG # S/N HM TACH Ta A36 ins	WITCH AND PRIND CONTINUED N610TC E-3660 202.4 N/A	ESSURE GAGE AIRWORTHINE	ON INSTRUMESS. RUN-UP DATE W/O AFT	MENT PANEL. , OP's, AND E 12/16/06 01M-998
T OF #6 SEAT. ELECTRICALLY OPERATED ON E FLIGHT MANUAL SUPPLEMENT FOR OPERATE AK CHECK OK. VID R. LANDRETH A&P 2651512 IA VID R. LANDRETH A&P 2651512 IA ALBUQUERQUE A Repair Station GMZR383E 505 842-4184 1. Completed annual inspection using Raytheon Bonanz 2. Resealed windscreen at several areas required with P 3. Reglued L/H wing root rubber seal. 4. Retorqued pilot seat arm rest bolts. 5. Adjusted cabin door striker plates.	REG # S/N HM TACH Ta A36 ins	WITCH AND PRIND CONTINUED N610TC E-3660 202.4 N/A	ESSURE GAGE AIRWORTHINE	ON INSTRUMESS. RUN-UP DATE W/O AFT	MENT PANEL. , OP's, AND E 12/16/06 01M-998
T OF #6 SEAT. ELECTRICALLY OPERATED ON E FLIGHT MANUAL SUPPLEMENT FOR OPERATE AK CHECK OK. NID R. LANDRETH A&P 2651512 IA **CONTROL OF THE AVIATION, INC.** ALBUQUERQUE** A Repair Station GMZR383E 505 842-4184 1. Completed annual inspection using Raytheon Bonanz 2. Resealed windscreen at several areas required with P 3. Reglued L/H wing root rubber seal. 4. Retorqued pilot seat arm rest bolts. 5. Adjusted cabin door striker plates. 6. Installed new R/H wing fuel sump drain.	REG # S/N HM TACH Ta A36 ins	WITCH AND PRIND CONTINUED N610TC E-3660 202.4 N/A	ESSURE GAGE AIRWORTHINE	ON INSTRUMESS. RUN-UP DATE W/O AFT	MENT PANEL. , OP's, AND E 12/16/06 01M-998
T OF #6 SEAT. ELECTRICALLY OPERATED ON E FLIGHT MANUAL SUPPLEMENT FOR OPERATE AK CHECK OK. VID R. LANDRETH A&P 2651512 IA VID R. LANDRETH A&P 2651512 IA ALBUQUERQUE A Repair Station GMZR383E 505 842-4184 1. Completed annual inspection using Raytheon Bonanz 2. Resealed windscreen at several areas required with P 3. Reglued L/H wing root rubber seal. 4. Retorqued pilot seat arm rest bolts. 5. Adjusted cabin door striker plates. 6. Installed new R/H wing fuel sump drain. 7. Installed new bulb lower beacon.	REG # S/N HM TACH Ta A36 ins	WITCH AND PRIND CONTINUED N610TC E-3660 202.4 N/A	ESSURE GAGE AIRWORTHINE	ON INSTRUMESS. RUN-UP DATE W/O AFT	MENT PANEL. , OP's, AND E 12/16/06 01M-998
T OF #6 SEAT. ELECTRICALLY OPERATED ON E FLIGHT MANUAL SUPPLEMENT FOR OPERATE AK CHECK OK. WID R. LANDRETH A&P 2651512 IA WID R. LANDRETH A&P 2651512 IA AUIATION, INC. ALBUQUERQUE A Repair Station GMZR383E 505 842-4184 1. Completed annual inspection using Raytheon Bonanz 2. Resealed windscreen at several areas required with P 3. Reglued L/H wing root rubber seal. 4. Retorqued pilot seat arm rest bolts. 5. Adjusted cabin door striker plates. 6. Installed new R/H wing fuel sump drain. 7. Installed new bulb lower beacon. 8. Installed new tail navigation light bulb.	REG # S/N HM TACH Ta A36 ins	WITCH AND PRIND CONTINUED N610TC E-3660 202.4 N/A	ESSURE GAGE AIRWORTHINE	ON INSTRUMESS. RUN-UP DATE W/O AFT	MENT PANEL. , OP's, AND E 12/16/06 01M-998
TOF #6 SEAT. ELECTRICALLY OPERATED ON E FLIGHT MANUAL SUPPLEMENT FOR OPERATE AK CHECK OK. WID R. LANDRETH A&P 2651512 IA WID R. LANDRETH A&P 2651512 IA AVIATION, INC. ALBUQUERQUE A Repair Station GMZR383E 505 842-4184 1. Completed annual inspection using Raytheon Bonanz 2. Resealed windscreen at several areas required with P 3. Reglued L/H wing root rubber seal. 4. Retorqued pilot seat arm rest bolts. 5. Adjusted cabin door striker plates. 6. Installed new R/H wing fuel sump drain. 7. Installed new bulb lower beacon. 8. Installed new tail navigation light bulb. 9. Installed new R/H wing stobe light bulb.	REG # S/N HM TACH ra A36 ins	WITCH AND PRIND CONTINUED N610TC E-3660 202.4 N/A	ESSURE GAGE AIRWORTHINE	ON INSTRUMESS. RUN-UP DATE W/O AFT	MENT PANEL. , OP's, AND E 12/16/06 01M-998
T OF #6 SEAT. ELECTRICALLY OPERATED ON E FLIGHT MANUAL SUPPLEMENT FOR OPERATED AND AK CHECK OK. WID R. LANDRETH A&P 2651512 IA WID R. LANDRETH A&P 2651512 IA AVIATION, INC. ALBUQUERQUE A Repair Station GMZR383E 505 842-4184 1. Completed annual inspection using Raytheon Bonanz 2. Resealed windscreen at several areas required with P 3. Reglued L/H wing root rubber seal. 4. Retorqued pilot seat arm rest bolts. 5. Adjusted cabin door striker plates. 6. Installed new R/H wing fuel sump drain. 7. Installed new bulb lower beacon. 8. Installed new tail navigation light bulb. 9. Installed new R/H wing stobe light bulb. 10. Adjusted L/H cowl door linkage to clear exhaust stack	REG # S/N HM TACH ra A36 ins	WITCH AND PRIND CONTINUED N610TC E-3660 202.4 N/A	ESSURE GAGE AIRWORTHINE	ON INSTRUMESS. RUN-UP DATE W/O AFT	MENT PANEL. , OP's, AND E 12/16/06 01M-998
TOF #6 SEAT. ELECTRICALLY OPERATED ON E FLIGHT MANUAL SUPPLEMENT FOR OPERATE AK CHECK OK. VID R. LANDRETH A&P 2651512 IA VID R. LANDRETH A&P 2651512 IA AVIATION, INC. ALBUQUERQUE A Repair Station GMZR383E 505 842-4184 1. Completed annual inspection using Raytheon Bonanz 2. Resealed windscreen at several areas required with P 3. Reglued L/H wing root rubber seal. 4. Retorqued pilot seat arm rest bolts. 5. Adjusted cabin door striker plates. 6. Installed new R/H wing fuel sump drain. 7. Installed new Bulb lower beacon. 8. Installed new tail navigation light bulb. 9. Installed new R/H wing stobe light bulb. 10. Adjusted L/H cowl door linkage to clear exhaust stack 11. Serviced NLG shimmey dampner as required with MI	REG # S/N HM TACH Ta A36 ins	WITCH AND PRIND CONTINUED N610TC E-3660 202.4 N/A	ESSURE GAGE AIRWORTHINE	ON INSTRUMESS. RUN-UP DATE W/O AFT	MENT PANEL. , OP's, AND E 12/16/06 01M-998
T OF #6 SEAT. ELECTRICALLY OPERATED ON E FLIGHT MANUAL SUPPLEMENT FOR OPERATED ON E FLIGHT MANUAL SUPPLEMENT FOR OPERATED ON AK CHECK OK. WID R. LANDRETH A&P 2651512 IA WID R. LANDRETH A&P 2651512 IA WID R. LANDRETH A&P 2651512 IA AVIATION, INC. ALBUQUERQUE A Repair Station GMZR383E 505 842-4184 1. Completed annual inspection using Raytheon Bonanz 2. Resealed windscreen at several areas required with P 3. Reglued L/H wing root rubber seal. 4. Retorqued pilot seat arm rest bolts. 5. Adjusted cabin door striker plates. 6. Installed new R/H wing fuel sump drain. 7. Installed new Bwilb lower beacon. 8. Installed new bulb lower beacon. 8. Installed new tail navigation light bulb. 9. Installed new R/H wing stobe light bulb. 10. Adjusted L/H cowl door linkage to clear exhaust stack 11. Serviced MLG shimmey dampner as required with Mil 12. Serviced MLG struts and NLG strut with nitrogen as in the structure of t	REG # S/N HM TACH Ta A36 ins PR 1425.	WITCH AND PRIND CONTINUED N610TC E-3660 202.4 N/A pection checklist as	a guide , PN 36-5	DATI W/O AFT	MENT PANEL. , OP's, AND E 12/16/06 01M-998
TOF #6 SEAT. ELECTRICALLY OPERATED ONE FLIGHT MANUAL SUPPLEMENT FOR OPERATER AK CHECK OK. WID R. LANDRETH A&P 2651512 IA AVIATION, INC. ALBUQUERQUE A Repair Station GMZR383E 505 842-4184 1. Completed annual inspection using Raytheon Bonanz 2. Resealed windscreen at several areas required with P 3. Reglued L/H wing root rubber seal. 4. Retorqued pilot seat arm rest bolts. 5. Adjusted cabin door striker plates. 6. Installed new R/H wing fuel sump drain. 7. Installed new Bwilb lower beacon. 8. Installed new bulb lower beacon. 8. Installed new tail navigation light bulb. 9. Installed new R/H wing stobe light bulb. 10. Adjusted L/H cowl door linkage to clear exhaust stack 11. Serviced MLG shimmey dampner as required with Mil 12. Serviced MLG struts and NLG strut with nitrogen as in 13. Installed new L/H and R/H MLG brake caliper pads, but in the college of the college pads, but in the college pads page page page page page page page page	REG # S/N HM TACH Ta A36 ins PR 1425.	WITCH AND PRIND CONTINUED N610TC E-3660 202.4 N/A pection checklist as	a guide , PN 36-5	DATI W/O AFT	MENT PANEL. , OP's, AND E 12/16/06 01M-998
T OF #6 SEAT. ELECTRICALLY OPERATED ON E FLIGHT MANUAL SUPPLEMENT FOR OPERATED AK CHECK OK. WID R. LANDRETH A&P 2651512 IA WID R. LANDRETH A&P 2651512 IA ALBUQUERQUE A Repair Station GMZR383E 505 842-4184 1. Completed annual inspection using Raytheon Bonanz 2. Resealed windscreen at several areas required with P 3. Reglued L/H wing root rubber seal. 4. Retorqued pilot seat arm rest bolts. 5. Adjusted cabin door striker plates. 6. Installed new R/H wing fuel sump drain. 7. Installed new bulb lower beacon. 8. Installed new tail navigation light bulb. 9. Installed new R/H wing stobe light bulb. 10. Adjusted L/H cowl door linkage to clear exhaust stack 11. Serviced NLG shimmey dampner as required with MI 12. Serviced MLG struts and NLG strut with nitrogen as II. Installed new L/H and R/H MLG brake caliper pads, b 14. C/W with cabin 12 month fire extinguisher inspection	REG # S/N HM TACH Ta A36 ins PR 1425.	WITCH AND PRIND CONTINUED N610TC E-3660 202.4 N/A pection checklist as	a guide , PN 36-5	DATI W/O AFT	MENT PANEL. , OP's, AND E 12/16/06 01M-998
TOF #6 SEAT. ELECTRICALLY OPERATED ON SEFLIGHT MANUAL SUPPLEMENT FOR OPERATE AK CHECK OK. AVID R. LANDRETH A&P 2651512 IA AVIATION, INC. ALBUQUERQUE A Repair Station GMZR383E 505 842-4184 1. Completed annual inspection using Raytheon Bonanz. 2. Resealed windscreen at several areas required with P. 3. Reglued L/H wing root rubber seal. 4. Retorqued pilot seat arm rest bolts. 5. Adjusted cabin door striker plates. 6. Installed new R/H wing fuel sump drain. 7. Installed new bulb lower beacon. 8. Installed new bulb lower beacon. 8. Installed new R/H wing stobe light bulb. 10. Adjusted L/H cowl door linkage to clear exhaust stack 11. Serviced NLG shimmey dampner as required with MI 12. Serviced MLG struts and NLG strut with nitrogen as 13. Installed new L/H and R/H MLG brake caliper pads, but the content of the content	REG # S/N HM TACH Ta A36 ins PR 1425.	WITCH AND PRIND CONTINUED N610TC E-3660 202.4 N/A pection checklist as	a guide , PN 36-5	DATI W/O AFT	MENT PANEL. , OP's, AND E 12/16/06 01M-998
TOF #6 SEAT. ELECTRICALLY OPERATED ON EFLIGHT MANUAL SUPPLEMENT FOR OPERATE AK CHECK OK. AVID R. LANDRETH A&P 2651512 IA AVIATION, INC. ALBUQUERQUE A Repair Station GMZR383E 505 842-4184 1. Completed annual inspection using Raytheon Bonanz. 2. Resealed windscreen at several areas required with P 3. Reglued L/H wing root rubber seal. 4. Retorqued pilot seat arm rest bolts. 5. Adjusted cabin door striker plates. 6. Installed new R/H wing fuel sump drain. 7. Installed new bulb lower beacon. 8. Installed new tail navigation light bulb. 9. Installed new R/H wing stobe light bulb. 10. Adjusted L/H cowl door linkage to clear exhaust stack 11. Serviced NLG shimmey dampner as required with MI 12. Serviced MLG struts and NLG strut with nitrogen as 13. Installed new L/H and R/H MLG brake caliper pads, b 14. C/W with cabin 12 month fire extinguisher inspection 15. C/W 100 hour lubrication requirements.	REG # S/N HM TACH Ta A36 ins PR 1425.	WITCH AND PRIND CONTINUED N610TC E-3660 202.4 N/A pection checklist as	a guide , PN 36-50	DATI W/O AFT	MENT PANEL. , OP's, AND E 12/16/06 01M-998
TOF #6 SEAT. ELECTRICALLY OPERATED ON EFLIGHT MANUAL SUPPLEMENT FOR OPERATE AK CHECK OK. AVID R. LANDRETH A&P 2651512 IA AVIATION, INC. ALBUQUERQUE A Repair Station GMZR383E 505 842-4184 1. Completed annual inspection using Raytheon Bonanz. 2. Resealed windscreen at several areas required with P. 3. Reglued L/H wing root rubber seal. 4. Retorqued pilot seat arm rest bolts. 5. Adjusted cabin door striker plates. 6. Installed new R/H wing fuel sump drain. 7. Installed new bulb lower beacon. 8. Installed new tail navigation light bulb. 9. Installed new R/H wing stobe light bulb. 10. Adjusted L/H cowl door linkage to clear exhaust stack. 11. Serviced NLG shimmey dampner as required with MI. 12. Serviced MLG struts and NLG strut with nitrogen as installed new L/H and R/H MLG brake caliper pads, b. 14. C/W with cabin 12 month fire extinguisher inspection. 15. C/W 100 hour lubrication requirements. 16. C/W with torque check of aircraft wing bolts.	REG # S/N HM TACH Ta A36 ins R 1425.	WITCH AND PRIND CONTINUED N610TC E-3660 202.4 N/A pection checklist as	a guide , PN 36-50	DATI W/O AFT	MENT PANEL. , OP's, AND E 12/16/06 01M-998
TOF #6 SEAT. ELECTRICALLY OPERATED ON EFLIGHT MANUAL SUPPLEMENT FOR OPERATE AK CHECK OK. AVID R. LANDRETH A&P 2651512 IA AVIATION, INC. ALBUQUERQUE A Repair Station GMZR383E 505 842-4184 1. Completed annual inspection using Raytheon Bonanz. 2. Resealed windscreen at several areas required with P 3. Reglued L/H wing root rubber seal. 4. Retorqued pilot seat arm rest bolts. 5. Adjusted cabin door striker plates. 6. Installed new R/H wing fuel sump drain. 7. Installed new bulb lower beacon. 8. Installed new tail navigation light bulb. 9. Installed new R/H wing stobe light bulb. 10. Adjusted L/H cowl door linkage to clear exhaust stack. 11. Serviced NLG shimmey dampner as required with Mil 12. Serviced MLG struts and NLG strut with nitrogen as a lail installed new L/H and R/H MLG brake caliper pads, but the complex of	REG # S/N HM TACH Ta A36 ins R 1425.	WITCH AND PRIND CONTINUED N610TC E-3660 202.4 N/A pection checklist as	a guide , PN 36-50	DATI W/O AFT	MENT PANEL. , OP's, AND E 12/16/06 01M-998
TOF #6 SEAT. ELECTRICALLY OPERATED ON EFLIGHT MANUAL SUPPLEMENT FOR OPERATE AK CHECK OK. AVID R. LANDRETH A&P 2651512 IA AVIATION, INC. ALBUQUERQUE A Repair Station GMZR383E 505 842-4184 1. Completed annual inspection using Raytheon Bonanz. 2. Resealed windscreen at several areas required with P 3. Reglued L/H wing root rubber seal. 4. Retorqued pilot seat arm rest bolts. 5. Adjusted cabin door striker plates. 6. Installed new R/H wing fuel sump drain. 7. Installed new bulb lower beacon. 8. Installed new tail navigation light bulb. 9. Installed new R/H wing stobe light bulb. 10. Adjusted L/H cowl door linkage to clear exhaust stack. 11. Serviced MLG shimmey dampner as required with MI 12. Serviced MLG struts and NLG strut with nitrogen as a laid installed new L/H and R/H MLG brake caliper pads, but also have been been been been been been been be	REG # S/N HM TACH TACH TACH TACH TACH TACH TACH TACH	N610TC E-3660 202.4 N/A pection checklist as	a guide , PN 36-50 a guide , PN 36-50 a guide , PN 36-50 a guide date 09/2007.	DATI W/O AFT	MENT PANEL. , OP's, AND E 12/16/06 01M-998 T 202.4

AVIATION, INC. 87.1 DATE REG # N610TC E-3660 W/O S/N **AFTT** HM 202.4 A Repair Station GMZR383E 505 842-4184 TACH N/A Propeller SN EE-5550B . Completed Annual inspection using Raytheon Bonanza A36 inspection checklist as a guide , PN 36-590001-9. 2. Dressed and painted propeller as required. 3. CK'd AD 2005-14-11 Hartzell Propeller. AMDT 39-14188. Propellers returned to service by Sourthern California Propeller Service. Not applicable, propeller has not been returned to service by Southern California Propeller Service. 4. Checked AD 2005-18-20 Goodrich "Fast Prop" de-icer boots. AMDT 39-14261. N/A by part number installed. 5. Operational and leak checked. This propeller and/or component is certified to be airworthy for return to service with respect to the work performed. Jose R Ramos **Bode Aviation** 11 October 2007 Hobbs/Total: 298.0 Albuquerque, NM N610TC Beech G36 S/N: E3660 Annual inspection completed this date in accordance with Bonanza Series Maintenance Manual. Inspected all controls, cables, pulleys, fluid and pneumatic plumbing, electrical wiring, surfaces and structures. Inspected and operationally tested ELT IAW FAR 91.207D and found airworthy for return to service, replaced battery next due Sept. 2010. Performed landing gear operational checks in both normal and emergency functions. Cleaned, inspected and greased wheel bearings. Replaced air conditioner drive belt p/n: 646293-34.00. Replaced air conditioner drive belt guard bracket. Resealed left brake caliper and bled brakes. Replaced flashing beacon bulb. I certify this airframe has been inspected IAW an Annual inspection and has been found airworthy for return to service. CRS J7BR555Y WO 3584 Dave Modisette AVIATION, INC. **REG # N 610TC** DATE ALBUQUERQUE S/N E3660 W/O FAA Repair Station GMZR383E 353.4 505 842-4184 Removed defective Comm 2 Antenna P/N DM C70-4 S/N 7364 and installed new Comm 2 Antenna P/N DM C70-4 S/N 7933. This aircraft and/or component is certified to be airworthy for return to service with respect to the work performed. Thomas A. Parks SIGNATURE: AVIATION, INC. REG # N610CT DATE S/N E-3660 W/O Repair Station GMZR383E HM 370.3 **AFTT** 505 842-4184 TACH N/A

12/16/06

01M-998

6/02/08

Page 1 of 1

N/A

08/04/08

01M2371

01A-2156

202.4

	Leading the Business	T	2802 Old Tower Road Phoenix Arizona 85034 FAA Repair Station No. EKGR571D		602-267-4070 Phon 602-267-4030 FAX
	Model Serial No. Registration	G36 E3660 N610TC	Aircraft Log	Work Order No. Hour Meter Aircraft Total Time	02M-4045 374.5 374.5
- 1	Replaced main air Replaced right ma	rcraft battery with new ain landing gear tire w	p/n G-242, s/n G02379016; ith new p/n 070-313-0, s/n7346-W00038 and		
	Signed:	Konnell			

N610TC Hartezell PHC-C3YF-1RF S/N EE5550B



Annual inspection completed this date in accordance with Aircraft maintenance Manual and 14 CFR 43 Appendix D. Replaced deice boot strap on blade S/N K40225. Dressed propeller. I certify that this propeller has been inspected in accordance with an annual inspection and has been found to be airworthy with respect to the above work performed.

Stuart Miles

CRS J7BR555Y WO 4511

HOURS	LINES IF REQUIRED

SIGNATURE

NUMBER

23 October 2008 Hobbs/Total: 391.5 N610TC Beech G36 S/N E3660



Annual inspection completed this date IAW Aircraft Maintenance Manual and 14 CFR 43 Appendix D. Inspected all controls, cables, fluid and pneumatic plumbing, electrical wiring, surfaces and structures. Inspected and tested ELT IAW FAR 91.207D and found it airworthy with battery EXP date of Sept. 2010. Performed landing geaar rigging and operational checks in both normal and emergency modes. Inspected and repacked all wheel bearings. Replaced left main tire and tube with new. Bled right brake. Replaced tail beacon bulb with new. Installed M-20 air/oil seperator. Rigged right cowl latch assembly mechanism. IFR certification performed by Bode Avionics. Replaced engine air filter with new. Serviced all landing gear struts with nitrogen. I certify that this aircraft has been inspected in accordance with an annual inspection and has been found to be airworthy with respect to the above work performed.

Stuart Miles.

08

12 01

CRS J7BR555Y WO 4511

LANDING LIGHT R. BALDOCK
GOOD Robolock

2660\$78

7 January 2009 Hobbs/Total: 438.0 N610TC Beech G36 S/N E3660

4/3.0



Resealed the drain fitting for the air/oil seperator on the # 2 rocker cover. Reinstalled the rocker cover with a new gasket and torqued. Performed a ground run-up for leak and operational checks, both checks good. I certify that this aircraft is OK for return to service with regard to the above work performed.

Chris Torres

CRS J7BR555Y WO 4676

22 October 2009 Hobbs/Total: 486.8 N610TC Beech G36 S/N E3660



Annual inspection completed this date IAW Aircraft Maintenance Manual and 14 CFR 43 Appendix D. Inspected all controls, cables, fluid and pneumatic plumbing, electrical wiring, surfaces and structures. Inspected and tested ELT IAW FAR 91.207D and found it airworthy with battery EXP date of Sept. 2010. Performed landing geaar rigging and operational checks in both normal and emergency modes. Inspected and repacked all wheel bearings. Replaced brake pads with new both sides. IFR certification performed by Bode Avionics. C/W fuel gauge accerancy check. C/W fuel flapper valve inspection. C/W AD-2009-15-01 by visual inspection, Connector chaffing on fuel line, no defects noted. I certify that this aircraft has been inspected in accordance with an annual inspection and has been found to be airworthy with respect to the above work performed.

Gilbert B. Aragon
CRS J7BR555Y WO 5295.

B. Brand

22 October 2009 Hobbs/Total: 486.8

N610TC Hartezell PHC-C3YF-1RF S/N EE5550B



Annual inspection completed this date in accordance with Aircraft maintenance Manual and 14 CFR 43 Appendix D. Dressed propeller. I certify that this propeller has been inspected in accordance with an annual inspection and has been found to be airworthy with respect to the above work performed.

F

Gilbrt B. Aragon CRS J7BR555Y WO 5295.

S.B. aragen

	DATE		TIME	ENTRIES MAY BE ON MULTIPLE	INSPECTOR'S	LICENSE
Y	M	D	HOURS	LINES IF REQUIRED	SIGNATURE	NUMBER
09	9	24	479,2	rerighed Passenger Cowl		
				latch as per Coul latch		
				Rigging instructions 71-10-00		4.4.0
				Page 1 A - a	RUTE	245745575

Bode Aviation

Cessna

2505 Clark Carr Loop SE, Albuquerque, NM 87106

Airframe

FAA CRS J7BR555Y

N#: N610TC Model: Beech G36 S/N: E3660

Date: 12/9/10 Hobbs/Total: 534.5

Completed Annual inspection IAW 14 CFR 43 Appendix D and Aircraft Maintenance Manual. Inspected all controls, cables, pulleys, plumbing, and surfaces and structures. Inspected ELT IAW FAR 91.207D and found airworthy, installed new battery. Performed landing gear rigging and operational checks in both normal and emergency modes. Cleaned and repacked all wheel bearings. Replaced nose landing gear tire and tube, and balanced assy. Resealed right brake caliper and bled brake. Replaced B3-5-1 garter filter. Replaced standby battery with new unit p/n: RG125 s/n: 40362313. Removed propeller, sent to New Mexico Propeller CRS N5PR141Y for reseal, and reinstalled. Removed and reinstalled oxygen bottle after hydrostatic test. Serviced oxygen. C/W AD 76-07-12 ignition switch function check. C/W AD 2008-02-06 Garmin auto pilot servo inspection IAW Garmin SB 0713 rev C, NDN. C/W SB27-3459 control lock inspection. I certify that this aircraft is airworthy for return to service with respect to the above work performed.

Dave Modisette

OM

_WO# ABQ1488

CL	ITTER
AL	BUQUERQUE

AVIATION, INC.

REG # N610TC S/N E-3660 DATE W/O

12/9/10 01A-3749

FAA Repair Station GMZR383E 505 842-4184 S/N E-3660 HM 534.7 TACH N/A

AFTT N/A

The static system has been tested as required by FAR 91.411 and found to comply with FAR 43 APPD. E(a) on 12/9/10 The Altimeter tests and inspections required by FAR 91.411 have been performed and comply with FAR 43 APPD. E(b). (LH S/N) 47805176 (DATE) 12/9/10 (Tested To) 20,000 ft.

The Transponder tests and inspections required by FAR 91.413 have been performed and found to comply with FAR 43 APPD.F.

The integrated system was tested as required by FAR 91.413 and FAR 91.217 and found to comply with FAR 43 APPD. E (c) on 12/9/10 (Model No.) GTX-33 (S/N) 89100051 (Date) 12/9/10

This aircraft and/or component is certified to be airworthy for return to service with respect to the work performed.

Joseph Dougherty

SIGNATURE:

Page 1 of 1

WEST TEXAS AERO 7000 ANDREWS HWY ODESSA TX 79765 FEBRUARY 13, 2012 N610TC RAYTHEON G36 S/N: E-3660 HOBBS: 562.0 HARTZELL PHC-C3YF-1R/F8468A (B,K) -6R CONSTANT SPEED PROP TT: 562.0 **PROPELLER**

I CERTIFY THAT THIS PROPELLER HAS BEEN INSPECTED IAW A ANNUAL INSPECTION AND FOUND TO BE AIRWORTHY. ALL AD'S C/W AND WORK DONE IAW APPROVED DATA ON FILE WITH WEST TEXAS AERO. THIS PROPELLER IS APPROVED FOR RETURN TO SERVICE FOR THE WORK PERFORMED.

DGLADSTONE AP467877872IA

DATE TIME ENTRIES MAY BE ON MULTIPLE Y M D HOURS LINES IF REQUIRED	INSPECTOR'S SIGNATURE	LICENSE NUMBER
EINES II REGGIRES	GIGHATORE	(VOIIIDE)
West Texas Aero 7000 Andrews Hwy Odessa Texas 79	762 432-552-7691	
N610TC 2/10/12 Beechcraft G36 S/N E-3660 A		
Airframe Log		-
Complied with MSB28-3967 and serviced nose strut to proper level, rep	olaced ELT battery and	! operational
check good at this time. Removed altimeter and reinstalled after IFR ce		
inspection at this time and found aircraft to be airworthy at this time. A	All AD's and logs comp	olied with a t
this time.	_	-
DGladstoneAP467877872IA		
e i T		l I
West Texas Aero 7000 Andrews Hwy Odessa Tx 79765 03/03/13		:
N610TC Beech G36 E-3660 AFTT: 571.1 Airframe		
Opened all access panels and checked cables, controls and sec	curity of equipment Cl	neck travel
of surfaces and jacked aircraft. Swing gear and service IAW M	4M, filled hydraulic flu	id and
repacked bearings. Serviced ship battery and check ELT IAW	FAR check ok at this ti	me I certify
that this airframe has been inspected IAW an annual and four	nd to be airworthy at th	nis time
Return to service for work performed, all AD's c/w up to dat	e and FAR91.411 c/w a	at this time
1 ransponder certification c/w and due FAR91.417 IFR Cert. 3	/15 DGladstoneAP467	877872IA
CRS & BONR SOLX 4)		(Land
	_	
	30	
West Texas Aero 7000 Andrews Hwy Odessa Tx 79765 03/03/13	ı	
N610TC Beech G36 E-3660 AFTT: 571.1 Propeller		7
I certify that this propeller has been inspected IAW an annu-		
airworthy at this time. All AD's c/w up to date and work or	n file with West Texas A	Aero.
DGladstoneAP467877872IA		A
	t	8
	i	

WEST TEXAS AERO 7000 ANDREWS HWY ODESSA TX 79765

MAY 05, 2014 N610TC RAYTHEON G36 S/N: E-3660 HOBBS: 588.9 AFTT: 588.9

AIRFRAME

I CERTIFY THIS AIRCRAFT HAS BEEN INSPECTED IAW AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AN AIRWORTHY CONDITION. AD RESEARCH COMPLETED THROUGH BIWEEKLY 2014-08.

INFLATE NOSE STRUT TO PROPER LEVEL. REMOVED AND REPLACED BATTERY WITH NEW G242 S/N: G02824150. REMOVE AND RESEAL LEFT HAND BRAKE CALIPER ORING P/N:MS28775-222. CLEAN NOSE WHEEL AS NEEDED. REMOVED AND REPLACED AIR FILTER WITH NEW P/N: P137627. REPLACE ALL LANDING GEAR GREASE ZERK DUST CAPS WITH NEW P/N: GC-5. REMOVED AND REPLACED ELT BATTERY WITH NEW P/N: 452-0130 NEW EXP DATE JUN 2016.

THIS AIRCRAFT WAS REPAIRED AND INSPECTED IAW CURRENT FEDERAL AVIATION REGULATIONS AND IS APPROVED FOR

RETURN TO SERVICE.

DAN WEBRE JR AP3501544IA

*	C 2 (a		F 3	(((
Aircraft Model	636	Serial Number	E 31	960	
Reg# NG	G36 =	Owner's Name			
	¥/				
		MAY BE ON MULTIPL NES IF REQUIRED			LICENSE NUMBER
MAY 05, 2014 N610 HARTZELL PHC-C3YI PROPELLER CERTIFY THIS PROF AIRWORTHY CONDI	7000 ANDREWS HWY ODESSA TO TEC RAYTHEON G36 S/N: E-3660 F-1R/F8468A (B,K) -6R CONSTAIN PELLER HAS BEEN INSPECTED IA TION. AD RESEARCH COMPLET RRENT FEDERAL AVIATION REGOLDS44IA	D HOBBS: 588.9 NT SPEED PROP TT: 588.9 AW AN ANNUAL INSPECTION TED THROUGH BIWEEKLY 201	4-08. THIS PROPELLE	ER WAS REPAIRED) AND
		ve., Lubbock, TX 794 - E3660, M/N- G36 H			
	Installed customer su Turned middle seats a Serviced Oxygen to 1 Serviced MLG struts to		ning oxygen. omer		
	Wade E. Jones A	&P 3647188			
		T make		100	
	7.5.	1,000	ATTE		p.

Aircrat	t Model Serial Number	
Reg #	Owner's Name	_
DAT		
Y M	D HOURS LINES IF REQUIRED SIGNATURE NUMBER	
/	31 627.3 REMOVED SEAT #5. WEIGHT & BALANCE ADS. JOSOCO.	129/4
per j	POH BOUR. 43. Roy R long O - OWNENSP. 105	
4		
	Aircraft Maintenance Services Camden, SC 29020	
	Phone: (803) 713-0200 Fax: (803) 713-0017	-
ate 8 N	Web: amscamden.com Email: frank@amscamden.com May 2015 Tach:661.3 TT: 661.3	
	Annual inspection and lubrication completed this date as per Beechcraft maintenance annual	
	100 hour/ annual inspection check list.	-
	1. Left wing quick drain leaking, cleaned drain and leak checked.	
	2. Performed 12 month inspection on Garmin G1000 as per check list,*(battery_replaced last	:
	year, due May 2017) weighed cabin fire bottle.	-
	3. Inspected landing gear motor brushes as per 500 hour inspection.	
	4. Serviced oxygen bottle and tightened fittings in tail.	
	5. Lubricated rear cabin door.	:
	6. C/W AD2001-08-08 by inspection of V band clamp for proper torque.	
	7. Painted RH flap cover where needed. 8. Found landing gear retract rod loose on nose gear, torqued as ner Beech maintenance	
	Found landing gear retract rod loose on nose gear, torqued as per Beech maintenance manual.	-
	9. Installed new flap rubber bumpers as needed.	
	10. Installed new fuel cap O rings.	
	11. Inspected Alternator as per 500 hour inspection.	
	12. Removed RH brake actuator and installed new seals due to leak.	
	13. Inspected Engine shock mounts as per 100 hour inspection.	-
	14. Preformed routine maintenance as per Beechcraft 100 hour/ annual inspection check list,	
	lubricated as per manual.	
	I certify that this aircraft was inspected IAW an annual inspection	
	And is approved for return to service this date, 8 May 2015.	
	Frank O. Schumpert A&P3565623IA	
-1		
*	Aircraft Maintenance Services Columbia, SC 29205 Phone: (803) 708-7191	
	www.amscolumbia.com Email: frank@amscolumbia.com	
Date	17 June 2015	
	ved pilots control yoke and complied with SB# 27-4136 as per service bulletin instructions.	-
ACTIO	who o school of Frank O. Schumpert A&P3565623IA	

Aircraft Model	Serial Number	
Reg #	Owner's Name	_^
	S MAY BE ON MULTIPLE INSPECTOR'S LICENS INES IF REQUIRED SIGNATURE NUMBE	
Bendix OH manual. Installed ne reassembled. Timed engine and 2. Removed turbocharger due to SN:KGL00179). Turbo installed 3. Removed starter drive adapter	Aircraft Maintenance Services, Inc. 1400 Jim Hamilton Blvd, Bldg E Columbia, SC 29205 www.amscolumbia.com ur inspection. Disassembled and inspected in accordance with w breaker points and capacitors in both magnetos and I reinstalled magnetos. Ground run checked good. eaking oil seal. Installed OH turbocharger (PN:632729-13, with new gaskets. Ground run to leak check, leak checked good. due to oil leak. Installed OH starter drive adapter alled with new gasket. Ground run to verify function and leak	
		, -
		_

g#_			Senai Number			
			Owner's Name			
ATE			Y BE ON MULT		ECTOR'S	LICENSE
M	D HOURS	LINES	IF REQUIRED	SIGN	IATURE	NUMBER
+				=		
ſ		Baker A	viation	IFR Cert	June 2018	
	\odot	333 South Street, N	New Smyma, FL	ELT Battery Date Engine Type	Nov 2018 IO-550-B	
		386-837-		Serial Number	687094	
	A D.C	Date:	05/27/16	TTSMOH:	717.8 717.8	
i	AB2	Registration:	N610TC G-36	TTIS: Propeller Type	PHC-C3YF-1	RF -
3.7	CENTER	Make/ Model:	E-3660	Serial Number	EE5292B	
	OF	Serial Number:		TTSMOH:	717.8	-
	EXCELLENCE	Tach / Hobbs:	717.8		717.8	
Į.	LACLELLIACE	TTAF:	717.8	TIIS:	111.0	
	Replaced ship's #2 Performed landing	1 battery with new G-242 2 battery with new G-125 gear retraction check and ock cable tensions	d set all clearances t	o factory specs.	9	
٠	Lubed flight contro		n new.		27	
	Checked rigging o					
		e fuel screen, cleaned & re	e-installed.			
:	Replaced fuel cap Removed oxygen	o-rings with new. cylinder and sent to Dayto	ona Fire Safety and	Equipment for hydro-station	testing. Re-inst	alled and
	filled. Adjusted cowl flap	lever for better operation.	. 4			
•	AD's Complied w			ery with new. Next due No	vember 2018.	
	· AD 07-08-08	Test Ignition Switch, next Lubricate Up-lock rollers,	next due TTAF: 817	7.8		
	All other AD's	s researched through this	date.	with an Annual inconcetion	a and was data-	nined to be in
	an airworthy cond	IRCRAFT has been inspe ition. All work performed i aft for return to service.	in reference to manu	with an Annual inspection ifacturer's specifications a	and all applicable	FAR's. I
i i	approve his aircie	an ioi journ a journe.				
-	1 ()	XZ)				
	nes Curtis Boulware	A&P 3232817 IA	- END		******	
Jam		1			1	
Jam						
Jam					(a):	
Jam					548	

Capital Aviation Instruments & Avionics

Repair Station No. OY1R391K 10660 Aviation Lane Manassas, VA 20110 Phone: 703-369-0500

DATE: 11/11/2016 A/C TSN: 758 2 HOBBS: 758 2

Avionics Entries

- · Added second PTT switch on pilots yoke in provisions supply by manufacture system operational check good.
- Removed Garmin GTX 33 remote transponder at station 50.0.

Installed the following equipment:

Garmin GTX 345 remote transponder at station 50,0, p/n 010-01217-43 s/n 3EH400542

Garmin GA-35 WAAS GPS antenna at station 87.0. p/n 013-00235-00 s/n 125169

Inserted Garmin FAA approved Flight Manual Supplement p/n 190-00734-15 Rev. 2 Mar. 8, 2016 into aircraft records. Inserted Garmin FAA Approved Instructions for Continued Airworthiness p/n 190-00734-11 Rev. 5 pages 4-1 thru 4-6, Oct 18, 2016 into the aircraft maintenance records.

A 5 amp circuit breaker labeled "XPNDR" located on the copilot's avionics bus supplies power to the system. Garmin GTX-345 installed in accordance with Garmin STC SA01714WI June 30, 2016 and Garmin STC installation Manual p/n 190-00303-61 Rev.

Installation completed in accordance with AC 43,13-1B Chapters 10, 11 and 12 and AC 43.13-2B Chapters 1, 2 and 3.An operational test was performed on the newly installed equipment IAW the equipment manufacturer's instructions and all functions performed properly. All aircraft systems were tested and determined that no Electro Magnetic Interference to or from the newly installed equipment occurred.

An electrical load analysis was performed and found that the continuous load of the alternator output does not exceed 80% of capacity. Weight and balance and equipment list revised.

- Updated all databases to current cycle, G1000 databases function check ok
- · Re Pinned MFD and PFD connectors, Ops Check Good

THE AIRCRAFT, AIRFRAME, AIRCRAFT ENGINE, PROPELLER, OR APPLIANCE DENTIFIED ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT REGULATIONS OF THE FEDERAL AVIATION SERVICE, PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS REPAIR STATION OF THE ABOVE WORK ORDER

DATE: 11/11/2016

SIGNED:

Work Order: 52734

Dawayne Wilcox pair Stat n No. OY15 Printed by EBis 3 (datcomedia.com)

MAKE: BEECH MODEL: G36 S/N: E-3660 REG. NO: N610TO WORK ORDER 52734

Capital Aviation Instruments & Avionics

Repair Station No. OY1R391K 10660 Aviation Lane Manassas, VA 20110 Phone 703-369-0500

DATE: 11/11/2016 A/C TSN 758 2 HOBBS 758 2

Airframe Entries

- Performed Annual Inspection IAW Beechcraft Bonanza AMM inspection checklist. Researched AD's thru biweekly issue 2016-22. Jacked aircraft & completed normal & emergency gear swings, Inspected & cleaned fuel strainer. Cleaned, inspected & repacked wheel bearings & lubricated aircraft. All work performed in accordance with manufacturers recommended procedures. Ground runs, leak & ops checks were good.
- ELT tested IAW FAR 91.207(d) 2-4 (ref CAIA W/O 10995), battery expires November 2018.
- Removed and cleaned old RTV from engine sump and LH pre-heater pad, Re-bonded pre-heater sump pad to engine sump,
- Re-torqued and safetied hardware on RH I/B fuel transmitter per Bonanza AMM 28-40-00
- Removed broken piece of drain fitting plastic from drain tube sleeve on evaporator housing and repaired as required. Reinstalled evaporator mounting hardware, evaporator air duct, and adjacent floor boards as required.
- Complied with Tornado Alley ICA's for 50 hr, 100 hr and 3 year inspection items.
- Complied with 10 year replacement of engine compartment flammable fluid hoses per Tornado Alley STC ICA Airworthiness Limitations and Beechcraft G36 AMM, ground run, leak & ops checks satisfactory.
- Removed exhaust v-band clamp P/N 11-1100035, installed new exhaust V-Band Clamp P/N 11-1100035 (Tornado Alley STC 400 hr airworthiness requirement) IAW TAT MSB 98-1. Exhaust gaskets P/N 642502 replaced IAW Beech G36 MM and TCM SB96-7C.
- Complied with Tornado Alley Oxygen system ICA 35-6460001 Continued Airworthiness Rev A
- Repaired landing light wire inside of nose bowl IAW AC 43,13-1B Ch 11,
- Removed RH baffle from engine, stop drilled crack, fabricated & installed doubler, reinstalled RH engine baffle.
- Primed and painted interior of battery box IAW AMM 20-08-00
- Installed new drain valve P/N CCA3400 at LH fuel bladder, leak check good.
- Removed RH brake caliper & disassembled, removed and discarded o-rings. Cleaned pucks and caliper. Installed new o-rings P/N MS28775-222 & reassembled caliper. Reinstalled caliper & torqued backing plate to 90 in-lbs. Bleed RH side brake system, ops check good
- Adjusted elevator control cable tension IAW AMM 27-30-00.
- Extracted broken grease fitting in RH MLG, installed new grease fitting P/N 3016 and serviced with grease,
- Fabricated and installed a new retaining tab at upper fwd RH wing bolt cover IAW AC 43.13-1B, Ch 3 and 6.

- · Adjusted LH and RH MLG up lock cable tension IAW AMM 32-00-00, ops check good.
- Installed AeroLED PMA landing light assembly P/N 01-1030-L-A IAW AeroLED installation guide Doc # 0003-0004. Installed AeroLED PMA taxi light assembly P/N 01-1030-L-B IAW AeroLED installation guide Doc # 0003-0004.
- Resealed shimmy dampener ref AMM 32-20-00 & serviced IAW Beechcraft AMM 12-20-00

Certified Repair Station No OY1R391K

- Adjusted nose gear up tension IAW AMM 32-00-00, ops check good.

 Repaired chafed starter power lead by removing damaged portion and replacing starter ring terminal with AMP4HDW in accordance with AC43.13-1B, ops checked good.

I certify this aircraft / engine / proportier has been inspected in accordance with an annual inspection and determined to be in airworthy condition

THE AIRCRAFT, AIRFRAME, AIRCRAFT ENGINE PROPELLER, OR APPLIANCE IDENTIFIED ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT REGULATIONS OF THE FEDERAL AVIATION AGENCY AND IS APPROVED FOR RETURN TO SERVICE PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS REPAIR STATION UNDER THE ABOVE WORK ORDER

DATE: 11/11/2016

SIGNED: WOOL Woodrow L Mowry

Work Order: 52734

Printed by EBis 3 (datcomedia.com)

ENGINE MODEL 10-550-B 39B

Capital Aviation Instruments & Avionics

ENGINE S/N: 687094 REG. NO: N610TC WORK ORDER 52786 Repair Station No OY1R391K 10660 Aviation Lane Manassas, VA 20110 Phone 703-369-0500

DATE 11/21/2016 A/C TSN 759 2 ENG TT 759 2 TSMOH HOBBS 759.2

Log Entries

Re-torqued exhaust V-band clamp IAW MSB TAT 98-1. Next V-band clamp replacement is due at 1158.2 ACTT.

THE AIRCRAFT AIRFRAME, AIRCRAFT ENGINE, PROPELLER OR APPLIANCE IDENTIFIED ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT REGULATIONS OF THE FEDERAL AVIATION AGENCY AND IS APPROVED FOR RETURN TO SERVICE PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS REPAIR STATION UNDER THE ABOVE WORK ORDER

DATE: 11/21/2016

SIGNED: WOOD

Work Order: 52786

Woodrow L Mowry Certified Repair Station No OY1R391K Printed by EBis 3 (datcomedia.com)

MAKE: BEECH MODEL G36 S/N E-3660 REG NO: N610TC WORK ORDER 52734 Capital Aviation Instruments & Avionics

DATE 11/21/2016 A/C TSN 759 2 HOBBS 759 2

10660 Aviation Lane Manassas, VA 20110 Phone: 703-369-0500

Repair Station No OY1R391K

Airframe Entries

· Installed Door Steward door assist gas spring modification on forward cabin door IAW Mountain View Aviation STC No. SA01120SE and Installation Instructions MVA-B40C10M&O, Rev. B, dated January 2, 2010, Instructions for Continued Airworthiness are contained within Installation Instructions MVA-B40C10M&O, Section B. Weight and balance change was negligible. Completed FAA Form 337 and submitted.

Installed battery minder leads and secured as required.

Removed and replaced alternate air door micro switch P/N ETI-B-703-SR IAW TAT GAMI Procedure #0965. Ops check good

THE AIRCRAFT. AIRFRAME, AIRCRAFT ENGINE, PROPELLER, OR APPLIANCE IDENTIFIED ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT REGULATIONS OF THE FEDERAL AVIATION AGENCY AND IS APPROVED FOR RETURN TO SERVICE PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS REPAIR STATION UNDER THE ABOVE WORK ORDER

DATE: 11/21/2016

SIGNED: WOR Woodrow L Mowry Certified Repair Station No OY1R391K

Work Order: 52734

Printed by EBis 3 (datcomedia.com)

MAKE: BEECH MODEL: G36 S/N: E-3660 REG. NO: N610TC WORK ORDER: 52805

Capital Aviation Instruments & Avionics

DATE, 2/6/2017 A/C TSN: 759.2 HOBBS 759 2

Repair Station No. OY1R391K 10660 Aviation Lane Manassas VA 20110 Phone 703-369-0500

Avionics Entries

· Confirmed Intermittent GIA failure. Removed the GIA, PN 011-01105-20 SN 1HQ012062, and installed the overhauled GIA, PN 011-01105-20 SN 1HQ015786. Loaded the Software and configuration files I/A/W Garmin G1000 Line Maintenance Manual

THE AIRCRAFT, AIRFRAME, AIRCRAFT ENGINE, PROPELLER, OR APPLIANCE IDENTIFIED ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT REGULATIONS OF THE FEDERAL AVIATION AGENCY AND IS APPROVED FOR RETURN TO SERVICE PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS REPAIR STATION UNDER THE ABOVE WORK ORDER

DATE: 2/6/2017

SIGNED:

Work Order: 52805

Leslie Touart Certified Repair Station No OY1R391K Printed by EBis 3 (datcomedia.com)



Barrier Island Aviation, Ltd.

Aircraft N610TC Date 8-19-17 Installed new Michelin 5.00x5 n Andy Rosman 3524208 A&P

Hobbs 799.9

wheel tube and McCreary Airhawk 5.00x5 tire

Aircraft	t Model		Serial Number		
Reg#_	X		Owner's Name		
DATE Y M			RIES MAY BE ON MULTIPLE LINES IF REQUIRED	INSPECTOR'S SIGNATURE	LICENSE NUMBER
	9/6/2017	N610TC	Beech G36	Aircraft Logbo	ook
	Hobbs Hours: 8	308.0	. 5		34
	Service oxygen				
	-	e pads on right hand k was completed in	accordance with current regulations of the	Federal Aviation	
	Administration	and is approved for	return to service for the work accomplished	d.	
		•	Signed		
			James Wrenn	A&P 2724810IA	
+					
			Wor TICH		1
			NA WATER		
	12/21/2017	N610TC	Beech G36	Aircraft Logb	ook
	Hobbs Hours: 8				9
	Annual Inspect	ion completed this	date in accordance with Beech Maintenanc nges and pulleys. Jacked aircraft and check	e Manual and 14CFR Part 43	3
	and normal ope	eration. Cleaned fue	el strainer. Checked magneto timing and el	ngine compression 1) 72 2)	су :
	70 3) 68 4) 68 battery due 11/	3 5) 70 6) 68. Chec	ked ELT operation in accordance with 14C	FR Part 91.409 (a). ELT	
	Replaced engir	ne air filter with new	•		
	Checked stand	by avionics battery,	operation OK. Replaced @ 717.0 TTAF 08 battery, operation OK. Replacement due of	5/27/2016.	-
	Serviced O2 cy	rlinder to 1600 psi. a	and checked date, OK. Hydrostat complete	d @ 717 TTAF 05/27/2016.	
	Serviced gear s	struts with 5606 hyd	raulic fluid and nitrogen. ohragm. Removed pump and sent to Aeron	notore IIC for ropair CBS #	
	01MR357Y. Pu	mp part number 46	13-00-5. Serial number 1274. Reinstalled	after overhaul. Operational	
	check ok. Lubricated latch	h mechanism on ca	bin door.	일	
	Replaced TIT p	probe with new.	- : 11		
	switch plunger	ig gear box with oil. IAW Beech AMM. I	Tightened gear box in mount. Set down tra Lubricated landing gear.	vel by adjusting gear down	
	Replaced bad s	static wick on elevat			
		the following AD's: on Switch 100 Hour.	Operational check OK.		31
	07-08-08 Uploc	k Roller 100 Hour.	Lubricated roller.	-U 750 0 LB4 44/44/0040	A
	Next due replace this AD.	cement in 400 hours	d Clamp. Inspected clamp. New clamp insi s 1234.3 HM, per TAT MSB 98.1 Next insp	ection due in 400 hours per	
	11-25-15 Starte	er adapter shaft failu	ire. PCW by replacement of starter adapter	705.2 HM, 12/28/2015.	
	Complied with	Tornado Alley Turbo	o Instructions for Continued Airworthiness Need borescope inspection of crossover heat	/lanual # 35-6460001 Rev. A	
	year schedule.	No cracks found.		exchanger for cracking IAVV	3
	TAT SB 12-01.	Change to five year	e Bulletins and Service Instructions: ir inspection interval on Kevlar O2 bottles. I	Next hydrostat due: 05/2021.	
	TAT SA 11-09.	Service advisory for	21. 15 year service life still applies. or Starter Adapter shafts. PCW by complia or correct spark plugs. Correct plugs are ir	nce with AD 11-25-15.	***
		s Aircraft has been i	nspected in accordance with an annual ins		to
	SO III GII GIIWOIL	ily condition.	Signed ////		
				A&P 2724810IA	
		Ç			

Aircraft Model	Serial Number		
Reg #	Owner's Name		
DATE TIME ENTRIES	MAY BE ON MULTIPLE	INSPECTORS	LICENCE
	IES IF REQUIRED	INSPECTOR'S SIGNATURE	LICENSE NUMBER
		er filmskaal	
1/21/2019 N610TC	Beech G36	Aircraft Logbook	
Annual Inspection completed this date in a Appendix D. Lubricated cables, hinges and 76 3) 76 4) 76 5) 76 6) 76/80 PSI. Jacked bearings and lubricated gear. Checked EL battery with new. Next due Nov. 2020. O2 Right and left side brake calipers leaking. Operational check ok. Left magneto leaking oil at gasket. Remo BTDC. Prop control rod end seized up. Remove Remove and replace nose gear strut servi Secure EGT wire for #1 cylinder to preven Torque engine mount bolts to 110 in/lbs w Tail navigation light burned out. Replace Remove and replace air conditioner belt w Remove battery box and clean underneat! Nose gear door bushings have excessive actuator rod ends. Serviced O2 cylinder to 1600 psi. and che Serviced gear struts with hydraulic fluid at Number 4 cylinder CHT is intermittent. To Replace with new. Operational check ok. TIT display is intermittent. TIT probe test. Complied with the following AD's: 93-05-06 Ignition Switch 100 Hour. Opera 07-08-08 Uplock Roller 100 Hour. Lubric 01-08-08 Exhaust Coupling V Band Clam due replacement in 400 hours 1234.3 HM 11-25-15 Starter adapter shaft failure. PC 17-16-01 AmeriKing ELT. Does not apply 18-03-04 CSE Pitot tube repair. Does not certify that this Aircraft has been inspectin an airworthy condition.	d pulleys. Checked magneto timing a aircraft and checked all landing gear. To operation in accordance with 14Cl bottle mandatory replacement due Common and rebuild both calipers, reverse and rebuild both calipers, reverse and rebuild both calipers, reverse and replace gasket with and lubricate, operational check ok. ice placard. It chaffing on exhaust pipe. In the extreme attached to nose gear tunnel. It bulb, operational check ok. It is new. In the service and charge airframe batter wear. Remove doors and install new locked date, OK. Hydrostat completed and nitrogen. It is probes by relocating to adjacent lock. Remove display and clean connectional check OK. In the extreme to the common late of the common	and engine compression 1) 76 2 operations. Greased wheel FR Part 91.409 (a). Replaced E 95/2021. e-install and bleed brake system new. Set timing to 22 degrees by, capacity test 86%. We hinge bushings. Tightened at @ 717 TTAF 05/27/2016. cylinder. #4 CHT probe bad. ectors. Operational check ok.	
	SOLI MANS.		_
		F	

Aircraft Model	Serial Nun	nber	
Reg #	Owner's i	Name	
DATE TIME Y M D HOURS	ENTRIES MAY BE ON I LINES IF REQUIF		
/// N61	LOTC Bonanza G36 SN E3660	Airframe Log-03/01/2020	,4
MAG	Total Aircraft Time: 938.7		
spection long form check list. In 1800 PSI with aviators oxygen Hyries Owner and operator manu 18-125 S/N 70007345 see 8130-3 w P/N 11-03208 lamp in tail na lt, replaced cowl chafe tape as lt cover, repaired engine air cleth new seals, service and reinst board retract rod bolts, all landin, jacked and serviced landing al, installed new Halon fire extirork done referencing Beechcraft plicable.	drostatic test due 6-1-2021, #2 batte al Document No. 5-0324 Rev. F date WW# 25505-04 dated 10/DEC/2015 v., cleaned and treated small amour needed, replaced fresh air scat duct aner seal as needed, repaired shim alled, Serviced brake system with Aring gear down lock and cable tension gear, retract checks normal with empuisher P/N 13-01966, Airworthine at G36 maintenance manual, G36 sup	utilizing Beechcraft Bonanza 36 annual par D. Batteries next due 08/2021. Set tery failed capacity check 3 times Refere ed Nov. 26/2019, installed new #2 batter 9 next due for test 03/2021, all lighting nt of corrosion under battery box, tight ting as needed, replaced clip on right up my dampener by freeing floating pistor teroshell #4 hydraulic oil. Tighten and pens check within limits, motor brushes comergency extension normal, installed new the proplement for G1000 series and AC43.13 with Annual inspection and was compared to the particle of the par	rviced O2 bottle to encing Concorde RG ery with Concorde g checked, installed ten air conditioning pper forward wing and reassemble win main gear check over 5/16 inch ew storm window rev. 02/25/2020, All 3-1B/2B as
found to comply wit	TC Transponder test required by	FAR 91.413 have been performs S/N 3EH 40052 S/N	42
SignedAero Avionics, Inc.(Saniord, N.C. CKS # A8XR424J	for	
1. Static system: Po 2. LH Altimeter: p 3. RH Altimeter: p 4. Integrated mode Performed items # Signed	aragraph (b) to 20.000 aragraph (b) to 20.000 "C" system per paragraph (c).	ft. S/N 47805176 ft. S/N 163508 W. O. # 16082 Date 210120	

Aircraft Model	Serial Nu	umber	
Tyler V. Brennan N7227B 06/02/2020 Raytheon-Beech G36 Bonanza S/N: B-3660 Hobbs: 947.5 AFTT: 947.5	Installed new Champion 481 Opened oil filter and did not	oved oil filter. Removed engi 109-1 oil filter, torqued and s find excessive debris or con arts Phillips X/C 20W50 Engi	afetied. taminants. LICENSE
Tyler V. Brennan Owner/Operator	3866875 FAA CPL #	04/28/2020 Date	
Inside & Out Aircraf 278 Aviation Rd., Pike	ct Services, Inc. ville, NC 27863 Ph. (919) 5	26-4287	
N7227B 06/02/2020 Raytheon-Beech G36 Bonanza S/N: B-3660 Hobbs: 958.7 AFTT: 958.7	inner tube and installed new Cleaned and repacked left m Grease. Reassembled wheel Serviced all tires with shop a and found indicator switche	I left main gear wheel assembly Michelin 7.00-6 Inner Tuber and wheel bearings with Moll assembly and torqued to mair. Troubleshot flap positions to be out of adjustment. Addandbook. Operational check to be out of adjustment. Declared to the control of the cont	(P/N: 06-00848.) bil SHC-100 Aviation anufacturer's specification. n indication error djusted switches I/A/W
bruce ic daruner	Gertificate #	1-	
Annual Inspection: CW AD 84-26-02 paper indureplacement every 3yrs, 5 cl Serviced all fuel screens. Greased wheel bearings and Replaced worn brake linings Resealed right and left whee Resealed NLG strut for leak, Serviced MLG struts with dr Replaced worn left aft nose Re-torqued loose nose whee Found NLG right and left do Found NLG Drag-brace aft at Performed landing gear ope (10) trouble free times with Replaced broken Air Condition	Transponder Cert. Dure to the property of the	It: 1043.2 2005 Raythe ue: Feb/2022 Aircraft and Idson P137627 filter at this time, where occurs first. Ity nitrogen. Heights. 2-410001-107 hinge and 105739X ar wrong, dis-assembled and re-assembled and re-assembled and greased. It will be an expensed of the with Raytheon G36 Mainten procedure. It new, 36-555048-3 and installed	on G36 ACSN: E-3660 Registration Due: 7/31/2023
Serviced aircraft battery and Installed new o'rings on Left Repaired broken attach on t	and Right fuel caps, Fluorosilkone	Kit #4.	ed satisfactory at this time.
Performed ground run opera Work performed in reference	ational checks, all checks normal at the to Raytheon G36 Maintenance M ACTT: 1043.2 I certify this aircraft	t this time. No leaks noted. Nanuals.	e with an annual inspection and AP 2730963 IA

Ai	Aircraft Model 636 Donaver Serial Number 3-3664						
Re	Reg #_ N GIOTC Owner's Name						
Y	ТАС			IME DURS	ENTRIES MAY BE ON MULTIPLE LINES IF REQUIRED	INSPECTOR'S SIGNATURE	LICENSE NUMBER
22			1183	,٦	This aircraft has been is spected	GIGIWITOTE	
					and found fate for the		
					intended Hight in accordance		
					with Special Flight Permit dated		
					28/Apr. 122	2099	CR3 041R387K
	1 5				Company Aminetican Commission In		
					Gemco Aviation Services Ii 10800 Sharrott Rd	ic.	
					North Lima, OH 44452 330-549-0337		
_		1610		7 (0.000	Make: Beechcraft Model: G36 Meter: 1184.1 ATT: 1184.		E-3660
	Pe	erfor	med a	7/2022 n Annual I	nspection using the Beechcraft A36 Inspection Form As a	guide. Lubricated per lub	e chart. ADs
_	ch	iecke	d thro	ugh ATP	biweekly 2022-9. Preformed several landing gear extension	ns and retractions to inclu	de and
L	emergency extension with no defects noted. C/W AD76-07-12R1, by function check of ignition switch with no defects noted at this time. Next due 1284.1 hrs.						
				08-08 and due 1584.	400-hour TAT tail pipe "V" band clamp replacement by in hours.	nstallation of new clamp	P/N N4211-
Г	C	/W A	D 202	21-23-12,	dated 12/09/2021 and found AD N/A because the aircraft in aft is not a commuter / commercial aircraft.	s not equipped with a radi	io / radar
_	C	/W A	AD 202	22-03-15.	dated 3/21/2022 and found AD is N/A because the affected	l Garmin equipment is no	t installed in
_	this aircraft and is not integrated to the aircraft fuel quantity indicating system. C/W 500-hour L/H and R/H engine magneto inspections, see engine log for details.						
	C/W 500-hour alternator bearing and brush inspection see below for details.						
	C/W annual battery #1 CAP test, by installing new Concord battery RG24-16, S/N 41223899, OCV 26.4 VDC. C/W battery #2 CAP test, passed 85%, top charged and reconnected.						
-	C/W annual ELT inspection per FAR 91.207(d), see below for repair details. Next battery replacement due 3/2025.						
	C/W annual gust lock inspection, per SB 27-3459, with no defects noted. C/W 1yr fire extinguisher inspection and weight check, with no defects noted and weight 4 LBS 14 OZ reinstalled in						
	aircraft. C/W B&C Stand by alternator ICA, with no defects noted.						
-	C/W Rosin Sun Visor ICA, adjusted tension on pilot's visor and no further defects noted.						
	C/W G&D tinted window inserts ICA, with no defects noted. C/W 1 Year Mid Continent 4300 series stand by instrument ICA 9015762 Rev. J and SC #116, see below for						
	repair details						
	C/W 1 Year Mountain high oxygen system ICA 35-6460001 Rev N/C, 6/22/2010, see below for repair						
details. C/W Door Steward Cockpit door stay ICA, no defects noted.							
	1		-				-

Gemco Aviation Services Inc.

10800 Sharrott Rd North Lima, OH 44452 330-549-0337

 N610TC
 Make: Beechcraft
 Model: G36
 S/N: E-3660

 Date: 06/17/2022
 Meter: 1184.1
 ATT: 1184.1
 PG2 of 5

C/W 1 Year Tornado Alley ICA per manual P/N 35-6460001 Rev. A dated 09/29/2011, see below for repair details.

C/W 3-year crossover heat exchanger pressure check with no leaks noted. Next due 6/30/2025.

C/W 3-year fuel cell flapper valve inspection with no defects noted.

C/W 3-year stand by attitude indicator battery replacement, see below for details. Next replacement due 5/31/2025.

C/W 10-year Tornado Alley flammable fluid carrying hose replacement by installation of new TAT hose kit P/N Hose kit -10 year replacement -kit-G36 and leak checking after engine test runs, with no leaks noted.

C/W 15-year oxygen bottle replacement, see below for details. 15-year replacement due in 4/30/2037

C/W 15-year oxygen remote control regulating and shut off valve overhaul, see below for details.

C/W SC 313 R1 by inspection of flap nose rib, with no defects noted.

C/W SC322 control cable inspection, with no defects noted.

ATA 21: Removed broken air conditioning belt guard P/N 36-555048-3. Removed worn air conditioning compressor belt P/N 646293-34.00. Extended air conditioning condenser, cleaned using solvent and dried with compressed air. Evacuated system of 1.3 LBS R134A refrigerant and 1 oz of refrigerant oil. Removed air conditioning compressor and sent to Skyline accessories of overhaul. Removed and replaced evaporator filter P/N 35-534470-19. Installed overhauled compressor P/N 36-555003-9, S/N 84S, see Skyline Accessories LLC 8130-3 tracking # 021124 / W/O# 17534, 6/13/2022, replaced receiver dryer P/N 90-384019-3 and preformed a system leak test with no leaks noted. Installed the following new components; belt P/N 646293-34.00, and belt guard P/N 36-555048-3. Tensioned belt and serviced system with 2.4 LBS R134A refrigerant and 8 OZ RL100E refrigerant oil and preformed a leak and operational check with no defects noted at this time.

ATA 24: Removed battery P/N RG24-16 and installing new Concord battery RG24-16, S/N 41223899, OCV 26.4 VDC Removed and replaced battery box drain tube. Removed alternator P/N 649304, S/N 005GA420 and sent out for 500-hour inspection. Inspected drive coupling and coupling failed torque check at 92-inch lbs. Installed overhauled drive coupling P/N 646655, S/N 962DH, see Skyline Accessories LLC, 8130-3 tracking # 020232 / W/O# R56213, dated

Gemco Aviation Services Inc.

10800 Sharrott Rd North Lima, OH 44452 330-549-0337

 N610TC
 Make: Beechcraft
 Model: G36
 S/N: E-3660

 Date: 06/17/2022
 Meter: 1184.1
 ATT: 1184.1
 PG30FF

2/22/2022 for details. Cleaned alternator mounting surface and reinstalled same alternator, see Aerotech of Louisville Inc. W/O# 149265, dated 5/25/2022 for details using new gasket.

ATA 25: Removed dead ELT battery and installed new battery P/N 452-0130, S/N 394287. Tested per FAR 91.027 (d), with no defects noted. Unbolted copilot's shoulder harness, untwisted belt and torqued attaching hardware. Adjusted and tightened glove box latch and strike plate hardware. Reattached copilots spar cover pocket using new hardware.

ATA 27: Troubleshoot flaps will not move to the approach position when selected from full up. Ohm out wiring and switches with no defects noted further investigation found approach switched way out of rigg. Adjusted approach switches per AMM 27-50-00-201. Removed and replaced L/H and R/H elevator trim tab hardware and verified trim tab free play is within limits. Checked operation and travels with no defects noted.

ATA 28: Removed R/H wing fuel vent check valve, cleaned, tested and reinstalled with no defects noted. Defuled aircraft and removed access panels to gain access to fuel sump area. Removed factory installed fuel drains and installed new Storehouse LLC fuel drain valve kit P/N 720B per installation instructions 720B rev. O. Installed access panel using new gaskets, torqued saftied. Removed fuel cap assemblies, disassembled, cleaned, inspected, lubricated reassembled and adjusted fuel cap tension and reinstalled fuel cap assemblies in their respective positions. Preformed the fuel quantity calibration procedures for L/H and R/H fuel quantity sending units per G1000 maintenance manual supplement 22-14-07-501 Rev. B2 table 501 and leak checked access panels and fuel drains with no leaks noted.

ATA 30: Removed propeller brush block assemblies, disassembled, cleaned, inspected and reassembled using brush kit RAPCO P/N RA1543-7, reinstalled on aircraft and set lead in angle. Preformed an operational and function check with no defects noted.

ATA 32: Torqued L/H MLG FWD pivot bolt and cotter pinned. Torqued L/H MLG drag brace to strut attachment bolt and cotter pinned. Torqued L/H MLG inner gear door retract rod end bolt on door and cotter pinned. Torqued L/H and R/H MLG inner door retract rod end attachment hardware at actuator and cotter pinned. Secured R/H MLG up lock cable Tygon tubing. Loosened NLG centering roller attachment hardware, cleaned, lubricated, tighten attachment hardware and cotter pinned. Torqued NLG drag brace to strut attachment bolt and cotter pinned. Torqued NLG drag brace to keel box attachment hardware. Torqued NLG forward retract rod end attachment bolt and cotter pinned. Torqued NLG retract rod bracket attachment bolts. Removed and replaced R/H wheel inner grease seal and L/H wheel outer grease seal with seal P/N 154-03000 Removed and replaced exposed brake hoses using 2 each of the following hoses P/N MS28741-4-0150 &

Gemco Aviation Services Inc.

10800 Sharrott Rd North Lima, OH 44452 330-549-0337

N610TC	Make: Beechcraft	Model: G36	S/N: E-3660
Date: 06/17/2022	Meter: 1184.1	ATT: 1184.1	P640F5
MS28741-4-0160, flu	ushed system and bleed brakes. Servic	ed reservoir with Aeroshell 41	

parking brake cable behind instrument panel, adjusted and tested with no defects noted. Remove shimmy damper, disassembled, cleaned, inspected, reassembled with new "O" rings, serviced and reinstalled. Adjusted both uplock cable tensions. Adjusted up sector gear clearance to 5/8 turn. Preformed several landing gear extensions and retraction to include an emergency extension with no defects noted.

ATA 33: Removed and replaced burned out tail nav light bulb P/N 34-0428070-64 and opps checked with no defect noted.

ATA 34: Removed and replaced discharged stand by attitude indicator battery P/N 9015607, S/N M14—10084 and installed new battery P/N 9015607, S/N E22-12407, DOM 5/2022 tested and verified operation with no defects noted. Serviced compass with compass fluid and check cardinal headings with no discrepancies noted.

ATA 35: Removed oxygen bottle P/N 1270152-4, S/N ALT 282-16473, DOM 4/2006 and installed new oxygen bottle P/N 1270152-4, S/N ALT 282-47456, DOM 4/2022. Removed RCV/RCR and sent out for overhaul. Installed overhauled RCV/RCR, S/N 2106-01see Mountain High Equipment Green tag, W/O# RR05980, 6/09/2022 for details. Purged system and serviced to 1850 PSI ABO and preformed a leak and operational check with no defects noted.

ATA 52: Adjusted upper cabin door latch to provide door with better contact to seal and eliminate leaking. Removed loose front utility door seal, cleaned structure and seal. Reinstalled seal using 3M 1300 adhesive. Secured glare shield using new hardware.

ATA 72: Tightened #2 cylinder oil separator fitting and leak checked during engine runs with no leaks noted. Installed missing oil drain patch plug P/N 132641-5G.

ATA 76: Torqued throttle cable rod end attachment hardware to throttle arm and saftied. Disconnected propel control cable rod end to governor arm and swapped propeller control cable to opposite side of mounting bracket to prevent cable from chafing on engine mount bracket. Replaced worn propeller governor control rod end by installing new rod end P/N 131765-1F and secured to arm with new hardware, tightened and saftied. Tighten loose R/H cowl flap hardware and cotter pinned. Adjusted L/H cowl flap to prevent fouling on tail pipe.

ATA 77: Troubleshoot ITT fluctuates when PTT switch is depressed and found com radio RF to be interfering with indicator. Wrapped indicator in lead tape to prevent interference.

Gemco Aviation Services Inc.

10800 Sharrott Rd North Lima, OH 44452 330-549-0337

N610TC	Make: Beechcraft	Model: G36	S/N: E-3660
Date: 06/17/2022	Meter: 1184.1	ATT: 1184.1	PG50F5

ATA 78: Gained access and removed cracked waste gate manifold assembly and installed new TAT waste gate manifold assembly P/N ETI-B-108 using gasket kit WGKB. Reinstalled repaired and pressure checked cross over heat exchanger. Reinstalled removed component and leak checked ion engine test run. Retorqued tail pipe "V" band clamp to 40 inch LBS after engine runs.

Christopher T. Kotch A&P173580771

I certify that this aircraft has been inspected in accordance with an annual inspection and was determined to be in airworthy condition.

Robert L. Grant A&P3719335IA



Alpha One Flight Services 246 South Meadow RD Plymouth, MA 02360

SERVICES

Date: 7/08/2022; Aircraft: N610TC; Type: BEECHCRAFT BONANZA; S/N: E3660; Hobbs: 1194.00; Tach: Removed and replaced the right tire with new Michelin p/n 070-313-0 and new tube p/n GL-7020B. Replaced internals of left fuel drain valve to correct oriantation. Aircraft was test run, no leaks noted, ops. check good. All work performed IAW current Federal Aviation Regulations and was found to be in an air worthy condition and returned to service.

Mitchell Buckley A+P 28302441.A.

20

Ai

R

Date: 8/01/2023; Aircraft: N610TC; Type: G36 Bonanza; S/N: E3660; Hobbs: 1338.00; Total Time: 1338.00; Engine -Type: IO-550-B39B, S/N: 687094, SMOH: 1338.00; Prop - Type: PHC-C3YF-1RF, S/N: EE5550B, SMOH: 153.90 Performed an annual inspection IAW FAR43.13 appendix D in reference to Beechcraft Service Manual. ADs checked through 2023-17. ELT tested good, battery due MAR2025. Complied with AD 76-07-12, Ignition switch inspection, next due TT 1438.00. Complied with service bulletin 27-3459 gust lock inspection. Inspected fire extinguisher per annual fire extinguisher inspection, next due AUG2024. Inspected B&C standby alternator per ICA, next due AUG2024. Removed left exhaust and sent out for repair. Reinstalled upon return with 3 new exhaust gaskets P/N 65258, and 1 new exhaust manifold gasket P/N 642502. Removed right exhaust and inspected. Returned exhaust after inspection with 3 new exhaust gaskets P/N 65258, and 1 new exhaust manifold gasket P/N 642502. Replaced left tire with new P/N 070-313-0 and tube P/N GL-7020B. Replaced gear box drive motor with new P/N 58-380090-1, and gear up switch P/N BZ-R31. Rigged gear per MM. Inspected air conditioning system and checked pulley alignment. Installed new belt P/N 646293-34-00 and tensioned per MM. Installed new fan motor P/N 36-380027-35. Fabricated sheet metal patches for cylinder 1 and 4 baffling. Repositioned and secured engine hoses to avoid chafe points. Rebuilt left and right brake callipers with 2 new O rings per side, P/N MS28775-222. Rebuilt pilot side right brake master cylinder with new kit P/N m-03-1001-1 IAW STC SA04634NY, see form 337 this date. Bled brake system. Blended wear point on left cowl flap. Adjusted cowl flap rods and safetied. Removed and replaced 7 loose cherry rivets on upper cowling heat shelld, P/N CR3213-4-2. Replaced all steel hardware on wings with new stainless steel hardware. Aircraft was test run, no leaks noted, ops. check good. All work performed IAW current Federal Aviation Regulations and was found to be in an airworthy condition and returned to service.

> Stephanie Mickiewicz A&P 4332728 I.A.



Alpha One Flight Services 246 South Meadow Rd Plymouth, MA 02360

SERVICES

Date: 10/07/2024; Aircraft: N610TC; Type: G36 Bonanza; S/N: E3660; Hobbs: 1389.10; Total Time: 1389.10; Engine Type: IO-550-B39B, S/N: 687094, SMOH: 1389.10; Prop - Type: PHC-C3YF-1RF, S/N: EE5550B, SMOH: 205.00 Performed an annual inspection IAW FAR43.13 appendix D in reference to Beechcraft Service Manual. ADs checked through 2024-21. ELT tested good, removed and replaced battery with new p/n 452-0130, battery due JUL2027. Complied with AD 76-07-12, Ignition switch inspection, next due HOB 1,489.1 Complied with service bulletin 27-3459 gust lock inspection. Inspected fire extinguisher per annual fire extinguisher inspection, next due OCT2025. Inspected B&C standby alternator per ICA, next due OCT2025. Preformed 3 year fuel cell flapper valve test, no defects noted; next due 10/2027. Preformed SC 322 flight control cable system inspection, no defects noted. Removed and replaced tail light bulb with new p/n 34-0428070-64. Removed and replaced corroded battery terminal end with new p/n 321275. Removed and replaced right brake pads with new p/n 066-10500. Removed and replaced shimmy dampener and bolt with new lord p/n SE1076-1 shimmy and bolt p/n 13090B293. Removed and replaced right main tire tube with new p/n GL-7020B. Installed three brake master seal kits p/n M-03-1001-1 from Marsh Brothers Aviation under STC SAO4634NY see STC on 10/07/2024. Aircraft was test run, no leaks noted, ops. check good. All work performed IAW current Federal Aviation Regulations and was found to be in an airworthy condition and returned to service.

> Travis Hyldburg A&P 4139360 I.A.



Alpha One Flight Services 246 South Meadow Rd Plymouth, MA 02360

SERVICES

Date: 6/20/2025; Aircraft: N610TC; Type: G36 Bonanza; S/N: E3660; Hobbs: 1433.50; Total Time: 1433.50; Engine - Type: IO-550-B39B, S/N: 687094, SMOH: 1433.50; Prop - Type: PHC-C3YF-1RF, S/N: EE5550B, SMOH: 249.40 Changed nose gear tow pin with newP/N-60-820029-1. Replaced the landing gear in-transit light bulb, P/N-GE327. Inspected AC drive belt, determined okay for continued service. Aircraft was test run, no leaks noted, ops. check good. All work performed IAW current Federal Aviation Regulations and was found to be in an airworthy condition and returned to service.

> Edward Brown A&P 3534614 LA