


The Standard


A IRCRAFT LOG

Aircraft Record General Informa	ation		
Manufacturer PPHU A	A AAC A		TOPAZ-LSA
Serial 30 - 10 - 0 Date of Manufacture 05 - 23		stration Number	NZIZKIZ
Engine(s) currently installed: Manufacturer	Model 912	0152-01	Serial <i>9570560</i>
Manufacturer			
Propeller(s) currently installed: Manufacturer ASPESZKE	·/A Mode	B-LINE AS	6 1700 - 1950 - A - 3 F
HUB Model	_	117	Serial
Blade Model	Serial <u>284</u> [Serial 284	12 Serial 2843
Blade Model	Serial	Serial	Serial

TIME	FLIGHT	TIME IN SERVICE	Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
19		.5	AIRWORTHINESS INSPECTION
-			FOR SISA ASEL.
		- 63	4017450
		1	
			! find that the aircraft meets the requirements for the
- 12			certification requested and have issued a special
3, 11, 3	86"		airworthmees certificate. Date: 07/10/2019
-37	4		James M. Leon
			CHI-FSDO / 401745054
	TIME IG	TIME 19	TIME SERVICE

YEAR 20 9 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
19	2.5		2,5	Periodical Inspection Schedule (2h)
				Perform inspection /chede 1,2,3,4,5,6,7,8,12
29			5.5	Periodical Inspection should (5h)
				Perform Tropefor (check 1.2.3, 4, 5, 6.7.8.12
				and the state of the
				KRZYSACT SWBIT SAMMENT OF SINDS
				5100-5135-8159 Lalllettel 181116/
117	25		25	The checks performed of the 25hrs
				inspection are the some as for the
				Whis Inspection, I carryly that this engine
				has been inspected on 09/17/2019 in accordance
	with A	he m	onalo	Lever and misection personing I solo upartion





YEAR 20 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)

July 1, 2020 N71748M Ekolot Topaz KR-030 sn 30-10-01. Rotax Engine sn 9.570.560 with 92.9 Hours Tach and Total time. Annual Condition Inspection in accordance with Light Sport Category Airplane Operating Limitations for PPHU Ekolot KR-030 Topaz N717SP dated July 2015, paragraph 14. Part 43 appendix D as well as the checklist located in the KR-030 Topaz Handling, Maintenance and Inspection Manual serial # 30-10-01 sections 4,5 & 6. And per the Rotax Maintenance Manual 912 series edition 4 rev, Maintenance Schedule 05-20-00 page #9-15 scheduled maintenance 100 hours and checks. Routine maintenance and Lubrication Performed. The oil was changed using Aero Shell Sport Plus 4sae 10W40A new oil filter was installed also. Rotax 825016 for Rotax 912/914/915 Engine Series. The ELT was inspected per 91-207d1-4 and found to be airworthy. ELT an ACK Technologies INC, battery expires Feb-21-2022. I certify that this aircraft and engine has been inspected on July 1st, 2020 in accordance with the manufactures maintenance and inspection procedures and was found to be in a condition for safe 7/01/2020 Dwain adkins A = P 1932696 1A operation.

	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
103	93.0	1.6	94,6	Test flying after oil and foller
				Change - checked for - lasks
				existion not discovery
				ADMINITED IN SMIFF 31005/358/59
ĺ				
i				
e.a	3			فعند دع

DeKalb Avionics LLC.

Aircfraft logbook entry

WO# 2020-021AV nician or S/N: 30-10-01 Date: 9/28/2020 Aircraft TC: N/A Hobbs: N/A

N717KM

Installed SkyFy-EXT GPS antenna on top fuselage

121.0

Aircraft:

Aircraft TT:

5 The installed ADS-B system was shown to meet the equipment performance requirements of TSO C154c & is complient

6 The echoUAT with the SkyFy-EXT GPS antenna is power with a 3 Amp circuit breaker & a ON/OFF switch

Installed uAvionix echoUAT ADS-B Transceiver below glove compartment s/n 100010148

Installation was carried out as per Installation manual UAV-1001(06-001 ECCN7A994

Function test carried out with Sun Avionics AV17 Ramp test set

Installed UAT antenna AFT of right hand baggage compartment

8 The installation was performed in accordance with 14CFR Part 43 acceptable methods

with FAR 91 225 & FAR 91,227

Equipment list updated

10 Weight & Balance change is negligible.

11 This aircraft, aircraft engine, or appliance identified above was inspected IAW current regulations of the FAA and is

approved for return to service. Pertinent details on mean principal business office Wilhelmis J Pieterse Signature:___

License number: A & P 3651352JA

PER RECO TACH TIME	н 1	TODAY'S FLIGHT		Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)	2021 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
01/3,0 147	17,0	0.3	147,3	Beringer Aero Warranty replacement land broke master astinder with metherical parking broke pin HABBZ fasting brokes for 20 minutes, checked for leaks what not discover. S10051358159 Keynter M saulo	02/25	1492	0,5	149,7	Changing Oil The Oil on the ourceoft was change for Aeroschell plus 4 kolex 912, 914 The Oil on the ourceoft was change for Aeroschell plus 4 kolex 912, 914 The Oil on the ourceoft was change for Aeroschell plus 4 kolex 48250 Checked for leads not discover, filter check for foreign object not found by freguest sicilor Stoo 51358159 flatality a suit

YEAR 202/ DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician Repair Facility. (See back pages for other specific entries.)	or
4/21	183,C			Menging Oll	-
April The c wear Aero	29, 2021 N7	17KM Ta ed, oil tai Installed AE 10W4	ch 183.1 C nk was cleanew oil fil 40 Oil. The	Rd, DeKalb, II 60115 Dil Change aned and inspected. The oil filter was removed and inspected, no abnormater Rotax Engine Type 912/914 part no825010.Installed 3new liters of engine ran and was checked for leaks; non found.	

YEAR 2021 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
offorfer	197.7			Annuel Condition Inspection

July 1, 2021 N717KM Ekolot Topaz KR-030 sn 30-10-01. Rotax Engine sn 9.570.560 with 197.7 Hours Tach and Total time. Annual Condition Inspection in accordance with Light Sport Category Airplane Operating Limitations for PPHU Ekolot KR-030 Topaz N717KM dated July 2016-12-06, checklist located in the KR-030 Topaz Handling, Maintenance and Inspection Manual serial # 30-10-01 sections 8, And per the Rotax Maintenance Manual 912 series edition 4 rev. Maintenance Schedule 05-20-00 page #7-16 scheduled maintenance 200 hours and checks. Routine maintenance and Lubrication Performed. The oil was changed using Aero Shell Sport Plus 4sae 10W40A new oil filter was installed also. Rotax 825016 for Rotax 912/914/915 Engine Series at the 183.0 Tach TTAF. The ELT was inspected per 91-207d1-4 and found to be airworthy. ELT an ACK Technologies INC, battery expires Feb-21-2022. I certify that this aircraft and engine has been inspected on July 1st, 2021 in accordance with the manufactures maintenance and inspection procedures and was found to be in a condition for safe operation.

Dwain Adkins A&P 1932696 1A Way (1)

wain adhines 07/01/202

PEAR 2027 DATE	RECORDING TACH TIME 229	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
The abr	e oil was dra normai wea w liters of A	ained, o or was fo aeroshel new safe	il tank wa ound. Insta I Plus 4SA ty wire pe	as cleaned and inspected. The oil filter was removed and inspected, no alled new oil filter Rotex Engine Type 912/914 part #825016. Installed 3 as 10W40 Oil. The engine ran was checked for Leaks-non found. Secure are manufacturing recommendation.
	A			
		P		

RECORDING

TODAY'S TOTAL FLIGHT

TIME IN SERVICE Description of Inspections, Tests, Repairs and Alterations

Entries must be endorsed with Name, Rating and Certificate Number of Technician or Renair Facility. (See back names for other specific entries)

Annual Condition Inspection

August 21, 2022 N717KM Ekolot Topaz KR-030 sn 30-10-01. Rotax Engine sn 9.570.560 with 229 Hours Tach and Total time. Annual Condition Inspection in accordance with Light Sport Category Airplane Operating Limitations for PPHU Ekolot KR-030 Topaz N717KM dated July 2016-12-06, checklist located in the KR-030 Topaz Handling, Maintenance and Inspection Manual serial #30-10-01 sections 8, And per the Rotax Maintenance Manual 912 series edition 4 rev, Maintenance Schedule 05-20-00 page #7-16 scheduled maintenance 200 hours and checks. Replaced Rotax Spark Plugs 297656, routine maintenance and Lubrication Performed. The oil was changed using Aero Shell Sport Plus 4sae 10W40A new oil filter was installed also. Rotax 825016 for Rotax 912/914/915 Engine Series at the 183.0 Tach TTAF. The ELT was inspected per 91-207d1-4 and found to be airworthy. NEW- ELT an ACK Technologies INC, battery expires June 29 2027. I certify that this aircraft and engine has been inspected on August 21st, 2022 in accordance with the manufactures maintenance and inspection procedures and was found to be in a condition for safe operation.

Dwain Adkins A&P 1932696 1A

YEAR 2022 DATE OF	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
10-18	2465			Install two new tives size 400-6 6-Ply
				Hero Clay (DTR 1280/400-66-Pix) ound new
-	0			wheel o-ving 6" (J-JTR-007N)
12-04	271.1			Halloulf M Sully 1 - 3-100-5135-8159

December 04,2022 N717KM Tech 277 OIL CHANGE

The oil was drained, oil magnetic screw cleaned and inspected. The oil filter was removed and inspected, no abnormal wear was found. Installed new oil filter Rotex Engine Type 912/914 part #825016. Installed 3 new liters of Aeroshell Plus 4SAE 10W40 Oil. The engine ran was checked for Leaks-non found.

Krzysztof Siuba S-100-5135-8159

SERVICED BRAKE RESERVOIR & CLEANED FLUTT FROM UNDER RESSURE LIMITER. NO LEAKS OF FAULTS & THIS TIME & GOD TAKOB KNITATKOKT ALP 39/7697 02/04/2023 321.9 Tach Time Replaced pressure limiter with Beringer Ultralight Pressure Limiter 25 bar, part #LM-002E(A). Jakob Kwiatkoski A&P 39/7697	YEAR 20 23 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
FROM UNDER RESSURE LIMITER. NO LEARS OF FAULTS & THE LEOD TAKOB KNEATKOKE AND 39/7697 02/04/2023 321.9 Tach Time Replaced pressure limiter with Beringer Ultralight Pressure Limiter 25 bar, part #LM-002E(A).	35AN	305.5			SERVICED BRAKE RESERVOIR & CLEANED HUTT
TAKOB KWIATKOKE BY 39/7697 02/04/2023 321.9 Tach Time Replaced pressure limiter with Beringer Ultralight Pressure Limiter 25 bar, part #LM-002E(A).					
02/04/2023 321.9 Tach Time Replaced pressure limiter with Beringer Ultralight Pressure Limiter 25 bar, part #LM-002E(A).					
Replaced pressure limiter with Beringer Ultralight Pressure Limiter 25 bar, part #LM-002E(A).					JAKOB KNIATKOKI AND 3917697
Replaced pressure limiter with Beringer Ultralight Pressure Limiter 25 bar, part #LM-002E(A).					
		02/04	_ /2023 3	21.9 Tach	Time
lakob_Kwiatkoski A&P 3917697		Repla	ced pres	ssure limit	er with Beringer Ultralight Pressure Limiter 25 bar, part #LM-002E(A).
		Jakob	Kwiatko	oski A&P	3917697

ZZ ZZ	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
-		1 2		
Oil C	hange			The second F70 F60 with 324 Hours
Tach was i	- nd Total 1	Time. Th so. Rota	ne oil was x 825016	ot Topaz KR-030 sn 30-10-01. Rotax Engine sn 9.570.560 with 324 Hours changed using Aero Shell Sport Plus 4sae 10W40A new oil filter for Rotax 912/914/915 Engine Series.

17 23 E	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Leuries must be eu	nspections, Tests, F dorsed with Name, Rati back pages for other s	Repairs and Alterations ng and Certificate Number of Technician or
15				is Rd., Ste. 104 + La		pecinc entries.)
	The	e transpon with the rec	ation are on der # 2 }	has been inspected and FAR 91.413. Pertine file at this repair station of the factor o	nt details of the nunder the	
		Gardner 649R038Y	(A	outhorized Signature) 214-886-5894		

AR RECORDING	TODAY'S	I I I I I I I I I I I I I I I I I I I	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Entries must be endorsed for other specific entries.)	YEAR 20_23 DATE	RECORDING TACH TIME	TODAY'S FLIGHT		Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
TIME	TACH TIME	SERVICE	Entries must be endorsed with Name, Training,	3501	472,3		(#)	Replaced factory physicaglass fact Louis with
		~ ~~~	h and Total Time OIL CHANGE outic screw was inspected and cleaned. Grounding wire was attached.					feelong SS replacements, Leole check Good, I Cert.
u droir	and The	e ou magi	letic solow was market and new oil filter. Rotax					this ACFT pit for return to service this date. All
ne oil filter was	remove	d and ins	netic screw was inspected and cleaned. Grounding with high pected, with no abnormal wear found. Installed new oil filter, Rotax 15 engine series. Installed 3 liters of AeroShell Sport Plus 4SAE 10W40A.					work performed IAW Khoso Topez maint. Mon.
art #825016 fo	r Rotax 9	912/914/9	15 engine series. Installed 5 literatives					E AC 43.13. Dilecch 122
he engine was	ran and	CHECKER	15 Tole					Apit 3954176.
Bob S. Lin, Priv	ate Pilo	t License	#4727096					
				07/14	/2023 N71	7KM Ta	ach and To	otal Time: 472.3 REPLACEMENT OF SEAT BOTTOM
			d Total Time: 472.3 INSTALLATION OF LANDING LIGHT	. Repla	aced both le	eft side a	and right s	ide seat bottoms. The leather and polyurethane foam materials underwe
	11 11	L	stalled taxi/landing light and installed a Thiesen Electronics GmbH Irdance with ASTM F2483. Made sure the electrical connection was Jight to ensure adequate function. The landing light functions properly.	- vertic	al flammab 3. Lin Priva	uity tests	s and pas	sed in accordance with 14 CFR Part 25 - Subpart D, 25.853.

properly secured and tested the light to ensure adequate function. The landing light functions properly. Distance #4727096

RECORD TACH TIME	NG TODAY FLIGHT		20 <u>23</u> DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TIME IN	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Contilinated
aug .		Memored [Replaced main which SN: 16163, SN: 16163 Enstelled, R/A Brake-Linings (Dista IAW Topaz pulon. D. Level Della April 3954176	9/15	ACFT TT: Performe part 43. (Open. No K&N elem ELT system 91.207 (F)	571 g ed Annual Compressi abnormal Pents from "INOP"	inspection ons as follo debris four ROTAX. A and remove not to except to return	Entries must be endorsed with Name, Rating and Certificate Number of Technician Repair Facility. (See back pages for other specific entries.) Illas Aero-Mech LLC Saeromech@gmail.com 682-459-7635 Obbs: ENG TT: PER Ekolot Topaz KR30 MM & appendix D Ows: 78, 77,78,76. Oil/ filter changed and cut and. Changed two engine air filters with New AD's checked; none published as of 21SEP23. The ded for Repair on 22SEP2023 (AW FAR part and to service. Elliot Davis Elliot Davis Elliot Davis

YEAR	RECORDING	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Entries must be endorsed for other specific entries.)	YEAR 20 LH DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
YEAR 20 23 DATE	TACH TIME		SERVICE	Repair Facility. (See back pages to other specific ANAMADER & S	3001	842.6			Oil change performed heplaced oil filter wholey px.
120ct	631.2		631.2	Repair Facility. (See back pages to the New North DCPR & E. Arplaced & Spark plus w/ New North DCPR & E. Changed oil & Filter, Serviced w/ Arm Stell Sport plus Changed oil & Filter, Serviced w/ Arm Stell Sport plus	-				82501 Serviced of Acroshell sport + 45AE 10440A
, -				changed oil & Filter, Service of Att stead of the State o	HT	L La			old Filter Cut open (Inspected. No abnormalities found.
				4 & holey \$150 16. 149.					Longine han (Least chaked : No Leaks Shown from all thouse .
				D-Lord Lesses					8 sperbplus replaced wi Same pertonouser. old pluss inen.
				April 3954176 Reported & Accordance Elt I Av Ekolot agus Dictory Corsa	130				no issues. Mas drop performed. NO issues. ACFT is approve
12 och	631.2		54.2	byone! & heinstalled Eli Int Entity and Colod					For return to Service for work performed. D. Level illes
12				APE 354176					Apt 3954176 2024
2.3					·				
-									
				/					

		FLICHT	TOTAL TIME IN	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Entries must be endorsed for other specific entries.)	YEAR 20 24 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
<u> </u>	TACH TIME	-	SEMAICE	Papair Facility. (See back pages for other specime	5/16	1081.3	/	1081.3	Gil Change & spark plug replacment Completed I AN
	8525			Enstalled Konordia Auto pilot actuators IAW Konordia & EKolot Ingraetions. All ground test performed			41		Potes & Ekolot Sm & AC-13.13, I certify this MEFT is
			1	The state of the s		(chart ar-		- 0.5	cleared to return to Service at this time wiregard to the
				I have been too s					work performed. Ill
			1	cheek Plight & post Plight Completed. ACFT returned to	5/16	1081.3	/	1081.3	Tire change, brake pad Change & wheel Bearing inspect
	853.5					200			Completed. 3 New Tires Installed, Book Left & Might hair
				I Spech at Every annual. Ollar 5 Fester 4					Cover brake pads replaced I Aw Ekolot Sm. I centily
				SHOW AT COC.	-	-			this Acet is deared to return to Service for work per
-		-							Formed on this Day AST 10 Spring Chough
+					-				AP# 395417C

EAR	TACH	FLIGHT		Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)	YEAR 2024 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
ATE	TIME			Repair Facility. (See back pages in the second Alfaeld See And, Account	9/3	1466		1466,0	Performed oil change. Service I Aw Actas m/m. Leplace
Mas	286.0			Changed 8 sparkpluss of new Mark San: AN. Account Strylaced Eng. coolant hadiator, Preserviced whenew	4		-1		SSparkplus w/ New NGK, hunup and brak check ok.
				Coolant 1 has Acet to operating temp. 10 looks at		Total St	L of the X	r Same	Ald 13 Stplott
	*			Wis Time.					AP\$ 3954176
		1114			10/18			1516.5	Completed Annual INSP. EAN Eldot TOPOZ
	-	-	500	1 will an Golf from C/H pail bonk line 10		X 400 1	13	2 34	m/m. fault list given to owner this Date.
afey.	1256.0			hal thillies bull bush on					D Level 18 19 3954176
				Locales ATT. Fuel flow restored.	10/18			15165	Replaced Eng. Coolant hoses. Asplaced man tires
		-	1	LICCRS ATT. FOR THE APPENSENTS					Remounted arm rest. Replaced O-ring on steater
		-		8					retorged Elevator naut bots
			-						Dhalled
		100							AP\$\$\$3964176\$A

YEAR 20 2 M DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)								
11/8	1516,5		1516.5	reinstalled over handed cords. Institute repaired profesion and 2 new springs, han engine checked for Leaks, min.								
	P			Edle & Mas drop, All OK. Ad	susted AlH wheel pont							
13/25			es, 670 Ferris	Rd. Ste. 104, Lancaster, TX, 75146	8 Leach 1881 8 nov 21 April 30521176							
	The requireme	transponde ents of FAR	er system has b 91,413, Pertin	een tested and found to comply with the ent details of the certification are on file at this of the certification are on the certification.	72509 39/4							
-	Trans	ponder: _	90000	C-H S/N: 210 46517								
	Col	In										
	Paul Gar			orized Signature) 1-13-25 4-886-5894 (Date)								

_