AIRCRAFT TECHNICAL LOGS

Section 3. ENGINE

ENGINE LOG

1.	Make	THIELERT AIRCRAFT ENGINES GMBH
2.	Model	TAE 125-02-99
3.	Specification	E00069EN
4.	Manufacturer's Serial Number	62-02-02132
5.	Date of Manufacture	
6.	Aircraft Inspection Cycle	

_HOURS.

OTAL THIS PAGE	
TOTAL FROM REVIOUS SUMMARY	
TOTAL SINCE MFG.	

TIME RUN

MIN.

HRS.

8

5.

41.6

HRS.

DATE

BROUGHT

FORWARD

MAR 17 2008

Oct 82008

ENGINE SERVICE AND

DATE	TIME	ERUN	TIME SINCE OVERHAUL		INSTALLATIONS, INSPECTIONS,	
DATE	HRS.	MIN.	HRS.	MIN.	NOTE: USE BOTH PAGES AND AS MANY LINES AS REQUIRED FOR COMPLETE	N. W.
BROUGHT FORWARD		 ▶				1
4/19/09	45.5	FACY		dn	AD2008-12-23 BY REPLACEMENT OF CLUTCH ASSEMBLY	
					p/N 05-7211-KOB6002 5/N 20993 WORK WAS PERFORMED	
					I/A/W CENTERIAN RM-02-02 CHAPTER 72-10,02 J.K. AP3114823	
4/19/09	45.57	BCH			REMOVED + REPLACED PROPCONTROL VALUE	ļ
111101					P/N 05-7212-KOZ1401 S/N 250 T/A/W CENTURUN RM	
					02-02-72-10.04 JE: 1/2 AP3114823	
Make	45.5	TACH			Applaced fuel PAUL ADJECTION CONTROL WALLE	
4/19/01	45.5	IAGI			REPLACED FUEL RAIL PRESSURE CONTROL VALUE	
			-		P/N 05-7320-E000702 A/A/W CENTURION RM02-02	
W	-	-			73-10.08 MODIFIED VRAIL ALUG HAJW AMOZ-02	
710					39-40.00 J-12-AP3114823	
41909	45.5	TACH	-		REPLACED EXHAUST TURBO HEAT SHIELD with SERVICABLE	
		-	-		SHIELD JULY AP3114823	
-					ANNUAL INSPECTION ENTRY W/O#	4
					Date 5/1/09 Acft Id N127US SMOH	
					Hobbs Tach <u>45.5</u> TT <u>45.5</u>	
		Г.		•	I certify that this ENGINE has been inspected in accordance with An Annual inspection and was determined to be in an airworthy condition.	
					Insp. Sign. & Cert. No. 1-1/2 TA3114823	
-					Largio fulption	
					Complied W// handle Inspection	
					Date 6 / 30 /2010 NO TT //8/6	
					Eng. II John Jid	
•					Prop TT_118.6	
					Certificate No 270 5 92 4	
					WO# HA 630	
-					CARRIED FORWARD	
TOTAL THIS PAGE						A
TOTAL FROM PREVIOUS SUMMARY		-				
	1		1			ł

TOTAL

SINCE MFG.



14600 North Airport Drive • Scottsdale, AZ 85260 • (480) 948-2400 N127US Date: January 27, 2011 1 of 3 Model #Diamond DA42 S/N 42.AC127 TACH: 138.5 HOBBS: 138.5 TAE125-02-98 s/n 02-02-02132 RH ENGINE LOG ENTRY

Downloaded FADEC and emailed to John Weber.

Performed a lightning strike Inspection.

Removed the FADEC ASSY, p/n 05-7610-E000201 s/n 4140. Installed new FADEC unit p/n same s/n 4564.

Removed the engine harness (loom) p/n 05-7150-E000901 s/n 00493-2007, from the engine. Installed new harness p/n 05-7150-E000904-AT s/n 00314-2007.

Removed the starter p/n 05-8010-E002801. Installed the new starter p/n 05-8010-E002802

Removed the alternator p/n 05-7150-E000601 s/n 00578. Installed the new alternator p/n 05-7150-E000601-AT s/n C0471.

Removed the alternator regulator p/n 05-7150-E000701 s/n 10562 and wire harness p/n 52-7150-E000107. Installed the new alternator regulator p/n 05-7150-E000701-AT s/n 10406 and new wire harness p/n 52-7150-E000102 s/n 0439-2010.

MAXIMUM HOURS BETWEEN OVERHAULS



14600 North Airport Drive • Scottsdale, AZ 85260 • (480) 948-2400 RH N127US DA42 S/N 42.AC127 1/27/2011 2 of 3

Drained and flushed antifreeze from engine and serviced with Zerex G05.

Replaced 4 ea glow plugs p/n 05-3940-K001301. Removed glow plug control unit p/n 05-7151-E000401. Installed new control unit p/n 05-7150-E000401 s/n 5534.

Removed the following sensors:

2 ea camshaft sensors p/n 05-3940-K000101. T-Air Sensor p/n 05-7311-K000501 Rail pressure sensor p/n 05-7320-E000102 2 ea crankshaft sensors p/n NE-0000-0133101 Throttle potentiometer lead 1 p/n 05-7320-E000301 Throttle potentiometer lead 2 p/n 05-7520-E000201 Coolant temp sensor p/n 05-7522-K000301 Oil pressure sensor p/n 05-3940-K001201 Gearbox temp sensor p/n NE-0000-0000201 Oil temp sensor p/n NE-0000-0000201

Installed the following new sensors:

2 ea new camshaft sensors p/n 05-3940-K000101. T-Air Sensor p/n 05-7311-K000501 Rail pressure sensor p/n 05-7320-E000102 2 ea crankshaft sensors p/n NE-0000-0133101 Throttle potentiometer lead 1 p/n 05-7320-E000301 Throttle potentiometer lead 2 p/n 05-7520-E000201 Coolant temp sensor p/n 05-7522-K000301 Oil pressure sensor p/n 05-3940-K001201 Gearbox temp sensor p/n NE-0000-0000201 Oil temp sensor p/n NE-0000-0000201



14600 North Airport Drive • Scottsdale, AZ 85260 • (480) 948-2400 RH N127US DA42 S/N 42.AC127 1/27/2011

Removed the following electrical actuators:

Wastegate Control valve p/n 02-7240-05308R1 PDRV Assy. p/n 05-7212-E002801 Pressure regulator Assy. p/n 05-7320-E000702 4 ea Fuel injector p/n 05-3940-K001602

Installed the following electrical actuators:

Wastegate Control valve p/n 02-7240-05308R1 PDRV Assv. p/n 05-7212-E002801 Pressure regulator Assv. p/n 05-7320-E000702 4 ea Fuel injector p/n 05-3940-K003501 Installed fuel injectors with new cap screws p/n NM-0000-0106601. Fuel system bled prior to running engine.

Installed new non serialized parts:

Engine turbo heat shield p/n 52-7140-H000104 Intake tube bracket p/n 52-7310-H000902

I certify that the above stated maintenance was performed in accordance with the current FAR's and this aircraft is approved for return to service W.O. S29-10-02637

LANDMARK AVIATION

FAA CRS # LN3R663L

ENGINE SERVICE AND

	95		
TIME RUN	OVERHAUL	INSTALLATIONS, INSPECTIONS, NOTE: USE BOTH PAGES AND AS MANY LINES AS REQUIRED FOR COMPLETE	Ris .
HRS. MIN.	Alle		1
			_
2011			-
166.1	_		-
166.1		WITH A 100 HR INSPECTION AND	-
166.1		WAS DETERMINED TO BE IN	
		AIRWORTHY COXIDITION	
		AZONECHEZ AHP 3077586	
209.7		4 7 7 7	
		No filter Change (OIL) Acroshell	_
		Diesel 10W40 (Ggts (Liters))	_
		By Duner - Mac Graham.	
DMAR	3K	RH N127US DA42 S/N 42.AC127 3/1/2013 2 of 6	
A T (AD 2010-06-12R1 dated 2/3/2012. V rail plug and rail pressure	
dale, AZ 85260 • (480) 9	948-2400	control valve was previously complied with per Thielert SB TM	,
Date: March 1.	2013 1 01	TAE 125-1008P1 dated 10/22/2010, has been previously accomplished by accomplishment of RM-02-02 chapter 73-10-	
		08 and RM 02-02 chapter 39-40-08 on 4/16/2009, @ 45.5	
s/n 02-02-02132	ETT: 243.2	AFTT.	-
NGINE LOG EN	NTRY	AD 2011-05-06 dated 3/30/2011, timing chain 600 hour life	
6/12 month annua	al inspection per	limit, is not applicable by installed s/n's 02-02-02131 & 02-02-02-02132 are not affected.	
310-K002001 ren	lacement		
, ,		version 2.91 on both engines.	7
Oil filter replacem	ent box oil.		
1 50,000 405 40 5 600 11			
f the presetting of	the proportional	affected at this time.	
4/14/0040 0001	ronlacement and	AD 2012-02-05 dated 3/2/2012, friction disk replacement, and	
nce with the follow	ving bulletins:	THERET SD TH TAL 123-10131 T dated of 10/2011, medicin acc.	_
1007P3 REV. 3. 0	jated 10/17/2011	,	
valve p/n 05-7212	E002801 on bot	AD 2012-20-12 dated 2/15/2015, AD is not applicable by the	
alled.		number.	
s were changed a	45.5 ACTT. The		
led at approximat	ely 45.5 ACTT. I	AD 2012-26-13 dated 2/13/2013, AD complied with by	
	DMAF ATIC dale, AZ 85260 · (480) Date: March 1, ond DA42 S/N 43.2 HOBBS: 3/N S/N 02-02-02132 S/NGINE LOG EN 6/12 month annual 310-K002001, repartites of 7990 gear f the presetting of 4/11/2012, PPRV nce with the follow 1007P3 REV. 3, valve p/n 05-7212 n's. There is no recalled at approximate severe changed a led at approximate	HRS. MIN. HRS. MIN. 2011 166.1 166	TIME RUN HRS. MIN. HRS. MIN. HRS. MIN. HRS. MIN. CONTROL CONT

updating the FADEC software to mapping version 028V301D.

SB TM TAE 125-1009P1 REV. 4 dated 10/22/2010, CSU vibration isolator. Removed the constant speed unit from the RH engine p/n 03-7212-K0068-02 s/n 0701. Installed isolation

kit p/n 05-9900-5000401 on this engine per this SB. This AD is complete, no further action required.

valve replacement will be 645.5 hours.

SINCE MFG.

RH N127US DA42 S/N 42.AC127 3/1/2013 5 of 6 Thielert SB TM TAE 125-1015 P1 dated 4/27/2012, gear box Gearbox temp sensor p/n NE-0000-0000201 Oil temp sensor p/n NE-0000-0000201 Installed the following new sensors: 2 ea camshaft sensors p/n 05-3940-K000101. T-Air Sensor p/n 05-7311-K000501 Rail pressure sensor p/n 05-7320-E000102 2 ea crankshaft sensors p/n NE-0000-0133101 Throttle potentiometer lead 1 p/n 05-7320-E000301 Performed engine task 02-02-02131/-02132 visual inspection Throttle potentiometer lead 2 p/n 05-7520-E000201 Coolant temp sensor p/n 05-7522-K000301 Oil pressure sensor p/n 05-3940-K001201 Gearbox temp sensor p/n NE-0000-0000201 Oil temp sensor p/n NE-0000-0000201 Removed the following electrical actuators: Installed repaired FADEC unit p/n same s/n 3255. See EASA Wastegate Control valve p/n 02-7240-05308R1 form 1 dated 7/5/2012, WO# FA2206023 by Thielert Aircraft PDRV Assy. p/n 05-7212-E002801 s/n 01440 Pressure regulator Assy. p/n 05-7320-E000703 4 ea Fuel injectors p/n 05-3940-K003501 Removed the engine harness (loom) p/n 05-7150-E000904-A7 Installed the following electrical actuators: Wastegate Control valve p/n 02-7240-05308R1 PDRV Assy. p/n 05-7212-E002801 s/n 02253 Pressure regulator Assy. p/n 05-7320-E000703 4 ea Fuel injector p/n 05-3940-K001602 RH N127US DA42 S/N 42.AC127 3/1/2013 6 of 6 Installed fuel injectors with new cap screws p/n NM-0000-Removed the alternator p/n 05-7150-E000601-AT s/n 0C0471 0106601. Fuel system bled prior to running engine. I certify that the above stated maintenance was performed in accordance with the current FAR's and this aircraft is approved for return to service: W.O. S29-12-04593 & S29-12-04534 LANDMARK AVIATION FAA CRS # LN3R663L

MAXIMUM HOURS BETWEEN OVERHAULS___

RH N127US DA42 S/N 42.AC127 3/1/2013 3 of 6

oil filling plug, is not applicable by the installed engine serial

Thielert SB TM TAE 125-1014 P1 dated 2/27/2012,

customer supplied the kit p/n 05-9900-S001101.

Performed a lightning strike Inspection.

s/n 00314-2007, from the engine.

Connecting pin waste gate lever, complied with SB by

replacing the connecting pin on the wastegate lever. The

Removed the FADEC ASSY. p/n 05-7610-E000201-AT1

Installed repaired harness p/n 05-7150-E000904-AT

s/n 00460-2007. See EASA form 1 dated 1/4/2012,

RH N127US DA42 S/N 42.AC127 3/1/2013 4 of 6

Installed an overhauled alternator p/n 05-7150-E000601

Removed the alternator regulator p/n 05-7150-E000701

Installed an inspected alternator regulator p/n 05-7150-

E000701 s/n 10562. See EASA form 1 dated 1/19/2011,

Removed the wire hamess (loom) p/n 52-7150-E000102

Installed new wire harness (loom) p/n same s/n 0139-2007.

WO# FA2104989 by Thielert Aircraft Engines.

Removed the starter p/n 05-8010-E002802. Installed the new starter p/n 05-8010-E002802

s/n 00385. See EASA form 1 dated 4/25/2012,

WO# FA2203273 by Thielert Aircraft Engines.

WO# FA2009947 by Thielert Aircraft Engines.

Replaced 4 ea glow plugs p/n 05-3940-K001301.

2 ea camshaft sensors p/n 05-3940-K000101.

Removed the following sensors:

T-Air Sensor p/n 05-7311-K000501 Rail pressure sensor p/n 05-7320-E000102 2 ea crankshaft sensors p/n NE-0000-0133101 Throttle potentiometer lead 1 p/n 05-7320-E000301 Throttle potentiometer lead 2 p/n 05-7520-E000201 Coolant temp sensor p/n 05-7522-K000301 Oil pressure sensor p/n 05-3940-K001201

Removed glow plug control unit p/n 05-7151-E000401

Installed new control unit p/n 05-7151-E000401 s/n 4963.

numbers.

Engines.

s/n 0439-2010.

for lightning exit points.

TOTAL SINCE MFG.

DATE	TIME	RUN		SINCE TH AUL	INSTALLATIONS, INSPECTIONS,	REPAIRS, ADJUSTMENTS, MODIFICATIONS	SIGNATURE	LICENCE
	HRS.	MIN.	HRS.	MIN.	NOTE: USE BOTH PAGES AND AS MANY LINES AS REQUIRED FOR COMPLETE	ENTRIES. DRAW A DIAGONAL LINE THROUGH ANY UNUSED LINES IN DATE AND TIME COLUMNS.		NUMBER
BROUGHT FORWARD -		 ▶			Replaced h/R Clutches pressure	Plates intermedita blance + year lovers	Kusall Film	122709
6/1/2015			348	ي	to the so limit gooded tupo	The state of the s	2	July 1000)
4/1/2/2			1		Change oil filters, Coolant and	dear boy sil, Completed annual Checkle	A Kussell Flor	pin 2705
12/31/2015	W		38%	5	Swaped Brown to left frame	position for diagnostics 1 398 Thour	Bursel I. Lani	,
					innotalled new proposito	and torque to 35 +1/bs.		
June 3, 201 ACTT: 461.					·	une 3, 2016		
—— N127US	-					ACTT: 461.2 N127US		
—— Changad a	naina ail	on loft	and sigh	t ongine	s and oil filters. Cut		-	
					anged left and right	Changed engine oil on left and right engines and oil filters. Cut open oil filters and inspected for metal. Changed left and right		
——gear box o		_	_		=	gear box oil filters. Changed gear box oil on left and right		<u> </u>
			_		rs. Replaced left ed. Ran tmg service	gearboxes. Replaced left and right fuel filters. Replaced left waste gate actuator. Ran up and leak checked. Ran tmg service		
tool and lo	oked for	alerts a	nd code	s. Cleare	ed codes. Adjusted	tool and looked for alerts and codes. Cleared codes. Adjusted		
both prop	syncs to	21 bar.	Farrell H	larris Al	22705924.	both prop syncs to 21 bar. Farrell Harris AP2705924.		
							V	
	-	-	-		L			2
	1.5				(*)			-
						ACTI: 645.7 160-1,2020	<u> </u>	
-	-					O: Till Ord in Engine and year box	•	
	-					dir filter and fuel filters changed		
	<u> </u>			-		120/40 + Adda/40l Such Vist Ellertel The	()	
	 			 		This engine has been unested and	men D	
						to be in an sinworth Condition.		
						Russell Farrell Harris 4A 270 5924.		
							to the	
					CARRIED FORWARD			
TOTAL THIS PAGE								
TOTAL FROM PREVIOUS SUMMARY			1			MAXIMUM HOURS BETWEEN OVERHAULSHOURS.		

TOTAL THIS PAGE TOTAL FROM PREVIOUS SUMMARY

TOTAL SINCE MFG.

MAXIMUM HOURS BETWEEN OVERHAULS_____HOURS.

					ENGINE SERVICE AND	MAINTENANCE RECORD		6		
	TIME RUN TIME SINCE				INSTALLATIONS, INSPECTIONS,	REPAIRS, ADJUSTMENTS, MODIFICATIONS				
DATE	HRS.	MIN.	HRS.	MIN.	NOTE: USE BOTH PAGES AND AS MANY LINES AS REQUIRED FOR COMPLETE	ENTRIES. DRAW A DIAGONAL LINE THROUGH ANY UNUSED LINES IN DATE AND TIME COLUMNS.	SIGNATURE	LICENCE		
BROUGHT FORWARD		→				6-21-2024 N127 119 ACTT: 725.8	*			
						DA 42 TAE A5-02-99				
						Inspected this one and kound following		-		
	25					Collant Enpansion tank Rubber Maint				
			2			ton offe Rudiator Bhose torn, Engine oil				
						and filling need to be changed your boy				
						Engine inspects of but needs listed etems				
						to be completed. Russoll Israel Havis				
						IA 2705924!				
	AR	RI	5					-		
Aviat	tion Mai	intene	nce		•					
wheel bearing Serviced main friction disk. R turbo waste gr accumulator v light. Replaced	s with greger and seplaced rate control with nitroger in the letter 32	ease. Rep nose ger ight engi oller and gen. Oil c rizonal st	olaced by ar struts ine shock hoses a changed tab station	rake cali with ni k moun nd chan and filte c wick. I	per piston O rings and seals. Serviced brakes with 5606. crogen. Replaced right engine gear box and clutch cs. Replaced right prop accumulator. Replaced right ge over valve. Serviced gear boxes with N1 oil. Serviced cers cut and inspected. Replaced right wing tip strobe deplaced right cabin door window latch. Inspected props pected this aircraft in Accordance with FAR 43.13 return to Service (1.20)	N127US Right Engine Model TAE 125-02-99 ENGTT:754.5 SN:02132 December 30 2024 Completed Annual inspection. Cut Oil filter and changed oil. Replaced gear box filter and changed oil. Pressure tested coolant system.Replaced radiator vibration dampners and intercooler vibration dampners. Inspected turbo and pressure checked waste gate. Used Diamond 100 hour check list and inspected in Accordance with FAR 43 Appendix D and found it to be airworthy at this time. Taxael Ta				
	DE DE	hy	20	es.	100 HR KITS Maine oil W/ AEROShell Cha gearboy W/New NI Les Air Filter A & N Way and Me-ciles CRAHAM MIMILIAN					
. 0					CARRIED FORWARD					

RECORD OF ENGINE AIRWORTHINESS DIRECTIVES (A/D), SERVICE BULLETINS (S/B),

SPECIAL INSPECTIONS (S/I) AND MODIFICATIONS (MODS)

DATE	A/D, S/B, S/I, MODS	DETAILS OF	WORK OR INSPECTION PERFORMED	SIGNATURE	LICENC
		Diamend			
		Date: 17 March, 2008 S/N: 42.AC127 Reg: N127US			\rightarrow
		TTAF: 5.9 HRS Engine RH S/N: 02-02-02132 TSN: 5.9 HRS			
		The following S/B and S/I have been carried out as applicable:			
		LBA AD D-2004-457/R2 –in case of failure of elec. power supply – N/A by M/N LBA AD D-2004-473 – Detachment of high press. pump mounting bolts – N/A by M/N			
		LBA AD D-2005-152/R1 - Chapter 5 to TAE Ops & Mainten Manual - N/A by M/N	\		
\		DAI-A AD D-2005-145 – Thielert Software m2.7 – N/A by M/N DAI-A AD D-2005-229/R1,SI42-007 – Engine, Exchange of the clutch disk			
\		only if Engine or Clutch has been replaced N/A			
1		DAI-A MSB 42-007/3 – Software for TAE Engine, approved version – C/W by TAE DAI-A MSB 42-016/2 – Installation of improved breather line ATA-Code:71-00 – N/A			
		by M/N DAI-A MSB 42-017 – Oil Lines ATA-Code:79-00 – N/A by A/C S/N			
1		DAI-A MSB 42-027/1 – Engine replacement requires engine control harness			
		Replacement(at next engine change/replacement) – N/A by M/N DAI-A MSB 42-028 – Engine replacement (at next engine change/replacement)			
		Requires Electrical Harness Sealant – N/A by A/C S/N			-
		DAI-A MSB 42-042/1 – Installation of additional ECU backup batteries – NCW DAI-A MSB 42-055 - Water circulation installation within next 100hrs but no later than			
1		Mar 15/08 – N/A by engine M/N DAI-A OSB 42-046/1 - Retrofit of TAE 125-02 engine – N/A			
/		DAI-A OSB 42-050/1 - Installation of additional ECU 30 min backup batteries			
		(FAA AD 2007-23-14) – N/A, C/W during Mfg.		 	
		EASA AD 2007-0182 - Engine inspection - NCW EASA AD 2007-0183 R2 - Installation of additional ECU backup batteries - NCW			
		EASA AD 2008-0016 R1 - Engine piston cooling nozzles inspection – NA by eng M/N			
		EASA AD 2008-0027 – Engine fuel system – High pressure fuel line bracket – NCW TAE SB TM TAE 000-0004 R60 – TAE manuals – C/W by TAE			+
		TAE SB TM TAE 000-0007,R3 – variants and software revisions – C/W by TAE			
		TAE SB TM TAE 125-0001,R2 – Engine Lifetime of 1000 Flight Hours/12 years – Due at 1000 HRS – N/A by M/N			
		TAE SB TM TAE 125-0002,R3 – Each 300 Flight Hours; Inspection of Gearbox,			
		Gearbox oil and filer, Engine oil and filter – Due after each 300 flying hours- N/A by M/N			
		TAE SB TM TAE 125-0003,R6 – Oil pressure sensor, prevention of damages – N/A by M/N			
		TAE SB TM TAE 125-0004,R4 - New version of firmware and mapping - N/A by M/N			
		TAE SB TM TAE 125-0005 – Conversion to compression 18:1 – N/A by M/N TAE SB TM TAE 125-0006,R4 – Current level of firmware, mapping compression			
	1	ratio 18:1 – See TM TAE 125-0004,R4 – N/A by M/N			_
		TAE SB TM TAE 125-0007,R5 – Cooling, prevention of electrochemical corrosion – N/A by M/N			
		TAE SB TM TAE 125-0008,R3 – Function of Alternator in case of a failure of the electrical aircraft power supply – N/A by M/N			
		TAE SB TM TAE 125-0009,R1 - Screw Retention - Bearing Shield High Pressure		1	_
		Pump – N/A by M/N TAE SB TM TAE 125-0010 – Airworthiness Limitation Section, Operation &		_	
	\	Maintenance Manual Due at 100HRS N/A by M//N			
		TAE SB TM TAE 125-0011,R3 – Exchange of the clutch disk – N/A by M/N			
		TAE SB TM TAE 125-0012,R1 – Customer furnished parts – N/A by M/N			
	<u> </u>	TAE SB TM TAE 125-0013,R1 – Gearbox oil filter – N/A by M/N TAE SB TM TAE 125-0015,R2 – Aluminum Pipe Combined Pump – Module Block		<u> </u>	_
	1	- N/A by M/N TAE SB TM TAE 125-0016 R1 – Adapter Catchtank for Turbocharger – N/A by M/N			
		TAE SB TM TAE 125-0017 R2 - Eng inspect'n within 100 flight hrs or next			
	-	maintenance, whichever occurs first – N/A by engine M/N. TAE SB TM TAE 125-1001 P1 - Exchange chain tensioner, short circuit water			+
		pipe, turbocharger studs, gearbox studs – C/W by			
		TAE TAE SB TM TAE 125-1003 P1/Rev 1 - Exchange mounting brackets of injectors –			
	3	NA by eng S/N TAE SB TM TAE 125-1004 P1 - Remove small o-ring of oil filter module – C/W		/	
-		TAE SB TM TAE 125-1005 P1/Rev 2 (EASA AD 2008-0056R1-E) - Instal. of bracket		† · · · · · ·	4
		High-Pressure fuel line – C/W Bi-weekly AWD check carried out to current revision 2008- 06			
	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	The maintenance described above has been performed in accordance with the			/
		applicable standards of airworthiness. DIAMOND AIRCRAFT INDUSTRIES INC. D.O.T. APPROVAL #161-93	With a second se	1	1
	+	DA \	\(\)	_	
	\\	Signature Lic or Stamp Q 42			
	1			TI.	