

ENGINE LOG BOOK

Publication ELB-01 JUN 2019

Service Information

Consult the Continental web site at http://www.continental.aero for engine related news or announcements. The web site contains useful information for Continental engine owners, including service information and illustrated parts catalogs.

If Internet access is not available, contact our Customer Service Department at: 1-888-826-5465 Toll free in the United States or 1-251-436-8299 for International customers

Warranty Information

This product is covered by Continental Aerospace Technologies™ product warranty. To read or download a copy for your records. please visit the Product Warranty page on our web site at: http://www.continental.aero/services/warranty.aspx or scan the QR Code to the right to navigate to the page:



Instructions for Continued Airworthiness

For complete access to the engine Instructions for Continued Airworthiness, Illustrated Parts Catalogs, Service Documents, Technical Briefs, company news, and upcoming events, please take a few moments to register the serial number of your engine on our web site: http://www.continental.aero/services/owner-registration.aspx or scan the QR Code to the right to navigate to the page:



Engine Returns

Return engines for core credit with this log book to: **Continental Aerospace Technologies** 2039 Broad Street Mobile, AL 36615 USA

Return engines for overhaul with this log book to: **Continental Services Factory Service Center** 8600 County Road 32 Fairhope, Alabama 36532 USA

USE ONLY FUEL SPECIFIED IN OPERATOR'S MANUAL OR TYPE CERTIFICATE DATA SHEET **USE OF AUTOMOTIVE FUEL IS PROHIBITED**



FAA PRODUCTION CERTIFICATE NO. 508

Printed:06/30/2022

Test Daten6/30/2022

This engine model I0550N41B, serial number 1043734 was manufactured by Continental Motors, Inc. in accordance with approved design data and the applicable requirements of 14 CFR, Part 21. The approved design data for this engine incorporates all changes required by applicable FAA Airworthiness Directives and Continental Motors Service Bulletins.

CONTINENTAL MOTORS, INC.

Form 6012-03 (Rev Sept 2014)



Date: 9/21/2022; Aircraft: 226CH; Type: CIRRUS SR-22; S/N: 0875; 2342.30; Tach:;AC AirTime:; Total Time: 2342.30; Engine - Type; IO-S/N: 1043734, Time:; Prop - Type: PHC-J3YF-1RF, S/N: FP27368, 1

Removed Alternator 1 p/n 646843 s/n 002DA072 from engine s/n 917 Checked alternator for torque slippage in reference to TCM SB11-3, good. Installed alternator on engine s/n 1043734. Ref Cirrus AMM 24

Removed #2 alternator p/n BC410-1 s/n 0142413 from engine s/n 91 and installed on engine s/n 1043734. Ref Cirrus AMM 24-30

Adjusted engine idle as required. Ground ran aircraft and checked for operations, ops check good. Ref Continental M-0

Removed and replaced engine mounts with new (p/n 96301-01) mount Installed new engine (p/n IO550N41 s/n 1043734). Routed and secur control cables and wiring. Installed exhaust and baffling. Drained end preservative. Serviced engine with 8 quarts of Aeroshell 100 mineral of Ground ran aircraft and checked for normal operation and leaks. Ops leak check good. Ref Continental standard practices manual M-0, and SR22 AMM.

The maintenance described above was performed and inspected in accordance with current FAA Regulations and is approved for return to service only for the work performed. Ref: 14 CFR Part 43.9. Pertinent details of the repair are on file at this repair station under

Work Order number_	3.49	73
	200	

Dominion Aviation CRS# ODAR018 7511 Airfield Drive Richmond, Virginia 23237 (804) 271-7793



Date: 10/19/2022; Aircraft: 226CH; Type: CIRRUS SR-22; S/N: 0875; Ho 2361.90; Tach: 2341.30; AC AirTime: 2341.30; Total Time: 2361.90; Engi Type: IO-550N41, S/N: 1043734, Time: 2360.90; Prop - Type: PHC-J3YF 1RF, S/N: FP2736B, Time: 19.60

Complied with the oil and filter change. Serviced with 8 quarts of Aerosho 100 Mineral. Installed new oil filter p/n AA48108-2. Cut open the old filter and found no defects. Ran the engine and no leaks detected.

The maintenance described above was performed and inspected in accordance with current FAA Regulations and is approved for return to service only for the work performed. Ref: 14 CFR Part 43.9. Pertinent

Dominion Aviation CRS#, ODAR018H 7511 Airfield Drive Richmond, Virginia 23237 (804)-271-7793

DAS FORM LB-1

npli	ance	with in	nspec	ctions	engine s, Airwe ce Bull	orthi	ness [oval Direc	e tiv
	1442	*** f			100		ē ,	Se:	
		9			1.760		593		
			e n		i i				
						Ř	1.0	167	
				ř.	a	6	395		
			E I		1.3	5			
						71			
(1)									je
- A					- 1		8		-
			7			1	w _{or}		
			2		-		Э.		
	* ×		D,				60		3
				6					
				0		, P	° 4	84	
્		*	27					T INC!	
		-							
	* /	,	ŭ.						٠
			× ,		5 2	12	5	5:	
.90			or ³⁶		18000	0	8:		
	8 8	3				- 00 10		177	^
-				_		×			
	- <u></u>		Ť	6.0	. 2.	90		-	4
				ě	Po _y		\$ Z		
	2	11.5	9	s v	8		.S. 5		Ď
-	_	-							en V
			# T	2"		-	3 10		2
	0	S - 12		18	¥	s.º	100 11	3 1	
				_					
		_	XI.	8	10	1)6	82		
	2	<u> </u>			es [®] n			, 0 1 8	
		_	-				100	- (
		15			- WX				_
		- N					- 1		_
			9	0				8	



Date: 12/09/2022; Aircraft: 226CH; Type: CIRRUS SR-22; S/N: 0875; Hobbs: 2393.40; Tach: 2341.30; AC AirTime: 2341.30; Total Time: 2393.40; LG Cycles:; Engine - Type: IO-550N41, S/N: 1043734, Time: 2392.40; Prop - Type: PHC-J3YF-1RF, S/N: FP2736B, Time: 51.10

Complied with the Annual and 100 hour inspection in accordance with Dominion Aviation Services FORM 0100 which meets the requirements of FAR 43 appendix D and with reference to Cirrus SR22 maintenance manual chapter 5.

Checked and listed all applicable Airworthiness Directives using ATP revision dated 12/09/2022.

Complied with the logbook research.
Updated the computer profiles.

Performed post engine oil and fuel system leak checks: no leaks found.

Complied with the 100 hour lubrication as required in chapter 12.

Cleaned engine of residual oil / dirt buildup as required with mineral spirits and dried with shop air.

Complied with a compression check on all engine cylinders. The readings were as follows: #1 - 74/80, #2 - 74/80, #3 - 76/80, #4 - 76/80, #5 - 76/80, #6 - 78/80, Master orifice 46/80

Complied with the oil and filter change. Serviced with 8 quarts of Aeroshell 15w50. Installed new oil filter p/n CH48108-1. Cut open the old filter and found no defects. Ran the engine and no leaks detected.

Removed the spark plugs. Inspected, cleaned, gapped and rotated the spark plugs. Reinstalled the spark plugs with new gaskets, p/n M674. Reference: Tempest aviation service manual 1710A.

Complied with borescope inspection of all engine cylinders. Good cross hatching on all cylinder walls.

The maintenance described above was performed and inspected in accordance with current FAA Regulations and is approved for return to service only for the work performed. Ref: 14 CFR Part 43.9. Pertinent details of the repair are on file at this repair station.

Signed Silfy (Salv

CRS# ODAR018H

certify that this EMAIN Inspection and was determined to be in airworthy condition. Details on like at this facility.

Inspector_

Work Order # 35

Dominion Aviation CRS# ODAR018H 7511 Airfielo Drive Richmond, Virginia 23237 (804) 271-7793

//2	13	18 E	0.0			1			545	¥-		
				S 840 B		}	, 	<u> </u>	Y	, n		* * *
	*		×		ж			8	2.5	* =	THE .	
Ì	*				81		*			÷ ,,	01	3
Ì	15 1		12 15	is .	11/2:			17672	10	×	x š	¥° =
	9) 7). ()	•	2 N		390				5960			- 181 a
	2			9				To.		# # # #	2	* v _ 1 *s.
::					DO:		Sa 90	ž.	9))	9 1	(8)	2 3
	<u>.</u>		i e		=		*		-		G.	5 _{.3}

ngine Service and Maintenance Record

ord maintenance actions including engine part removal and

allation and compliance with inspections, Airworthiness Directives,

cial Inspections, Modifications and Service Bulletins

To		Total Time S			Engine Service and Maintenance Record
Date •	Hours	Min	Hours	Min	Record maintenance actions including engine part removal and installation and compliance with inspections, Airworthiness Directives Special Inspections, Modifications and Service Bulletins
arried forward —		-			The second secon
1-29-2003 2444 3		13	102,	5	DYNINA 5: TOOK EAMPLO, BORTA
			2//		oil filter with more champion
					LA 18409-1 safety wired, Baplace
95				al .	o'il with 8 ots Aaroshall 15. W-50
	15	19			Annergine mocked for Jenks prom
		-0			found. SATOICON &) BATCOLY.
à		-	-	*	philon M. withou PP 1486237
					* 3 3 E
1-29-200	24	3	102.	o	cut oil Filet shacked made
					FOR cont a mineral resulty and
					with my great. Nothing Found
			· ·		disto w. estates pp 1 486239

Date: 3/21/2023; Aircraft: N226CH; Type: SR22; S/N: 0875

HOVA Flight Services | 804-798-600

† 11152 Air Park Road, Ashland, Virginia, 23005, USA

23-14087 Tach: 2445.4

Discrepancy: 1

Oil change requested by owner in compliance with new Continental AD 2023-05-16 Drained oil and removed filter, No contaminants found, Replenished engine with 7 quarts of

Aeroshell 15W-50 and installed AA4109 oil filter. No leaks present at this time and operations performs satisfactory. Engine was run up to operating tempertures and no leaks found during and after run up. Operation of engine performs satisfactory and has been determined to make

the flight from KOFP to KFCI safely. No faults known at this time. Stephen M Leo AP3678028

6-	Total	Total Time Since Overhau						
Date	Hours	Min	Hours	Min	Record maintenance actions including engine part removal and installation and compliance with inspections, Airworthiness Directives Special Inspections, Modifications and Service Bulletins			
Carried forward		-						
4								
					· · · · · · · · · · · · · · · · · · ·			
					DOMINION AVIATION			
œ	A.	-	244: S/N: Time	5.30; Tac	023; Aircraft: 226CH; Type: CIRRUS SR-22; S/N: 0875; Hobbs: ch:;AC AirTime:; Total Time: 2445.30; Engine - Type: IO-550N41, 4, Time: 103.00; Prop - Type: PHC-J3YF-1RF, S/N: FP2736B,			
ŭ ŭ			l har	ve Inspec t from K0	cted this Aircraft and found it to be safe for the intended ferry DFP to KFCI. All ADs pertaining to this flight have been			
		25	Spe Oil a Cor	and filter nplied wi	t Permit request per AD 2023-05-16: change complied with date 3/21/2023. Aircraft total time 2445.4. th by shop name, HOVA Flight Services. Per HOVA Flight Contaminants found in filter.			
	No.		+ acc	ordance v	ance described above was performed and inspected in with current FAA Regulations and is approved for return to for the work performed. Ref: 14 CFR Part 43.9. Pertinent			
20					repair are on file at this repair station under			
3			751 Rich	ninion Av 1 Airfield	irginia 23237			
			DAS	FORM	LB-1			
		0.						
			*		n d s			
					3			
F		IV.						
	-			<u>, </u>	*			
<u> </u>			1.00	80 80	2 00 0			
8		£		8:	<u> </u>			
	F							
200	0.00	*:		· ·				
2			<u></u>	35/	- N - W			
3			*					
P\$1			2	7-				
		n 5	E.	E 00	9 3 2 2			
			1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	8 5				
		, - B		720				



Date: 4/07/2023; Aircraft: 226CH; Type: CIRRUS SR-22; S/N: 0875; Hobbs: 2446.70; Tach:;AC AirTime:; Total Time: 2446.70; Engine - Type: IO-550N41, S/N: 1043734, Time: 104.40; Prop - Type: PHC-J3YF-1RF, S/N: FP2736B, Time: 104.40

ENGINE

Complied with AD 2023-05-16 To Prevent Departure of Counterweight & Retaining Ring Eff. Dt. 03/15/2023 C/W paragraph (G) by completing Continental MSB23-01A Paragraphs III. Found All Three conditions specified in Figure 1 are met.

Removed and reinstalled #1 cylinder (P/N 658815A1 S/N AC22D823) with new gaskets and hardware in reference to Continental IO-550-N Maintenance and Overhaul Manual M-16 Rev. 2.

Removed and reinstalled #3 cylinder (P/N 658815A1 S/N AC22CC179) with new gaskets and hardware in reference to Continental IO-550-N Maintenance and Overhaul Manual M-16 Rev. 2.

Reinstalled exhaust stud in Cylinder 1 exhaust port with reference to Continental M-0 Appendix C section 6.

Removed #1 and #3 cylinder rocker box covers, cleaned mating surfaces and reinstalled with new gaskets (PN: 668893). Work performed was with reference to Continental standard practice manual M-0.

Verified oil quantity is sufficient on dipstick.

Performed ground engine run. No leaks detected.

The maintenance described above was performed and inspected in accordance with current FAA Regulations and is approved for return to service only for the work performed. Ref: 14 CFR Part 43.9. Pertinent details of the repair are on file at this repair station under

Work Orde	er number_	3561)	,	
Signed	4				_

				×	8			Y
	₹018H *	-		6). X.	-	2 2	N N	H ,
F 1	î.	0			8			
249	0.1	147	. છે ડ					
		171	8	Repl	Acab FILT	er wild	- L N B	
			8.0	AR	1109 5Afe	ty with	al ¢	: I Ter
				Repla	acedoil a	جا + أ ور	8.975	Aero
:		-	8	5 haell	154-50.	RANE	regin.	a elect
		75		for 1	RAKS, NONE	found	J.	15
				. Hiela	in my what	hers PF	148	6239
23 25	51.6	198	3 5100	Draine	oil, Tos	RSAM	ale A	emplace a
				4,2800 N	, th new	Tampa	AA TE	48109 81
				TOPPUS	MAD SAIPED	miles ,	e de pa	o) metal o
				with 80	TE AERETH	01 150	450 R	والم والم الم والم الم
	3, -	N.		alesok	ed BOV he	2 16 Ks.	۳ م و در	Y 2 4 1º
	2.5			Dietor e	4- entres	10 7 LES	6279	
				06 8	-, -			
3	249	2790.J	2490.1 147	2490,1 147, 8 ₅ .	2790.1 147.8 SINCE NEW Repl AR Repl Shell For 1 Hill 73 25 51.6 198 3 SIM DOMINE TO PROS With 8; alread	2490.1 147.8 SINCE NEW Orningel Replaced Filt AR 4109 SAFE Replaced oil of Shell 1520-50. Gor leaks, NOWE Miller M. 255 232581.6 1983 SIMP Drained oil, TOD Ailten With 8055 AERETH OLDER AND ARETH	2490.1 147.8 since New Ormined oil, Replaced oil with Shell 15w 50, Ran E Gor leaks, NONE found Allow m. with New Jamps 132581.6 198 3 sind Drained oil, TOOK Same Torpud And Smiled with with 8075 AERESHED 15 w. almoked of Rov he with	2490.1 147.8 SINCE NEW OFMINED OIL, TOOK REPIACED FILTER WITH NE AR 4109 SAFETY WITEL & REPIACED OIL WITH BOTS Shell 15W-50, RAN ENGIN FOR leaks, NONE COUND. Aleken M. Withen PP* 148

vice and Maintenance Record

ice actions including engine part removal and npliance with inspections, Airworthiness Directives,

i, Modifications and Service Bulletins

		- 1. E.	e we'	% = 1					
n	Total	Time	Time Since Last Overhaul		Engine Service and Maintenance Reco				
Date	Hours	Min	Hours	Min	Record maintenance actions including engine part removal ar installation and compliance with inspections, Airworthiness Directive Special Inspections, Modifications and Service Bulletins				
Carried forward -	'-	→	754	G					
AN GO HOUSE	2541	, É	7600	The Land					
11-24-23	2593	2.	249.9		DRAINED OIL, TOOK SAMPLE, REPLACED				
	3,	*			FILTER WITH NOW CHAMPION CHUSIO9-1				
					TORONED TO ISFILM AND SAPETY WIRED.				
					REPLACEDOIL WITH & QUARTS AEROSHUZC				
EC. (%)					WISW-50. RAN ENGINE AND CHECKED				
7 1					FOR LEAKS, NOW DETECTED: SERVICEN				
		- ×	-		Take the second				
			-		1 Skiller 1.				
10			1		Man & Bran #1973895C7				
3 ×					*				
					6				
				22.	W 5				
					Heart of Virginia Aviation Phone: 804-798-6500				
					- 11152 Airpark Rd Fax: 804-798-6544 Ashland, VA 23005, 01/08/2024				
<u> </u>		- 2			=				
				1.7	- Continental IO-550N41 SN: 1043734				
		-			- HOBBS: 2607.3				
	F			,	ГТТ: 2607.3 = SMOH: 264				
*):	ä				1) Performed Annual Inspection				
W (1)					2) Engine Compressions 1: 64/80, 2: 70/80, 3: 60/80, 4: 68/80, 5: 64/80, 6: 68/80				
10)		(%)			3) Drained oil and reserviced with 7 quarts of Aeroshell 15W-50.				
€ 5					5) Removed, inspected, reinstalled fuel bowl and screen with new o-rings.				
				,<	 6) Inspected exhaust mufflers. No faults noted. 7) Removed, cleaned, gapped, inspected and reinstalled 12 spark plugs wit 				
	-	1	-		new washer gaskets. 8) AD research completed thru Biweckly 2024-01 and applicable AD's				
	wa t				complied with				
g 25 d					9) Post maintenance leak checks completed. No faults found at this time.				
_32 ₀					I certify this engine has been inspected in accordance with a Annual Inspection and was determined to be in airworthy condition. All operational and leak checks				
43					satisfactory.				
	14				Tommy Grimes A&P 35546531 IA				
2 :									
					81				
				100					
	- 02		-		*				
	ļ .	-			32 : 5				
8			10		* n e * * * * * * * * * * * * * * * * *				
				1	5 Jr				



	Total	Total Time	Time Sin Over		Engine Service and Maintenance Record				
Date	Hours Min		Hours Mir		Record maintenance actions including engine part removal and installation and compliance with inspections, Airworthiness Directives, Special Inspections, Modifications and Service Bulletins				
Carried forward –		→							
5/31/24	2651		50.9		Draines oil Took sample, replaced				
	2				Filter th new Tempest AA48109.				
SINCE NEW		2)	314.5	ì	Torqued to 15 Ft pd: And shift wind				
					Replace 0-1 U/ Fgts Acrosten W/5W50				
				-	NAW Engine and etected For leaks				
				3:	NOU Detected Service #1 DARtery				
					Danue # 3557741				
				F*	381				
8-4-2024	2713.7				DRAINED oil, Obtained sil sample.				
					Replaced sit Filter with tempest				
SINCE NEW			369.9		An 48109 Filter, Tourged To 1587 LES				
1:					and safety wired RAN Engine				
T # 3				1	Acheekad for heaks, None found.				
				-/	1 ister m. Without PP # 1486239				
					Filled with 8 OTS A EROSLEII w 15-50				
				70	Hillow M. Withoux PP 1486239				
		- E	- 30		Hiller Wy. Wiles 2 11 11 50221				
		2:	-						
· · · · · · · · · ·			. 2						
##*****					8 0 2				
				4,					
3									
м .									
					1				
+,	7.	2			2 8 8 8 7				
E.	927	:•	E .						
· ·									
*				- 11					
, <u>8</u> ×					- A A A A A A A A A A A A A A A A A A A				
				Ε.					
			160		100 PT				
		. 520			, , , , , , , , , , , , , , , , , , ,				

Heart of Virginia Aviation

Ashland, VA 23005 (804) 798-6500 SN: 1043734

H24-15593

Shop Order:

Model: 10-550N41B

Make: Continental

Component: Airframe

AFTT: 2815.6

ETT: 493.9

02-14-2025

N226CH

Registration #:

11152 Airpark Rd

Maintenance Record

luding engine part removal and spections, Airworthiness Directives, nd Service Bulletins

Compiled with the following Scheduled Inspections:

Complied with ANNUAL ENGINE inspection referencing HOVA 100 HR/ANNUAL and Cirrus SR22 Inspection Checklist.

Compiled with the following Maintenance Items:

- Drained oil and removed oil filter; no contaniments found. Rep'enished engine with Aeroshell 15W50 (8 quarts) and installed new oil filter,
 - Fabricated small single tap skin splice in reference to AC43.131b Fig 4-5 pg 4-20 on front left engine baffle.
 - Removed and replaced alternate air cable bracket attached at engine.
 - Compressions @ 80 PSI: 1/73, 2/75, 3/69, 4/66, 5/70, 6/71
- Removed and replaced all spark plugs due to past tolerance on "go/no go" gauge; All spark torqued to 30 ft lbs.

Compiled with the following AD's: Researched Bi-weekly 2025-04

l certify this ENGINE has been inspected IAW ANNUAL Inspection per 14 CFR 43 Appendix (d) and was determined to be in airworthy condition.

Signature: _

02/14/2025

Date:

i i	T.a.	H TIME	· · · · · · · · · · · · · · · · · · ·
9/22/25	285		CHANGED OIL + FILTER
1/00/80	14/		TASDECTED FICTER - NO MOTEL FOUND
			SENT OIL SAMPLE TO BLEEKSTONE BUT SEEMS TO BELOST IN TRANS,T
	28		BleckSTONE BUTSBEMS TO
			BULOST IN TRANSIT

Engine Logbook

Date: December 1, 2025



Dute: Deterinder 1, 2023		AIRCDAFT SALES & BRUNERAGE
Reg No: N226CH	Aircraft Type: SR22	Aircraft S/N: 0875
Flight Hours: N/A	Hobbs: 2866.4	Aircraft Total Time: 2866.4

- Performed compression test M/O 46/80 1:67/80 2:70/80 3:70/80 4:70/80 5:70/80 6:71/80.
- 2. Cut and inspected oil and found no discrepancies at this time. Installed new Tempest oil filter P/N AA48109-2.

This aircraft, airframe, engine, propeller, or appliance identified was repaired and/or inspected in accordance with the current regulations of the Federal Aviation Administration and is approved for return to service for the work performed.

Date: 12-1-2025 Signed: 2014 May Matthews A/P 3804633