

Book 2

AirMart.com

AIRCRAFT SALES & BROKERAGE

The Standard



AIRCRAFT LOG

ASA-SA-2

Manufacturer Cirrus

Serial 1906

Model SR 22 GTS

Registration Number N531SD

Date of Manufacture 2006

Engine(s) currently installed:

Manufacturer _____


Model _____

Serial _____

Manufacturer _____

Model _____

Serial _____



AIRCRAFT SALES & BROKERAGE

Propeller(s) currently installed:

Manufacturer _____

Model _____

HUB Model _____

Serial _____

Serial _____

Blade Model _____

Serial _____

Serial _____

Serial _____

Blade Model _____

Serial _____

Serial _____

Serial _____

MAKE: Cirrus Design Corp
MODEL: Sr22
S/N: 1906
REG. NO: 531SD
WORK ORDER: 7803

Columbia Avionics & Aircraft Services, Inc.

Repair Station No. C42R104N
11200 Airport Road
Columbia, MO 65201
Phone: 573-874-4141

DATE: 28 December, 2010
A/C TSN: 911.8
HOBBS: 911.8


Airframe Entries

2 Replaced left wing walk with new, P/N 12683-004. Replaced right wing walk with new, P/N 12683-005 IAW Cirrus AMM, Chapter 20, Standard Practices.

Maintenance Release

The aircraft, airframe, or appliance on N531SD was repaired and inspected in accordance with current Federal Aviation Regulations and is approved for return to service. Pertinent details of the repair are on file at this repair station under Work Order No. 7803, Dated 28 December, 2010.

DATE: 28 December, 2010

SIGNED: 

Eric
Certified Repair Station No. C42R104N

Work Order: 7803

Printed by EBis 3 (datcomedia.com)

ENGINE MODEL: IO550N42
ENGINE S/N: 589670
REG. NO: 531SD
WORK ORDER: 7803

Columbia Avionics & Aircraft Services, Inc.

Repair Station No. C42R104N
11200 Airport Road
Columbia, MO 65201
Phone: 573-874-4141

DATE: 28 December, 2010
A/C TSN: 911.8
ENG TT: 45.9
TSMOH:
HOBBS: 911.8




Engine Entries

1 Performed oil change on engine. Drained oil, removed oil filter, cut open oil filter and inspected for contaminants. No contaminants noted. Serviced engine with 8 Quarts of Aeroshell 15W-50 and installed new oil filter, P/N CH48108-1. Ran engine and performed leak check. No leaks were noted.

Maintenance Release

The aircraft, airframe, or appliance on N531SD was repaired and inspected in accordance with current Federal Aviation Regulations and is approved for return to service. Pertinent details of the repair are on file at this repair station under Work Order No. 7803, Dated 28 December, 2010.

DATE: 28 December, 2010

SIGNED: 

Eric
Certified Repair Station No. C42R104N

Work Order: 7803

Printed by EBis 3 (datcomedia.com)

YEAR 2014 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
2/7/2014	1203.9			Replaced Gill Battery - Serial # G02827351 Engine started - electrical devices checked and operating correctly - Dennis Mollman - private pilot # 3090948 <i>Dennis Mollman</i>

MAKE: Cirrus Design Corp
MODEL: Sr22
SN: 1906
REG. NO: 531SD
WORK ORDER: 7611

Columbia Avionics & Aircraft Services, Inc.

Repair Station No. C42R104N
11200 Airport Road
Columbia, MO 65201
Phone: 573-874-4141

DATE: 30 August, 2010
A/C TSN: 873
HOBBS: 873

Airframe Entries

2 Replaced both left and right aileron gap seals. P/N 14590-502 IAW Cirrus A.M.M., Chapter 57-50, pages 17 & 18.

Maintenance Release

The aircraft, airframe, or appliance on N501SD was repaired and inspected in accordance with current Federal Aviation Regulations and is approved for return to service. Pertinent details of the repair are on file at this repair station under Work Order No. 7611, Dated 30 August, 2010.

DATE: 30 August, 2010

SIGNED: *[Signature]*

Eric
Certified Repair Station No. C42R104N

Work Order: 7611

Printed by EBis 3 (datcomedia.com)

3/14/16				Replaced Gill Battery with Conard RG 24-15M SN 40788294, parts 40788301, 40788306, 40792374; Digital Voltage initial 25.67 volts Terminals torque to 70 in lbs. Engine started - all electronic devices checked and operating correctly Dennis Mollman private pilot # 3090948 <i>Dennis Mollman</i>
---------	--	--	--	---

ENGINE MODEL: IO-550-N
(42)

ENGINE S/N: 689670
REG. NO: N531SD
WORK ORDER: 5343



Ideal Aviation

2100 Vector Dr.
Cahokia, IL 62206
Phone: 618-337-5845

DATE: 1/6/2016
A/C TSN: 1029.9
ENG TT: 1029.9
TSMOH:
TACH: 1029.9

Engine Entries

(2) Serviced all spark plugs, resistance ck below 5000 k on all plugs. Installed spark plugs, ground run-up ok.

Maintenance Release

The aircraft and/or component(s) on N531SD was repaired and inspected in accordance with current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service with respect to work performed. Pertinent details of the repair are on file at this facility under Work Order No. 5343, Dated 1/6/2016.

DATE: 1/6/2016

SIGNED: 
Ray Manipala, A&P: 3395161

Work Order: 5343

Printed by EBis 3 (datcomedia.com)



MAKE: Cirrus Design Corp
MODEL: Sr22
S/N: 1906
REG. NO: N531SD
WORK ORDER: 5343



Ideal Aviation

2100 Vector Dr.
Cahokia, IL 62206
Phone: 618-337-5845

DATE: 1/6/2016
A/C TSN: 1029.9
TACH: 1029.9

Airframe Entries

(1) Installed repaired fuel quantity gage pn 13557-001, sn 1995, cks ok.

Maintenance Release

The aircraft and/or component(s) on N531SD was repaired and inspected in accordance with current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service with respect to work performed. Pertinent details of the repair are on file at this facility under Work Order No. 5343, Dated 1/6/2016.

DATE: 1/6/2016

SIGNED: 
Ray Manipala, A&P: 3395161

Work Order: 5343

Printed by EBis 3 (datcomedia.com)

Technician or Repair Facility. (See back pages for other specific entries.)



18600 Edison Ave.
Chesterfield, MO 63005
(636) 536-1341

Airframe

Date: 9/01/2016


Reg: N531SD

Model: Cirrus SR22

Hobbs: 1922

ACTT: 1922

S/N: 1906



Aircraft has been inspected and has been found to be in safe condition for a ferry flight from KSUS to KLUK. Provided all provisions of the approved ferry flight permit and operational limitations are followed. This approval expires upon arrival at destination or Sept. 12, 2016 whichever occurs first.

Douglas Behrick A&P2606246

Douglas Behrick



4510 Airport Rd.
Cincinnati OH 45226
(513) 321-1200



N531SD S/N 1906 **Date: 9/13/2016** **Airframe** **Hobbs: 1309.4** **Flight: 1078.8**

1. Accomplished service bulletin **SB 2X-95-13** CAPS strap inspection and grommet installation.
2. Accomplished service bulletin **SB 95-18R3** CAPS rocket motor assembly replacement. By installation of parachute assy. p/n 25574-004 s/n 02484R1, rocket motor assy. p/n 29554-001 s/n 1941, electronic ignition retrofit kit p/n 70268-002 rocket retrofit kit p/n 70271-001, crossbeam retrofit p/n 70271-002 and frangible link assy. p/n 29705-402 per service bulletin instructions and CAPS CMM 95-01-01rev E3 dated 4 May 2015.
Rocket Expiration: 9/1/2026 **Parachute Expiration: 8/24/2026.**
3. Installed new #2 batteries p/n 53979-001.

Greg Herrmann 406901563IA