

540

U.S. Propeller Service of California

Stockton Metro Airport • 1911 E. Sikorsky • Stockton, CA 95206

(800) 749-PROP • (209) 982-4565 • Fax (209) 982-1240

FAA Approved Repair Station No. UIHR910L

Propeller Logbook

Book 1

USP

US Propeller Service of California

Stockton Metropolitan Airport • Stockton, CA 95206

FAA Approved Repair Station #UIHR910L

CUSTOMER <i>Sierra Pacific Av.</i>		DATE <i>1-27-97</i>
ITEM <i>Propeller</i>	MFG. <i>Hartzell</i>	
MODEL NO. <i>HC-C2YK-1BF/F3477-4</i>		
SERIAL NO. <i>CH27833</i>		
BLADE SERIAL NO.'S <i>F64248, F64251</i>		
<input checked="" type="checkbox"/> OVERHAUL <input type="checkbox"/> REPAIR <input type="checkbox"/> OTHER		
WORK PERFORMED <i>— done —</i>		
OVER		

PROPELLER ASSEMBLED, ADJUSTED, LUBRICATED, BALANCED AND SAFETIED. C/W A.D. 77-12-06 AND SB 118D, 136H, 142B, 150, 151A, 155 AND 159A.

MAINTENANCE RELEASE

THE AIRCRAFT AND/OR COMPONENT IDENTIFIED ABOVE WAS REPAIRED IN ACCORDANCE WITH CURRENT FEDERAL AVIATION ADMINISTRATION REGULATIONS AND WAS FOUND AIRWORTHY FOR RETURN TO SERVICE. PERTINENT DETAILS OF THE REPAIRS ARE ON FILE AT THIS AGENCY UNDER WORK ORDER

NO. *CAR-3222*

DATE *01/27/97*

SIGNED

AUTHORIZED INDIVIDUAL

REPAIRMAN #2493292

U.S. PROPELLER SERVICE OF CALIFORNIA
STOCKTON METRO AIRPORT • 1911 E. SIKORSKY • STOCKTON, CA 95206
REPAIR STATION #UIHR910L TEL: 1-800-749-PROP

SERVICEABLE

3
C.
TEEL
ARTS
NIED.

**DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS**

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
------	-----------	---------------------	-----------

The New AVEX, Inc.

C.R.S. X11R595Y

205 Durley Avenue, Suite A, Camarillo, CA 93010 (805) 389-1188 FAX (805) 389-3323

PROPELLER

Hartzell HC-C2YK-1

S/N CH27833

N91TB

Work Order: 3975

Date: 8/6/2003

Tach: 2594.9

Hobbs:

TTSN:

2594.9 TSO:

- I certify that an propeller inspection of this aircraft was performed IAW the Socata M.M. and the Hartzell Service Manual and that it was found to be airworthy. AD's checked through revision dated 07/07/03; see AD compliance record accompanied with the airframe logbook

This aircraft, airframe, aircraft engine, propeller or appliance was repaired/inspected in accordance with the current Federal Aviation Regulations and is approved for return to service. Pertinent details of the repair are on file at this Repair Station under Work Order No. 3975.

[Handwritten Signature] 8/6/03


Date

For: FAA Approved Repair Station # X11R595Y

09 July 2004 2607.75 Total Time, 429.74 T.S.M.O.H. I certify that this prop has been inspected IAW Hartzell's Service Manual & is found to be airworthy. No AD's apply. Through this date.

[Handwritten Signature]
GARY L. EVERTON SR
APP#561207527

DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
5/29/97	2178.01	INSTALLED PROPELLER AFTER OVERHAUL BY U.S. PROPELLER SERVICE ON SOCATA TB-20 REG. NO. #N91TB \$/W 540	 APP 548157621

DATE: 12-27-98

N: N8YX

TACH: 2267.56

PROP: Hartzell HC-C2YK-1BF

S/N: CH 27833

TSPOH: 89.55

Complete Annual inspection. Dress and inspect blades. Inspect spinner, hub, and bulkheads.


I certify that this **PROPELLER** has been inspected in accordance with an **ANNUAL** inspection and was determined to be in an Airworthy Condition.

Larry Hallock
IA521806350




Professional Aircraft Services
4824 Earhart Rd., Loveland, CO 80538
970-679-4633

**DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS**

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
		The New AVEX, Inc. C.R.S. X11R595Y 205 Durley Avenue, Suite A, Camarillo, CA 93010 (805) 389-1188 FAX (805) 389-3323	
		PROPELLER Hartzell HC-C2YK-1 S/N CH27833	N8YX
		Work Order: 3598	Date: 3/20/02
		Tach: 2466.3 Hobbs: TTSN: TSO: 288.3	
		1. Accomplished 100 Hour/Annual inspection per Socata TB20 maintenance manual. 2. 6 year prop overhaul due Jan 2003.	
		This aircraft, airframe, aircraft engine, propeller or appliance was repaired/inspected in accordance with the current Federal Aviation Regulations and is approved for return to service. Pertinent details of the repair are on file at this Repair Station under Work Order No. 3598.	
			 Date
			For: FAA Approved Repair Station # X11R595Y

**DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS**

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
		DATE:3/13/00	HC-C2YK-1BF
		N:8YX	TACH:2369.21
		S/N:CH27833	TSPOH:0191.20
		Inspected propeller blades for condition and dressed as required.	
		Performed visual inspection of hub for cracks. Inspected spinner and	
		bulkheads for cracks. Painted blade tips and face. I certify that this	
		propeller has been inspected in accordance with a 100 Hour Inspection	
		and was determined to be in an airworthy condition. W.O.1132 - END -	
		DANIEL L. INGRAM	VALLEY AIR SERVICE
		IA505904232	Fort Collins, CO 80524
			

**DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS**

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
	DATE:5/4/01 N:8YX	HC-C2YK-1BF S/N:CH27833	TACH:2395.14 TSPOH:0217.13
		Inspected propeller blades for condition and dressed as required.	
		Performed visual inspection of hub for cracks. Inspected spinner and	
		bulkheads for cracks. Painted blade tips and face. I certify that this	
		propeller has been inspected in accordance with a 100 Hour Inspection	
		and was determined to be in an airworthy condition. W.O.1316 - END -	
	DANIEL L. INGRAM	VALLEY AIR SERVICE	
	IA505904232	Fort Collins, CO 80524	
	<i>Daniel L. Ingram</i>		