

HARTZELL

Superseded
PROPELLER LOGBOOK

PROPELLER MODEL HC-DYN-3A

PROPELLER S/N FY331A

LOGBOOK # 1
RH

Date

Propeller
TSN TSO

A/C
Hrs

Description of all operations pertaining to Airworthiness Directives,
Service Documents, Overhaul, Major or Minor Repair, and Inspections.

HARTZELL SERVICE CENTER

5465 W. St. Rt. 185
Piqua, Ohio 45356-2634 U.S.A



August 23, 2007

S/N: FY331A

Overhauled, and assembled propeller. Static balanced, lubricated, and inspected prop assembly. All work was performed in accordance with Hartzell manuals 143A-R12, 127-R2, 133C-R21, 159-R6, 180-R1, 202A (Vol. 1-R31, Vol. 2-R28, Vol. 3-R28, Vol. 6-R29, Vol. 7-R30, Vol. 8-R28, Vol. 9-R28, Vol. 10-R29, Vol. 11-R29) and Hartzell Service Bulletins HC-SB-61-136I, HC-SB-61-215-R4, HC-SB-61-225-R3, HC-SB-61-231, HC-SB-61-235-R1, HC-SB-61-276R4, HC-SB-61-289-R1 and Service Letters HC-SL-61-61Y-R1, HC-SL-61-229, HC-SL-61-234, HC-SL-30-259-R6, HC-SL-30-260-R6, HC-SL-30-261 and Service Instruction 152A. TSN 1612.1 TSO 0.0 Pertinent details of the repair are on file at this agency under Work Order M581810. Certifies that the work specified in Block 12/13 was carried out in accordance with EASA Part-145 and in respect to that work the component is considered ready for release to service under EASA Part-145 Approval Number: EASA.145.4516. ---END-----

Mark Baker, Repairman # 2582389
Repair Station # SJ3R843L

14/9/07	1612.1	00:00	Repaired iaw Hartzell Manuals 143A Rev 12, 159 Rev 6, 180 Rev 1 & 202A (Vol.11 Rev 29)(Vol.7 Rev 30)(Vol. 1 Rev 31). Work carried out by Proptech, under w/o 6304975.
07/10/07	1612.1	00.00	DETAILS TRANSFERRED TO CAR PROPTECH LOG BOOK (CAP 388) (R.A.H. 502) 26.10.07.

OAS
010
PT

R.A.H.
502

Proptech

Proptech,
Nevil Shute Road,
Portsmouth,
Hampshire PO3 5RX,
England

Telephone:
E-Mail:
Facsimile:

+44 (0)23-92 65777
darron_phillips@proptech.info
+44 (0)23-92 65777

THE PROPELLER OVERHAUL & REPAIR SPECIALISTS

Propeller type	Serial Number	Proptech project number	EASA Part 145 Approval. UK.145.01137 FAA Repair Station DM0Y001O BSI Approval LRQ 0920706
HC-D4N-3A/D9383K	FY331A	6304975	

TSN: 1,612.1 Hours.

TSO: 00.00 Hours.

Reported fault.

Assemble propeller & paint Blades iaw AC 83/1997.

Inspection Findings

Propeller Blades painted in standard Hartzell colours.
All other parts inspected and found satisfactory.

Work Carried Out

Propeller assembled.
Blades painted iaw A/C 83/1997.
Propeller balanced, angles set & tested.
All found satisfactory.

FAA AD Satisfied: None.
Service Bulletins embodied: None.
Service Letters embodied: 61-189 Rev 2.
Service Instructions embodied: None.

All repair work carried out IAW Hartzell Manual 143A Rev 12, 159 Rev 6, 180 Rev 1 & 202A (Vol.11 Rev 29)(Vol.7 Rev 30)(Vol. 1 Rev 31).

Pertinent work details of this repair are held on file at this Repair Station under the Proptech Project Number shown above.

Date	Name	Signature	Stamp
14 September 2007	D Phillips	<i>DJ Phillips</i>	