

16146 COVELLO STREET • VAN NUYS, CALIFORNIA 91406 (818) 779-7767 • FAX (818) 779-0848 FAA CRS # EU6R595N



PROPELLER LOGBOOK



Thank You for choosing Executive Propellers, Inc.

WARRANTY

All propellers overhauled by Executive Propellers, Inc. will carry what we believe to be the most comprehensive warranty in the industry.

Executive Propellers, Inc. offers a Full TBO Warranty. This warranty will cover workmanship and parts that were replaced at the time of overhaul.

This warranty entitles purchaser to repairs through Executive Propellers, Inc. only. Assemblies must be accompanied by original Invoice/Work Order or Logbook.

<u> </u>	PROPELLER MAINTENANCE RECORD
Offer you	Propeller Manufacturer: HAUZGU
CHAZICAN STRATEGY	Hub Model No. HC-C3yR-1RF
OK, CK	Hub Serial No.
11, 16,	Blade Model No. F/865-ZR
20	Blade Serial No. 1 49082
228	No. 2 (+31643
CK	No. 3 _ H 51494
V	No. 4
	No. 5
High 32.0°	Low 12.5° PITCH RANGE Feather Reverse
	Governor Manufacturer:
	Governor Model No.
	Governor Serial No.
Maximum Hours or Se	ervice Life between overhaul recommended by Mfg. 2000 Hrs. or Stx
voore whichever com	ero firot

CUSTODY RECORD

Owner		Date Rec'd.
Owner		Date Rec'd.
Owner	1 1 1 1 1 1 1	Date Rec'd.
Owner		Date Rec'd.
Aircraft Installed On:	Make/Model PA 32R-30	Serial # 32R-8013022
	N 35621	

OVERHAUL RECORD

No.	Date	Repair Station and No.	Signature
	7.30.2009	Executive Propellers, Inc.	
4.1	1 1001	FAA CRS # EUSRS95N	
		16146 Cavello Street, Van Nuys CA 91406	, (
		(818) 779-7767	
			Man /
			
		1G .	

SERVICE BULLETINS, SERVICE LETTERS, & MINOR ADJUSTMENTS

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
		PROPELLER COMPLETELY OVERHAULED LAW	220
		HARTZELL SERVICE MANUAL 19 1138, 2024 ;	133c
2 2		ALL A.D.'s AND HARTZELL S.BY AND S.L. A	
.30.009	()	CONGLED WITH TO DETE feel mut Ceffee	-1 /
1	S.D.O. H.	y My struct and on feet	3 <u>1</u>
-	P.V.	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
		the followy lefar flerty.	
4		executive Propellers, Inc.	
5		FAA CRS # EU6R595N 16146 Covello Street, Van Nuys CA 91406	
	y	(818) 779-7767	
1		4 78	
	T:		
1			a On
			1 11 .

DESCRIPTIONS OF ALL OPERATIONS PERTAINING TO AIRWORTHINESS DIRECTIVES, SERVICE BULLETINS, SERVICE LETTERS, & MINOR ADJUSTMENTS

W. 1

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
7-31-09	3419	INSTALLED OVERHAULED	Land
		Prof on N35621 see	AP572868374IA
		Previous entry TesT	
		RAN OK AT THIS	
		Time Approved AIRPLAN	
		Return To service	
7-13-10	3449	TS POH - 30	*
		INSP PROF IAW AN ANNUAL	1 1
,		INSPA FOUND TO BE IN AIR-	de
		WONTHY CONDITION MEST	nav
		See AD'S IN RAP OF BOOK	AP57L868374JA

DESCRIPTIONS OF ALL OPERATIONS PERTAINING TO AIRWORTHINESS DIRECTIVES, SERVICE BULLETINS, SERVICE LETTERS, & MINOR ADJUSTMENTS

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
1-27-13		Propeller Flush out as Aero	Paul Buraus
		Propeller Flush out as Aero Propeller Co. Hemel. Soe	UP2R248 L
		W.0# 6717	
	STATE OF THE PARTY	The Aircraft of Common Live	Carlo de la Carlo
	Inspe	The Aircraft or Component Identified abouted in accordance with current F.A.R. Regulative to service.	ve was repaired and
		11.3 10 0011100:	17810
	Path	ant datable of the repair are on file at this ag-	SUCA RUSSE MOLK
		140. 6717	
	Data	1-27-13	
	₽ gaø	1 Paul Bureaus	10:
		roneller Co. Ins.	VE2B248L
		ensy Hums)	(Gardlicate Isp.)
	510 S.	CAWSTON AVE., HEMET, CA 92546 (Address)	

AIRCRAFTERS, INC. FRENCH VALLEY AIRPORT-F70 37552 WINCHESTER ROAD, BLD 2, SUITE F, MURRIETA, CA 92563 951-304-1292

DATE: 4/15/2013 REG # N35621 MODEL: HARTZELL HC-C3YR-1RF S/N; DY 996 A/C TACH: 3528.0 TSOH: 109.0 WO: 134603

1. INSTALLED THIS PROP BACK ON PIPER N35621 AFTER BEING FLUSHED BY AERO PROPELLER CO, INC. SEE 8130-3 FORM IN THE PROPELLER LOG BOOK.

THIS PROPELLER WAS INSPECTED AND FOR AN ANNUAL INSPECTION AND WAS FOUND TO BE AIRWORTHY FOR RETURN TO SERVICE.

	PROP MODEL: HC-C3YR-1RF PROP S/N: DY996 REG, NO: N35621	Gryphon Aircraft Services, LLC. 37680 Sky Canyon Drive #602	DATE: 5/1/2015 A/C TSN: 3545.4 PROP IT: 3545.4 TSPOH: 17.4 TACH: 3545.4
	WORK ORDER: Murrieta6282-02-2015	Murrieta, CA 92563 Phone: 951-698-4260	
-	Prop Entries		
_	Completed 100 HR II governor.	NSPECTION per GAS form, inspected prop blades and hub, spinner and sp	oinner bulkhead and prop
1 6—3	I Certify that thisPRC	OPELLER has been inspected IAW and 100 hour inspection and was determ enormed IAW applicable service manuals or other approved documentation	nined to be in AIRWORTHY Pertinent details of the repair
	are on file at this rep	air facility under Work Order No. Murrieta6282-02-2015. FAA CRS #2SDR2	271B
-		NO MO	rk Order: Murrieta6282-02-2015
	DATE: 5/1/2015	SIGNED: Wor	NOTORI. Marriela0202-02-2010
	PROP MODEL:	Gryphon Aircraft Services, LLC.	DATE: 7 10, 17
	HC-C3YR-1RF PROP S/N: DY996	37680 Sky Canyon Drive	A/C TSN: 3578 23 PROP TT: 3578 23
	REG. NO: N35621 WORK ORDER:	GRYPHON #602	TSPOH: 50,23
	Murriela8047-07-2017	Murriela, CA 92563 Phone: 951-698-4260	TACH: 3578 23
	Prop Entries		
	Completed 100 HF	R INSPECTION per GAS form, inspected prop blades and hub, spinner and note update sheet and master list for complete AD note history thru this dat	spinner bulkhead and prop te and current revision
	Completed 100 HF governor See AD	R INSPECTION per GAS form, inspected prop blades and hub, spinner and note update sheet and master list for complete AD note history thru this dat ROPELLER has been inspected IAW and 100 hour inspection and was determined	te and current revision

PROP MODEL: HC-C3YR-1RF PROP S/N: DY996 REG, NO: N35621 WORK ORDER: Murrieta9167-10-2018



Gryphon Aircraft Services, LLC.

37680 Sky Canyon Drive #602 Murrieta, CA 92563 Phone: 951-698-4260 DATE: 12/1/2020 A/C TSN: 3584.1 PROP TT: 3584.1 TSPOH: 56.1 TACH: 3584.1

Prop Entries

DAT ——	Condition All work perforn are on file at this repair fa	ned IAW applicable service manuals of othe cility under Work Order No. Marrieta 167-1	ir inspection and was determined to be in AIRWORT experience and was determined to be in AIRWORT experience details of the 10/2018 FAA CRS #2SDR271B. Work Order: Murrieta9167-	
	DATE: 12/1/2020	SIGNED:	Printed by FBis 3 (datcomed	
REM	3584.4 TTAF 35 MOVE SPINNER AND IN CRAFT GROUND RUN, RTIFY THAT THIS PROF	84.4 SMOH 56.3 TSPOH 56 ISPECTED PROP AND HUB ASSY ALL OPS NORMAL AT THIS TIMI PELLER HAS BEEN INSPECTED IN O BE IN AN AIRWORTHY COND	, REINSTALL SPINNER E N ACCORDANCE WITH A 100 HR INSPE NITION AT THIS ȚIME	ECTION