THE OO STATE AIRCRAFT MAINTENANCE MAINTENANCE RECORD RECORD SYSTEM

AVIONICS MAINTENANCE RECORDS Monmouth Area

GARMIÑ.

FAA UNIT SERVICE REPORT

RMA NUMBER

UNIT NAME

GNS430W.Blk,Upgd

SERIAL NUMBER 97131751 UNIT NUMBER 011-01060-40

79905710 SERVICE START DATE

SERVICE
COMPLETION DATE

RETURNED TO SERVICE BY

382

Service Request Number

5/28/2015

6/1/2015

28/2015

UNIT DISCREPANCY WAAS Upgrade

REPAIR SUMMARY

Upgraded unit to include WAAS capability. Repaired the CDU and COM board to correct issues found while upgrading.

Confirmed all applicable hardware modifications are installed. Updated software to the latest version. Aligned unit for optimum performance. Master cleared unit. Unit passes all tests and is operating within normal limits. Unit acquired satellites. OK to return to Service.

The Main and GPS Softwares are at the latest revision. This unit complies with these Service Bulletins 1317, 1461, It is the responsibility of the Installer to verify that the installation complies with the previous listed Service Bulletins. The following Mod's were installed into this unit under its previous configuration prior to it being upgraded and configuration changed to part number 011-01060-40.

This unit complies with MOD 1 per Garmin's Service Bulletin No. 0019.

This unit complies with MOD 2 per Garmin's Service Bulletin No. 0101.

This unit complies with MOD 3 per Garmin's Service Bulletin No. 0203B.

This unit complies with MOD 4 per Garmin's Service Bulletin No. 0207.

This unit complies with MOD 5 per Garmin's Service Bulletin No. 0211.

This "Certifies that the work specified in block 11/12 was carried out in accordance with EASA Part-145 and in respect to that work the component is ready for release to service und TASA Part-145 Approval Number: EASA.145.5534". The work that was performed on this unit was done to meet the Equirements of GNS400W/500W Series WAAS Upgrade Procedure, part number 005-00221-72 and all sections of the Maintenance Manual, part number 190-00364-00 Rev-Q 7/16/2008

On the Garmin website "garmin.com", you will be able to download and receive more detailed information on the difference between the Classic GNS units and WAAS GNS units. A manual dedicated for the new WAAS GNS series units titled "What's New with the 400W/500W series" is available through

http://www.garmin.com/support/userManual.jsp.

For more detailed instructions on the operation of the WAAS GNS 400W500W series, please review the Pilot's Guide for the appropriate units. For your convenience, you will be able to download the Pilot's Guide from the Garmin website. http://www.garmin.com/support/userManual.jsp

Addition to the manuals, you will be able to download the WAAS GNS simulator from the Garmin website as well. Please review the Trainer User Gide for detailed operation instructions on the training simulator.

To receive additional operational information, download the free WAAS Training Video from Garmin website. www.garmin.com

If you have any questions, comments, or need a technical assistance on the GNS series units, please contact Garmin product support specialist at 1-800-800-1020 or e-mail us through Garmin website, www.garmin.com.

Thank You for Choosing Garmin! If you have any questions or concerns please do not he sitate to contact our customer

Warranty Information

Customer Copy

					2 Farm Tracking No.	whor
	approving even	AUTHORIZED REL	EASE CER	TIFICATE	3. Form Tracking Num	поет.
1	Authority/Country:	RMA 79905710				
	FAA/UNITED STATES	FAA Form 8130-3, AIRWO RMIN International 1200 E 151st Olathe, KS 66062	Certificate No. G6XR		5. Work Order/Contra	ct/Invoice Number:
4. Organ	ization Name and Address: GAI	RMA 799				
6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:		11. Status/Work:,
	GNS430W,Blk,Upgd	011-01060-40	1	97131751		REPAIRED
		AAS capability. Repaired the CDU and COM board to correct issues for	und while upgrading.			
to Service The Mai The foll This un This rCa perform On the For mon http://ww Addition To recei If you ha	in and GPS Softwares are at the latest revisioning Mod's were installed into this unit unit complies with MOD 1 per Garmin's Servit complies with MOD 2 per Garmin's Servit complies with MOD 3 per Garmin's Servit complies with MOD 4 per Garmin's Servit complies with MOD 5 per Garmin's Servit complies with MOD 1 per Garmin's Servit complies with MOD 2 per Garmin's Servit complies with MOD 1 per Garmin's Servit complies with MOD 2 per Garmin's S	ice Bulletin No. 0101. ice Bulletin No. 0203B. ice Bulletin No. 0207.	that work the component is responsibility of the Installer in changed to part number 011 that work the component is responsible to the component is support specialist at 1-800-8	to verify that the installation complies we also to verify that the installation complies we also to service under EASA Pations of the Maintenance Manual, part not its and WAAS GNS units. A manual deconvenience, you will be able to downlot for detailed operation instructions on the 00-1020 or e-mail us through Garmin we	art-145 Approval Number: EASA amber 190-00364-00 Rev-Q 7/16/ dicated for the new WAAS GNS so bad the Pilot's Guide from the Gar training simulator.	145.5534". The work that was 2008. eries units titled "What's New min website.
		aced GARMIN units have a 90-day warranty or the continuati	on of the original factory	warranty from the original purchas	se date, whichever is longer.	
13a. Cert	tifies the items identified above w	ere manufactured in conformity to:	14a. 🔀 14 CFR 43	3.9 Return to Service	Other regulations specifie	d in Block 12
	pproved design data and are in condition- on-approved design data specified in		Block 12 was ac	ess otherwise specified in block 12 complished in accordance with Tit ork, the items are approved for retu	le 14. Code of Federal Regula	11 and described in ations, part 43 and in
13b. Au	thorized Signature	13c Approval/Authorization No.: N / A	14b. Authorized Signa	nture:	(2 14c /	Approval/Certificate No.: G6XR582Y
13d Nam	ne (Typed or Printed	13e. Date (dd/mmm/yyyy)	14d. Name (Typed or		14e	Date (dd/mmm/yyyy)
	N / A	N / A		Tu Nguyen	1.0	01 Jun 2015
		User/Install	er Responsibilities			
It is impo	ortant to understand that the existence	e of this document alone does not automatically constitute aut		oft angina/propalla-/a-tiala		
Where th	e user/installer performs work in acc	cordance with the national regulations of an airworthiness authiness authority accepts aircraft engine(s)/propeller(s)/article(s	arity different the of		ry specified in block 1, it is e	ssential that
Statemen	ts in Block 13a and 14a do not const as by the user/installer before the airc	titute installation certification. In all cases aircraft maintanen	ce records must contain	an installation certification issued	in accordance with the nation	nai

US Department
of Transportation Federal Aviation

IB No. 2120-0020	Electronic	Tracking t	E NO

of Transpor	ristion		entries. See Title 14			T. D. and AC A	3.9-1 (or subseq	uent re sion thereof) for in a cital per / for each
	ons and disponantial disponanti	isition of U	Total Tres report is re	quired by	law (49 U.S.	5. §44/01). Pandle to	Toport sair room	, ioi caci
such vio	National	ty and Regis	stration Mark	N Set	Year, BY	Serial No. 28R-7335291		
A !	N55804 Make PIPER					Model	Sei	ries
. Aircraft						PA-28R-200		
		Name (As shown on registration certificate)				Address (As shown of	on registration ce	rtin sate
	Monmouth Area Flying Club					Address P.O. Box 24 City Farmingdale		State N.J.
Owner	major dis pro				Zip 07727 Country U.S. A.			
		-		3. Fc	or FAA Use C	only		
4. Ty	vne			5. U	nit Identifica	ition		
Repair	Alteration	Unit	LANGE TO THE MAN	Make	ne- edit	Mod	del	Serial No.
	Z	AIRFRAM	Elab La	A A	entropy by .	(As described in I	tem 1 above)	90 <u>1 </u>
Ingi	R V D a 8	POWERP	LANT		NO main	Lament for the C	que ternaMu	egif est sele bevi
		PROPELL	ER					ATEN CONTROL
	Mr. I me	APPLIANC	THE RESERVE TO A PARTY OF THE P	mily it.	arman SITC A se woh	Contance with G ATC SAU19331		0387-90 Per D
: d	<i>#</i>	AFFLIANC	Manufacturer		Districted to	o ent lu e 111 a une o	THE REPORT OF	Land Samuran Isla
-	g and the same	Program	n 100 11 0 11 0		nformity Sta		The new text	ments by the contract
	Name and A			В.	Kind of Agen		1 14	nufacturer
-	Crown Avi			- -		tificated Mechanic		ificate No.
1-	ex Airport, 5	3 Kt. 639	State N.J.	- 		Repair Station		
Susse 0746		untry U.S.A		- M		Maintenance Organiz	TXXF	014L
nave b funish rded rar	een made in ed herein is nge fuel	accordance	alteration made to the e with the requiremen rrect to the best of my Signature/Date of Au	knowled	ge.	em 5 above and de S. Federal Aviation R	and the	everse or attachments I that the information
P			Junper	7		m to Service		
rsuant t	o the author	ority given	persons specified b	pelow, th	e unit ident	rn to Service ified in item 5 was Approved	inspected in Rejected	the manner prescribe
F	AA Fit. Stand		on Administration and Manufacturer			Organization		oved by Canadian f Transport
In	spector	-		1	spection Au	thorization	ther (Specify)	
F	AA Designee	X	Repair Station	1 "	specuonina			

NOTICE

Weight and balance or operating limitation changes shall be entered in the appropriate aircraft record. An alteration must be compatible with all previous alterations to assure continued conformity with the applicable airworthiness requirements.

 Description of Work Accomplished (If more space is required, attach additional sheets. Identify with 		
	N55804	June 24 2015
	Nationality and Registration	on Mark Date
Validated that the previous installation of the GNS 43 stamped field approval documented on FAA form 33 equipment are covered under the STC AML.	30 was installed IAW Garmin Ins 7 dated 02-10-2006. Verified tha	tructions and approved via a FA It this aircraft and all interfaced
Removed Following Equipment from the Aircraft. 1. Garmin GNS 430 GPS/COM/NAV/ILS Receiver at 2. Garmin GA 56 GPS Antenna.	nd returned it to Garmin for facto	ory GNS 430W conversion.
Installed after Conversion by Garmin the Following E 1. Garmin GNS 430W GPS WAAS (TSO-C146a) CO F.S.#.57.0.		1933LA) located at
2. Garmin A-35 GPS Antenna located at F.S.#. 98.0	The state of the s	MAN
The GNS 430W was installed as No.1 NAV/COM us existing Garmin GL106 ORS Indicator. The GNS 430	ing the same tray and wiring as t	the previous GNS 430 and the terfaced with the aircraft's
existing Garmin GI-106 OBS Indicator. The GNS 430 Autopilot System. The GA 35 GPS Antenna was instanced also the Flight Manual Supplement for the Manual Supplement. The installation was performed in accordance with G	W is left/right information was in alled on the top of the fuselage a Garmin GNS 430 and replaced in Garmin STC Upgrade Installation	terfaced with the aircraft's It F.S.#. 124.0. It with the GNS 430W Flight Manual Garmin P/N
existing Garmin GI-106 OBS Indicator. The GNS 430 Autopilot System. The GA 35 GPS Antenna was instanced also the Flight Manual Supplement for the Manual Supplement. The installation was performed in accordance with G 90-00357-06 Rev. D. (March. 2008). STC SA019331 Chapter 1, 2, 3 and with AC 20-138B.	W is left/right information was in alled on the top of the fuselage a Garmin GNS 430 and replaced in Sarmin STC Upgrade Installation LA as well as with AC 43.13-1B	terfaced with the aircraft's It F.S.#. 124.0. It with the GNS 430W Flight Manual Garmin P/N
Autopilot System. The GA 35 GPS Antenna was installed and Supplement for the Manual Supplement for the Manual Supplement. The installation was performed in accordance with G90-00357-06 Rev. D. (March. 2008). STC SA019331 hapter 1, 2, 3 and with AC 20-138B. The total electrical load is not exceeding 80% of the general supplement.	W is left/right information was in alled on the top of the fuselage a Garmin GNS 430 and replaced in Garmin STC Upgrade Installation LA as well as with AC 43.13-1B generated capacity.	terfaced with the aircraft's at F.S.#. 124.0. It F.S.#. 124.0. It with the GNS 430W Flight Manual Garmin P/N chapter 10, 11, 12, AC 43.13-2
The GNS 430W was installed as No.1 NAV/COM usexisting Garmin GI-106 OBS Indicator. The GNS 430 Autopilot System. The GA 35 GPS Antenna was installed as the Flight Manual Supplement for the Manual Supplement. The installation was performed in accordance with G90-00357-06 Rev. D. (March. 2008). STC SA019331 hapter 1, 2, 3 and with AC 20-138B. The total electrical load is not exceeding 80% of the GMI and RFI test analyses were performed with no a	W is left/right information was in alled on the top of the fuselage a Garmin GNS 430 and replaced in Garmin STC Upgrade Installation LA as well as with AC 43.13-1B generated capacity.	terfaced with the aircraft's at F.S.#. 124.0. It F.S.#. 124.0. It with the GNS 430W Flight Manual Garmin P/N chapter 10, 11, 12, AC 43.13-2
Autopilot System. The GA 35 GPS Antenna was installed and Supplement for the Manual Supplement for the Manual Supplement. The installation was performed in accordance with G90-00357-06 Rev. D. (March. 2008). STC SA019331 hapter 1, 2, 3 and with AC 20-138B. The total electrical load is not exceeding 80% of the general supplement.	W is left/right information was in alled on the top of the fuselage a Garmin GNS 430 and replaced in Garmin STC Upgrade Installation LA as well as with AC 43.13-1B generated capacity. dverse effect on the aircraft syst	terfaced with the aircraft's at F.S.#. 124.0. It F.S.#. 124.0. It with the GNS 430W Flight Manual Garmin P/N chapter 10, 11, 12, AC 43.13-2 Item noted.
Autopilot System. The GA 35 GPS Antenna was installed autopilot System. The GA 35 GPS Antenna was installed autopilot System. The GA 35 GPS Antenna was installed autopilot System. The GA 35 GPS Antenna was installed autopilot System. The Installation was performed in accordance with Ga 90-00357-06 Rev. D. (March. 2008). STC SA019331 hapter 1, 2, 3 and with AC 20-138B. The total electrical load is not exceeding 80% of the Ga and RFI test analyses were performed with no accordance of Instruction to continued airworthiness Garmaircraft's maintenance records.	W is left/right information was in alled on the top of the fuselage a Garmin GNS 430 and replaced in a Garmin STC Upgrade Installation LA as well as with AC 43.13-1B generated capacity. In diverse effect on the aircraft system of the company of	terfaced with the aircraft's at F.S.#. 124.0. It F.S.#. 124.0. It with the GNS 430W Flight Manual Garmin P/N chapter 10, 11, 12, AC 43.13-2 Item noted.
existing Garmin GI-106 OBS Indicator. The GNS 430 Autopilot System. The GA 35 GPS Antenna was installed a semoved also the Flight Manual Supplement for the Manual Supplement. The installation was performed in accordance with G 90-00357-06 Rev. D. (March. 2008). STC SA019331 hapter 1, 2, 3 and with AC 20-138B. The total electrical load is not exceeding 80% of the Gamman of the seminary of the se	W is left/right information was in alled on the top of the fuselage a Garmin GNS 430 and replaced in Garmin STC Upgrade Installation LA as well as with AC 43.13-1B generated capacity. dverse effect on the aircraft system Document 190-00356-65 Respectively.	terfaced with the aircraft's at F.S.#. 124.0. It F.S.#. 124.0. It with the GNS 430W Flight Manual Garmin P/N chapter 10, 11, 12, AC 43.13-2 Item noted.
existing Garmin GI-106 OBS Indicator. The GNS 430 Autopilot System. The GA 35 GPS Antenna was installed a semoved also the Flight Manual Supplement for the Manual Supplement. The installation was performed in accordance with G90-00357-06 Rev. D. (March. 2008). STC SA019331 hapter 1, 2, 3 and with AC 20-138B. The total electrical load is not exceeding 80% of the garman of the seminary of the se	W is left/right information was in alled on the top of the fuselage a Garmin GNS 430 and replaced in Garmin STC Upgrade Installation LA as well as with AC 43.13-1B generated capacity. dverse effect on the aircraft system Document 190-00356-65 Respectively.	terfaced with the aircraft's at F.S.#. 124.0. It F.S.#. 124.0. It with the GNS 430W Flight Manual Garmin P/N chapter 10, 11, 12, AC 43.13-2 Item noted.
existing Garmin GI-106 OBS Indicator. The GNS 430 Autopilot System. The GA 35 GPS Antenna was installed a semoved also the Flight Manual Supplement for the Manual Supplement. The installation was performed in accordance with G90-00357-06 Rev. D. (March. 2008). STC SA019331 Appter 1, 2, 3 and with AC 20-138B. The total electrical load is not exceeding 80% of the GMI and RFI test analyses were performed with no accopy of Instruction to continued airworthiness Garmaircraft's maintenance records. Log Book entry was made this date. Flight test was petall of this work is filed at this repair station under Vertical Continued airwork is filed at this repair station under Vertical Continued airwork is filed at this repair station under Vertical Continued airwork is filed at this repair station under Vertical Continued airwork is filed at this repair station under Vertical Continued airwork is filed at this repair station under Vertical Continued airwork is filed at this repair station under Vertical Continued airwork is filed at this repair station under Vertical Continued airwork is filed at this repair station under Vertical Continued airwork is filed at this repair station under Vertical Continued airwork is filed at this repair station under Vertical Continued airwork is filed at this repair station under Vertical Continued airwork is filed at this repair station under Vertical Continued airwork is filed at this repair station under Vertical Continued airwork is filed at this repair station under Vertical Continued airwork is filed at this repair station under Vertical Continued airwork is filed at this repair station under Vertical Continued airwork is filed at this repair station under Vertical Continued airwork is filed at this repair station under Vertical Continued airwork is filed at this repair station under Vertical Continued airwork is filed at this repair station under Vertical Continued airwork is filed at this repair station under Vertical Continued airwork is filed at this repair station under Vertic	W is left/right information was in alled on the top of the fuselage a Garmin GNS 430 and replaced in Garmin STC Upgrade Installation LA as well as with AC 43.13-1B generated capacity. dverse effect on the aircraft system Document 190-00356-65 Respectively.	terfaced with the aircraft's at F.S.#. 124.0. It F.S.#. 124.0. It with the GNS 430W Flight Manual Garmin P/N chapter 10, 11, 12, AC 43.13-2 Item noted.
existing Garmin GI-106 OBS Indicator. The GNS 430 Autopilot System. The GA 35 GPS Antenna was installed a semoved also the Flight Manual Supplement for the Manual Supplement. The installation was performed in accordance with G90-00357-06 Rev. D. (March. 2008). STC SA019331 Appter 1, 2, 3 and with AC 20-138B. The total electrical load is not exceeding 80% of the GMI and RFI test analyses were performed with no accopy of Instruction to continued airworthiness Garmaircraft's maintenance records. Log Book entry was made this date. Flight test was petall of this work is filed at this repair station under Vertical Continued airwork is filed at this repair station under Vertical Continued airwork is filed at this repair station under Vertical Continued airwork is filed at this repair station under Vertical Continued airwork is filed at this repair station under Vertical Continued airwork is filed at this repair station under Vertical Continued airwork is filed at this repair station under Vertical Continued airwork is filed at this repair station under Vertical Continued airwork is filed at this repair station under Vertical Continued airwork is filed at this repair station under Vertical Continued airwork is filed at this repair station under Vertical Continued airwork is filed at this repair station under Vertical Continued airwork is filed at this repair station under Vertical Continued airwork is filed at this repair station under Vertical Continued airwork is filed at this repair station under Vertical Continued airwork is filed at this repair station under Vertical Continued airwork is filed at this repair station under Vertical Continued airwork is filed at this repair station under Vertical Continued airwork is filed at this repair station under Vertical Continued airwork is filed at this repair station under Vertical Continued airwork is filed at this repair station under Vertical Continued airwork is filed at this repair station under Vertical Continued airwork is filed at this repair station under Vertic	W is left/right information was in alled on the top of the fuselage a Garmin GNS 430 and replaced in Garmin STC Upgrade Installation LA as well as with AC 43.13-1B generated capacity. dverse effect on the aircraft system Document 190-00356-65 Respectively.	terfaced with the aircraft's at F.S.#. 124.0. It F.S.#. 124.0. It with the GNS 430W Flight Manual Garmin P/N chapter 10, 11, 12, AC 43.13-2 Item noted.
Autopilot System. The GA 35 GPS Antenna was installed a system. The GA 35 GPS Antenna was installed a system. The GA 35 GPS Antenna was installed a system of the Manual Supplement of the Manual Supplement. The installation was performed in accordance with Ga 90-00357-06 Rev. D. (March. 2008). STC SA019331 hapter 1, 2, 3 and with AC 20-138B. The total electrical load is not exceeding 80% of the Game of the Manual RFI test analyses were performed with no analyse of the copy of Instruction to continued airworthiness Game of the Game of the Manual Supplement. Accopy of Instruction to continued airworthiness Game of the Game	W is left/right information was in alled on the top of the fuselage a Garmin GNS 430 and replaced in Garmin STC Upgrade Installation LA as well as with AC 43.13-1B generated capacity. dverse effect on the aircraft system Document 190-00356-65 Respectively.	terfaced with the aircraft's at F.S.#. 124.0. It F.S.#. 124.0. It with the GNS 430W Flight Manual Garmin P/N chapter 10, 11, 12, AC 43.13-2 Item noted.

Additional Sheets Are Attached

Instructions for Continued Airworthiness GDL 84/88 Part 23 AML STC

as installed in

PIPER PA-28R-200

(Make and Model Airplane)

Reg. No. <u>N55854</u>

S/N 28R 7335791

Dwg. Number: 190-01310-01 Rev. 3

Garmin International, Inc. 1200 E. 151st Street Olathe, Kansas 66062 USA

Record of Revision

Rev.	Date	Description of Change
1	11/21/2012	Initial Release
2	1/7/2015	Updated to add GDL 84
3	10/22/2015	Update to add Flight Stream
		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
- 1		

Approving Civil Aviation Authority/Country:	AUTHORIZED REI FAA Form 8130-3, AIRWO	LEASE CER' ORTHINESS APPRO	FIFICATE OVALTAG	RMA 8263	39879
FAA/UNITED STATES	ARMIN International 1200 E 151st Olathe, KS 66062	Certificate No. G6XR5	32Y	5. Work Order/Contract RMA 8263	00 Nov. 2000 192
4. Organization Name and Address: G.	ARMIN International 1200 E fores		10 G to 1 Normalism	RWIN 0203	11. Status/Work:
6. Item: 7. Description:	8. Part Number:	9. Quantity:	10. Serial Number: 83715384		REPAIRED
1. GTX327	011-00490-00 Repaired CDU to correct return issue. Confirmed all applicable hardways	are modifications are installed.	Updated software to the latest version. Alig	med unit for optimum performa	nce. Unit passes all tests and
This unit complies with this Service Bulletin 0809,	. It is the responsibility of the Installer to verify that the installation com	iplies with the previous listed 5	A VICE BUILDING.	145 Approval Number: FASA	145 5534" The work that was
This "Certifies that the work specified in block 11/	12 was carried out in accordance with EASA Part-145 and in respect to	that work the component is rea 4-00 Rev- AL, Revision Date 5	22/2015.	rw.garmin.com for any update of	or product information.
Thank You for Choosing Garmin! If you have any	questions or concerns please do not hesitate to contact our customer ser	rvice department at 1-800-800-	020. Please view Gaining wee site at win	, ,	
All repaired or re	placed GARMIN units have a 90-day warranty or the continu-	ation of the original factory	warranty from the original purchase	date, whichever is longer.	
	were manufactured in conformity to:			Other regulations specific	
	The state of the section of the sect		ess otherwise specified in block 12, t		
Approved design data and are in con	dition for safe operation	Block 12 was ac	complished in accordance with Title	14, Code of Federal Regu	lations, part 43 and in
Non-approved design data specified	in block 12		ork, the items are approved for return		
13b. Authorized Signature	13c Approval/Authorization No	o.: 14b. Authorized Sign	iture:	14c	Approval/Certificate No.:
N / A	N / A		Whoth X. a.		G6XR582Y
13d Name (Typed or Printed	13e. Date (dd/mmm/yyyy)	14d. Name (Typed or	Printed)	14e	Date (dd/mmm/yyyy)
N / A	N / A		Wathana Syhavong	\cup	22 Sep 2015
	User/Insta	aller Responsibilities			
It is important to understand that the exis	tence of this document alone does not automatically constitute		aft engine/propeller/article		
Where the user/installer performs work is	accordance with the national regulations of an airment in an	the a wite . different them the	imuanthinasa authanitu af tha acuntmi	specified in block 1, it is e	essential that
diat mario and	constitute installation configuration. Let U	le(s) from the Airworthines	Authority of the country specified in	ı block 1.	

3. Form Tracking Number.



FAA UNIT SERVICE REPORT

RMA NUMBER

UNIT NAME

82639879

GTX327

SERVICE START DATE SERVICE COMPLETION DATE

9/22/2015

9/22/2015

SERIAL NUMBER

83715384

RETURNED TO SERVICE BY

1304

UNIT NUMBER

011-00490-00

Service Request Number

UNIT DISCREPANCY

IDENT key is INOP. Test, repair, and update as needed.

REPAIR SUMMARY

Confirmed the return issue. Repaired CDU to correct return issue. Confirmed all applicable hardware modifications are installed. Updated software to the latest version. Aligned unit for optimum performance. Unit passes all tests and is operating within normal limits. OK to return to Service.

This unit complies with this Service Bulletin 0809, . It is the responsibility of the Installer to verify that the installation complies with the previous listed Service Bulletins.

This "Certifies that the work specified in block 11/12 was carried out in accordance with EASA Part-145 and in respect to that work the component is ready for release to service under EASA Part-145 Approval Number: EASA.145.5534". The work that was performed on this unit was done to meet the requirements of all sections of the maintenance manual part number 190-00364-00 Rev- AL, Revision Date 5/22/2015.

Thank You for Choosing Garmin! If you have any questions or concerns please do not hesitate to contact our customer service department at 1-800-800-1020. Please view Garmin's web site at www.garmin.com for any update or product information.

FAA Approved Product

This appliance has been repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service. The details of the repairs to this appliance are on file at this repair station under the above listed RMA Number

Wathana Sylvayong
FAA Certified Repairman

9/22/2015

Date

3158270

Certificate Number

FAA Repair Station Number G6XR582Y

Warranty Information



AVIONICS MAINTENANCE RECORDS

(including transponder blennial checks)

WEED AL.	Log No.
Aircraft Registration No. N55894	
Aircraft Manufacturer P/Par Model PA 28R-200	
Model 28R-7335291	

EQUIPMENT LISTING

List all installed avionics, autopilot and flight director equipment.

Mfg.	Model	Serial No.	
1			
2			
3			
4			
5			
6			
7			
8	and the same of th		
9			
10			
11			
12			
13		manager and a second second second	
14		A Control of the Control	
15		3 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	- 1 1
16	SON PREPRINCE		
17		1637 344	
18		The state of the second	
19			
20		12 (1 to 1 t	



AROTECH PUBLICATIONS INC. www.adlog.com PO BOX 1359 / SOUTHOLD, NY 11971-0965



MID-CONTINENT INSTRUMENTS CO., INC.

9400 E 34TH ST. NORTH WICHITA, KS 67226 FAA CRS OL2R061L

WRK0057967 May 13, 2005,

		Final	Work Order			T AR#
Nomenclature ALTIMETER 20K	,	Serial No 74727	Location KS	RMA # RMA000000723	27	10654
Manufacturer's Part No. 5934P-A.56		Model No. C661071-010	1	Quantity 1		
Manufacturer UNITED		Customer Item	Number	Service Period		
Customer OCEAN AIRE		Customer PO N 55804	lo.	Customer Reference	ce No.	
Reason For Removal PLEASE REPAIR	est per	*		u Norwa Portuga Norwa	The page of	
Work Instructions Warranty Repair Functional Test	D Y	n As Is	Special Instructions			
reliminary Inspection Seals Broken No Nameplate Damage	Cover Damaged	No	Hidden Damage Inspection	on Required No		
Preliminary Inspector E	BOBBY PHILLIPS			, c	Date N	May 13, 2005
	OF CALIBRATION. Installed: AD 74-24-13		Custome	r Complaint Verified		
ork Accomplished	7.0 74-24-13).				
REPAIRED AS NECE	SSARY, TESTED TO MF PARTS 91.411 & 43, APF	G. SPEC. PENDIX E.				
		- A				
I.A.W Manual # TM- Outgoing Service Bullet	5934 REV 1 7/1/02 ins AD 74-24-13.		19			*
Technician	CAROLYN DURHAM	1 4	1 13		Date	May 17, 2005
In-Process Inspector	PHONG NGUYEN	lana (A			Date	May 17, 2005
FINAL INSPECTOR	RANDALL FERGUSON	samalel	K. Sum		Date	May 18, 2005
Parts Used			/			

Part Number 34-1-24 4011557 1114-301507 Part Description **GASKET** O RING **POINTER A.57**

Quantity

1 1

MID-CONTINENT INSTRUMENTS

Altimeter Scale Correction Card

Altimeter S/N 7472 Part No. 59349-A3

Reference Altitude in Ft.	Altimeter Reads	Reference Altitude in Ft.	Altimeter Reads
-1000	-1000	14000	14000
0	-5-	15000	15020
500	495	16000	16040
1000	990	18000	18085
1500	1490	20000	20100
2000	1995	22000	e e
3000	2995	25000	
4000	4000	30000	
5000	5005	35000	
6000	6005	40000	
8000	8000	45000	
10000	10000	50000	
12000	11985		

Tested By:

311633

Inspector:

ROD

Date:

5/18/05



9400 E. 34th St. North Wichita, KS 67226 USA Tel 800-821-1212 • 316-630-0101 FAA Repair Station # OL2R061L



16320 Stagg Street Van Nuys, CA 91406 USA Tel 800-345-7599 • 818-786-0300 FAA Repair Station # OL2D061L

inent Instrument Co.

34th Street North

O C10b

et)

20

20

20

20

25

30

30

35

35

40

60

80

90

100

100

110

120

130

± | Friction

Tol.

(Feet)

70

70

70

70

70

70

70

70

70

70

70

80

80

80

90

90

90

100

KS 67226 1-800-821-1212

Certified Repair Station No. OL2 R061L

ALTMTR.

READING \

NO VIB.

-975

-30

470

970

1,470

1,970

2,975

3,975

4,980

5,975

7,965

9,970

11,950

13,965

14,975

16,000

18,030

20,050

FRICTION

FINAL

READING

W/VIB.

-1,000

-5

495

990

1,490

1,995

2,995

4,000

5,005

6,005

8,000

10,000

11,985

14,000

15,020

16,040

18,085

20,100

±

TOL.

(Feet)

25

25

25

20

20

25

20

25

25

30

35

30

FAR PART 43 APPENDIX-E **COMPLIANCE REPORT**

CHG. PT. OF	Test type
ENCODER	W.O. Nu
Tol. 125 ' WITH REF. TO	Part Nui
ALTIMETER IND.	Serial N
	1
	1. VIS
1,	2. PC
	3. C
	→ 4. H
	7
0	7
	\neg
25 25	\neg
	5.
30	一 6.
35	\neg
30	\neg
35	\neg
35	
40	
55	
50	
-30	
4	

Test type:	Standard Altimeter	Tested Through:	20,000 '
------------	--------------------	-----------------	----------

57967 umber:

5934P-A.56 mber:

Number: 74727

Good SUAL EXAMINATION:

10 OSITION ERROR (Tol. \pm 20 '):

-10 ASE LEAK (Tol. ± 100 ' / min.):

ALTIMETER READS YSTERESIS (Tol. ± 75 '):

	UP	DOWN
40% - 8,000 '	8,000 '	8,020 '
50% - 10,000 '		10,025 '

AFTER EFFECT (Tol. ± 30 '): 5

BAROMETRIC SCALE ERROR (Tol. ± 25 ')

Ŭ.	NAD	IN HG	FEET		RANGE	READINGS
\vdash	MB			1	(-1,702 / -1,752)	-1,725
F	951.6		1	T	(-1,315 / -1,365	
1	965.1	28.50	-1,34	<u>ot</u>		1
	982.	29.0	-88	33	(-838 / -88	
	999.	The State of the S	0 -39	2	(-367 / -417	7) -400
		-		ol	(-25 / +25	i) -
	1013.			_	(+506 / +556	530
	1032.		*	\neg	(+868 / +918	
	1046.	4 30.9		\dashv		/
	1049	.4 30.9	9 +97	4	(+949 / +999)] 9/3

No 7. Lighting:

No 8. Alerter Output:

9. Check for Master Altimeter: No

9a. Calibrated: No

^{*} Took Readings after 50,000 feet

SERVICE	TIME IN SERVICE	
(A 5 / 1 / 1 / 1 / 1 / 1 / 1 / 1 / 1 / 1 /	DEHAICE	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK Altimeter Log Description
		Altimot
		Altimeter Log Book Entry Reg # 55 804
		Reg # 55 809 Date 05 - 2 - 05 Make Pie, Model PASAR - 200 The Aircrat Static System was tested and found to make The Aircraft System was tested and
		S/N 7335251 Model PAZAR - 200
		The Aircrat Static System 1125/. /
	CASS I	The Aircrat Static System was tested and was found to meet FAR 91.411. The Usited System Prior S/N 389804
		Altimeter Make/Model Onit Sysylv 3 Pilot S/N 389804
		20,000 was tested to FAR PART 43 Appendix E. Details of this in the second second to meet
		Details of this inspection
		Repair Station under WO# 0253 FAA Cert #0F1P373W
		FAA Cert. #OF1R372K Signed Signed
		Signed William Sellar
		Ocean Aire, P.O.Box 1245
		Toms River, NJ 08754
56		
	Trai	nsponder Log Book Entry ————
	Reg	# 55804 Date 5-2-05 ke Piper Model P4 28k-200
	Mak	Ke Piper Model P4 28R-200
		733525/ Tach/Hobbs 251.1
100		Transponder Make/Model Garnia GTX327011-004000
	S/N_	837/5384 was tested and inspected
		equired by FAR 91.413. Tested to specs using
		Ramp tester ATC 601.
		ails of this inspection are on file at this air Station under WO# 025 3
1		
1	Sign	Cert. #OF1R372K
1		an Aire, P.O.Box 1245
LT	Tom	s River, NJ 08754
17		
1.1		
BOS FACE		
03504	A COLUMN TO SERVICE STATE OF THE PARTY OF TH	
M	RE	Moved Lormen ALTIM ETER. INSTALL OPIGIAN,
M	The RE	Flores ALT IM ETER. INGTALLER OFFICE
M		
X	1	EAR Cheld of FAR 91.411.
1	17	12 1411. A 11/h
	1	Vorall H. Genebery
	1	OFIR372K
		OFID31.LK

ATE 2006	AIRFRAME TIME IN SERVICE	AVIONICS TIME IN SERVICE	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
0-06			
	12456	Date	e: 02-10-06 Reg. N55804 Model: Piper 28R-200 S/N:28R-7335291 Tach. 0515.3
		Rem	oved King KX-170B NAV/COM King KI-208 NAV Indicator, Garmin GPS 150XL GPS
		Rece	eiver, Bendix ADF-T-12C Receiver and Model 551RL ADF Indicator.
	Market 1	Inst	talled Garmin GNS 430 GPS/COM/VOR/ILS and GI 106A VOR/ILS Indicator.
		The	GNS 430 was installed below the existing King KA-134 Audio Panel and connected
W. 442	Section 1	to t	the GI 106A OBS Indicator, as well as to the existing Centery II Autopilot.
	The state of the s	The	GNS 430 was also connected to the existing Garmin GTX 327 Transponder. installation was performed i.a.w. Garmin installation manuals 190-00140-02
	ACRES OF	Rev.	Q (Oct. 5).and 190-0180-00 Rev.B (July 99), as well as with AC 43.13-1B
and the second		chan	ter 10, 11, 12, AC 43, 13-2A chapter 1, 2, 3, and AC 20-13B. The Century
		Flio	ht System's drawing No. 63D358 was also used as reference. Performed data
		corr	espondence test to 18,000 feet and found the error not exceeding 123 feet.
		File	d Form 337 with ICA this date.
		Upda	ted the Weight and Balance as well as the Equipment List.
		A dec	cal " GPS LIMITED TO VFR USE ONLY " was attached on the instrument panel. ils of this work is filed at Three Crown Avionics Inc. C.R.S. # TXXR014L
			Work Order No. 04671.
		Autho	prized Signature for Three Crown Avionics, Inc. C.R.S. # TXXR014L
			- pupul
		Atter	ntion: Do not Strip or Paint the GPS Antenna.
			Transponder Log Book Entry
			Reg # 55 804 Date 6-1-07
			Make first Model 14 28 R-200
9.50	No. and Associated the State of		S/N 7335291 (Tach) \$65.6
			The Transponder Make/Model 6-Arm w 6733-7
			S/N 8371 5384 was tested and inspected
			as required by FAR 91.413. Tested to specs using
			IFR Ramp tester ATC 601.
			Details of this inspection are on file at this
- 500			Repair Station under WO#
			FAA Cert. #9F1R37/2K, //
			Signed Novald HD eneberg
			Ocean Aire, P.O.Box 1245
			Toms River, NJ 08754
STATE OF THE PARTY	CONTRACTOR OF STREET		

	TIME	SERVICE	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
6-1-07	Trut		Bemarel ALT
			Removed perimenge 5935 P-A56 5W 74727 INSTAURA 30EVICE pole Refused Actimental P[N5934P.A56 9W 73672 TEGTER 379TEM FOUND TO MEET 5 POCS IN FIRE PO
			PLN 5934PACC
			FOUND TO MOST SPOCS IN FAR Q1.411
			1 Mary 3 POCS IN FAR 91.411
			onale of Dearles
S			OFIR 372K
(CL)			
			Date: 06-20-06 Reg. N55804 Model: Piper PA-28R-200 S/N 28R-7335291
			Class A1.
			Prepared flight manual supplement for the installed Garmin GNS 430 GPS
			Flight test was performed by the customer/pilot and ground by the inspector Filed Form 227 with any
4			Details of this work is filed at Three Crown Avionics, Inc. C.R.S. # TXXR014L
	A SECTION		
			Authorized Signature for Three Crown Avionics, Inc. C. R. S. MOXRO14L
			- fufue f
136		400	
128	12 2	4384	CONTRACTOR OF THE PARTY OF THE
	-		
-			
		100	
		4	
		-	
		-	
			5
			- p-2

AIRFRAME

AVIONICS

Page No.

DATE	AIRFRAME TIME IN SERVICE	AVIONICS TIME IN SERVICE	Page No.
-24-15			DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
	GPS An The insta SA0193 Replaced Filed Fo	tenna was replaced allation was perfected allation was perfected al. A., as well as well as the Flight Perm 337. No change of this work is filed	155804 Model: Piper PA-28R-200 S/N: 28R-7335291Tach: 2260.7 130 GPS/Com/Nav./ILS, and GA 56 GPS Antenna. 130 as upgraded to a GNS 430W (P/N 011-01060-40) and reinstalled in same tray. The GA 56 certain distribution of the second of the se
		4	
	The GDL-88 GNS 430 W. Mod.C Seria The installat SA02119SE, Updated the A Form 337 Details of thi	B was hooked up AAS GPS, GTX lizer, the GDL-8 ion was performe, as well as with Weight and Bala for this work wa is work is filed a	automatic Dependent Surveillance broadcast system on the equipment shelf at F.S.# 188.0, as on the bottom of the fuselage at F.S.# 209.0 and an Northstar Aviation Mod.C serializer. to the AV-74 Antenna and interfaced with the following existing equipment: Garmin 327 Transponder and also with the existing Trans-Cal SSD120-3A Encoder through 38 Audio was connected to the existing Audio Panel. ed i.a.w. Garmin Installation Manuals P/N 190-01310-00 Rev. 8. and the STC AC 43.13-2A chapter 2 Section 202. ance as well as the Equipment list. as filed on this date. It Three Crown Avionics Inc. C.R.S. # TXXR014L under Work Order # 06541.
_	, idanomico d		
			· · · · · · · · · · · · · · · · · · ·
			1

DATE	AIRFRAME TIME IN SERVICE	AVIONICS TIME IN SERVICE	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
Reg # Make S/N2 The A found Altime S/N4 and w Detail Repai	ircraft Static Sto meet FAR ster Make/Mod 10 409 ras found to make of this inspection of this inspection under the station under the sta	Model PA-2812- If Tach Hobbs 470 yestem was tested and yestem was tested and yestem was tested and yestem was tested to 20,000 eet FAR PART 43, Approximate the yestem was tested to 20,	was S/N 28 - 7335 271 Tach (Hobbs) 470.1 The Transponder Make Model was tested and inspected as required by FAR 91.413. Tested to specs using IFR Ramp tester ATC 601. Details of this inspection are on file at this Repair Station under WO # 17 - 3 865 FAA Cert. #0F1R372K Signed B 2 Matter Cocoan Aire, PO Box 1245 Toms River, NJ 08754
Reg # N 5 Make P1 Make	7535291 Ta ft Static Syster eet FAR 91.41 lake/Model was und to meet F his inspection tion under WO FOF1R372K	ate 6-12-2019 Indel 79288-200 In was tested and was In the 1-1-1 In tested to 20,000 AR PART 43, Appendiate on file at this # 19-46/5	as required by FAR 91.413. Tested to specs using IFR Ramp tester ATC 601. Details of this inspection are on file at this Repair Station under WO # 17 - 46 15 FAA Cert. #OF1R372K Signed Ocean Aire, PO Box 1245, Toms River, NJ 08754

OCEAN AIRE CRS # OF1R372K ALTIMETER TEST FORM ATS REVISED: 8/16/2017

	FAR 43 APPENDIX E ALTIMETER TEST			7
	AIRCRAFT # N N 55804	ALTIMETER P/N: United 5934P-3 ALTIMETER S/N: 470409	ADC P/N: N/A	-
- 1	DATE: 6-12-2019	MAX ALTITUDE PER POH 20 000	,	

			MAX ALTITUDE P	ER POH:	0,000			
REFERENCE	ALT TOL +/-						ACT	JAL
ALTIMETER SETTING	(IN	AIRCRAFT SYSTEM	ALT REPORTING	FRICTIO	CASE LEAK	+/- 100	o' -8	
OLITING	FEET)	TEST	INTEGRATION TEST *	N TOL +/-	HYSTERISIS, 50%	+/- 75'		
		READINGS ACTUAL	(PRESSURE	(IN	HYSTERISIS, 40%	+/-75'		
-1000	20	-1006	ONLY)	FÈET)	AFTER EFFECT	+/- 30	' +2	
0	20	-1000	The Market Control					
500	20	500	0				t	1.05
1000	20		A Cities 2		BARO SCALE ERROR	-25	ACTUAL	+25
1100		1008		(70) 15	28.1 (-1727)	-1752	-1720	-1702
1500	20	1500	1100	100	28.5 (-1340)	-1365	-1340	-1315
1800		1300			29.0 (-863)	-888	- 860	-838
2000	30	2010	1800		29.5 (-392)	-417	-390	-367 +25
3000	30	3010		(70)15	29.92 (0)	-25	0	+556
4000	35	4010		(70)10	30.5 (531)	+506	530	+918
5000		7010	The second second		30.9 (893)	+868	910	+916
6000	40	6000		(70)15	30.99 (974)	+949	990	+999
6800			48.00					INITIAL
8000	60	8000	6800			-DOM		INTTIAL
10000	80	10000		(00)	ENSURE FREEDOM			
12000	90	12000		(80) 15	ENTRAPPED MOISTURES RESTRICTIONS	JKE AND		WB
14000	100	14000		13.25 top (1)		INITIMITO		
14800			14860		SYSTEM LEAK WITH 23.1325 OR 25.1325	IN LIMITS	FAR	ws
15000	No. of Control of Control		(1000	(90) 20	STATIC PORT HEAT			
16000	110	16020		(90) 20	(IF APPLICABLE)	EK WORK	5	
18000	120	18060		1	(II AFFLICABLE)			
20000	130	20120		لر (100)				N/A
22000	140	NIA		(100)	3			
25000	155	1177	Tradition of the	(120)Nb				
30000	160			(140)	ENSURE NO ALTER	ATIONIO		
30800			NIT	(140)	DEFORMATIONS OF	A HONS O	K	
35000	205			(160)	WOULD AFFECT TH	WC SURI	ACE	
	230			(180)	STATIC AIR RELATI	ONCLUD		w
	255				Z Z Z Z Z Z Z Z Z Z Z Z Z Z Z Z Z Z Z	CINSHIP		
The state of the s	280			(250)	469			

*PRESSURE ALTITUDE REPORTING MUST BE WITHIN +/- 125' OF A/C ALTIMETER

	STICKED AFFIXED TO MOTO	INITIAL
NOTES:	STICKER AFFIXED TO INSTRUMENT	uz
	DATE 6-12-2019	SIGNATURE
· *)	TECHNICIAN	Villes Bland
<i>*</i>	SUPERVISOR	
DEV 1 0/20/2017	INSPECTOR	Villa Bollen

REV 1 9/30/2017

Ocean Aire

	CRS # OF1R372K
ATCRBS Transp	oonder worksheet
Date: 6-12-2	019
Work Order: 19	
Aircraft N: N55	
Type: PA18R	1-200
#1 Xpndr	
#1 p/n: _ GTX 3	27
#1 s/n: 83713	5384
#2 Xpndr	
#2 p/n:	
#2 s/n:	
Preliminary Inspection	on by:
	•

TEST	TOLERANCE	# 1	#2
Radio Reply Frequency	1090 ± 3 Mhz	Mhz (087.12	Mhz
Radio Frequency Peak Output Power	Min, Class 1A: 125 Watts Class 1B: 70 Watts Mex, 500 Watts	Watts	Watts
Receiver Sensitivity	-73 ± 4 dbm Additional 3 dB loss allowed w/ portable test equipment measuring a radiated signal	-75 dbm	dbm
MTL Difference	Mode 3A and Mode C receiver does not exceed 1 dbm	0.0	· db
Suppression Interrogation Rate 235 ± 5 Hz PRF at 4 db higher than MTL	Maximum of 3 replies per second when P2 = P1. Minimum of 212 replies per second when P2 is 9 db less than P1	Pass Fell Pass Fall	Pass Fail Pass
Altitude Reporting ON		Pass Fail Pass	Pass Fail Pass
OFF	Only F1 and F2 transmitted	Pall	
Identification	Check ID annunciation is displayed for approx. 20 seconds.	Pass	Pas

Form Instructions:
Technician will use ATCRBS Transponder test box and insert results for each test in appropriate Box and/or indicate "Pass/Fail" as required.

N/A will be inserted where item is not applicable.

Technician: William Bollan Inspector: ___

Ocean Aire

CRS # OF1R372K

ATCRBS Transponder worksheet

Date: 5/20/2021

Work Order: 21- 5846

Aircraft N: N.55804

Type: P.Per PA-28K-200

#1 Xpndr Garmin GTX 327.

#1 p/n: 011-00490-00

83715384

#2 Xpndr

#2 p/n:

#2 s/n:

Identification

TEST

Radio Reply Frequency

Radio Frequency

Peak Output Power

Receiver Sensitivity

MTL Difference

Suppression

MTL

ON

OFF

Interrogation Rate

235 ± 5 Hz PRF at

4 db higher than

Altitude Reporting

Technician will use ATCRBS Transponder test box and insert results for each test Form Instructions: in appropriate Box and/or indicate "Pass/Fail" as required.

#2

NM

Vatts

dbm

db

ass

Fail

888

Fail

Pass

Fail

Pass

Fall

Pass

Fail

1090.23

23 Vatts

-72.6

-0.1

dbm

Pass

Pass

Pass

N/A will be inserted where item is not applicable.

seconds.

than P1

TOLERANCE

Min. Class 1A: 125 Watts

portable test equipment

does not exceed 1 dbm

second when P2 = P1.

Maximum of 3 replies per

Minimum of 212 replies per

second when P2 is 9 db less

Only F1 and F2 transmitted

Check ID annunciation is

displayed for approx. 20

Class 1B: 70 Watts

Additional 3 dB loss allowed w/

measuring a radiated signal

Mode 3A and Mode C receiver

1090 ± 3 Mhz

Max. 500 Watts -73 ± 4 dbm

Preliminary Inspection by:

No defects notes

Technician: Bt With

Inspector: 1st

OCEAN AIRE CRS # OF1R372K ALTIMETER TEST FORM ATS REVISED: 8/16/2017

FAR 43 APPENDIX E ALTIMETER TEST	United		
	ALTIMETER P/N: 5 974 P-3	ADC P/N:	NIA
AIRCRAFT # N N 55804	ALTIMETER S/N: 470409	ADC S/N:	NIA
WORK ORDER # 21- 5846		ADO SIN.	
DATE: 5/20/2021	MAX ALTITUDE PER POH: 20,000		

	ALT							ACT	UAL
REFERENCE ALTIMETER	TOL +/- (IN	AIRCRAFT	ALT REPORTING	FRICTIO	CASE	LEAK	+/- 10	0' -1	2
SETTING	FEET)	SYSTEM TEST	INTEGRATION TEST *	N	HYSTE	RISIS, 50%	+/- 75	42	24
		READINGS	(PRESSURE	TOL +/- (IN		RISIS, 40%	+/-75		
1000	A/2	ACTUAL	ONLY)	FEET)	AFTER	EFFECT	+/- 30		
-1000	20	-1000		1170 100 100 100	/ (1 /				
0	20	18	0					,	
500	20	505			BARO	SCALE ERROR	-25	ACTUAL	+25
1000	20	1016	Control of the State of the Sta	(70)20	28.1	(-1727)	-1752	-1705	
1100			1100		28.5	(-1340)	-1365	-1330	-1315
1500	20	1505			29.0	(-863)	-888	-845	-838
1800		(3)	1800		29.5	(-392)	-417	-382	-367
2000	30	2020		(70)25	29.92	(0)	-25	18	+25
3000	30	3020		(70) 25	30.5	(531)	+506	539	+556
4000	35	4012		Carlo Salos	30.9	(893)	+868	915	+918
5000				(70)35	30.99	(974)	+949	983	+999
⊃000	40	6000			00.00	(0).1)	0.10	, 0, 5	19
6800			6800			7			INITIAL
8000	60	7997			ENSUR	RE FREEDOM FR	OM		
10000	80	9996	and the second second	(80)35	20 200 20 2	PPED MOISTUR			11
12000	90	12005			1	RICTIONS			BL
14000	100	14010	200		SYSTE	M LEAK WITHIN	LIMITS	FAR	
14800			14800			5 OR 25.1325	2	7	BK
15000				(90)40		PORT HEATER	WORKS		
16000	110	16035	A STATE OF THE STATE OF		(IF APF	PLICABLE)	· · · · · · · · · · · · · · · · · · ·		
18000	120	18080			(BR
20000	130	20115		(100)60					DIL
22000	140	NIA				× 5			
25000	155			(138) A					1
30000	160	25		(140)	ENGLIE	DE NO ALTERAT	10110 0		-
30800			NIA		DEFOR	RE NO ALTERAT	IONS OF	105	
35000	205			(160)	WOLILI	RMATIONS OF A D AFFECT THE	C SURF	ACE	A n
40000	230	742		(180)	STATIC	CAIR RELATION	CLUD		BL
45000	255	7				AIN KELATION	2HIP		
50000	280	1		(250)		2			

*PRESSURE ALTITUDE REPORTING MUST BE WITHIN +/- 125' OF A/C ALTIMETER

NOTES:	STICKER AFFIXED TO INSTRUMENT	INITIAL B/Z
	DATE 5/20/2021	SIGNATURE
	TECHNICIAN	Rt With
	SUPERVISOR	
DEV 1 0/20/2017	INSPECTOR	ht htt

OCEAN AIRE CRS # OF1R372K ALTIMETER TEST FORM ATS REVISED: 8/16/2017

FAR 43 APPENDIX E ALTIMETER TEST	united	
ALTIMETER TEST	ALTIMETER P/N: 59348-3	ADC P/N: VIA
AIRCRAFT # N N 55 804	ALTIMETER S/N: 470409	ADC S/N: N/A
WORK ORDER # 23 - 6906		
DATE: 5/24/2023	MAX ALTITUDE PER POH: 20,000	

	ALT			o Ciple				ACTU	JAL
REFERENCE	TOL +/-	AIRCRAFT	ALT REPORTING	FRICTIO	CASE LE	AK	+/- 10	0' - 1	6
ALTIMETER SETTING	(IN FEET)	SYSTEM TEST	INTEGRATION	N	HYSTER	ISIS, 50%	+/- 75	and the same of th	.0
0211110	1	READINGS	TEST * (PRESSURE	TOL +/- (IN	HYSTER	ISIS, 40%	+/-75	+	8
		ACTUAL	ONLY)	FEET)	AFTER E		+/- 30)' +	2
-1000	20	-1010	18 18 No. 24 18 18 18 16 16 16 16 16 16 16 16 16 16 16 16 16		/ ((
0	20	18	0					1	
500	20	502			BARO SO	CALE ERROR	-25	ACTUAL	+25
1000	20	1008		(70)25	28.1	(-1727)	-1752	-1718	-1702
1100		The state of the s	(100		28.5	(-1340)	-1365	-1330	-1315
1500	20	1505			29.0	(-863)	-888	-855	-838
1800			1800		29.5	(-392)	-417	-380	-367
2000	30	2020		(70)25	29.92	(0)	-25	18	+25
3000	30	3020		(70)20	30.5	(531)	+506	530	+556
4000	35	4010		No service	30.9	(893)	+868	898	+918
5000			Actualism in the Color of Colors	(70) 30	30.99	(974)	+949	985	+999
6000	40	6000							
6800			6800						INITIAL
8000	60	7995				FREEDOM FF			0 4
10000	80	9980		(80)40		PPED MOISTUF	RE AND		BK
12000	90	12000	Palaise e Sandala (2.12 / 2.23)		RESTRI				
14000	100	14015			(A)	I LEAK WITHIN	LIMITS	FAR	BK
14800		Laborate a second and	14800		22	OR 25.1325			1310
15000				(90)40	. Trees reports trees to less the	PORT HEATER	RWORK	S	
16000	110	16040			(IF APP	LICABLE)			
18000	120	18010	Region of the Committee						BR
20000	130	20085	patient and the feet out.	(100)45					00
22000	140	NIA							*
25000	155			(130YA					
30000	160			(140)		E NO ALTERA			
30800			NIA			MATIONS OF A		FACE	R U
35000	205		The source and a second second des	(160)		AFFECT THE			BK
40000	230		Balancia de Santos de Caración	(180)	STATIC	AIR RELATION	NSHIP		
45000	255		Barbara San San San San San						
50000	280	Y		(250)					

*PRESSURE ALTITUDE REPORTING MUST BE WITHIN +/- 125' OF A/C ALTIMETER

	STICKER AFFIXED TO INSTRUMENT	INITIAL
NOTES:	DATE 5/24 /2023	SIGNATURE At MIT
	SUPERVISOR	
	INSPECTOR	nt hit

Occan Aire	TEST	TOLERANCE	#1	#2
Ocean Aire	Radio Reply Frequency	1090 ± 3 Mhz	Mhz 1088.80	N/4
CRS # OF1R372K	Radio Frequency Peak Output Power	Min. Class 1A: 125 Watts Class 1B: 70 Watts Max. 500 Watts	155 Watts	Watts
Date: 5/24/2023	Receiver Sensitivity	-73 ± 4 dbm Additional 3 dB loss allowed w/ portable test equipment	-76,7	dh.m.
Work Order: 23-6906 Aircraft N: N55804	MTL Difference ;	measuring a radiated signal Mode 3A and Mode C receiver does not exceed 1 dbm	O.O db	dbm
Type: PA-28R-200	Suppression Interrogation Rate 235 ± 5 Hz PRF at 4 db higher than MTL	Maximum of 3 replies per second when P2 = P1. Minimum of 212 replies per second when P2 is 9 db less than P1	Pass Fail	Pass Fail Pass Fail
#1 Xpndr Garnin GTX 327 #1 p/n: 011-00490-00	Altitude Reporting ON		Pass Fall	Pass Fail
#1 s/n: 83715384	OFF	Only F1 and F2 transmitted	Fail	Pass Fall
#2 Xpndr	Identification	Check ID annunciation is displayed for approx. 20 seconds.	Pass Fall	Pass
#2 p/n: N/A	Form instructions: Technician will use A in appropriate Box ar	TCRBS Transponder test box and ad/or indicate "Pass/Fail" as require	insert resulted.	s for each te
	N/A will be inserted y	mere item is not applicable.		
Preliminary Inspection by:				
				•
No defects noted.			,	

Technician: __ Inspector:

DATE	AIRFRAME TIME IN SERVICE	AVIONICS TIME IN SERVICE	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK	
			Altimeter Log Book Entry Reg #N55 804 Date 5/20/2021 Make	
			Transponder Logbook Entry Reg # NSS 804 Date: \$\sigma 2021 Make: Piper Model: \(\textit{M} - \textit{A}\textit{R}\textit{-}\ 200 S/N:\(\textit{2}\textit{R}\textit{-}\ 737\(\textit{S}\textit{2}\textit{1}\) The transponder Make/Model \(\textit{Makes: 6Tx 727} \) S/N \(\textit{S}\textit{7}\textit{5}\textit{8}\textit{4}\) was tested and inspected as required By FAR 91.413. Tested to specs using IFR ATC 601 \(- \textit{IFR ATC 6000} \) 601 Cal Date \(- \textit{6}\) Details of this inspection re on file at this Repair Station under WO #\(\textit{2}\textit{1}\textit{-}\textit{5}\textit{9}\textit{6}\) FAA Cert. # OF1R372K Signed \(\textit{1}\textit{1}\textit{1}\textit{1}\textit{2}\textit{1}\textit{2}\textit{1}\textit{2}\textit{1}\textit{2}\textit{2}\textit{1}\textit{2}\textit{3}\textit{2}\textit{3}\textit{2}\textit{5}\textit{7}\textit{0}\textit{8}\textit{7}\textit{3}\textit{2}\textit{3}	

DATE	AIRFRAME TIME IN SERVICE	AVIONICS TIME IN SERVICE	DESCRIPTION OF WORK PERFORMED SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
			Altimeter Logbook Entry Reg # N 5580 + Date: 5/24/2023
			Reg # <u>N 5 5 8 0 +</u> Date: <u>5 / 2 4 / 2 0 2 5</u> Make: <u>Piper</u> Model: <u>PA - \ </u>
			S/N: 28R-7335291 Tach/Hebbs: 3413.0
			The aircraft static system was tested and was found
			to meet FAR 91.411. The Aircraft
			altimeter Make/Model United 5934P-3
			S/N 470409 was tested to Z0000 feet
			and found to meet FAR Part 43, Appendix E. Details of this inspection are on file at this Repair
			Station under WO #_23-6906
			FAA Cert. # OF1R372K
			Signed Rt Mitte
	-		Ocean Aire, PO Box 1245, Toms River, NJ 08754
			Transponder Logbook Entry
			Reg # N 55 804 Date: 5 24 2023
			Make: Piper Model: PA-28R-Z00
			S/N: 28K-733 5 291 Tach/Hobbs: 34 13.6 The transponder Make/Model Garnin GTX 327
			S/N 837/538 + was tested and inspected as required
			By FAR 91.413. Tested to specs using
			IEP ATC 601 IER ATC 6000
			601 Cal Date 6000 Cal Date 9 29 2022
			Details of this inspection re on file at this Repair Station under WO # 23-6906
		-	FAA Cert. # OF1R372K
			Signed At Mit
			Ocean Aire, PO Box 1245, Toms River, NJ 08754

List the product name, serial number and date of purchase for all Garmin products.

Keep this document for your records.

product	serial number	purchase date
Garmin GNS 430	010-00139-11	97131751
Garmin GA 56	010-10040-01	59415061
Garmin GI 106A	013-00049-00	L05-11637