

HARTZELL

PROPELLER LOGBOOK

PROPELLER MODEL P14C-C34F-1RF

PROPELLER S/N QG 535B

LOGBOOK # 1

THIS SERVICE RECORD shall accompany the propeller equipment at all times. When equipment is installed as part of an Aircraft or engine, this record shall be maintained concurrently with and become a part of the Aircraft and Engine Service Records.

PROPELLER MAINTENANCE RECORD

Position _____

Propeller Model PHC-C34F-1RF

Propeller S/N QG 535B

Blade Design F8468AK-6R

Blade S/N's

No. 1 L 34434

No. 2 L 34435

No. 3 L 34436

No. 4 _____

No. 5 _____

No. 6 _____

Spinner Assembly Part No. _____

PITCH RANGE

High/Feather _____

Start Lock _____

Low _____

Reverse _____

Aircraft Manufacturer Beechcraft Corp.

Aircraft Model G36

S/N E-4602

Registration _____

Date	Propeller TSN TSO		A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
6-5-13	0	0	0	Installed on E-4002
				<i>Dale W. Dodd</i> Dale W. Dodd For Beechcraft Corporation
July 3/13	29.1	29.1		Arrival at CYPQ for import to Canada FCC AMO 45-08 ACA 2

Flying Colours Corp.
901 Airport Road, Peterborough Airport,
Peterborough, Ontario, Canada
Ph: (705) 742-9631 Fax: (705) 742-1494

Date: **July 25, 2013**
Reg'n: **C-FRWD**
TTAF: **29.1** TCAF: **20**

Import - Propeller
~ This aircraft has been inspected per MSI-26 for importation into Canada from United States under Type Approval Certificate A-245 Issue 3 and was found to meet the design standard.
~ Aircraft will be maintained in accordance with CAR 625 Appendices B and C.

Release
The maintenance described above has been accomplished in accordance with the applicable standards of airworthiness. Details of work performed are maintained on file at Flying Colours under work order 136054.

Tim Pickett
Tim Pickett, Chief Inspector
Flying Colours Corp., AMO 45-08 FCC
AMO 45-08
ACA 2



901 Airport Road, Peterborough Airport,
Peterborough, Ontario, Canada
Ph: (705) 742-9631 Fax: (705) 742-1494

Date: **June 27, 2014**

Reg'n: **C-FRWD**

TTAF: **63.0** TCAF: **48**

Propeller

~ 100 hour / annual inspection carried out per Maintenance Manual, Chap 05-20-00-001, and CAR 625 Appx B.
~ Electric prop deicer 100 hour inspection carried out. Prop deice boot lead retaining straps replaced by Hope Aero, ref work order T104113.

Release

The maintenance described above has been accomplished in accordance with the applicable standards of airworthiness. Details of work performed are maintained on file at Flying Colours under work order 14-53.

Tim Pickett
Tim Pickett, Chief Inspector
Flying Colours Corp., AMO 45-08 FCC
AMO 45-08
ACA 2

LEGGAT AVIATION LTD
www.leggataviation.com

Beech B36
C-FRWD

WORK ORDER # 203900

Inspection

→ Annual inspection carried out referenced CARs 625 B & C and Beech G36 100 hour check list.

Resulting from inspection the following maintenance completed:

→ Dressed and painted prop.

"The described maintenance has been performed in accordance with the applicable airworthiness requirements and performance rules of CAR 571.02".

Signed on behalf of AMO 2.73 *AR*

END

//Date: June 22, 2017

