

---

## AVIONICS MAINTENANCE RECORD

  
AIRCRAFT SALES & BROKERAGE

AIRCRAFT SERIAL AND REGISTRATION 18281589 N14007

# MICHIGAN AVIATION CO.

CRS NO. KL2R956 6150 Highland Rd.  
Waterford, MI 48327

Date 12/14/2005

DATE	TOTAL IN SEF
19	HOURS

Reg. No. N14007

Ser. No. 18281589

WO No. 31608B

Hours 145.2

Removed defective Audio Panel GMA 1347, p/n 011-00809-00 s/n 47101191. Installed exchange Audio Panel GMA 1347, p/n 011-00809-00 s/n 47100812. Tested and unit functions normal, Marker Beacon functions normal.

Uploaded aircraft specific software and configuration data per Garmin technician for compatibility purposes for the GMA 1347 and to prevent service alerts. G1000 system functions normal.

-----  
END  
-----

*MichiganAviation.com*  
AIRCRAFT SALES & BROKERAGE


The Aircraft/Component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and is approved for return to service.

CRS NO. KL2R956

*William R. Pappas*

\_\_\_\_\_  
ED SIGNATURE,  
CATE TYPE  
UMBER  
\_\_\_\_\_

DATE	TOTAL TIME IN SERVICE	
	HOURS	1
19		



1661 Airport Road  
Waterford, MI 48327-1304 USA

Date 12/30/05

Reg. No. N14007 Ser. No. 18281589

WO No. 16078 Hours NA

---

KAP-140 Certification Gain File 1870002.cer has been saved into the non-Volatile memory. Reference Honeywell Installation Bulletin #523.

X	X	X	X
X	X	X	X

aircraft and/or component identified above was repaired and inspected in accordance with current air regulations and found airworthy for return to service

CRS OA5R086N *[Signature]*

AUTHORIZED SIGNATURE, CERTIFICATE TYPE & NUMBER

---



---



---



---



---



---




---



---



DATE	TOTAL TIME IN SERVICE	
	HOURS	1
19		



1661 Airport Road  
Waterford, MI 48327-1304 USA

Date 1/31/06

Reg. No. N14007 Ser. No. 18281589

WO No. 16104 Hours NA

---

Removed failed pitch servo, KS-270C P/N065-00178-2200 S/N8122, and Installed serviceable exchange KS-270C P/N065-00178-2200 S/N8588. Tested the system operation normal.

X	X	X	X
X	X	X	X

aircraft and/or component identified above was repaired and inspected in accordance with current air regulations and found airworthy for return to service

CRS OA5R086N *[Signature]*

AUTHORIZED SIGNATURE, CERTIFICATE TYPE & NUMBER

---



---



---



---



---



---



---



---



DATE	TOTAL TIME IN SERVICE	
	HOURS	10ths
19		



1661 Airport Road  
Waterford, MI 48327-1304 USA

Date 7/25/06

Reg. No. N14007

Ser. No. 18281589

WO No. 1616238

Hours NA

Removed pitch servo KS-270C P/N 065-00178-2200 S/N 8588. Installed warranty exchange servo S/N 7089. Installed new pilot's PTT switch. Ops check ok.

X X X X  
X X X X

aircraft and/or component identified above was repaired and inspected in accordance with current air regulations and found airworthy for return to service

CRS OA5R086N

*James Johnson*

ORIGINED SIGNATURE,  
CERTIFICATE TYPE  
& NUMBER

---

---

---

---

---

---

---

---