

**HARTZELL**

*Superseded*  
**PROPELLER LOGBOOK**

PROPELLER MODEL \_\_\_\_\_

PROPELLER S/N Fy347A.

LOGBOOK # 1  
**LH**

**HARTZELL SERVICE CENTER**

5465 W. St. Rt. 185

Piqua, Ohio 45356-2634 U.S.A



**October 23, 2007**

**S/N: FY347A;**

**TSN 14065.3, TSO 0.0**

Overhauled, and assembled propeller. Installed new blades. Static balanced, lubricated, and inspected prop assembly. All work was performed in accordance with Hartzell o/h manuals 143A-R12, 127-R2, 133C-R22, 159-R6, 180-R2, 181, 202A ( Vol. 1-R31, Vol. 2-R28, Vol. 3-R29, Vol. 6-R29, Vol. 7-R30, Vol. 8-R28, Vol. 9-R28, Vol. 10-R29, Vol. 11-R29 ), Hartzell Service Bulletins HC-SB-61-215-R4, HC-SB-61-225-R3, HC-SB-61-231R1, HC-SB-61-235-R1, HC-SB-61-276R4, HC-SB-61-289-R1, and Service Letters HC-SL-61-61Y-R1, 160, HC-SL-61-187R2, HC-SL-61-217, HC-SL-61-229, HC-SL-61-241-R1, HC-SL-30-259-R6, HC-SL-30-261, HC-SL-61-267, and Service Instructions 152A. Reference Form # 25 for serial numbers, and times. Prop was disassembled for shipping, customer to reassemble IAW all applicable service information. Pertinent details of the repair are on file at this agency under Work Order M598430.

A handwritten signature in blue ink, which appears to read "Dennis Pittsenbarger". The signature is fluid and cursive, extending across the width of the text area below it.

Dennis Pittsenbarger, Repairman # 2424395  
Repair Station # SJ3R843L





Proptech,  
 Nevil Shute Road,  
 Portsmouth,  
 Hampshire, PO3 5RX.  
 U.K.

Telephone:  
 E-Mail:  
 Facsimile:

+44 (0)23-92 657779  
 darron\_phillips@proptech.info  
 +44 (0)23-92 657771

THE PROPELLER OVERHAUL & REPAIR SPECIALISTS

Propeller Type.	Serial Number.	Proptech project number.	EASA Part 145 Approval. UK.145.01137
HC-D4N-3A	FY347A	6313468	FAA Repair Station. DM0Y0010
			BSI Approval. LRQ 0920706

PROPELLER TSN: 14,065.3 Hrs.

PROPELLER TSO: 00:00 Hrs.

HARTZELL PROPELLER DATA AND SERIAL NUMBERS OF MAJOR COMPONENTS

DIAMETER :	94"	HUB NO. :	FY347A	BLADE TYPE :	D9383K
REPAIR & REASSEMBLED IAW MANUAL:	133C Rev 22, 143A Rev 12, 159 Rev 7 & 202A (Vol. 8,9 Rev 28) (Vol. 11 Rev 29)(Vol. 7 Rev 30)(Vol. 1 Rev 31).				
BLADE NO.1 S/NO.:	K52325	HOURS :	TSN 00:00 Hrs.	CT/WT S/NO.:	1
BLADE NO.2 S/NO.:	K52326	HOURS :	TSN 00:00 Hrs.	CT/WT S/NO.:	2
BLADE NO.3 S/NO.:	K52327	HOURS :	TSN 00:00 Hrs.	CT/WT S/NO.:	3
BLADE NO.4 S/NO.:	K52328	HOURS :	TSN 00:00 Hrs.	CT/WT S/NO.:	4
SERVICE BULLETINS SATISFIED:	None.				
SERVICE LETTERS SATISFIED:	61-189 Rev 2.				
SERVICE INSTRUCTIONS SATISFIED:	None.				
SERVICE ADVISORY SATISFIED:	None.				
AIR DIRECTIVES SATISFIED:	None.				
REMARKS:	Blades painted iaw customer supplied scheme.				

Pertinent work details of this reassembly are held on file at this Repair Station under the Proptech Project Number shown above.

Date	Name	Signature	Stamp
03 December 2007	D Phillips	<i>D J Phillips</i>	OAS 010 PT