

HARTZELL

PROPELLER LOGBOOK

AirMart.com
AIRCRAFT SALES & BROKERAGE

LH

PROPELLER MODEL PHC-J34F-2UF

PROPELLER S/N EDS873B

LOGBOOK # _____

PROPELLER MAINTENANCE RECORD

Position L.H.

PITCH RANGE

Propeller Model PHC-J34F-2UF

High/Feather _____

Propeller S/N ED5873B

Start Lock _____

Blade Design FC7391DK

Low _____

Blade S/N's

Reverse _____

No. 1 L10267

No. 2 L10268

Aircraft Manufacturer _____

No. 3 L10275

Aircraft Model _____

No. 4 _____

S/N _____

No. 5 _____

Registration _____



No. 6 _____

Spinner Assembly Part No. _____



Date	Propeller TSN TSO		A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.		
4-15-11	0	0	0	Installed on TH-2307 LH <i>Robert Alliband</i>		
				Robert Alliband For Hawker Beechcraft Corporation		
Hawker Beechcraft				5615 S. Sossaman Road Mesa, AZ 85212 Phone (480) 457-8400		
SERVICES						
LEFT PROPELLER LOG ENTRY						
MODEL	A/C S/N	A/C REG.	WORK ORDER#	AC TT	HR MTR:	DATE
G58	TH-2307	N589LB	23-05-1171	47.8	47.8	6/01/2011
LT PROP SN		LT PROP TT		LT PROP TSO		
ED5873B		47.8		N/A		
A. TIME ITEMS COMPLIED WITH:						
1. Complied with 50 hour Prop Deice Inspection . In accordance with Hawker Beechcraft G58 MM PN- 55-590000-13, revision G2 dated 10/2010. Task code 611021.						
All maintenance, ground runs, leak checks and ground operational checks have been performed in accordance with the applicable portions of the Maintenance Manual.						
I certify that this Propeller identified above was repaired and inspected in accordance with FAA regulations and, for the work performed only, was found airworthy and is approved for return to service.						
Hawker Beechcraft Services CRS # 7HWR274B				<i>James McDaniel</i> James McDaniel Title: Inspector		




Hawker Beechcraft				5615 S. Sossaman Road Mesa, AZ 85212 Phone (480) 457-8489		
SERVICES				LEFT PROPELLER LOG ENTRY		
MODEL	A/C S/N	A/C REG.	WORK ORDER#	AC TT	HR MTR:	DATE
G58	TH-2307	N589LB	23-04-1216	94.3	94.3	7/7/2011
PROP MODEL		PROP SN		PROP TT		
PHC-J3YF-2UF		ED5873B		94.3		
A. TIME ITEMS COMPLIED WITH:						
1. 100 Hour Inspection per Baron 55 and 58 MM P/N 55-590000-13 Rev G3 Dated 4/2011 Chapter 5-20-00 (051010)						
2. 100 Hour Service and Lube Items per Baron 55 & 58 MM 12-12-00 (121010)						
3. 50/100 Hour Electric Prop Deicer System Inspection per MM 5-20-00 (611021, 611031)						
4. Hartzell Prop HC-ASB-61-322 Dated 1/14/2011, Blade Replacement- N/A by the Blades Model Number						
All maintenance, ground runs, leak checks and ground operational checks have been performed in accordance with the applicable portions of the G58 Series Maintenance Manual PN- 55-590000-13 G3 revised April 1, 2011.						
I certify that this Propeller identified above was repaired and inspected in accordance with FAA regulations and, for the work performed only, was found airworthy and is approved for return to service.						
Hawker Beechcraft Services CRS # 7HWR274B				<i>Frank Wilson</i> Frank Wilson Title: Inspector		


Date	Propeller		A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.				
	TSN	TSO						
							5615 S. Sossaman Road Mesa, AZ 85212 Phone (480) 457-8400	
SERVICES				LEFT PROPELLER LOG ENTRY				
	MODEL	A/C S/N	A/C REG.	REPAIR ORDER#	AC TT:	HR MTR:	DATE	
	G58	TH-2307	N589LB	6812	137.3	137.3	8/04/2011	
		LT PROP SN	LT PROP TT	LT PROP TSO				
		ED5873B	137.3	N/A				
A. TIME ITEMS COMPLIED WITH:								
1. Complied with 50 hour Prop Deice Inspection . In accordance with Hawker Beechcraft G58 MM PN- 55-590000-13, revision G2 dated 10/2010. Task code 611021.								
All maintenance, ground runs, leak checks and ground operational checks have been performed in accordance with the applicable portions of the Maintenance Manual. I certify that this Propeller identified above was repaired and inspected in accordance with FAA regulations and, for the work performed only, was found airworthy and is approved for return to service.								
Hawker Beechcraft Services CRS # 7HWR274B				 James McDaniel Title: Inspector				



							5615 S. Sossaman Road Mesa, AZ 85212 Phone (480) 457-8400	
SERVICES				LEFT PROPELLER LOG ENTRY				
	MODEL	A/C S/N	A/C REG.	REPAIR ORDER#	AC TT:	HR MTR:	DATE	
	G58	TH-2307	N589LB	22491	185.5	185.5	9/20/2011	
		LT PROP SN	LT PROP TT	LT PROP TSO				
		ED5873B	185.5	N/A				
A. TIME ITEMS COMPLIED WITH:								
1. Complied with 50 and 100 hour Prop Deice Inspections . IAW Hawker Beechcraft G58 MM PN- 55-590000-13, revision G2 dated 10/2010. Task codes 611021 and 611031.								
All maintenance, ground runs, leak checks and ground operational checks have been performed in accordance with the applicable portions of the Maintenance Manual. I certify that this propeller has been inspected in accordance with a 100 hour inspection and was determined to be in airworthy condition.								
Hawker Beechcraft Services CRS # 7HWR274B				 James McDaniel Title: Inspector				

Date	Propeller		A/C	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.			
	TSN	TSO	Hrs				
	Hawker Beechcraft			5615 S. Sossaman Road Mesa, AZ 85212 Phone (480) 457-8400			
	SERVICES			LEFT PROPELLER LOG ENTRY			
	MODEL	A/C S/N	A/C REG.	REPAIR ORDER#	AC TT:	HR MTR:	DATE
	G58	TH-2307	N589LB	112442	326.1	326.1	4/18/2012
		LT PROP SN	LT PROP TT	LT PROP TSO			
		ED5873B	326.1	N/A			
	A. TIME ITEMS COMPLIED WITH:						
	1. Complied with 50 hour Prop Deice Inspections. IAW Hawker Beechcraft G58 MM PN- 55-590000-13, revision G4 dated 10/2011. Task codes 611021 and 611031.						
	All maintenance, ground runs, leak checks and ground operational checks have been performed in accordance with the applicable portions of the Maintenance Manual.						
	With respect to the work performed this Propeller was repaired and inspected in accordance with current FAA regulations. Only those items specified in the work order have been inspected and found to be airworthy and has been approved for return to service. No other representations concerning airworthiness are expressed or implied.						
	Hawker Beechcraft Services CRS # 7HWR274B			 James McDaniel Title: Inspector			



Date	Propeller		A/C	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.			
	TSN	TSO	Hrs				
	Hawker Beechcraft			5615 S. Sossaman Road Mesa, AZ 85212 Phone (480) 457-8400			
	SERVICES			LEFT PROPELLER LOG ENTRY			
	MODEL	A/C S/N	A/C REG.	REPAIR ORDER#	AC TT:	HR MTR:	DATE
	G58	TH-2307	N589LB	175560	422.6	422.6	9/26/2012
		LT PROP SN	LT PROP TT	LT PROP TSO			
		ED5873B	422.6	N/A			
	A. TIME ITEMS COMPLIED WITH:						
	1. Complied with 50 hour Prop Deice Inspections. IAW Hawker Beechcraft G58 MM PN- 55-590000-13, revision G4 dated 10/2011. Task codes 611021 and 611031.						
	All maintenance, ground runs, leak checks and ground operational checks have been performed in accordance with the applicable portions of the Maintenance Manual.						
	I certify that this Propeller has been inspected in accordance with the instructions and procedures of a current manufacturer's recommended inspection program, approved for 14 CFR Part 91.409(f) (3) and was determined to be in airworthy condition.						
	Hawker Beechcraft Services CRS # 7HWR274B			 James McDaniel Title: Inspector			



Sawyer Aviation
 15115 North Airport Drive, #12
 Scottsdale, AZ 85260-2462
 (480) 922-5221
 (480) 922-907-2276 Fax

N-NUMBER: N589LB; **MODEL:** G58; **S/N#:** TH-2307
ENGINE MODEL: PHC-J3YF-2UF; **Left Propeller S/N#:** ED5873B
DATE: 01/18/2013; **Prop Total Time:** 468.7

Inspection Items Complied with:

1. Annual Inspection per Baron 55 & 58 MM P/N 55-590000-13 Revision G5 - July 1, 2012 (05010, 05020)
2. 100 and 300 Hour Lubrication per Baron MM 12-12-00 (121010, 121020)
3. 50/100 Hour Left Electric Prop Deicer System Inspection per MM 5-20-00 (611021)

AD/Service Bulletins Accomplished:

1. AD's researched through bi-weekly 2012-26.
2. AD's 2012-10-02 and 2012-21-05 are N/A due to Aircraft SN.
3. *HC-SB-61-319 blade MODIFICATION IS N/A by Blade P/N 009 01/18/2013*

Maintenance Items:

1. Removed Left Spinner (Dome, "CNC Machined") and Replaced with New Spinner (Dome, "CNC Machined")
 PN Off: D-7811-7P PN On: D-7811-7P
 SN Off: 1100725C SN On: 1207141C

All maintenance, ground runs, leak checks and ground operational checks have been performed in accordance with the applicable portions of the G58 series Maintenance Manual P/N 55-590000-13 Revision G5 - July 1, 2012.

I certify that the propeller identified above was repaired and inspected IAW FAA regulations and, for the work performed only, was found airworthy and is approved for Return To Service.

Robert A. Anderson
 AP 2820387 IA



Sawyer Aviation
 15115 North Airport Drive, #12
 Scottsdale, AZ 85260-2462
 (480) 922-5221
 (480) 922-907-2276 Fax

N-NUMBER: N589LB; **MODEL:** G58; **S/N#:** TH-2307
ENGINE MODEL: PHC-J3YF-2UF; **Left Propeller S/N#:** ED5873B
DATE: 04/24/2013; **Prop Total Time:** 514.5

Inspection Items Complied with:

1. 50 Hour Left Electric Prop Deicer System Inspection per MM 5-20-00 (610101)

AD/Service Bulletins Accomplished:

1. AD's researched through bi-weekly 2013-07

All maintenance, ground runs, leak checks and ground operational checks have been performed in accordance with the applicable portions of the G58 series Maintenance Manual P/N 55-590000-13 Revision G5 - July 1, 2012.

I certify that the propeller identified above was repaired and inspected IAW FAA regulations and, for the work performed only, was found airworthy and is approved for Return To Service.

Robert A. Anderson
 AP 2820387 IA



Sawyer Aviation
15115 North Airport Drive, #12
Scottsdale, AZ 85260-2462
(480) 922-5221
(480) 922-907-2276 Fax

N-NUMBER: N589LB; **MODEL:** G58; **S/N#:** TH-2307

ENGINE MODEL: PHC-J3YF-2UF; **Left Propeller S/N#:** ED5873B

DATE: 02/21/2014 **Prop Total Time:** 660.4

Inspection Items Complied with:

1. 100hr/Annual Inspection (Long Form) per Baron 55 & 58 MM P/N 55-590000-13 Revision G7 - Oct 1, 2013 (05010)
2. 100 and ~~600~~^{371 2/21/14} Hour Lubrication per Baron MM 12-12-00 (121010, 121030)
3. 50/100 Hour Left Electric Prop Deicer System Inspection per MM 5-20-00 (611021, 611031)

AD's/Service Bulletins Accomplished:

1. AD's checked through bi-weekly 2014-03

airmart.com
AIRCRAFT SALES & BROKERAGE

All maintenance, ground runs, leak checks and ground operational checks have been performed in accordance with the applicable portions of the G58 series Maintenance Manual P/N 55-590000-13 Revision G7 Oct 1, 2013.

I certify that this propeller has been inspected in accordance with an **Annual inspection** and was determined to be in **airworthy** condition.

Jeffrey J Hettling
A&P 2736512 IA



Sawyer Aviation
15115 North Airport Drive, #12
Scottsdale, AZ 85260-2462
(480) 922-5221 Tel.
(480) 922-5653 Fax

N589LB Model #: Barron G58 S/N:TH-2307
Engine Model: PHC-J3YF-2UF LH Prop S/N: ED5873B
August 02, 2014 ACTT: 747.6 HOBBS:

LH Propeller Log Entry:

C/W 50 HR Inspection of LH and RH Engines.
C/W 50 HR LH & RH Prop deicer System Inspection per
MM-5-20-00 (610101).

All maintenance ground run ops checks have been
performed in accordance with the applicable portions of the
G58 Maintenance Manuals.

I certify this aircraft approved for return to service with
respect to work performed.

Richard Castillo A/P 3528659



Sawyer Aviation
 15115 North Airport Drive, #12
 Scottsdale, AZ 85260-2462
 (480) 922-5221 Tel.
 (480) 922-5653 Fax

N589LB Model #: Barron G58 S/N:TH-2307
Engine Model: PHC-J3YF-2UF Left Propeller S/N: ED5873B
August 25, 2014 ACTT: 758.3 HOBBS:

LH Propeller Log Entry:

Complied with the following inspection items:

100 HR Inspection per Baron 55 & 58 MM P/N 55-590000-13 Rev G7 – Oct 1, 2013 (051010, 05020)
 50/100 HR Left and Right Electric Prop Deicer System Inspection per MM 5-20-00 (611021, 611031)

All maintenance, ground runs, operational checks have been performed in accordance with the applicable portions of the G58 Series Maintenance Manuals P/N 55-590000-13 Rev G6 – April 1, 2013.

I certify this propeller approved for return to service with respect to work performed.

Richard Castillo A/P 9528659



CENTERLINE AIRCRAFT, LLC
 15290 NORTH 78TH WAY
 SCOTTSDALE AZ 85260
 602-300-3791

N589LB S/N: TH2307 TT: 796.0 10/22/2014
 LH PROP S/N: ED5873B

1. BALANCED PROPELLER IAW HARTZEL MANUAL 115N CHAPTER 61-00-15

I CERTIFY THAT THE AIRCRAFT IDENTIFIED ABOVE WAS REPAIRED AND INSPECTED IAW FAA REGULATIONS AND, FOR THE WORK PERFORMED ONLY, WAS FOUND AIRWORTHY AND IS APPROVED FOR RETURN TO SERVICE.

LAWRENCE AFANA
 AP 3643646

N589LB S/N: TH-2307 TT:855.5 3/7/2015
 PHC-J3YF-2UF S/N: ED5873B

1. PERFORMED 100 HR INSPECTION
2. AD'S CHECKED THRU 2015-04

I CERTIFY THAT THE AIRCRAFT ENGINE IDENTIFIED ABOVE WAS REPAIRED AND INSPECTED IAW FAA REGULATIONS AND, FOR THE WORK PERFORMED ONLY, WAS FOUND AIRWORTHY AND IS APPROVED FOR RETURN TO SERVICE.

LAWRENCE AFANA
 AP 3643646

Date

Propeller
TSN TSO

A/C
Hrs

Description of all operations pertaining to Airworthiness Directives,
Service Documents, Overhaul, Major or Minor Repair, and Inspections.

Date: 7/02/2015; Aircraft: N589LB; Type: G58; S/N: TH-2307

Hobbs: 942.60; Total Time: 942.60

Prop 1 Type: PHC-J3YF-2UF, S/N: ED5873B, Time: 942.60

I certify that this propeller has been inspected and serviced in accordance with an 100 HR inspection and has been determined to be in airworthy condition. Records are on file at this agency under WO# SVC15-04475.

Signed _____

for CRS# PZ4R458M

Douglas J Bramer



Aircraft Specialists, Inc.

Clark Regional Airport (KJVY)
Sellersburg, Indiana

800-356-3723