

104069K

# PROPELLER LOG BOOK



*SENSENICH PROPELLER MFG. CO.*

Lititz, Pennsylvania 17543

Internet: <http://www.sensenich.com>.

THIS LOG BOOK IS TO BE KEPT  
WITH THE PROPELLER  
FOR RECORDING OF ALL PROPELLER MAINTENANCE WORK PERFORMED

**DESCRIPTION OF ALL OPERATIONS  
PERTAINING TO AIRWORTHINESS DIRECTIVES,  
SERVICE BULLETINS, SERVICE LETTERS,  
& MINOR ADJUSTMENTS**

| DATE | TACH TIME | DESCRIPTION OF WORK | SIGNATURE |
|------|-----------|---------------------|-----------|
|------|-----------|---------------------|-----------|



43769 Heilner Rd.  
Baker City, OR 97814  
541-523-5663

|                       |                       |
|-----------------------|-----------------------|
| <b>N2316K</b>         |                       |
| MAKE/MODEL:           | Piper Archer III      |
| SERIAL NUMBER:        | 2843683               |
| TACH/HOBBS:           | 245.0                 |
| AFTT:                 |                       |
| ENGINE MAKE/MODEL:    | Lycoming O-360-A4M    |
| ENGINE SERIAL NUMBER: | L-41694-36E           |
| ENGINE TTSN:          | 245.0                 |
| ENGINE SMOH:          | 245.0                 |
| PROP MAKE/MODEL:      | Sensenich 76EM8S14-0- |
| PROP SERIAL NUMBER:   | 104069K               |
| PROP SMOH:            | 0.0 TT: 0.0           |

**DESCRIPTION OF WORK:**

Installed New Sensenich propellor (PN: 76EM8S14-0-62 SN: 104069K) in accordance with Piper Maintenance Manual chapter 61-10-00 (2). Checked blade track per 61-10-00 (2)D.

Carl Mattheis AP3813037



Date:

3/22/2017

