

## PROPELLER LOGBOOK

PROPELLER MODEL (-E4/U-3U

PROPELLER S/N HH 2771

LOGBOOK #\_\_\_\_



PositionR.H.	PITCH RANGE
Propeller Model HC-54N-3N	High/Feather
Propeller S/N HH277/	Start Lock
Blade Design D8990SK	Low
Blade S/N's	Reverse
No. 1 K 50536	
No. 2 K 50535	Aircraft Manufacturer
No. 3 K 50534	Aircraft Model
No. 4 KS0533	S/N
No. 5	Registration
No. 6	
Spinner Assembly Part No	

Date	TSN	eller TSO	A/C Hrs	Descripti Service De	ion of all or ocuments,	oerations perta Overhaul, Maj	ining to Airwort or or Minor Rep	hiness Directives, pair, and Inspection	ins.	
1-1607	0	0	0	Installed	ion	LJ-1817	R.H.	- Hh	11	
								FUOTUS HAINAS	204	
		EUGENE HAINS								
		FOR RAYTHEON AIRCRAFT								
		RONSON AVIATION, INC CRS EHHR538D TRENTON-MERCER AIRPORT TRENTON, NJ 08628 (609) 771-9500 FAX (609) 771-0651								
					REG #		DATE: W/O #:	11/5/2007		
					0.00000000000	2000 2000 2000 2000		24050		
-		RI	GHT PR	ROPELLER LOG	MODEL: S/N:	HC-E4N-3 HH-2771	HM:	196.4		
		<ol> <li>C/W FAR 91.409(f)(3) BY PERFOR</li> </ol>			MING PHAS	E 1&2 INPSECTION				
100		M/M INSPECTION FORM FOUND IN CHAPTER 5.  2. DRESS AND LUBRICATED HUB.								
			Fat.	MAINT	ENANCE	RELEASE		-		
-		I certif	y that this	s aircraft has been inspecte	ed in accorda	nce with a PHASE	1&2 and was insp	ected and		
				tails of the inspection are o		agency under the v				
		10	ertify that	the article described abov	e has been i	nspected and appr	oved for return to s	service.		
$\vdash$		,	V	Sa the	1			-		
$\vdash$		Sig	ned A	agtellle			, INC. CRS EHH			
	1	RONS	ON AVIAT	ION. INC 10 CRS EHHR5381 (609) 771-		(609) 771-0651	ORT TRENTON,	NJ 08658		
	(	1				1				
	6	1								
								0		
ulasi	C PUL	)	200		9		49			
14/08 4	918:2	7 2	299 (	pcs Of OH		1			8	
14/08 4	9/18:2 7	) Y 2	299 (	Ofw PHA	86-30		7	Iful	Becel	
14/08 4	9/18:2 )	) Y 2	299 8	Ofw PHA		TY INS	7	Ifw	Becel	
14/08 4	9/18:2 )	7 2	299 8	Ofw PHA	MANU	Aco B	pt 5	is Requ	11964	
14/08 4	9/18:2 7		299 8	Munt	MANU	Aco B	pt 5	is Requ	11964	
14/08 4	4/18:2 /		299 6	Munt Dressen	MANU	Aco B	pt 5		11964	
14/08 4	1/18:2 7		2998	Munt Dressen	MANU	Aco B	pt 5	is Requ	11964	
14/08 4	418:2 7		299 &	Munt Dressen	MANU	Aco B	pt 5	is Requ	11964	
14/08 4	418:2 7		2998	Munt Dressen	MANU	Aco B	pt 5	is Requ	11964	
14/08 4	418:2 )		2998	Munt Dressen	MANU	Aco B	pt 5	is Requ	11964	
14/08 4	SI	EVENS AVI	ATION INC	Munt of	MANU	N610SC	1975 14005 K 100 WIFE	ACTT 740.	11REA.	
	Sist	EVENS AVI.	ATION INC	Munt of Dresses of Ly 8 programs	MANUS + PAI	N610SC S/N LJ-18	19 5 (ABCS PO (CA WIFE 134446	A Requ	11REA.	
- Oc	stober 29,	EVENS AVI NASHVILL 2009	ATION INC	MMNT NACSSED C.  Right Prop S/N I	111-2771	N610SC S/N LJ-18 TSN 740.6	19 5 (4005 p) (CD WIFE 184446	ACTT 740.	11REA	
— Oc Dro	stober 29,	EVENS AVIL NASHVILL 2009 ides, Pain	ATION INC	C.  Right Prop S/N F	HH-2771	N610SC S/N LJ-181 TSN 740.6	17 gle.	ACTT 740.6	11RC13	
— Oc Oc I c	stober 29, essed Bla	EVENS AVI NASHVILL 2009 ides, Pain	ATION INC.	C.  Right Prop S/N Feen inspected in accordance.	HH-2771 Propeller, A	N610SC S/N LJ-18 TSN 740.6 djusted blade an	PF 5  (ADCS P)  (CR WIFI  (BYYU)  (BYYU)  (Ble.  and a HB Comp	ACTT 740.6  HM 740.6	1/RCA	
Oc Dro	stober 29, essed Bla	TEVENS AVI. NASHVILL 2009 des, Pain s Propella ed and th	ATION INC.	C.  Right Prop S/N F	HH-2771 Propeller, A	N610SC S/N LJ-18 TSN 740.6 djusted blade an	PF 5  (ADCS P)  (CR WIFI  (BYYU)  (BYYU)  (Ble.  and a HB Comp	ACTT 740.6  HM 740.6	1/RCA	
Oc Dro	etober 29, essed Bla ertify this	EVENS AVI NASHVILL 2009 ides, Pain a Propello ed and the er 1490.	ATION INC E, TN ated Tips er has be	C.  Right Prop S/N Feen inspected in accordance.	HH-2771 Propeller, A	N610SC S/N LJ-18 TSN 740.6 djusted blade an	PF 5  (ADCS P)  (CR WIFI  (BYYU)  (BYYU)  (Ble.  and a HB Comp	ACTT 740.6  HM 740.6	1/RC1	

Dressed Blades, Painted Tips & Faces. Lubricated Propeller.  I certify this Propeller has been inspected in accordance with FAR 91.409(F) 3 and a HB Phase 1 & 2 Inspection was accomplished and the aircraft is approved for return to service. Pertinent details are on file at this agency under work order number 2449.  SIGNED  For STEVENS AVIATION, Nashville, TN 37217, CRS VIB3368K  SIEVENS AVIATION INC.  Nashville, TN 37217, CRS VIB3368K  SIEVENS AVIATION, Nashville, TN 37217, CRS VIB3368K	November 1, 2010 Right	N610SC S/N LJ-1817 Prop S/N HH-2771 TSN 876.7	ACTT 876.7 HM 876.7
I certify this Propeller has been inspected in accordance with FAR 91.409(F) 3 and a HB Phase 1 & 2 Inspection was accomplished and the aircraft is approved for return to service. Pertinent details are on file at this agency under word order number 2449.  SIGNED  For STEVENS AVIATION, NaShville, TN 37217, CRS VIB3368K  SIEVENS AVIATION INC.  NG 10SC  NG 11-1817  FOR 987.9  SIN LJ-1817  TSN 987.9  HM 987.9  TSN 987.9  SIEVENS AVIATION INC.  NG 10SC  SIEVENS AVIATION INC.  NG 10SC  SIEVENS AVIATION INC.  NG 10SC  SIEVENS AVIATION, Nashville, TN 37217, CRS VIB3368K	TOTAL MINERAL DE MINERA MINERAL MANAGEMENT	en l'Allemanan semi	
STEVENS AVIATION, Nashville, TN 37217, CRS VIB3368K  STEVENS AVIATION INC.  ACTT 987.9  HM 987.9  TSN 987.9  Right Prop S/N HH2771  ressed Blades. Lubricated Propeller.  Sort STEVENS AVIATION, Nashville, TN 37217, CRS VIB3368K  STEVENS AVIATION, INC.  NASHVILLE, IN  NASHVILLE, I	I certify this <i>Propeller</i> has been inspected accomplished and the aircraft is approved	d in accordance with FAR 91.409(F) 3 and a HE	B Phase 1 & 2 Inspection was le at this agency under work
SIEVENS AVIATION, Nashville, TN 37217, CRS VIB3368K  SIEVENS AVIATION, Nashville, TN 37217, CRS VIB3368K  SIEVENS AVIATION INC.  NG10SC SN LJ-1817 SN 130.3  SPECIAL STEVENS AVIATION, Nashville, TN 37217, CRS VIB3368K  SIEVENS AVIATION, INC.  NASHVILLE, IN  SIN LJ-1817  HM 1220.0  TSN 1220.0  TSN 1220.0  TSN 1220.0  TSN 1220.0  TSN 1220.0  TSN 1220.0			
NASHVILLE,TN  NASHVILLE,TN  S/N LJ-1817  TSN 987.9  HM 987.9  Right Prop S/N HH2771  ressed Blades. Lubricated Propeller.  certify this Propeller has been inspected in accordance with FAR 91.409(F) 3 and a HB Phase 3 & 4 Inspection was oder number 3318.  GNED  STEVENS AVIATION, Nashville, TN 37217, CRS VIB3368K  STEVENS AVIATION, INC.  NASHVILLE, TN  SIN LJ-1817  TSN 1220.0		ville, TN 37217, CRS VIB3368K	
NASHVILLE, TN  TSN 987.9  TSN 1.4.09(F) 3 and a HB Phase 3 & 4 Inspection was complished and the aircraft is approved for return to service. Pertinent details are on file at this agency under work of the service of the ser	STEVENS AVIATION INC.		ACTT 987.9
Right Prop S/N HH2771 ressed Blades. Lubricated Propeller. certify this Propeller has been inspected in accordance with FAR 91.409(F) 3 and a HB Phase 3 & 4 Inspection was der number 3318.  GNED FOR STEVENS AVIATION, Nashville, TN 37217, CRS VIB3368K  STEVENS AVIATION INC. NASHVILLE, TN SIN 1130.3 TSN 1130.	NASHVILLE, TN		HM 987.9
STEVENS AVIATION INC.  NASHVILLE, TN  Seed Blades. Lubricated Propeller.  ight this Propeller has been inspected in accordance with FAR 91.409(F) 3 and a HB Phase 3 & 4 Inspection was complished and the aircraft is approved for return to service. Pertinent details are on file at this agency under work der number 3318.  STEVENS AVIATION, Nashville, TN 37217, CRS VIB3368K  STEVENS AVIATION INC.  NASHVILLE, TN  SN LJ-1817  TSN 1130.3  HM 1130.3  TSN 1130.3  ACTT 1130.3  HM 1130.3  TSN 1130.3  ACTT 1220.0  STEVENS AVIATION, Nashville, TN 37217, CRS VIB3368K  STEVENS AVIATION, Nashville, TN 37217, CRS VIB3368K  STEVENS AVIATION, INC.  NASHVILLE, TN  SN LJ-1817  TSN 1220.0  ACTT 1220.0  Department of the at The Agency under Work Order Number 4906.  Internet Details on File at The Agency under Work Order Number 4906.  Internet Details on File at The Agency under Work Order Number 4906.  Internet Details on File at The Agency under Work Order Number 4906.  Internet Details on File at The Agency under Work Order Number 4906.	October 25, 2011 Right P	Prop S/N HH2771	
STEVENS AVIATION, Nashville, TN 37217, CRS VIB3368K  STEVENS AVIATION INC.  NASHVILLE, TN  TSN 1130.3  STEVENS AVIATION, Nashville, TN 37217, CRS VIB3368K  MACTT 1130.3  TSN 1130.3  TSN 1130.3  TSN 1130.3  MACTT 1220.0  MACTT	Dressed Blades. Lubricated Propeller.		
STEVENS AVIATION, INC.  NASHVILLE, TN  SIN LJ-1817 TSN 1130.3  TSN 1200.6  TSN 1200.6  TSN 1200.6  TSN 1220.6	SIGNED_///	le, TN 37217, CRS VIB3368K	*)
STEVENS AVIATION, INC.  NASHVILLE, TN  SIN LJ-1817 TSN 1130.3  TSN 1200.6  TSN 1200.6  TSN 1200.6  TSN 1220.6	Ó		
STEVENS AVIATION, INC.  NASHVILLE, TN  SIN LJ-1817 TSN 1130.3  TSN 1200.6  TSN 1200.6  TSN 1200.6  TSN 1220.6			
SITEVENS AVIATION, INC.  NASHVILLE, TN  S/N LJ-1817 TSN 1130.3  Syn LJ-1817 TSN 1220.0		N610SC	ACTT 1130.3
the prop S/N HH2771  sed Blades. Lubricated Propeller.  ify this Propeller has been inspected in accordance with FAR 91.409(F) 3 and a HB Phase 1 & 2 Inspection was implished and the aircraft is approved for return to service. Pertinent details are on file at this agency under work number 4130.  NED  Tor STEVENS AVIATION, Nashville, TN 37217, CRS VIB3368K  SIEVENS AVIATION, INC.  NASHVILLE, IN  NASHVILLE, IN  NASHVILLE, TN  NASHVILLE, TN		S/N LJ-1817	HM 1130.3
sed Blades. Lubricated Propeller.  ify this <i>Propeller</i> has been inspected in accordance with FAR 91.409(F) 3 and a <i>HB Phase 1 &amp; 2</i> Inspection was implished and the aircraft is approved for return to service. Pertinent details are on file at this agency under work number 4130.  NED  For STEVENS AVIATION, Nashville, TN 37217, CRS VIB3368K  STEVENS AVIATION, INC.  NASHVILLE, TN  NASHVILLE, TN  S/N LJ-1817  TSN 1220.0  Devember 5, 2013  Right Prop S/N HH2771  Removed serviceable propeller and sent out for overhaul.  Pertinent Details on File at This Agency under Work Order Number 4906.  Regned  Master Stevens Aviation (Stevens of the Agency under Work Order Number 4906.  Regned  Master Stevens Aviation (Stevens of the Agency under Work Order Number 4906.  Regned  Master Stevens Aviation (Stevens of the Agency under Work Order Number 4906.  Regned  Regned  Regner Under Work Order Number 4906.	vember 7, 2012	TSN 1130.3	
ify this <i>Propeller</i> has been inspected in accordance with FAR 91.409(F) 3 and a <i>HB Phase 1 &amp; 2</i> Inspection was implished and the aircraft is approved for return to service. Pertinent details are on file at this agency under work number 4130.  NED  OUT STEVENS AVIATION, Nashville, TN 37217, CRS VIB3368K  STEVENS AVIATION, INC.  NASHVILLE, IN  NASHVILLE, IN  NASHVILLE, IN  NASHVILLE, IN  Right Prop S/N HH2771  Demoved serviceable propeller and sent out for overhaul.  Pertinent Details on File at This Agency under Work Order Number 4906.  Right Prop S/N Under Number 4906.  Right Prop S/N Under Number 4906.  Right Prop S/N Under Number 4906.	ght Prop S/N HH2771		
mplished and the aircraft is approved for return to service. Pertinent details are on file at this agency under work number 4130.  NED FOR STEVENS AVIATION, Nashville, TN 37217, CRS VIB3368K  STEVENS AVIATION, INC.  N610SC  S/N LJ-1817  TSN 1220.0  Details on File at This Agency under Work Order Number 4906.  Service and service	essed Blades. Lubricated Propeller.		
STEVENS AVIATION, INC.  NASHVILLE, TN  TSN 1220.0  Property of the state of th	complished and the aircraft is approved for der number 4130.	return to service. Pertinent details are on file at	use 1 & 2 Inspection was this agency under work
NASHVILLE, TN  S/N LJ-1817 TSN 1220.0  Every service able propeller and sent out for overhaul.  Sertinent Details on File at This Agency under Work Order Number 4906.  Segmed	For STEVENS AVIATION, Nashville,	TN 37217, CRS VIB3368K	
NASHVILLE, TN  S/N LJ-1817 TSN 1220.0  Every service able propeller and sent out for overhaul.  Sertinent Details on File at This Agency under Work Order Number 4906.  Segmed	+ +		
NASHVILLE, TN  S/N LJ-1817 TSN 1220.0  Every service able propeller and sent out for overhaul.  Sertinent Details on File at This Agency under Work Order Number 4906.  Segmed	Talent AVIATION, INC.	N610SC	ACTT 1220.0
emoved serviceable propeller and sent out for overhaul.  ertinent Details on File at This Agency under Work Order Number 4906.  gned		S/N LJ-1817	HM 1220.0
ertinent Details on File at This Agency under Work Order Number 4906.	November 5, 2013 Right Pr		
gned /////	Removed serviceable propeller and sent ou	at for overhaul.	
	Pertinent Details on File at This Agency ur	nder Work Order Number 4906.	
	Signed M/-/h		
		e, Tn 37217 CRS VIB3368K	

Date	Prop	TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
				THIS PROPELLER/COMPONENT HAS  BEEN OVERHAULED/REPAIRED AS  PER MAINTENANCE RELEASE TAG  UNDER WORK ORDER NO. 20133  DATED 11/12013  FOR: HC-E4N-3N S/N HH2771  MEMPHIS PROPELLER SERVICE, INC.  OLIVE BRANCH, MISSISSIPPI  FAA C.R.S. # PIAR441M  BY:  Trong Vu, Cheif Inspector
		)		
	0			•
	ember 1:	NAS 3, 2013 S/N HH2		S/N LJ-1817 HM 1220.0 TSN 1220.0 TSO 0.0
Wor Pert Sigr	amically rk performinent Defined	balanced med IAW tails on F	d propeller / Microvib file at This	72 mth/4000 hr Overhaul by Memphis Propeller Service Inc. CRS# PI4R441M.  1 to below .1 ips using Dynamic Solutions System Inc. Microvib II Aircraft Analyzer.  2 II and Hawker Beech Maintenance Manual Chapter 61.  3 Ageney under Work Order Number 4906.  N Nashville, Tn 37217 CRS VIB3368K
+				