

Transport Canada Aviation

Transports Canada Aviation

AIRCRAFT TECHNICAL LOGS


Section 4. PROPELLER

1/21 es 21 1/21/21

Second Edition

January 1987





PROPELLER LOG

1.	Make		HARTZELL
2.	Model		HC-F24R-1F
3.	Specification No		
4.	Date of Manufac	ture	1994
5.	Hub Serial No.		CM 10251A.
6.	Blades		
	(a) Design No.		F8468A-4R
	(b) Blade Seria	al Nos.	
	(i)		H.64640
	(ii)		H 64641
	(iii)		THINK IN THE RESERVE AND THE R
	(iv)		THOU SOME THE STANDED TO SEE STANDED TO SE STANDED TO SE STANDED TO SE STANDED TO SE STANDED TO
	(v)		
			BTHEW BOMACROOL KEEL CO. BOLLEGO.
	(c) Pitch Setti		MATHEN OF THE STANDIX O MAINTEN
	(i)	Basic	
	(ii)	High	
	(iii)	Low	
	(iv)	Reverse	ELIGHTHW SOMAGROSCAL

APPENDIX O MAINTENANCE CONFOUNT O XIONES ON A 1 1 2

									PROPELLER SERVICE AND
		DATE 199	5	T HR:	IME RU	N S	TOT SINCE	AL TIM OVERHA	INSTALLATIONS, INSPECTIONS, NOTE: USE BOTH PAGES AND AS MANY LINES AS REQUIRE
		BROUGH						0	
		JAN 24	193		-		21	0	TRANSFERES FROM U.S Logs
			,						
	14	4/16/	10			1	Jez	0	100 HR / ANNUAL INSPECTION CARRIED OUT IN ACCORDANCE WITH TRANSPORT CANADA AWM571/101(a)
									APPENDIXA Brosp Ruked weith Alexantel
		913/97		54	2	-4	1	2	ANNUAL INSPECTION CARRIED OUT IN ACCORDANCE WITH TRANSPORT CANADA CAR 625-86(2), APPENDIX B, PART 1 MAINTENANCE SCHEDULE.
	dug	20/98	2	6	8	5	05		ANNUAL INSPECTION CARRIED OUT IN ACCORDANCE WITH TRANSPORT CANADA CAR 625-86(2), APPENDIX B, PART 1 MAINTENANCE SCHEDULE.
	Sep	19/99		70	1	57.			ANNUAL INSPECTION CARRIED OUT IN ACCORDANCE WITH TRANSPORT CANADA CAR 625-86(2), APPENDIX B, PART 1 Blades Dressel Dressel
1/4	43	-00	3	29	9.	613	5 2	7	ANNUAL INSPECTION CARRIED OUT IN ACCORDANCE WITH TRANSPORT CANADA CAR 625-86(2), APPENDIX B, PART 1, APPENDIX C MAINTENANCE SCHEDULE. B Laces District
1	1	2-02	/		7	631	1	7	ANNUAL INSPECTION CARRIED OUT IN ACCORDANCE WITH TRANSPORT CANADA CAR 625.86(2), APPENDIX B, PART 1, APPENDIX C MAINTENANCE SCHEDULE, Aluxheel #6
PRE	OTAL	HIS PAGE FROM SUMMARY TAL MFG.							CARRIED FORWARD

\	REPAIRS, ADJUSTMENTS, MODIFICATIONS ENTRIES, DRAW A DIAGONAL LINE THROUGH ANY UNUSED LINES IN DATE A	AND TIME COLUMNS.	SIGNATURE	LICENCE
1	"The maintenance descr	ibed has been	1//	
-	performed in accordance	Company of the second s	Add late	071242
-	standards of air worthing		TRUCKS	
	AVIATION UNLIMITED MAINTENANCE "The maintenance descr	ibed has been	1	
	MANSPURI CANADA performada a constante		able ///	
	AMO No. 65-94 standards of airworthing	ess."	The holes	971242
	#/		March 1997	
	*Corled			
Applican	certify thishas been			
	EA HARMON FOR THOUSE TO BUILD AND A CONTRACT OF A CONTRACT			
	AVIATION UNLIMITED MAINTENANCE	THE DESCRIBED	MAINTENANCEHAS	3
-	ABBO DE CONTRACTOR	DEEN DEDENDAME	FOIN AUGUSTUANUS	
	po lolled	A CREEK OF THE REPORT OF THE STATE OF	ARRIVE MICHAEL BILL	ALC:
	Swift Aviation Services	REQUIREMENTS	Jalua Mo	19292
	Drue Lukens of AVIATION UNLIMITED MAINTENANCE	THE DESCRIBE	D MAINTENANCE H	AS.
	TRANSPORT CANADA		MED IN ACCORDAN	CE
	Austrial 46 AMO No. 65-94	WITH THE APP	LICABLE ARYSONTI	HINESS
		REQUIREMENT	S / HOLE BY	16/124
	AVIATION UNLIMITED MAINTENANCE	A CALL SECTION AND ADDRESS OF THE PARTY OF T	ED MAINTENANCE H	IAS
	With Aushall #6 TRANSPORT CANADA AMO No. 65-94	BEEN PERFOR	MED IN ACCORDAN	1CE
	MOVE FELLOSINGE PO AMO No. 65-94	REQUIREMEN	LIVADUZ AHWUHI	HINESS
	and families		1 de de de	272
	With Auroral #6 AVIATION UNLIMITED MAINTENANCE	CF THE DESCRIE	ED MAINTENANCE	HAC
	TRANSPORT CANADA	BEEN PERFO	RMED IN ACCORDA	NCE
-	AMO No. 65-94	WHITHEAP	TLICABLE AIRWING	THINESS
-	MOTOSTATONE	REQUIREMEN	VIS /////	
			11000	7120
1				
	-1			
,	W/K	ALADIO FARE COMO		
	AVIATION UNLIMITED MAINTE TRANSPORT CANADA	NANCUME DESC	RIBED MAINTENAN	CEHAS
	AMO No. 65-94	WITH THE	THIMED IN ACCOR	DANCE
-		REQUIREM	APPLICABLE AIRWANTS OF THE PROPERTY OF THE PRO	ATHINES
,			1 Haca	- 71Z

PROPELLER SERVICE AND

					, , , , , , , , , , , , , , , , , , ,
DATE	TIME	RUN	CONTRACTOR OF THE PROPERTY OF	L TIME VERHAUL	INSTALLATIONS, INSPECTIONS,
	HRS.	MIN.	HRS.	MIN.	NOTE: USE BOTH PAGES AND AS MANY LINES AS REQUIRED FOR COMPLETE
BROUGHT					
7-3-02			703	1	GREATED PROP WITH AMOSHER #6. AD
					BLADER S/NI PER (a) (1).
					dispesta contractation of a BOMAMETONAM CENTRAL PROPERTY.
		o led			AND STREET OF THE PARTY OF THE
					REDRIED PONTERED TO THE PROPERTY OF THE PARTY OF THE PART
21					
97103	985	-			I certify that this Roof has been 7
					I certify that this Recordance with F.A.R. 43,
					and was determined to be in Airworthy
) CONGUNO
					Swift Aviation Services PAP 3840 W36
					AN EXENANCE PROPERTY OF THE PROPERTY AND
					POR CONTRACTOR OF THE PARTY OF
					Market Ma
			015551	7 71 5 6 70	
					AGRANGED THE THE PERSON OF THE STATE OF THE
	MAN A	NAME OF THE PERSON OF THE PERS	10 10 10 10 10 10 10 10 10 10 10 10 10 1	353 35 FG	The state of the s
NAME OF THE PERSON OF THE PERS					ASSINOTATED TATES IN
					35) W - 4 / 3 - 4 / 3 - 4 / 3 - 4 / 3 - 4 / 3 - 4 / 3 - 4 / 3 / 3 / 3 / 3 / 3 / 3 / 3 / 3 / 3 /
				TO THE PARTY	
			THE REAL PROPERTY.	199	ACCUPATION OF THE PARTY OF THE
				0	CARRIED FORWARD
TOTAL THIS PAGE	CONTRACTOR OF THE PROPERTY OF				
TOTAL FROM PREVIOUS SUMMARY					
TOTAL SINCE MEG					

		REPAIRS, ADJUSTMENTS,	MODIFICA	TIONS		SIGNATURE	LICENC
	ENTRIES. DRAW A DI	AGONAL LINE THROUGH ANY UNUS	SED LINES IN	DATE AND TIME	COLUMNS.		
2-	09-08 500	RACKORY A.O. 77-12	2-0602	-0.N.A.	34		
	Appendix and was of condition.	In accordance with F.A.I D for an 100 hr. inspecti letermined to be in Airwo tion Services	on orthy				
			4Die				
		Shoreline Aviate 93 Old Colony Marshfield, MA 781-837-85	y Lane 02050				
	as a g and refunction that this	00 00 0004 T	faces. Groase or oil lea	ade leading edges und runup and ks noted. I certify			
	Edwar Edwar	vary AMoral J. Novak W. A+P 22445833 A					
					Marshfi	eld, MA 02050 -837-8521	
			Da	: N14PZ te: 09-26-2005 Tac			PropTT: 1459.1
			Pro	opeller removed for	overhaul du	e to calendar time.	
			A DE	Elwand J. Novak Jr. A	Hora +P 2832024	y	

It is important to understand that the oxide It is important to discontance with the national regulation of the country specified in Block 1.

Where the user/installer performs work in accordance with the national regulation of the country specified in Block 1. Where the user/installer performs work in accepts parts/components/assemblies from the airworthiness authority of the country specified in Block 1.

that his/her airworthiness authority accepts parts/components/assemblies from the airworthiness authority of the country specified in Block 1. that his/her airworthiness authority accordance with the national regulations by the Statements in Blocks 14 and 19 do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the Statements in Blocks 14 and 19 do not constitute installation certification. * Installer must cross check eligibility with applicable technical data. before the aircraft may be flown. PROPELLER SERVICE FAA Form 8130-3 (6-01) INSTALLATIONS, INSPECTIONS, INSTALLATIONS, LINES AS REQUIRED FOR COMPLETE DATE TIME RUN TOTAL TIME SINCE OVERHAUL HC-F248-1F/F8468A-4R HRS. BROUGHT MIN. HRS. MIN. FORWARD MAJOR OVERHAUL. BLADES REFINISHED, PARTS FLORESCENT PENETRANT INSPECTED, MAGNAFLUXED, REPLATED & REPLATED & REPLACED WHERE REQUIRED. PROPELLER TRACKED, BALANCED, PLACED WHERE REQUIRED. PROPELLER TRACKED, BALANCED, SET ANGLES GREASED & PAINTED, COMPLIES WITH AD'S & SET ANGLES GREASED & PAINTED, COMPLIES WITH AD'S & SET ANGLES GREASED & PAINTED, COMPLIES WITH AD'S & SE'S LISTED ON BI30-3 FORM. BLADE KNOBS 00 SHOTPEENED. AUTHORIZED BY THE NEW ENGLAND PROPELLER SERVICE INC. EAST HADDAM, CT FAAREPAR STATION # RC2R130L 1-800-876-8377 Shoreline Aviation, Inc. 93 Old Colony Lane Marshfield, MA 02050 781-837-8521 PropTT: 1459.1 Ser. #: 28-11050 N#: N14PZ TSMOH: 0.0 Date: 10-11-2005 Tach: 1459.1 ACTT: 1459.1 Completed Annual insection per FAR 43, appendix D using Piper form 230-811 as a guide. Propeller reinstalled after overhaul as shown in the previous log entry. Ground runup completed satisfactorily with no grease or oil leaks noted. I certify that this propeller has been inspected in accordance with an annual inspection and was determined to be in airworthy condition. ME CONTRACT OF THE STATE OF THE Edward J. Novak Jr. A+P 2832024 IA Shoreline Aviation, Inc. 93 Old Colony Lane Marshfield, MA 02050 781-837-8521 N#: N14PZ PropTT: 1661.1 Ser. #: 2811050 Date: 11-01-2006 TSMOH: 202.0 Tach: 1661.1 ACTT: 1661.1 Completed Annual insection per FAR 43, appendix D using Piper form 230-811 as a guide. Ground runup completed satisfactorily with no grease or oil leaks noted. I certify that this propeller has been inspected in accordance with an annual inspection and was determined to be in airworthy condition. TOTAL THIS PAGE

3. Form Tracking No .: AUTHORIZED RELEASE CERTIFICATE Approving National Aviation FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG Authority/Country: FAA/United States 5. Work Order/Contract/Invoice Number: New England Propeller Service, Inc. P.O. Box 244 East Haddam, CT 06423-2388 4. Organization: CR-31779 (860) 873-1494 • Fax: (860) 873-2388 RC2R130L 12. Status Work: 11. Serial/Batch Number: 10. Quantity: 9. Eligibility:* 8. Part Number: 7. Description: PROPELLER F8468A-4R NIA CM1025A OVERHAULED This propeller was inspected and repaired in accordance with manufacturer's manual: 1136R30,133CR19,202AR2C(VIR28,V2R28,V3R28, Total Time: 1459.1 hrs. Time Since Overhaul: 00.00 The following work was performed: MAJOR OVERHAUL. BLADES REFINISHED. PARTS FLORESCENT BLADE SN'S PENETRANT INSPECTED, MAGNAFLUXED, REPLATED & RE-H64640 PLACED WHERE REQUIRED. PROPELLER TRACKED, BALANCED. H64641 SET ANGLES GREASED & PAINTED, COMPLIES WITH AD'S & SB'S LISTED ON 8130-3 FORM. BLADE KNOBS SHOTPEENED. MAJOR PARTS REPLACED The following Service Bulletins have been complied with; Nomenclature Part # Qty. Reason Completed Annual insection per FAR 43, appendix D using Piper form 230-811 as a guide. Propeller reinstalled after overhaul as shown in the previous log entry. Ground runup completed satisfactorily with no grease or oil leaks noted. I certify that this propeller has been inspected in accordance with an annual inspection and was determined to be in airworthy condition. Shoreline Aviation, Inc. 93 Old Colony Lane Marshfield, MA 02050 781-837-8521 N#: N14PZ Ser. #: 2811050 Date: 11-01-2006 PropTT: 1661.1 Tach: 1661.1 ACTT: 1661.1 Completed Annual insection per FAR 43, appendix D using Piper form 230-811 as a guide. Ground runup completed satisfactorily with no in accordance with noted. I certify that this propeller has been inspected in accordance with an annual inspection and was determined to be in TOTAL THIS PAGE TOTAL FROM

PREVIOUS

	NS	THE COLUMN TWO IS NOT THE OWNER, THE PARTY OF THE PARTY O	SIGNATURE	LICENCE NUMBER
REPAIRS, ADJUSTMENTS, MODIFICATION OF AWA DIAGONAL LINE THROUGH ANY UNUSED LINES IN CO.	ATE AND TIME COLL	UMNS.		
Shoreline Aviation, Inc				
93 Old Colony Lane Marshfield, MA 02050				
781-837-8521	TSO: 387.3			
	ropTT: 1846.4			
Completed Appual inspection per FAR 43, appendix D	using Piper			
form 230-811 as a guide. Ground run up ok. on leaks no that this Propeller has been inspected in accordance wit	II all allitual			
inspection and was determined to be in airworthy conditi	ion.			
11/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1				
1 homes C. Abel				
Thomas D. Hall 2351789IA				
LOGBOOK ENTR ENGINE	OY .			
	A/C: N14PZ			
	A/C: N14PZ	CONTROL OF A CONTROL OF STREET	COS SECURIOR DE LA COSTA DEL COSTA DE LA COSTA DEL COSTA DE LA COSTA DE LA COSTA DE LA COSTA DEL COSTA DE LA COSTA DEL COSTA DE LA COSTA DEL COSTA DE LA COSTA DEL COSTA DE LA COSTA DEL COSTA DE LA COSTA DE LA COSTA DE LA COSTA DE LA COSTA DEL COSTA DE LA COSTA DEL COSTA DEL COSTA DEL COSTA DEL COSTA DEL COSTA DE LA COSTA DEL COS	
Name: Paul Zavracky W O · 5750	Tach Time: 1898.6			
W.O.: 5750 Date: 5/22/08	Tach Time: 1898.6 AC S/N: 2811050			
W.O.: 5750 Date: 5/22/08 Serviced engine with 12 ats Aeroshell 15W50. Insta	Tach Time: 1898.6 AC S/N: 2811050 Iled new oil filter			
W.O.: 5750 Date: 5/22/08 Serviced engine with 12 qts Aeroshell 15W50. Insta [P/N ES48103]. Sample taken, submit for analysis. check satisfactory. See work order for detail.	Tach Time: 1898.6 AC S/N: 2811050 Iled new oil filter Engine run and leak			
W.O.: 5750 Date: 5/22/08 Serviced engine with 12 qts Aeroshell 15W50. Insta [P/N ES48103]. Sample taken, submit for analysis. check satisfactory. See work order for detail. With respect to the work performed and described a	Tach Time: 1898.6 AC S/N: 2811050 Iled new oil filter Engine run and leak			
W.O.: 5750 Date: 5/22/08 Serviced engine with 12 qts Aeroshell 15W50. Insta [P/N ES48103]. Sample taken, submit for analysis. check satisfactory. See work order for detail.	Tach Time: 1898.6 AC S/N: 2811050 Iled new oil filter Engine run and leak bove, this aircraft is			
W.O.: 5750 Date: 5/22/08 Serviced engine with 12 qts Aeroshell 15W50. Insta [P/N ES48103]. Sample taken, submit for analysis. check satisfactory. See work order for detail. With respect to the work performed and described a approved for return to service. Signature:	Tach Time: 1898.6 AC S/N: 2811050 Iled new oil filter Engine run and leak			
W.O.: 5750 Date: 5/22/08 Serviced engine with 12 qts Aeroshell 15W50. Insta [P/N ES48103]. Sample taken, submit for analysis. check satisfactory. See work order for detail. With respect to the work performed and described a approved for return to service. Signature: Christopher Voggt FlightLevel Norwood LLC - Mainte	Tach Time: 1898.6 AC S/N: 2811050 Iled new oil filter Engine run and leak bove, this aircraft is A&P 3223075 nance			
W.O.: 5750 Date: 5/22/08 Serviced engine with 12 qts Aeroshell 15W50. Insta [P/N ES48103]. Sample taken, submit for analysis. check satisfactory. See work order for detail. With respect to the work performed and described a approved for return to service. Signature:	Tach Time: 1898.6 AC S/N: 2811050 Iled new oil filter Engine run and leak bove, this aircraft is A&P 3223075 nance		Shoreline Aviation, In 93 Old Colony Lane	
W.O.: 5750 Date: 5/22/08 Serviced engine with 12 qts Aeroshell 15W50. Insta [P/N ES48103]. Sample taken, submit for analysis. check satisfactory. See work order for detail. With respect to the work performed and described a approved for return to service. Signature: Christopher Voggt FlightLevel Norwood LLC - Mainte	Tach Time: 1898.6 AC S/N: 2811050 Iled new oil filter Engine run and leak bove, this aircraft is A&P 3223075 nance		Shoreline Aviation, In 93 Old Colony Lane Marshfield, MA 0205 781-837-8521	
W.O.: 5750 Date: 5/22/08 Serviced engine with 12 qts Aeroshell 15W50. Insta [P/N ES48103]. Sample taken, submit for analysis. check satisfactory. See work order for detail. With respect to the work performed and described a approved for return to service. Signature: Christopher Voggt FlightLevel Norwood LLC - Mainte	Tach Time: 1898.6 AC S/N: 2811050 Illed new oil filter Engine run and leak bove, this aircraft is A&P 3223075 nance		93 Old Colony Lane Marshfield, MA 0205 781-837-8521	O PropTT: 1
W.O.: 5750 Date: 5/22/08 Serviced engine with 12 qts Aeroshell 15W50. Insta [P/N ES48103]. Sample taken, submit for analysis. check satisfactory. See work order for detail. With respect to the work performed and described a approved for return to service. Signature: Christopher Voøgt FlightLevel Norwood LLC - Mainte 209 Access Rd., Norwood, MA 02	Tach Time: 1898.6 AC S/N: 2811050 Illed new oil filter Engine run and leak bove, this aircraft is A&P 3223075 nance N#: N14PZ Date: 12-05-2008	Ser. #: 28 Tach: 19	93 Old Colony Lane Marshfield, MA 0205 781-837-8521 811050 85.0 ACTT: 198	PropTT: 1 85.0 TSMOH:
W.O.: 5750 Date: 5/22/08 Serviced engine with 12 qts Aeroshell 15W50. Insta [P/N ES48103]. Sample taken, submit for analysis. check satisfactory. See work order for detail. With respect to the work performed and described a approved for return to service. Signature: Christopher Voøgt FlightLevel Norwood LLC - Mainte 209 Access Rd., Norwood, MA 02	Tach Time: 1898.6 AC S/N: 2811050 Illed new oil filter Engine run and leak bove, this aircraft is A&P 3223075 nance N#: N14PZ Date: 12-05-2008 Completed Annu	Ser. #: 28 Tach: 19 al insp. p	93 Old Colony Lane Marshfield, MA 0205 781-837-8521 85.0 ACTT: 198 er FAR 43, app. Dud d runup and function	PropTT: 1 85.0 TSMOH: using Piper form 2 nal check satisfac
W.O.: 5750 Date: 5/22/08 Serviced engine with 12 qts Aeroshell 15W50. Insta [P/N ES48103]. Sample taken, submit for analysis. check satisfactory. See work order for detail. With respect to the work performed and described a approved for return to service. Signature: Christopher Voøgt FlightLevel Norwood LLC - Mainte 209 Access Rd., Norwood, MA 02	Tach Time: 1898.6 AC S/N: 2811050 Illed new oil filter Engine run and leak bove, this aircraft is A&P 3223075 nance N#: N14PZ Date: 12-05-2008 Completed Annuas a guide. Engine	Ser. #: 28 Tach: 19 al insp. p	93 Old Colony Lane Marshfield, MA 0205 781-837-8521 811050 85.0 ACTT: 198	PropTT: 1 85.0 TSMOH: using Piper form 2 nal check satisfact propeller has be

PROPELLER SERVICE AND

DATE	TIMERUN	SINCE OVERHAUL	NOTE: USE SOLUTIONS	TALLATIONS, INSPECTIONS
	HRS. MIN.	HRS. MIN.	NOTE: USE BOTH PAGES	TALLATIONS, INSPECTIONS, S AND AS MANY LINES AS REQUIRED FOR COMPLE
BROUGHT				OR COMPLE
	2-1	10	4.0.1	
	Cortifu that	-10 TACH	Mir allo has been.	100 TIT. 2181.
	- Secondary TIT ()	ICCOLGANCA WILL	0 11 10 11 11	TIMOH: 722 Hrs
		TO TO THE PERIOR	. CO DO 224	
146	echanic (n)	Lasty Lie	TA-1480872	
		7		
314111 B	S.			
Tach & Acft. TT 23				
		F	agle Fact	Fng Total 4:
		MARKET	agle East Aviation	Eng Total time and TSMOH 189 Prop TT 2341 and TSMOH 882
Complied with				- TOIMOH 882
Complied with Pipe	er AD10-15-10 (C)	n accordance with FA	AR 43 appendix D.	
		"		hecked all AD's through biweekly 11-04.
ondition.	ppeller has been in	spected in accordance	e with an annual inspection	hecked all AD's through biweekly 11-04. Ind was determined to be in an airworthy
			Thispection a	nd was determined to be in an airworthy
				Brian Eason AP17326119IA
02/17/12				
Tach, Acft TT Pro			Atlantic Aircraft Serv	ices
Complied with an	annual inspection	in accordance with T	Lawrence Municipal A N. Andover Ma. 0184 AR 43 appendix D.	irport N14PZ Eng TT 274
				Prop TSMOH 967
certify that this no	opeller has been in	nspected in accordant	painted.	2.
condition		accordant	e with an annual inspection.	
condition. Brian Ea	Son AP17326119L		Poction	and was determined to be in an airworth.
condition. Brian Ea	Son AP17326119L	A	Pocton	and was determined to be in an airworthy
condition. Brian Ea	Manufacture and a second			and was determined to be in an airworthy
condition. Brian Ea	Model HC-F2YR		A W.0 56044-5604	and was determined to be in an airworthy
Brian Ea	Model HC-F2YR	-11 Series Bassons		and was determined to be in an airworthy
Brian Ea	Model HC-F2YR	-11 Series Bassons		and was determined to be in an airworthy
Brian Ea	Model HC-F2YR	-11 Series Bassons		and was determined to be in an airworthy
Brian Ea	Model HC-F2YR	-11 Series Bassons		and was determined to be in an airworthy
Brian Ea	Model HC-F2YR	-11 Series Bassons		and was determined to be in an airworthy
Brian Ea	Model HC-F2YR	-11 Series Bassons		and was determined to be in an airworthy
Make: Hartzell Date: 2/22/2013 On this date: Drassed and pair Abs thecked thru Lenily hat this Pro- and making in EAR P. By. James P On Les Griffin A	Model HC-F2YR	-11 Series Bassons		and was determined to be in an airworthy
Make: Hartzell Date: 2/22/2013 On this date: Drassed and pair Abs checked thru I Contly hat this Pro actilities Por La Griffin A	Model HC-F2YR	-11 Series Bassons		and was determined to be in an airworthy
Make: Hartzell Date: 2/22/2013 On this date: Drassed and pair Alle thecked thru I Conity hat this Promodulated in FAR P. By Griffin Alles	Model HC-F2YR	-11 Series Bassons		and was determined to be in an airworthy
Make: Hartzell Date: 2/22/2013 On this date: Dissect and pair Alls checked thru Leanity had this Promodulated in FAR P. By. Street Port La. Griffin All IIS PAGE	Model HC-F2YR	-11 Series Bassons		and was determined to be in an airworthy
Make: Hartzell Date: 2/22/2013 On this date: Drassed and pair Abs uncoked thru I Comity hat this Promodulated in FAR Pair By Griffin Al	Model HC-F2YR	-11 Series Bassons		and was determined to be in an airworthy

NUMBER SIGNATURE REPAIRS, ADJUSTMENTS, MODIFICATIONS ENTRIES, DRAW A DIAGONAL LINE THROUGH ANY UNUSED LINES IN DATE AND TIME COLUMNS. N14PZ Eng TT 442 Atlantic Aircraft Services 12/04/13 Prop TSMOH 1135 Lawrence Municipal Airport Tach, Acft TT Prop TT 2594 N. Andover Ma. 01845 Complied with an annual inspection in accordance with FAR 43 appendix D. I certify that this propeller has been inspected in accordance with an annual inspection and was determined to be in an airworthy condition. Brian Eason AP17326119IA N14PZ Atlantic Aircraft Services Eng TT 558 10/08/14 Prop TSMOH 1251 Lawrence Municipal Airport Tach, Acft TT Prop TT 2710 N. Andover Ma. 01845 Complied with Bendix AD76-07-12R1 (Switch Ops Test), Piper AD95-26-12 (Oil Cooler Hose Insp), and checked all AD's through Complied with an annual inspection in accordance with FAR 43 appendix D. biweekly 2014-19. I certify that this propeller has been inspected in accordance with an annual inspection and was determined to be in an airworthy condition. Brian Eason AP17326119IA N14PZ Lawrence Airmotive LC Eng TT 698 39/10/15 Lawrence Municipal Airport Prop TSMOH 1391 Acft TT Prop TT 2850 N. Andover Ma. 01845 redied with an annual inspection in accordance with FAR 45 appendix D. wited with Bendix AD76-07-12R1 (Switch Ops Test), Piper AD95-26-12 (Oil Cooler Hose Insp), and checked all AD's through cicly 2015-18. ther was cleaned, leading edges dressed, and face repainted. tilly that this propeller has been inspected in accordance with an annual inspection and was determined to be in an airworthy condition Nickolas Flammia AP33395111A N14PZ Lawrence Airmotive LLC 07/29/2016 Lawrence Municipal Airport Tach: 2958 N. Andover, MA 01845 Removed propeller for overhaul at Sensenich Propeller Service. Reinstalled after overhaul with new seal. Nickolas Flammia AP3339511 N14PZ Lawrence Airmotive LLC 09/26/2016 EngTT: 828 Lawrence Municipal Airport Tach, A/F, PropTT: 2980 **PSMO: 22** N. Andover, MA 0184 Complied with an annual inspection I/A/W FAR43 App. D. Complied with Bendix AD76-07-12R1 (Switch), Piper AD95-26-12 (Oil Cooler Hose), checked all other Ads through biweekly 2016-18. Propeller was cleaned, leading edges dressed and aft face repainted. I certify this propeller was inspected in accordance with an annual inspection and determined to be in an airworthy condition. Nickolas Flammia AP3339511IA

been	inspecte	ed in accordance	with an ann	ual inspection	and was uc		ed to be in an airwo		N14PZ
THE RESERVE THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TWO IS NAMED IN COLUMN TWO I	2850	ection in accord	lance with F/	Lawrence Lawrence N. Andov	ylunicioal er Ma 018	Astrort 45		Pro	Eng TT 698 p TSMOH 1391
ear pr	I. Appro	oving Civil Aviation thority / Country: NITED STATES	AUTH	OPTOD I	RELEA	SF C	Hose Inan) and the ERTIFICATI PROVAL TAG		racking Number: 16-0119 Order/Contract/Invoice No. CTO5919
	4. Organiza 6. Item:	7. Description:	21 Airport Road 8. P	- North Windham, Cart Number: HC-F2YR-1F	9. Quantity:	10.	Serial Number: CM1025A		Status / Work: OVERHAULED
ap	SERVIC	E LITERATURE RE	R IAW: HARTZ	'S: N/A			R32, 202A V1 R52, V2 F	29,V3 R37,V6	R34, V7 R41, V8 R31
258 ed p	SERVIC SB'S: 11	AULED PROPELLE V10 R34, V11 R36 E LITERATURE RE 8F R1 02/20/08,136 Y R9 12/22/15,177 0 SER NUMBERS: H	R IAW: HARTZ EFERENCED: AD R1 04/25/03 02/04/97,217 03/2	'S: N/A 1/03,267 03/19/07,				29,V3 R37,V6	R34, V7 R41, V8 R31
258 ed p	SERVIC SB'S: 11 SL'S: 61 BLADE TTSN:U TSO: -0-	AULED PROPELLE V10 R34, V11 R36 E LITERATURE RE 8F R1 02/20/08,136 Y R9 12/22/15,177 0 SER NUMBERS: H NK crtifies the items identified Approved design	R IAW: HARTZ EFERENCED: AD R1 04/25/03 02/04/97,217 03/2 64641,H64640	red in conformity to:	278 11/05/08,3	14a. Certi described. Fede		Other reg	ulation specified in Block 12 work identified in Block 11 ar
58 d p	SERVIC SB'S: 11 SL'S: 61 BLADE TTSN:U TSO: -0-	AULED PROPELLE V10 R34, V11 R36 E LITERATURE RE 8F R1 02/20/08,136 Y R9 12/22/15,177 0 SER NUMBERS: H NK crtifies the items identified Approved design	ER IAW: HARTZ EFERENCED: AD R1 04/25/03 02/04/97,217 03/2 64641,H64640 above were manufact data and are in a cond	ured in conformity to: lition for safe operation. Block 12. 13c. Approval/A	278 11/05/08,3 uthorization No.:	14a. Certidese Federal To see	14 CFR 43.9 Return to Service ifies that unless otherwise specification of the Block 12 was accomplished in Block 12 was accomplished and in recruice. Service.	Other reg	ulation specified in Block 12 work identified in Block 11 are with Title 14, Code of the items are approved for retained to the items are approved for retained to the CRS QOPRO113
ed p : 29 ann ndix	SERVIC SB'S: 11 SL'S: 61 BLADE TTSN:U TSO: -0-	AULED PROPELLE V10 R34, V11 R36 E LITERATURE RE 8F R1 02/20/08,136 Y R9 12/22/15,177 O SER NUMBERS: H NK ertifies the items identified Approved design Non-approved design	ER IAW: HARTZ EFERENCED: AD R1 04/25/03 02/04/97,217 03/2 64641,H64640 above were manufact data and are in a cond esign data specified in	ured in conformity to: ition for safe operation. Block 12. 13c. Approval/A 13e. Date (dd/m 00/00	uthorization No.:	14a. Certi described to see 14b. Auth	14 CFR 43.9 Return to Service iffies that unless otherwise specification in Block 12 was accomplised and Regulations, part 43 and in recruice. The Control of Printed is a service if it is a service in BLAIR D WAGE!	Other regulation of the state o	ulation specified in Block 12 work identified in Block 11 are with Title 14, Code of the items are approved for ret
ed p : 29 ann ndix aned eller	SERVIC SB'S: 11 SL'S: 61 BLADE TTSN:U TSO: -0-	AULED PROPELLE V10 R34, V11 R36 E LITERATURE RE 8F R1 02/20/08,136 Y R9 12/22/15,177 0 SER NUMBERS: H NK crtifies the items identified Approved design Non-approved de norized Signature: ne (Typed or Printed): ortant to understand that the ne user/installer performs we	EFERENCED: AD R1 04/25/03 02/04/97,217 03/2 64641,H64640 data and are in a conduction of the control of the con	ured in conformity to: ition for safe operation. Block 12. 13c. Approval/A 13e. Date (dd/m 00/00 Usument alone does not auto the the national regulations reworthiness authority accellation certification. In all	authorization No.: omm/yyyy): 0/00 ser/Installer Recomatically constitutes of an airworthing cepts aircraft engine	14a. Certidese Federal Sponsibiling authority (es)/propelle	14 CFR 43.9 Return to Service iffies that unless otherwise specification in Block 12 was accomplised and Regulations, part 43 and in recruice. The Control of Printed is a service if it is a service in BLAIR D WAGE!	Other regulation of the countries authority of t	ulation specified in Block 12 work identified in Block 11 are with Title 14, Code of the items are approved for retained the items are approved for retained the CRS QOPRO113 14e. Date (dd/mmm/yyyy) 26 JUL 2016 atry specified in Block 1, the country specified in Block 1

N. Andover Ma. 01843

