

N617DA

Propeller Logbook



SENSENICH PROPELLER SERVICE, INC.

McCauley	<input type="checkbox"/>
Hartzell	<input checked="" type="checkbox"/>
MT	<input type="checkbox"/>
Sensenich	<input type="checkbox"/>
Dowty	<input type="checkbox"/>
Hamilton Standard	<input type="checkbox"/>

PSN: EF476B

INSTALLING AGENCY PLEASE NOTE:
Recording of Propeller Total Time Since New (TTSN)
is Required Per F.A.R. 91.417

Lancaster Airport, 519 East Airport Road, Lititz, PA 17543 (800) 462-3412 (717) 560-3711 Fax: (717) 560-4354 FAA Certified Repair Station #QV9R194N

Lee Gilmer Memorial Airport, 1245 Palmour Place, Suite A, Gainesville, GA 30501 (800) 791-7767 (770) 538-0444 Fax: (770) 538-0117 FAA Certified Repair Station #S46R346N

Propeller Model BHC-J2YF-1BF

Blade Model F7694

Hub Serial No. EF476B

Blade Serial No. 1 K63030

2 K63031

3 _____

4 _____

5 _____

6 _____



INSTALLATION HISTORY

[illegible]

SERVICE HISTORY

[illegible]

SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description of Work	Authorized Signatures
<div style="display: flex; justify-content: space-between; align-items: center;"> <div> <p>Make: Hartzell</p> <p>Model: BHC-J2YF-1BF</p> <p>S/N: EF476B</p> </div> <div style="text-align: center;">  <p>ADVANCED WINGS</p> </div> <div> <p>Date: 03/01/2021</p> <p>N617DA</p> <p>Hobbs: 4476.2</p> <p>Flight: 3249.4</p> <p>Propeller TT: 3249.4</p> <p>PSMOit: 0.0</p> </div> </div>				
<p>Propeller Entry:</p> <p>Removed and reinstalled propeller after overhaul by Sensenich Propeller Service Inc. under W/O: L4245 Dated: 02/22/2021. Performed an Annual inspection IAW FAR 43. Appendix D. using Cirrus MM Chapter 5-20 as reference. AD's checked through 2021-05 biweekly. Details of this inspection are on file at this facility under work order #LWO-13773. END</p>				
<p>I certify that this PROPELLER has been Inspected IAW an Annual Inspection and was determined to be in airworthy condition.</p>				
<div style="display: flex; justify-content: space-between; align-items: center;"> <div> <p>Joe DiSipio</p> <p>A&P39536851A</p> </div> <div style="text-align: center;">  </div> </div>				

SERVICE HISTORY

Date	Propeller Logbook Entry	Paragon Aircraft Service, Inc. 19 Wright Way, Fairfield, NJ 07004 Phone: (973)575-0364 Fax (973)244-1884					Authorized Cirrus Service Center		
		Date	N' Number	Make/Model	Serial#	Flight		SPOH	Total Time
		3/18/2022	N617DA	BHC-J2YF-1BF	EF476B	3294.7	45.3	3294.7	10924
I certify that this Propeller has been inspected in accordance with an Annual Inspection and determined to be in an airworthy condition.									
I certify that the work described above was performed satisfactorily and in accordance with approved/acceptable data and is approved for return to service with regard to work performed.									
Authorized Signature:  Steven VanderValk A&P 2919106 IA									

wo: 4223		Propeller - page 1 of 1	
			
Sweet Aviation · 902 W. Ludwig Rd Ste 118 · Fort Wayne, IN 46825 · (260) 267-5505			
N617DA hobbs: 4635.6	Hartzell, BHC-J2YF-1BF/F7694, S/N: EF476B tach: 3355.1	April 03, 2023	
PTSN: 138.3 1. Propeller blades dressed. 2. Propeller hub greased with: Aeroshell 5. 3. Propeller tracking checked.			
I certify that this propeller has been inspected in accordance with an ANNUAL Inspection and found to be in an airworthy condition.			
With respect to the work performed, this propeller is approved for return to service. Details of work performed are on file with Sweet Aviation under work order: 4223.			
Tom Mollenauer A&P IA 4696240 			

Date: 06/07/2024

Hours: Hobbs:4703.1 Flight:3396.5 TSN:147.1

Tail: N617DA

Make: Hartzell

Model: BHC-J2YF/F7694

S/N: EF476B

Name: Josh Green

Cert: AP4324650

Co: Rise Up Aviation

Signed:

Josh Breen

signatures

Performed Annual inspection on propeller I/A/W Appendix D, Removed spinner, serviced with aeroshell 5 grease. 5 pumps on each fitting, Checked blade for play and nicks, reinstalled spinner. Installed Placard in view of pilot that states, prohibited flight if OAT is under -40 degrees F. Per Hartzell maintenance practices manual 61-00-15 under approved lubricants.

I hereby certify that this propeller was inspected in accordance with an Annual Inspection in the scope and detail of 14 CFR Part 43, Appendix D and is determined to be in an airworthy condition as of the date of this logbook service record.

Robert Coyle

De C2

AP3150828IA

[illegible]



N617DA
Hartzell
Date: 5/20/2025

Cirrus
8HC-J2YF-1RF
Hobbs: 4750.8

EAGLE POINT AVIATION LLC
156 Howard Woltz Jr. Way Mount Airy, NC 27030

SR20

S/N: 1867

S/N EF476B


TTAF: 3424.7

TTP: 3424.7

TSMOH: 175.3

Completed Propeller Annual Inspection per locally generated guide per CFR Part 43 Appendix D
Dressed nicks from prop leading edge.

The propeller identified above was inspected in accordance with an ANNUAL INSPECTION utilizing locally generated guide per CFR Part 43 Appendix D, current manufacturer's technical data and current Federal Aviation Regulations. Parts replaced or repaired meet standards set forth by current FAR's. The propeller is in airworthy condition and is therefore approved for return to service. WO# 430 on file.


Michael J. Thompson 96689416 1A