

Cirrus SR22
**Airworthiness Directives
Compliance Report**

Date: 10/27/2025	Tail #: 658PG	
Airframe: Cirrus SR22	S/N: 4820	Hours: TT: 1021.1 Hobbs: 822.1
Front Engine: Continental Motors IO-550-N	S/N: 1037759	Hours: TTE: 822.1
Nose Propeller: Hartzell PHC-I3YF-1	S/N: FP9498B	Hours: TTP: 822.1

Airframe: Cirrus SR22							
AD# Eff Date Category	Subject	Date/Hours at Compliance	Method of Compliance	Notes	Rec	Date/Hours Next Due	Signature and Number
2006-21-03 11/17/2006 Airframe	Prevent overheating damage to the brake caliper piston O-ring seals	3 Nov 25 1021.1	N/A by aircraft serial number		No		Seth Miller 3252306
2023-09-09 07/17/2023 Airframe	Failures of Spot-Welded Multi-Segment V-Band Couplings	3 Nov 25 1021.1	N/A - affected part(s) not installed		No		Seth Miller 3252306
2024-24-11 12/23/2024 Airframe	Upper Power Lever	20 Dec 24 785.4	C/W by inspection IAW Cirrus SB2X-76-05		Yes	Flight: 895.4	Randall Weaver CRS 1MYD828C

Front Engine: Continental Motors IO-550-N							
AD# Eff Date Category	Subject	Date/Hours at Compliance	Method of Compliance	Notes	Rec	Date/Hours Next Due	Signature and Number
2020-16-11 09/21/2020 Engine	Cross-Flow Cylinder Assemblies Integrity	3 Nov 25 1021.1	N/A - affected cylinders not installed per s/n and "S" stamping		No		Seth Miller 3252306
2023-02-12 02/17/2023 Engine	Intake Valve Failures	3 Nov 25 1021.1	N/A - affected cylinders not installed		No		Seth Miller 3252306
2023-05-16 03/15/2023 Engine	Improper Installation of Counterweight Retaining Rings	3 Nov 25 1021.1	N/A - affected crankshaft not installed		No		Seth Miller 3252306
2023-09-09 07/17/2023 Engine	Failures of Spot-Welded Multi-Segment V-Band Couplings	3 Nov 25 1021.1	N/A - affected part(s) not installed		No		Seth Miller 3252306
2023-17-04 10/26/2023 Engine	STC F&M or Stratus Oil Filter Adapter Fiber Gasket Oil Loss	3 Nov 25 1021.1	N/A - affected STC not installed		No		Seth Miller 3252306

Appliance: Propeller Governors							
AD# Eff Date Category	Subject	Date/Hours at Compliance	Method of Compliance	Notes	Rec	Date/Hours Next Due	Signature and Number
2020-19-06 11/03/2020 Appliance	Idle Gear Bearing Unapproved Variant	3 Nov 25 1021.1	N/A by propeller governor serial number		No		Seth Miller 3252306

Appliance: Power Plant Ignition - Switches							
AD# Eff Date Category	Subject	Date/Hours at Compliance	Method of Compliance	Notes	Rec	Date/Hours Next Due	Signature and Number
93-05-06 04/29/1993 Appliance	ACS Ignition switches	3 Nov 25 1021.1	Due IAW ACS SB92-01 at TTAF: 2000.0		Yes	2000.0	Seth Miller 3252306