

NEW RECIPROCATING ENGINE CERTIFICATE

This is to certify that the engine as described hereinafter has been manufactured run-in and tested as prescribed by **TEXTRON LYCOMING** specifications and Federal Aviation Regulations. No further run-in is required. All applicable Federal Aviation Administration Directives and Textron Lycoming Service Bulletins have been complied with at time of Manufacture.

0-360-A4M	L-38089-36A
MODEL 2-20-01	Goe more
DATE	(AUTHORIZED REPRESENTATIVE)

TEXTRON Lycoming

652 Oliver Street Williamsport, PA 17701 U.S.A.

FORM NO. 777-B (Rev. 3/94)

OWNER

N53 2 3 AIRCRAFTSALES & BROKERAGIA	24P 16
3 AIRCRAFT SALES & BROKERAGE	MAY
AIRCRAFT SALES & BROKERACI	- 1
AIRCRAFT SALES & BROKEDAGE	
AIRCRAFT SALES & BROKEDAGE	
4	
5	
5	

If this book is found, please return it to the owner.

ENGINE DESCRIPTION

LYCOMING - WILLIAMSPORT, PER Manufacturer: Model: 0-360-A4M	Serial No)
Engine Accessories	Serial No.	Weight
	Atcom	
AIRCRAFT SALES &	BROKERAGE	
		=

Date	Engine Time	Recorder	Maintenance
Santa Monica, C ACTT 46.7 N53	24P 4-11-02		
1) Accomplish o	d change. Changed oil, ins	stalled new CH4	8110 filter, 8 quarts of ASW-
100 oil. Cut old Authorized Sign	filter, inspected for abnorm	mal conditions in	CUTTER AVIATION 3100 Donald Douglas Loop North Santa Monica, CA 90405 Phone 310-399-0480 Repair Station U23R624Y
Cutter Aviation 3100 Donald Dou Santa Monica, Ca ACTT 51.3 N532	. 90405		CRAFT SAL
D d. comburgo	tor and replaced with loan ok. IAW Piper / Lycomir	er carburetor M ng service manu	A-4-5 s/n 75128011. Ran and al. CUTTER AVIATION 3100 Donald Deuglas Loop North Santa Monica, CA 90405 Phone 310-399-0480

and Remarks/	Sig	Signature					
N Number	A/C T.T.	Hobbs	ENG. SMOH	Tach Time			
5324P	83.0		83.0	83.0			
ITEM		DESCRIPTION					
Labor Labor Labor Labor Labor ANNUAL	and was for DATE 6/4/ SIGNATURI Kim Davids	AV BULB NALYSIS. INSPECT ARTER LE 1.207(D) CTION. Ch at this Air n accordant per FAR P und to be 2002 E	FOR METALE AD BOOT. 12 MONTH IN OK. craft/Engine nice with a A APP in airworth	N/A AT ELT TEST e was ANNUAL PENDIX D y condition			

Date	This Date Brought Forward	Since Major	Reading		Maintenance
	N Number	A/C T.T.	Hobbs	ENG. SMOH	Tach Time
	5324P	137.1		137.1	137.1
	ITEM			RIPTION	
La	ibor ibor IGNATURE	ANALYSIS. SERVICE NO SIGNATURE DATE 10/9 Kim Davids Santa Moni	OSE STRU 9/2002 on Aviatio	on Inc.	

and Remarks				Signature	Certificate No
N Number	A/C T.T.	Hobbs	ENG. SMOH	Tach Time	
5324P	154.4		154.4	154.4	
ITEM		DESC	RIPTION		
Labor	REMOVE CA REPLACE W INDICATOR LIGHT. NO				
Labor	C/N 75110	720	5128011. I	NSTALL	
SIGNATURE	SIGNATURE DATE 10/3				
	Kim Davids Santa Moni	ca CA 904	105		
	F.A.A. Appr	oved Repa	air Station #	YYKR678L	

		Moyer Aviatio	n 3800 Sullivan Trail Easton, F	'A 18040 (610) 258 04	73	
	DATE	TAIL#	MAKE / MODEL	SERIAL#	TACH / HOBBS	
Dai	11/7/2002	N5324P	Piper PA28-181	2843452	161	е
	Wash engi	ne. Compression	Iter with new, inspect elements: #1 75/80 #2 75/80 #3 ten #2,4 exhaust clamps. Add. END	78/80 #4 77/80. Tig	ghten #1,3	
	Tom Gilbert		Ma CI	ERT # AP19262872	EIIA	
				RCRA	FT S/	
						1
al To	rward					

=		Moyer Av	viation 3800 Sullivan I rail Easton, P	A 18040 (610) 258 047	3	
	DATE	TAIL#	MAKE / MODEL	SERIAL#	TACH / HOBBS	ificate No.
	7/10/2003	N5324P	Lycoming O-360-A4M	L-38089-36A	176 (TTSN)	

Compression test: #1 75/80 #2 72/80 #3 78/80 (post replacement) #4 75/80. Drain crankcase, replace oil filter with new, inspect element and screen, service with Aeroshell 100 mineral, wash engine. Clean, gap, test, rotate, reinstall and torque spark plugs. Cleaned lower spark plug holes. Clean fuel system filters. Reinstall #3 cylinder after repair (CRS NJ1R350K WO# 12389) using new seals per Lycoming OH manual. Reform primer line to clear lower left engine mount boss. Secure primer "T" fitting to bracket. Adjust internal timing of both magnetos, reinstall with new gaskets and time to engine. Replace missing screw in #3 rocker cover with new. CW Piper SL 1066(ignition harness routing). Shim and tighten lower engine mount to firewall bolts. Tighten lower compressor mount bolts and line clamps. Replace induction air duct from filter to carb box with new. Service in accordance with Piper 100 hour inspection checklist. Ground run and test fly, all indications normal, all equipment functioning, no leaks found. Annual inspection complied with in accordance with FAR43 appendix D and found airworthy. Returned to service. END

Edward Fulmer Jr Edward May

Cert # AP202480835IA

DATE	TAIL#	MAKE / MODEL	SERIAL#	TACH	Moyer Aviation 3800 Sullivan Trail	
1-5-04	N5324P	LYC 0360 A4M	L-38089-36A	206	Easton, PA 18040 (610) 258 0473	
		TER (1) CH48110 (70 QTS 1 URN TO SERVICE END	5W50 AEROSHELL (1) PINT AVI	BLEND. RUNUP	
	V					
KURT R S	INGER DOM	5-10-	CE	RT# A&P	182441812 IA	
DATE	TAIL#	MAKE / MODEL	SERIAL#	TACH	Moyer Aviation 3800 Sullivan Trai	
— 1-9-04	N5324P	PIPER PA28-181	L-38089-36A	206	Easton, PA 18040 (610) 258 0473	
DISTAL	LED NEW SCREWS II	FILTER (1) CH48110 (7) Q N CARB HEAT SHAFT LOC	KILLE KON OF LEC	AND O	D CHILDIS BILL	
RETUR	N TO SERVICE END.	1.165	IRCR	A		
RETUR	N TO SERVICE END. R SINGER DOM	luskby	HROR	A	&P 182441812 IA	
RETUR	N TO SERVICE END.	Lus K. Sug-		A-1		
RETUR	N TO SERVICE END.	lus K. Sug-		A-1		
RETUR	N TO SERVICE END.	Lus K. Sug.		A-1		

DATE TAIL # MAKE/MODEL SERIAL # TACH/HOBBS 3/13/2004 N5324P Lycoming O-360-A4M L-38089-36A 210 (TTSN) Compression test: #1 76/80 #2 74/80 #3 78/80 #4 78/80. Drain crankcase, replace oil filter with new, inspect element and screen, service with Aeroshell 15W50 and AvBlend, wash engine. Clean, gap, test, rotate, reinstall and torque spark plugs. Cleanéd lower spark plug holes. Clean fuel system filters. Replace points and brushes, reset internal timing of both magnetos, reinstall with new gaskets and time to engine. Replace #2,4 intake gaskets with new. Tighten all rocker cover screws. Tighten several loose compressor mount bolts. Tighten carburetor half bolts and resaftey Service in accordance with Piper 100 hour inspection checklist. Ground run and test fly, all indications normal, all equipment functioning, no leaks found. Annual inspection complied with in accordance with FAR43 appendix D and found airworthy. Returned to service. END Tom Gilbert Cert # AP192628721IA	-	Moyer Av	viation 3800 Sullivan Trail Easton, P.	A 18040 (610) 258 047	3	
Compression test: #1 76/80 #2 74/80 #3 78/80 #4 78/80. Drain crankcase, replace oil filter with new, inspect element and screen, service with Aeroshell 15W50 and AvBlend, wash engine. Clean, gap, test, rotate, reinstall and torque spark plugs. Cleanéd lower spark plug holes. Clean fuel system filters. Replace points and brushes, reset internal timing of both magnetos, reinstall with new gaskets and time to engine. Replace #2,4 intake gaskets with new. Tighten all rocker cover screws. Tighten several loose compressor mount bolts. Tighten carburetor half bolts and resaftey. Service in accordance with Piper 100 hour inspection checklist. Ground run and test fly, all indications normal, all equipment functioning, no leaks found. Annual inspection complied with in accordance with FAR43 appendix D and found airworthy. Returned to service. END	DATE	TAIL#	MAKE / MODEL	SERIAL#	TACH / HOBBS	
Compression test: #1 76/80 #2 74/80 #3 78/80 #4 78/80. Drain crankcase, replace oil filter with new, inspect element and screen, service with Aeroshell 15W50 and AvBlend, wash engine. Clean, gap, test, rotate, reinstall and torque spark plugs. Cleanéd lower spark plug holes. Clean fuel system filters. Replace points and brushes, reset internal timing of both magnetos, reinstall with new gaskets and time to engine. Replace #2,4 intake gaskets with new. Tighten all rocker cover screws. Tighten several loose compressor mount bolts. Tighten carburetor half bolts and resaftey. Service in accordance with Piper 100 hour inspection checklist. Ground run and test fly, all indications normal, all equipment functioning, no leaks found. Annual inspection complied with in accordance with FAR43 appendix D and found airworthy. Returned to service. END	3/13/2004	N5324P	Lycoming O-360-A4M	L-38089-36A	210 (TTSN)	
Tom Gilbert Cert # AP192628721IA	with new engine. Co holes. Clo magnetos new. Tigi Tighten co inspection functioni	inspect elem Clean, gap, test ean fuel system s, reinstall with then all rocker carburetor half n checklist. Gong, no leaks for	ent and screen, service with Aer in rotate, reinstall and torque spain filters. Replace points and bruin new gaskets and time to enging cover screws. Tighten several libolts and resaftey. Service in round run and test fly, all indication. Annual inspection complisions.	oshell 15W50 and Ark plugs. Cleaned lo shes, reset internal e. Replace #2,4 inta oose compressor maccordance with Piptions normal, all equed with in accordance	AvBlend, wash wer spark plug timing of both ke gaskets with bount bolts. er 100 hour hipment	
	Tom Gilbe	ert /	RAGE	ert # AP192628721	<u>IA</u>	
		``	\wedge			
	1					

		Moyer Av	iation 3800 Sullivan Trail Easton, PA	A 18040 (610) 258 047	3	1			¥0				
	DATE	TAIL#	MAKE / MODEL	SERIAL#	TACH / HOBBS		DATE	TAIL#	MAKE / MODEL	SERIAL#	TACH	Moyer Aviation	0.
	3/25/2005	N5324P	Lycoming O-360-A4M	L-38089-36A	261 (TTSN 261)	nance	3-21-06	N5324P	LYC O-360-A4M	L-38089-36A	340	3800 Sullivan Trail Easton, PA 18040 (610) 258 0473	e No.
	with new engine. Choles. Classidden engines or reinstally Replace reroute conspection functions appendix Edward Fu	inspect elements, inspect elements, gap, test, ean fuel system ingine stoppage in many many many many many many many man	MAKE / MODEL S LYC 0-360-A4M L	rk plugs. Cleaned lo C1 not due until properties or belts. Tig tributors, adjust into vacuum pump mouce carb heat cable cordance with Piper tions normal, all equed with in accordance with Piper tions normal, all equed with in accordance with Piper tions normal, all equed with in accordance with Piper tions normal, all equed with in accordance with Piper tions normal, all equed with in accordance with Piper tions normal, all equed with in accordance with Piper tions normal, all equed with in accordance with Piper tions normal, all equed with in accordance with Piper tions normal, all equed with in accordance with Piper tions normal, all equed with in accordance with Piper tions normal, all equed with in accordance with Piper tions normal, all equed with in accordance with Piper tions normal, all equed with in accordance with Piper tions normal, all equed with Piper tions normal with Piper tio	AvBlend, wash ower spark plug op strike or then several ernal timing, ant bolts. lamps and 100 hour uipment ce with FAR43 Moyer Avia 3800 Sulliv Easton, PA (610) 258 (6	an Trail 18040 0473	Replaced #4 roo Tighten dipstick Checked Ads to requirements an	ker drain back tube. Replaced alternate Checked engine d found to be in airwoo NGER DOM	Replaced induction air filter. Ched and rotated spark plugs. Ad 05 eadjusted exhaust pipe duct. CW ator belt idler pulley. Lt mag rep controls. Run up leak and ops of the condition at this time return when the condition at the condition of the	19-19-11 300HP DNA Add 400 HR valve inspection laced points and carbon bleck sat. Inspected IAW H to service. End,.	05-26-10 ECI con Replaced rock rush, Set E gap a FAR 43 Apex D	7) Qts 15W50 aero ylinders DNA. er box gaskets, and timed to engine, annual inspection P 2857290 IA	
CHA CAR	NGED ENGIN B HEAT BOX	IE OIL AND FI RUN UP LEAF	LTER (1) CH48110 (7) QTS 15W5 K AND OPS CHECK SAT . RETU	50 AEROSHELL RE RN TO SERVICE EN	PLACED GROMME ND.	IIN	ti						
				W.E. 272									
KUI	RT R SINGE	ER DOM	but has	CER	Γ# A&P 2857290	IA —	-		Ti.				

DATE		A CAME IN CODE!	SERIAL#	TACH	Moyer Aviation	D	ATE	TAIL#	MAKE / MODEL
01/08/07	TAIL # N5324P	MAKE / MODEL Lycoming O360-A4M	L-38089-36A	440	3800 Sullivan Trail Easton, PA 18040 (610) 258 0473	1	1-26-07	N5324P	LYC 0-360-A4M
During d graphs	ase, replaced filter up leak and ops che	with new CH48110. Inspect elenck satisfactory. Return to service	END.		oshell 15W50 and	L:	EAK AND O	NGINE OIL AND F PS CHECK SAT . I NGER DOM	FILTER (1) CH48110 (7) QTS 1 RETURN TO SERVICE END.
Kurt R Singe	r DOM	wtler -		CERT# A	&P 2857290 IA	_	(610) 258 047		Moyer Aviation, l
DATE	TAIL#	MAKE / MODEL	SERIAL#	TACH	Moyer Aviation		Date	Tail#	Make / Model
3-22-07	N5234P	Lyc 0-360-A\$M	L-38089-36A	448	3800 Sullivan Trail Easton, PA 18040 (610) 258 0473		4-7-08	N5234P	Lyc 0-360-A4M 3-73/80 #4-71/80 Changed en
parts not installed	d. Ad 06-12-07 ECI C	lyl affected parts not installed. Ad 06			norte not installed	i	installed. Tig	hten rocker drain	back tubes, Replaced exhaus
Ad 07-04-19 Sup plug hole and ign	perior Cyl Affected pa 1 leads. Replaced Hei	arts not installed. Repaired #1 primer coil in #4 Top plug hole. Run up leal und to be in airworthy condition at the	and ops check sat. In	spected IAW F	rque. Cleaned lower		inspection re	quirements and fo	. Checked Ads to date. Lubeo and to be in airworthy conditi
Ad 07-04-19 Sup plug hole and ign annual inspection	perior Cyl Affected pa 1 leads. Replaced Hei	irts not installed. Repaired #1 primer coil in #4 Top plug hole. Run up leal	and ops check sat. In is time return to service	spected IAW F ce end.	rque. Cleaned lower		inspection re	and ops check sat quirements and fo nger DOM	. Checked Ads to date. Lubec

Moyer Aviation 3800 Sullivan Trail TACH SERIAL# Easton, PA 18040 L-38089-36A 523 (610) 258 0473 15W50 AEROSHELL (1) PINT AVBLEND RUN UP

KURT R SINGER DOM	but RQ:	CERT # A&P 2857290 IA	
		i - i -	_

(610) 258 0473		Moyer Aviation, Inc.	3800 Sullivan T	3800 Sullivan Trail, Easton, PA, 18040		
Date	Tail#	Make / Model	Serial #	Tach / Hobbs		
4-7-08	N5234P	Lyc 0-360-A4M	L-38089-36A	528		

plugs. Cleaned ign leads. Replaced Vacuum pump ction air filter. Ad 07-04-19R1 Superior cylinder not ust ball joint AN3C-15 Tighten throttle linkage bolt.

ped controls. Inspected IAW FAR 43 Apex D annual lition at this time return to service end.

CERT # A&P 2857290 1A

-(610) 258 0473 Mover Aviation, Inc. 3800 Sullivan Trail, Easton, PA, 18040 Date Tail # Make / Model Serial # Tach / Hobbs 7-14-11 N5324P Lycoming O-360 TTE 602 TSMOH 602. #1 76/80 #2 76/80 #3 74/80 #4 73/80 Changed engine oil and filter (1) CH48110 (7) Qts 15W50 Aeroshell (1) Pint Avblend. Replaced induction air filter. Cleaned rotate and gapped plugs. Adjusted mag E Gap and set timing to engine. Adjusted carb heat. Checked Ads to date. Run up leak and ops check sat. Inspected IAW FAR 43 Apex D annual inspection requirements and found to be in airworthy condition at this time return to service end. Kurt R Singer DOM CERT # A&P2857290 IA TACH Mover Aviation SERIAL# DATE TAIL# MAKE / MODEL 3800 Sullivan Trail Easton, PA 18040 L-38089-36A 618 LYC 0360 A4M 2-7-12 N5324P (610) 258 0473 Replaced Points. M3081 Capacitor K3984 on Lt Mag Set E gap and timed to engine. Installed with new gaskets (1) 62224 (1) LW12681. Cleaned plugs gapped and rotated. Run up leak and ops check sat. CERT # A&P 182441812 IA KURT R SINGER DOM



Moyer Aviation, Inc.

3800 Sullivan Trail, Easton, PA, 18040

(610) 258 0473

Cessna					Tach / Hobbs
Date	Tail #	Make / Model		Serial #	
6-22-12	N5234P	Lycoming 0-360		L-38089-36A	624
#2 #3 under W/6	O 35153 35154 1	35154. #4 cylinder was re	eplaced wit	n heads of pistons. Penn th NEW Lycoming 05K2	1104 cylinder Kit
due to one of the	e rocker shaft ears	cracked. CRS# Y2GR3	96Y. Sent	Carb to Penn Yan for ev	aluation for rich
condition. Penn	Yan repaired car	b under W/O 35285 See	W/O's. Ch	anged engine oil and filt	er (1) CH48110
(8) Qts 20W50	Phillips Type (M)	. Run up leak check sat.	compression	on #1 75/80 #2 75/80 #3	/5/80 #4 /6/80 a
Ad 12-03-07 Ca	arb mixture DNA	due to type installed. Re	placed oil	dipstick gasket. Replaced	t an Accessory
line at engine. R	Removed Rt and L	t mags adjusted E gaps a	nd timed to	engine. Replaced gaske	avalue arm P/N
case blank. Cle	aned gapped and	rotated plugs. Adjusted c	arb neat ar	nd instilled new swivel or	s check sat
70371-002 and	70371-003. Chec	ked Ads to date. See Ad	ist for upu	ates. Run up leak and op	orthy condition at
Inspected engin	e IAW Far 43 Ap	ex D annual inspection re	squiremen	s and found to be in airw	orthy Condition di
this time return		butter		CFRT#	A&P2857290 IA
Kurt R Singer	DOM		7	Y Living	, (61, 256, 256, 1
			-1111/		
		20			
Total To Carry Forward					



N5324P AIRFRAME LOG ENTRY 08/10/2012 PAGE 1 OF 1 PIPER PA28-181 S/N 2843452 TOTALTIME: 720.9 TACH: 668.8 HOBBS: 720.9

Complied with oil and filter change. Drained oil and removed oil filter. Cut oil filter and inspected for wear metal and none found. Replaced oil filter with new oil filter P/N CH48110-1 and 8 QTS Aeroshell W100 plus oil. Cleaned engine and ground ran, no leaks found at this time.

I CERTIFY THAT THE ABOVE MAINTENANCE AND/OR ALTERATION DESCRIBED ABOVE WAS ACCOMPLISHED IN ACCORDANCE WITH THE REQUIREMENTS OF 14CFR43, AND WITH RESPECTTO THE WORK PERFORMED IS AIRV. ORTHY AND APPROVED FOR RETURN TO SERVICE. DETAILS ON FILE WITH THIS AGENCY UNDER UORK ORDER # 100630

	CEDRIC C PALM AI/A&P 2690573		-
& BROK	ERAGE		
	le .		
31			
		0	

Tach 717.1 H/M 769.7 Date 6-24-13 Log Book Entry N5324P Engine Logbook Entry Performed an Annual Inspection I/A/W FAR 43 Appendix "D" and Piper Inspection Report p/n 767-008. Checked compression 1=76/80 2=76/80 3=77/80 4=76/80. Installed all new spark plugs p/n REM38E; installed a new oil temp probe p/n 102-00000—ops. Checked o.k.; changed oil and filter; serviced engine with Aeroshell W-100 and installed a new Ch48110 filter; opened old oil filter and checked for any F.O.D.—none found; Lubed all engine controls; Ad's checked to date. I certify that this Engine and Prop. have been inspected I/A/W an annual inspection and was found to be in an airworthy condition. IA 3650511 Total To Carry Forward

1 July 2015 TACH 736,5 1401335 789.4 Sianature Certificate No. CIW 100 HR, INSPECTION USING PIPEZ NOOP REPORT #767-008 AND FAR 43 APPX D. CHANGED OIL SUCW A.S. 1000+, Filter CH48110-1. Cut : INSPECT FILTER, CLEAN SINSPECT SCREEN- NO DEFECTS, COMPRESSION. THE 276 THE THE DATE. GEOLDO ELL EPS/LEAK CHECK CIW-LO PEFECTS I CEETFY THAT THE ENGINE HAS BEEN INSPECTED 1/A/W AN ANNUAL INSPECTION AND WAS FOUND TO BE IN AN AIRWORTHY CONDITION

N5324P ~-N532P-Lycoming Engine 0-360-A4M July 20, 2016 Engine Total Time: 815.6 hrs. Tach: 815.6 hrs. and Remarks Certificate No. Signature Complied with a 100 hr. Inspection per FAR - Appendix D to part 43. In conjunction with Piper Inspection Report. Change Oil and Filter CH48110-1 and serviced with Aeroshell AD 100 and CamGuard. Compressions: 1-78/80 2-Removed + Rellaced All & stank Plugs with New 78/80 3-76/80 4-78/80. This Engine Found Airworthy, and is approve for return to service. REM 38\$ Fine wire Plugs. Removed MAGS Fric Larabell IA 3004778 out For 500 HA inspection See 81 30 those Ain force All confressions 77 over so on Deffor 05-04,17 RIR methanical Fuel Pump with NEW Part # LW 15472 Tach 844.9 Dip stick tousing & Re-SAFfield Old Sho UNKEN SIN ON RC32163646 IAW Lyloming maint manual AD 2017-16-11 D.N.A. Pen S/N 7-20-18 has Been Instited IAW An track 909. Candition And 448110-

			IGHAL LOG				
Date	Engir This Date	e Time Since Major	Recorder Reading	Maintenance	and Remarks	Signature	Certificate No.
	Brought Forward				DATE 17 July 2017 TACK 851.6	TT ENG 851.6	
N 5324	PD	Ate 7-	23-15	TACK 746.7	Changed oil & Filter Cutopen Filt	er & Pulled Oil	Screen Fou
R+R le Reinstale	ft ma	gneto jed an	for seg d rues 3058	sais by Navajo Accy- up all ck good.	Insp OK Serviced with Aeroshell 10 Compress Test 117/80 277/80 377	-	
W Cass	Let X8	100	AIF	CRAFISALES_	I CERTIFY I HAVE INSPECTED THIS Engine IN ACCORDAN A ARNUEL INSPECTION AND	CE WITH	
6-12-19	OLD	Filter.	inslected	No Detats noted	DETERMINED TO BE IN AIR' VORTHY COMMENT OF SIgnature HOP 3117402 FA	ONDITION "	
Total To Carry Forward	N /	with Agr	shell 100	Sorrell Services engine Sorrell Services AHR3472028			

U.S. Flight Support Inc. Date 6-12-19 N5324P PA-28-181 S/N 2843452 Tach 955.6 O-360-A4M S/N L-38089-36A

Performed oil and filter change installed new CH48110-1 filter and safetied. Cut open old filter and inspected serviced engine with 8 quarts aeroshell 100+. Performed run up and leak check A&P I/A 3472028 Edward Sorrell

U.S. Flight Support Inc. Date 8-14-19 N5324P PA-28-181 S/N 2843452 Hobbs time 1050.6 Tach 959.4

O-360-A4M S/N L-38089-36A

Performed 100 hour / annual inspection as per FAR43 appendix "D". Performed compression check #1 75/80 #2 78/80 #3 79/80 #4 77/80. Cleaned, Gapped and Rotated spark plugs
Removed and replaced All engine fuel hoses with new 303 hose material verified oil cooler hoses type "D". Removed and replaced all 4 intake gaskets with new P/N 71973 installed with new lock washers. Adjusted magneto to engine timing on both mags secured using new lock washers. Removed and replaced engine exhaust tail pipe with new FAA PMA P/N A85477-011.

Tightened A/C compressor belt and safetied. Installed new BA-3 induction air filter. Performed dynamic prop balance added 10.1 grams of split weight to starter ring gear @ 225 degrees in existing holes locations results were .04 IPS. Checked AD compliance this date. I certify that this engine has been inspected IAW an annual inspection and is approved for return to service.

A&P I/A 3472028 Edward Sorrell

U.S. Flight Support Inc. Date 8-19-20 TACH: 961.2

Performed 100 hour/annual inspection. Performed compression check #1 77/80 #2 78/80

#3 78/80 #4 77/80. Performed oil and filter change cut open old fiter and inspected. Serviced

N5324P Engine O-360-A4M S/N L-38089-36A

cted I.A.W. an annual inspection and was fou approved for return to service.	nd to be in	airworthy condition	on at this time
P I/A 3472028 Edward Sorrell		8-19-20	
BROKERAGE			

FNGINE LOG

U.S. Flight Support Inc. Date 10-14-20

N5324P PA-28-181 S/N 2843452

MS0G4002

Carburetors, LLC

9. Quantity

Total Total

Carry F 56B)

Removed and replaced carburetor with overhaul exchange MA-4-5 P/N 10-5193 S/N MS0G4002 from Marvel Schebler Aircraft carburetor company see 8130-3. Adjusted idle and

idle mixture as per maintenance manual. Perform engine run up and leak check. A&P I/A 3472028 Edward Sorrell

O-360-A4M S/N L-38089-36A Engine Tach 965.0 Performed 100 hour annual inspection. Performed oil and filter change, cut open old filter and inspected for metal none found. Installed new CH48110-1 oil filter and safetied. Serviced engine with 8 quarts of Aeroshell 100+. Cleaned, gapped and

U.S. Flight Support Inc. Date 9-17-21 N5324P

rotated spark plugs. Performed compression check hot #1 77/80 #2 78/80 #3 77/80 #4 78/80. Installed new BA-3 induction air filter. Checked magneto to engine timing Checked AD compliance. I certify this engine has been inspected IAW an annual inspection and was determined to be in airworthy condition and is approved for return

to service. A&P I/A 3472028 Edward Sorrell

0G40 Page 1 of 1 10. SerialNumber

11. Status / Work

5. Work Order/Contract/Invoice Number:

Overhauled