

PROPELLER LOGBOOK

PROPELLER MODEL 503-NK 336A1/9158

PROPELLER S/N TS 228

LOGBOOK #___








PROPELLER MAINTENANCE RECORD

PositionRH	PITCH RANGE
Propeller Model <u>503-NK336AI/910</u> 15B	High/Feather <u>W/M</u> 85.7
Propeller S/N	Start LockN/A
Blade Design	Low18.4
Blade S/N's	Reverse
No. 1	
No. 2 D7672	Aircraft Manufacturer BEECH
No. 3 <u>D 7859</u>	Aircraft Model <u>B200</u>
No. 4 D 79 4(S/N_BB-1368
No. 5 D 8099	Registration N200 EA
No. 6	
Spinner Assembly Part No	

STEVENS AEROSPACE AND DEFENSE SYSTEMS	Documents, Overh	ons pertaining to Airworthiness naul, Major or Minor Repair, an	d Inspections.
Right Propeller Serial no.: TS228			
Installed Raisbeck 5 bladed composite prop NK366A1/91D15B IAW Raisbeck Enginee 19BC-61-003.	peller p/n 5D3- ering Document		
ACTT: 8485.6 PTSN: 0.0 PTSO: 0.0 Date: 08/07/2023 Work Order No.: DAY Signed Mullin For Stevens Aerospace & defense, CRS VI	'-WO- 1843	·	
	D-1500K		

			· · · · · · · · · · · · · · · · · · ·	
				SA-0505
STEVEN	S AFROSPACE A	ZND	N200EA S/N BB-1368 TSN 81.6	ACTT 8567.2 HM 1347.7 TSO N/A
C/W 12 C/W 12 certify	mth/200/400 n mth/400 hr Re this <i>Propeller</i> h mplished, and	as been inspected in accord the aircraft is approved for	nion & Lubrication. Thibitor on Hartzell Propeller Steel Counter lance with FAR 91.409(F) 3 and a <i>Beechcra</i> return to service. Pertinent details are on ms, Smyrna, TN 37167, CRS VIB3368K	file at this agency under
igned F o				



Record of 100DD44/) Composite Blade Damage Repair

mal & gran

es to and

WAY C BURN

and Caren

493

PREMIER	of all operations pertaining to Airworthiness Directives, ments, Overhaul, Major or Minor Repair, and Inspections.
Right Propeller Serial no.: TS228	
1. C/W 200 hr. propeller assy. and de-ice system inspection.	
ACTT: 8600.0 PTSN: 114.4 PTSO: 114.4 Date: 6/3/25 Work Order No.: DAY-WO- 340	
Signed For, Premier Aviation Services, CRS PPJR496E	