

PROPELLER LOG BOOK



SENSE NICH PROPELLER COMPANY
519 EAST AIRPORT ROAD
LANCASTER, PA 17601
USA

LITITZ, PA 17543

THIS LOG BOOK IS TO BE KEPT
WITH THE PROPELLER
FOR RECORDING OF ALL PROPELLER MAINTENANCE WORK PERFORMED

DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
		Date <u>4-8-96</u>	<u>TTSN 168.1</u>
		I certify that this <u>Propeller</u> has been inspected in accordance with an <u>Annual</u> inspection, and was determined to be in airworthy condition.	
		Signed: <u>William A Lord</u>	
		William A. Lord A&P 1898972 IA	

PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
		Date <u>3-13-97</u> TT <u>296.6</u>	
		I certify that this <u>Propeller</u> has been inspected in accordance with an <u>Annual</u> inspection, and was determined to be in airworthy condition.	<u>Tach 3557.6</u>
		Signed: <u>William Lord</u>	
		William A. Lord A&P 1898972 IA	
<u>4/8/02</u>	<u>4085.6</u> <u>SMOH-824.6</u>	I certify that this propeller has been inspected in accordance with an Annual inspection and has been found to be airworthy.	<u>JCWong A&P 259591158 IA.</u>

DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
5/5/2007 ³	4188.00	I certify that the propeller has been inspected in accordance with an annual inspection and has been approved for return to service.	Thomas P. Malechuk IA375605708 Guardian Aviation Services, LLC


N222US TACH = 4187.3 Propeller TT = 926.3

05/05/2004

I certify that this propeller has been inspected in accordance with an annual inspection and has been found to be in an airworthy condition.

Thomas P. Malechuk
Thomas P. Malechuk IA375605708
Guardian Aviation Services, LLC


DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
		PIKEVILLE AIRCRAFT SERVICE (606) 432-5377 DATE 07-01-05 TAC TIME 4249.4, PROPELLER TIME 988.4 SN Cessna 172N, N# 222US, Propeller Sensenich, 76EM8514-0-60, S/N 29256K	
		Aircraft inspected in-accordance with an annual inspection. Propeller inspected and cleaned. Ray C. Brooks A&P 299324448	

PIKEVILLE AIRCRAFT SERVICE (606) 432-5377

DATE 08-03-06 TAC TIME 4337.5, PROPELLER TIME 1076.5 SN
Cessna 172N, N# 222US, Propeller Sensenich, 76EM8514-0-60, S/N 29256K

Aircraft inspected in-accordance with an annual inspection. Propeller inspected and cleaned. Checked AD's 2005-14-11 Propeller not overhauled by SCPS (see AD compliance record for details) Ray C. Brooks A&P 29932444



DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS

PIKEVILLE AIRCRAFT SERVICE (606) 432-5377

DATE 09-01-07 TAC TIME 4416.6, PROPELLER TIME 1155.6 SN

Cessna 172N, N# 222US, Propeller Sensenich, 76EM8514-0-60, S/N 29256K

Aircraft inspected in-accordance with an annual inspection. Propeller inspected and cleaned. Checked AD's 2005-14-11 Propeller not overhauled by SCPS, (see AD compliance record for details) Ray C. Brooks A&P 29932444 *Ray C. Brooks*

10-3-08	4469.3 Tach Time	1208.3 propeller Time
	Annual Inspection - Jimmy RMM = low	AP40505403IA
10-01-09	4492.8 Tach Time	Annual Insp Jimmy RMM = low
		AP40505403IA

DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
			<i>Daytona Aircraft Services, Inc.</i>
DATE: 12/1/2010	TACH: 4512.1		
		I certify that this Propeller has been inspected in accordance with an annual inspection and was determined to be in airworthy condition. Dressed blades. All work was performed in accordance with current regulations of the FAA and is approved for return to service. Details are on file at this Repair Station under WOP 3070	
			<i>Daytona Aircraft Services, Inc. CRS DYTR262K</i>