

104069K

PROPELLER LOG BOOK



SENSENICH PROPELLER MFG. CO.

Lititz, Pennsylvania 17543

Internet: <http://www.sensenich.com>.

THIS LOG BOOK IS TO BE KEPT
WITH THE PROPELLER
FOR RECORDING OF ALL PROPELLER MAINTENANCE WORK PERFORMED

**DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS**

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
------	-----------	---------------------	-----------



43769 Heilner Rd.
Baker City, OR 97814
541-523-5663

N2316K	
MAKE/MODEL:	Piper Archer III
SERIAL NUMBER:	2843683
TACH/HOBBS:	245.0
AFTT:	
ENGINE MAKE/MODEL:	Lycoming O-360-A4M
ENGINE SERIAL NUMBER:	L-41694-36E
ENGINE TTSN:	245.0
ENGINE SMOH:	245.0
PROP MAKE/MODEL:	Sensenich 76EM8S14-0
PROP SERIAL NUMBER:	104069K
PROP SMOH:	0.0 TT: 0.0

DESCRIPTION OF WORK:

Installed New Sensenich propellor (PN: 76EM8S14-0-62 SN: 104069K) in accordance with Piper Maintenance Manual chapter 61-10-00 (2). Checked blade track per 61-10-00 (2)D.

Carl Mattheis AP3813037



Date:

3/22/2017