

HARTZELL

PROPELLER LOGBOOK

AirMart.com
AIRCRAFT SALES & BROKERAGE

PROPELLER MODEL PHC-J3YF-1RF/F7498

PROPELLER S/N FP9103B

LOGBOOK # 1

PROPELLER MAINTENANCE RECORD

Position _____

PITCH RANGE _____

Propeller Model PHC-J3YFIRF/F7498

High/Feather _____

Propeller S/N FP9103B

Start Lock _____

Blade Design _____

Low _____

Blade S/N's

Reverse _____

No. 1 L81739

No. 2 L81740

Aircraft Manufacturer Mooney Int'l Corp

No. 3 L81743

Aircraft Model M20V

No. 4 _____


S/N 33-0007

No. 5 _____

Registration N3465Y

No. 6 _____

Spinner Assembly Part No. A-2295-10P

Date	Propeller TSN TSO		A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
				<p>Mooney International Corporation Repair Station CRS# 8MBR609C 165 Al Mooney Road, North Kerrville, TX 78028 N63PA M/N M20V S/N 33-0007 Hobbs Time: 108.9 G1000 Time: 119.6</p>
				<p>Propeller was serviced per Hartzell Manual 115N. This propeller has been inspected and found to be in a condition for safe operation at this time. I certify that this propeller has been inspected in accordance with annual inspection and was determined to be in airworthy condition. The aircraft, airframe, aircraft engine, propeller, or appliance identified above was repaired and inspected in accordance with current Regulations of the Federal Aviation Agency and is approved for return to service. Pertinent details of the repair are on file at this repair station under Order No. <u>0115</u>.</p>
				<p>Signature  _____ Mooney International Corporation</p>
				<p>CRS# 8MBR609C Date 04/09/2019</p>