

HARTZELL

PROPELLER LOGBOOK

AirMart.com
AIRCRAFT SALES & BROKERAGE

PROPELLER MODEL PHC-C34E-1RE/FS468AK-GR

PROPELLER S/N QG1708B

LOGBOOK # _____

PROPELLER MAINTENANCE RECORD

Position _____

PITCH RANGE

Propeller Model PHC-C34F-1RF

High/Feather _____

Propeller S/N QG1708B

Start Lock _____

Blade Design F8468AK-6R

Low _____

Blade S/N's

Reverse _____

No. 1 L99927

No. 2 L99934

No. 3 L99935

No. 4 _____

No. 5 _____

No. 6 _____

Aircraft Manufacturer _____

Aircraft Model _____

S/N _____

Registration _____

Spinner Assembly Part No. _____

Date	Propeller		A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
	TSN	TSO		
11/14/19	0.0	N/A	0.0	Installed on Aircraft E-4137.


 Cary Klug
 For Textron Aviation Inc.



Thoroughbred Aviation Maintenance, Inc.
Propeller

Date: 09/15/2020
 AC: N71DK
 Hobbs: 35.1
 Prop S/N: QG1708B

Type: Beech G36
 AC SN: E-4137
 AFTT: 35.1
 Prop TT: 35.1

WO: 203226
 Tach: N/A
 Prop M/N: PHC-C3YF-1RF
 Prop TSMOH: N/A

1. Lubed blades as needed.
2. I certify this propeller has been inspected IAW an annual inspection per 14 CFR part 43 appendix D and found to be in airworthy condition. Beech G36 Annual checklist used as a guide.

End

MAINTENANCE RELEASE

The aircraft and/or component identified was repaired in accordance with current FAA regulations and was found airworthy for return to service for the work performed. "Pertinent" details of the repair are on file at this agency under **Work Order: 203226**

Date: 09/15/2020 Signed: James Bailey

CRS: R814199Y

