

# Aircraft Specialists, Inc.

Clark County Airport (JVY) • 6005 Propeller Lane • Sellersburg, Indiana 47172

## PROPELLER MAINTENANCE LOG



(812) 246-4696 • (800) 356-3723 • fax (812) 246-4365

[www.800projets.com](http://www.800projets.com)

FAA Approved Repair Station No. PZ4R458M

1. Approving Civil Aviation Authority/Country: FAA/United States		2. <b>AUTHORIZED RELEASE CERTIFICATE</b> FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG			3. Form Tracking Number: PRP17-03171	
4. Organization Name and Address: Aircraft Specialists, Inc. 6005 Propeller Lane Sellersburg, IN 47172			Repair Station # PZ4R458M		5. Work Order/Contract/Invoice Number: PRP17-03171	
6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:	
1	McCauley Propeller	D3A34C443	1	023029	Repaired	
12. Remarks: Reassembled propeller (disassembled, cleaned, visually inspected, and reassembled, using new seals and gaskets) and balanced propeller. All work performed in accordance with McCauley manual MPC400 Rev. 4 dated 1/1/2015.						
13a. Certifies the items identified above were manufactured in conformity to: <input type="checkbox"/> Approved design data and are in a condition for safe operation. <input type="checkbox"/> Non-approved design data specified in Block 12.			14a. <input checked="" type="checkbox"/> 14 CFR 43.9 Return to Service <input type="checkbox"/> Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.			
13b. Authorized Signature:		13c. Approval/Authorization No.:	14b. Authorized Signature: 		14c. Approval/Certificate No.: PZ4R458M	
13d. Name (Typed or Printed):		13e. Date (dd/mm/yyyy):	14d. Name (Typed or Printed): Jeff Davis		14e. Date (dd/mm/yyyy): 09 NOV 2017	
<b>User/Installer Responsibilities</b>						
It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1. Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.						
FAA Form 8130-3 (02-14)				NSN: 0052-00-012-9005		

## PROPELLER MAINTENANCE LOG

<b>DATE</b>		4316 Hangar Drive Lexington, KY 40510 859-255-1902
		<b>McCauley D3A34C443</b>
	10/14/2017 Reg. N8149W	s/n:023029
		Shop Order: M-17-7032 PropTT: 1404.6
	1. Installed repaired propeller McCauley D3A34C443, s/n: 023029, from Aircraft Specialists, Inc. Torqued as required.	
	2. Installed (3) new rubber bumpers, p/n:11825-45, on propeller de-ice feed tube brackets.	
	3. I certify that this propeller has been inspected IAW with an annual inspection and found to be in airworthy condition. Inspection performed IAW 14 CFR 43 Appendix D, using the Cirrus SR22 MM Inspection Guide as a reference.	
	The aircraft, airframe, engine, propeller, or appliance identified was repaired and/or inspected in accordance with the current regulations of the Federal Aviation Administration and is approved for return to service for the work performed.	
	Date: 10/14/2017	Signed: 
		Jeffrey William Borders A&P 3596771 IA

