

PA	PROP MODEL: B3D36C424-E PROP S/N: 020249 REG NO: N5352D WORK ORDER: 11670	Turbine Aircraft Services, LLC. Repair Station No. TBWR469X 7101 Millionaire Drive, Hangar 21 Bethany, Oklahoma 73008 Phone: 405-491-8995	DATE: 04 November, 2017 A/C TSN: 4993.2 PROP TT: 0 FLIGHTTIME: 4993.2	
	Prop Entries (4) Completed a 100 hour Propeller inspection, utilizing 14 CFR 43 Appendix (D) in scope and detail to inspect this Propeller.			Signature & Certificate Number
Da	The aircraft and/or component(s) on N5352D was repaired and/or inspected in accordance with current Federal Aviation Regulations and was found Airworthy for return to service with regard to work performed on this work order. Pertinent details of the inspection/repair are on file at this Repair Station No. TBWR469X under Work Order No. 11670 Dated 04 November, 2017.			
	DATE: 04 November, 2017 SIGNED: Michael Harbison Certified Repair Station No. TBWR469X		Work Order: 11670 Printed by EBis 3 (datcomedia.com)	

	PROP MODEL: B3D36C424-E PROP S/N: 020249 REG NO: N5352D WORK ORDER: 11800	Turbine Aircraft Services, LLC. Repair Station No. TBWR469X 7101 Millionaire Drive, Hangar 21 Bethany, Oklahoma 73008 Phone: 405-491-8995	DATE: 18 January, 2018 A/C TSN: 5082.6 PROP TT: 89.4 TSPDH: 89.4 TACH: 89.4	
	Prop Entries (3) Completed a 100 hour Propeller inspection, utilizing 14 CFR 43 Appendix (D) in scope and detail to inspect this Propeller.			
	The aircraft and/or component(s) on N5352D was repaired and/or inspected in accordance with current Federal Aviation Regulations and was found Airworthy for return to service with regard to work performed on this work order. Pertinent details of the inspection/repair are on file at this Repair Station No. TBWR469X under Work Order No. 11800 Dated 18 January, 2018.			
	DATE: 18 January, 2018 SIGNED: James C. Morphey Certified Repair Station No. TBWR469X		Work Order: 11800 Printed by EBis 3 (datcomedia.com)	

PROPELLER ASSEMBLY LOG					
PAGE NUMBER _____					
Date	Total Time	Time Since Overhaul	Aircraft Model & Registration Number	Maintenance Service History	Signature & Certificate Number
9/19/17			B3D36C424-E S/N 170807	THIS PROPELLER WAS MANUFACTURED NEW AT MCCAULEY PROPELLER SYSTEMS. INSPECTED AND FOUND TO BE AIR-WORTHY ON THIS DATE.	

PROP MODEL: B3D36C424-E PROP S/N: 020249 REG NO: N5352D WORK ORDER: 11666	Turbine Aircraft Services, LLC. Repair Station No. TBWR469X 7101 Millionaire Drive, Hangar 21 Bethany, Oklahoma 73008 Phone: 405-491-8995	DATE: 04 November, 2017 A/C TSN: 4993.2 PROP TT: 0 FLIGHTTIME: 4993.2	
Prop Entries (14) Installed new McCauley Propeller Model B3D36C424-E, S/N 170807.			
The aircraft and/or component(s) on N5352D was repaired and/or inspected in accordance with current Federal Aviation Regulations and was found Airworthy for return to service with regard to work performed on this work order. Pertinent details of the inspection/repair are on file at this Repair Station No. TBWR469X under Work Order No. 11666 Dated 04 November, 2017.			
DATE: 04 November, 2017 SIGNED: Michael Harbison Certified Repair Station No. TBWR469X		Work Order: 11666 Printed by EBis 3 (datcomedia.com)	