

McCAULEY...

PROPELLER LOGBOOK

Owner NameAddress	- K
Propeller Model Babaye 213-B	
Blade Model N-90 DNA-16	
Hub Serial No. 1000 38	
Blade Serial No. 1 AEA 26085	
2 AEA26/11	
3	
4	

INSTALLATION HISTORY

Date	Aircraft Model & Registration Number	F Engine Serial Number & Position
MAR 01 2	THIS PROPELLER WAS MANUF	
	INSPECTED AND FOUND TO	
	WORTHY ON THIS DATE.	ul au
B2D340 PROP S REG. N S/N 100	ORDER:	DATE: 5/13/2013 A/C TSN: PROP TT: 0 TACH
Visual	Entries lly inspected propeller in accordance with the long time storage rechapter 61-00-06. No corrosion noted at this time.	equirements of McCauley Owner/Operator Manual MPC26
5 Yea	r Inspection due 3/8/15	
Mainte	nance Release	

DATE: 5/13/2013

SIGNED:

Work Order: 1881-05-2013

Printed by EBis 3 (datcomedia.com

Freedom Aviation

Repair Station No. BGSR439C 310 Hangar Road Lynchburg, VA 24502 Phone: 434-237-7002

DATE: 1/28/2014 A/C TSN: 98 6 PROP TT: 98 6 TACH: 98 6

Prop Entries

Complied with 100 hour inspection items on propeller IAW Piper Arrow PA-28R-201 Inspection Report.

Maintenance Release

The aircraft and/or component(s) on 751LU as listed above was repaired and/or inspected in accordance with current Federal Aviation Regulations and was found airworthy for return to service. Pertinent details are on file at this repair station under Work Order No. 7980, dated 1/28/2014.

DATE: 1/28/2014

SIGNED:

Joe Leonard Certified Repair Station No. BGSR439C Work Order: 7980

PROP MODEL: B2D34C213-B PROP S/N: 100038 REG. NO: 751LU WORK ORDER: 8185

Freedom Aviation

Repair Station No. BGSR439C 310 Hangar Road Lynchburg, VA 24502 Phone: 434-237-7002

DATE: 3/7/2014 A/C TSN: 191 4 PROP TT: 191 4 TACH: 191 4

Printed by EBis 3 (datcomedia.com)

Prop Entries

Complied with 100 hour inspection IAW Piper PA-28R-201 inspection report.

Maintenance Release

The aircraft and/or component(s) on 751LU as listed above was repaired and/or inspected in accordance with current Federal Aviation Regulations and was found airworthy for return to service. Pertinent details are on file at this repair station under Work Order No. 8185, dated 3/7/2014.

DATE: 3/7/2014

SIGNED James Mashburn

Work Order: 8185

Certified Repair Station No. BGSR439C

Printed by EBis 3 (datcomedia.com)

PROP MODEL: B2D34C213-B PROP S/N: 100038 REG. NO: 751LU WORK ORDER: 8348



★ Freedom Aviation

Repair Station No. BGSR439C 310 Hangar Road Lynchburg, VA 24502 Phone: 434-237-7002

DATE: 4/23/2014 A/C TSN: 290 3 PROP TT: 290 3 TACH: 290 3

Prop Entries

Complied with 100 hour inspection IAW Piper PA-28R-201 inspection report.

The aircraft and/or component(s) on 751LU as listed above was repaired and/or inspected in accordance with current Federal Aviation Regulations and was found airworthy for return to service. Pertinent details are on file at this repair station under Work Order No. 8348, dated 4/23/2014.

DATE: 4/23/2014

Rang SIGNED: in

Work Order: 8348

Printed by EBis 3 (datcomedia.com) Marty Wright Certified Repair Station No. BGSR439C ges in and ਰ Numbers Jnatures Station

B2D34C213-B PROP S/N: 100038 REG. NO: 751LU WORK ORDER: 8533



Freedom Aviation

Repair Station No. BGSR439C 310 Hangar Road Lynchburg, VA 24502 Phone: 434-237-7002

DATE: 6/3/2014 A/C TSN: 366 4 PROP TT: 366 4 TACH: 366 4

Prop Entries

Complied with 100 hr. Inspection IAW Piper PA-28R-201 (p/n 230-1946) Inspection forms

Maintenance Release

The aircraft and/or component(s) on 751LU as listed above was repaired and/or inspected in accordance with current Federal Aviation Regulations and was found airworthy for return to service. Pertinent details are on file at this repair station under Work Order No. 8533, dated 6/3/2014

DATE: 6/3/2014

SIGNED

Jee Leonard Certified Repair Station No. BGSR439C Printed by EBis 3 (datcomedia.com)

PROP MODEL: B2D34C213-B PROP S/N: 100038 REG_NO: 751LU WORK ORDER: 8698



★ Freedom Aviation

Repair Station No. BGSR439C 310 Hangar Road Lynchburg, VA 24502 Phone: 434-237-7002

DATE: 7/24/2014 A/C TSN: 465.2 PROP TT: 465.2 TACH: 465.2

Prop Entries

Complied with 100 hour inspection IAW Piper PA-28R-201 inspection report.

The aircraft and/or component(s) on 751LU as listed above was repaired and/or inspected in accordance with current Federal Aviation Regulations and was found airworthy for return to service. Pertinent details are on file at this repair station under Work Order No. 8698, dated 7/24/2014.

DATE: 7/24/2014

SIGNED:

Work Order: 8698

1 doe Leonard

7 Certified Repair Station No

Printed by EBis 3 (datcomedia.com)

PROP MODEL: B2D34C213-B PROP S/N: 100038



★ Freedom Aviation

Repair Station No. BGSR439C 310 Hangar Road Lynchburg, VA 24502 Phone: 434-237-7002

DATE: 9/6/2014 A/C TSN: 561 9 PROP TT: 561 9 TACH: 561 9

Prop Entries

Complied with 100 hour inspection items IAW Piper PA-28R-201 Inspection Report PN: 230-1946.

Maintenance Release

The aircraft and/or component(s) on 751LU as listed above was repaired and/or inspected in accordance with current Federal Aviation Regulations and was found airworthy for return to service. Pertinent details are on file at this repair station under Work Order No. 8860, dated 9/6/2014.

DATE: 9/6/2014

SIGNED: Marty Wright

Work Order: 8860 Printed by EBis 3 (datcomedia com)

> umbers Station

Certified Ren

BGSR439C

nnal propeller inspection IAW Piper PA-28R-201 inspection report 230-ed spinner cuff P/N 455-634 IAW Piper PA 28-201 AMM 61-10-00.

letins On Pages 11 & 12

HORY Authorized Signatures Repairman and Station Certificate Numbers

DATE	TACH	DESCRIPTION OF WORK PERFORMED	SIGNATURE
19 Dec 14	676.2	Removed and disassembled (1) propeller m/n B2D34C213-B	
		s/n 100038 and repaired grease leak c/w s/b 119A, 227B, s/l	U.S.U
		87-3. Assembled, greased, and balanced. Installed on	3
		aircraft PA-28R-201 N751LU.	
-		H & H Propeller Service, Inc.	
		3439 S. Aviation Dr.	D V
		Burlington, NC 27215	
		1-800-334-6437	
		FAA Repair Station PS4R451M	met
	77		
		PROP MODEL:	
		PROF MODEL: B20340213-B PROP S/N: 100038 REG. NO: 751LU Repair Station No. BGSR439C	DATE: 2/18/2015 A/C TSN: 719.4
		WORK ORDER: 9464 FREED OM Lynchburg, VA 24502	PROP TT: 719.4 TACH: 719.4
		Prop Entries	
		Ran aircraft engine could not dualisate dis-	
		to H & H Propeller Service Removed non-de-at-de-	s good. creen. Sent gov -
1		Ground run ops checks good at this time. Work done IAW Piper PA-28R-201 AMM 61-00-00.	ter repair.
		Maintenance Release	
		Maille larice Release	-

Note: Enter Complian DATE: 2/18/2015

Work Order: 9464

र्रे 12

Marty Wright Certified Repair Station No. BGSR439C

SIGNED: Man

Printed by EBis 3 (datcomedia.com)

FREEDOM

Freedom Aviation 310 Hangar Road Lynchburg, VA 24502 (434) 237-3342 CRS# BGSR439C

MA

Date	Total Pr Tir

Date: 3/19/2015; Aircraft: N751LU; Type: PA-28R-201; S/N: 2844146; Tach: 759.3; WO#: F15-1055 Prop Model: B2D34C213-B; S/N: 100038; Prop TT: 759.3

Prop Entries

Complied with 100 hour inspection IAW Piper PA-28R-201 Inspection Report PN: 230-1946.

Maintenance Release

The aircraft and/or component(s) as listed above were inspected in accordance with current Federal Aviation Regulations. Pertinent details are on file at this repair station.

Joe Leonard CRS# BGSR439

FREEDOM

Freedom Aviation 310 Hangar Road Lynchburg, VA 24502 (434) 237-3342 CRS# BGSR439C

Date: 4/30/2015; Aircraft: N751LU; Type: PA-28R-201; S/N: 2844146; Tach: 858.3; AFTT; 858.3 WO#: F15-1252; Prop Model: B2D34C213-B; S/N: 100038; Prop TT: 858.3

Prop Entries

Complied with propeller 100 HOUR inspection i/a/w Piper PA-28R-201 inspection report PN: 230-1946.

Maintenance Release

The aircraft and/or component(s) as listed above were inspected in accordance with current Federal Aviation Regulations. Pertinent details are on file at this repair station.

Alada Keeth George

GLADDEN KEITH GEORGE CRS#: BGSR439C

has been inspected in accordance with

as been inspected in accordance with

n _________inspection and was

determined to be in airworthy condition.

Freedom Aviation, Repair Station #BGSR439C

Signatures

and Station

e Numbers

e Bulletins On Pages 11 & 12



Freedom Aviation 310 Hangar Road Lynchburg, VA 24502 (434) 237-3342 CRS# BGSR439C

E HISTORY

Date: 6/10/2015; Aircraft: N751LU:	Type: Piper PA28R-201; S/N: 2844146; Hobbs: 1046	0: Took: 050 4:
NO#: F15-1420; Prop Model: Mc	Cauley B2D34C213-B; S/N; 100038; Prop TT: 950 1	.u, Tach. 950.1;

Prop Entries

Complied with 100 hour inspection items on propeller IAW Piper Arrow PA-28R-201 Inspection Report P/N X 230-1946

Authorized Signatures Repairman and Station Certificate Numbers

Maintenance Release

The aircraft and/or component(s) as listed above were inspected in accordance with current Federal Aviation Regulations, Pertinent details are on file at this repair station.

January Gladden Ke

gertify that this I KOPEUER

has been inspected in accordance with

determined to be in airworthy condition.

Freedom Avietin

an 100 hove __inspection and was

Note: Enter Compliance With All Appli

Inspector World Kark (Inc.)

Repair Station #BGSR439C

Gladden Keith George CRS#; BC

			3	(
X		1		
FR	EE	D	MON	

Freedom Aviation 310 Hangar Road Lynchburg, VA 24502 (434) 237-3342 CRS# BGSR439C

Date: 7/13/2015; Aircraft: N751LU; Type: PA28R-201; S/N: 2844146; Tach: 1039.7; AFTT;1039.7 W0#: F15-1685

Prop Model: B2D34C213-B; S/N: 100038; Prop TT: 1039.7

Prop Entries

Complied with 100 hour inspection IAW Piper PA-28R-201 inspection report PN: 230-1946.

Maintenance Release

The aircraft and/or component(s) as listed above was repaired in accordance with current Federal Aviation Regulations. Pertinent details are on file at this repair station.

Joe Leonard CRS#: BGSR439C

δ



Freedom Aviation 310 Hangar Road Lynchburg, VA 24502 (434) 237-3342 CRS# BGSR439C

Date: 10/06/2015; Aircraft: N751LU; Type: PIPER PA28R-201; S/N: 2844146; TACH: 1128.8; HOBBS: 1234,7; AFTT: 1128.8; WO#: F15-1945; Prop Model: B2D34C213-B; S/N: 100038; Prop TT: 1128.8

Complied with 100 hr / Annual Inspection of prop IAW Piper Inspection Report P/N 230-1946.

Maintenance Release

The aircraft and/or component(s) as listed above were inspected in accordance with current Federal Aviation Regulations. Pertinent details are on file at this repair station.

Gladden K George CRS#: BGSR439C

310 Hanger Road Lynchburg, VA 24502 434-237-7002 CRS# BGSR439C

Date: 12/20/2015; Aircraft: N751LU; Type: PA-28R-201; S/N: 2844146; Tach: 1226.6;

Total Time: 1226.6; Prop - Type: B2D34C213-B, S/N: 100038, Time: 1226.6 Shop Order #: F15-2295

Prop Entry

Complied with 100 hr / Annual Inspection IAW Piper Inspection Report p/n 230-1946.

Maintenance Release

I certify that this propeller as listed above has been repaired IAW current Federal Aviation regulations and inspected IAW a 100 Hour/Annual Inspection and is considered to be airworthy for return to service.

Pertinent details are on life at this repair station.

Signed: CRS# BGSR4390

Bulletins On Pages 11 &

Repairman and Station uthorized Signatures ertificate Numbers

FREEDOM

310 Hanger Road Lynchburg, VA 24502 434-237-7002 CRS# BGSR439C

Date: 4/22/2016; Aircraft: N751LU; Type: PA-28R-201; S/N: 2844146; Tach: 1317.3; Total Time: 1317.3; Prop - Type: B2D34C213-B, S/N: 100038, Time: 1317.3

Shop Order #: F16-1475

Prop Entry

Complied with 100 hr / Annual Inspection on prop IAW Piper Inspection Report p/n 230-1946.

Maintenance Release

The aircraft and/or component(s) as listed above was repaired and/or inspected in accordance with current Federal Aviation Regulations and was found airworthy for return to service. Pertinent details are on file at this repair station.

Signed:

CRS# BGSR439C



310 Hanger Road Lynchburg, VA 24502 (434) 237-7002 RGSR430

Date: 6/13/2016; Aircraft: N751LU; Type: PA-28R-201; S/N: 2844146; Tach: 1395.6; Total Time: 1395.6; Prop - Type: B2D34C213-B, S/N: 100038, Time: 1395.6 Shop Order #: F16-1693

Propeller Entry

Complied with 100 hr / Annual Inspection on prop IAW Piper Inspection Report p/n 230-1946.

Maintenance Release

The aircraft and/or component(s) as listed above was repaired in accordance with current Federal Aviation Regulations. Pertinent details are on file at this repair station.

CRS# BGSR439C

A.A. AIRWORTHINESS D E AND SERVICE BULL

Total

Propeller

œ

etin/Letter Number

Authorized Signatures Repairman and Station

AIRWORTHINESS DIRECTIVE AND SERVICE BULLETIN RECORD

 $\overline{\mathfrak{a}}$

Date: 8/02/2016; Aircraft: N751LU; Type: PA-28R-201; S/N: 2844146; Tach: 1494.1; Total Time: 1494.1; Prop - Type: B2D34C213-B, S/N: 100038, Time: 1494.1

Shop Order #: F16-1864

Prop Entry Complied with Annual/100 hour inspection IAW the Piper PA28R-201 Inspection Report 230-1946

Maintenance Release

The aircraft and/or component(s) as listed above was repaired in accordance with current Federal Aviation Regulations. Pertinent details are on file at this repair station.

CRS# BGSR439C Signed:

310 Hanger Road Lynchburg, VA 24502 (434) 237-7002 FREEDOM CRS# BGSR439C

Date: 10/23/2016; Aircraft: N751LU; Type: PA-28R-201; S/N: 2844146; Tach: 1592.3; Total Time: 1592.3; Prop - Type: B2D34C213-B, S/N: 100038, Time: 1592.3 Shop Order #: F16-2185

Propeller Entry Complied with 100 hr / Annual Inspection IAW Piper Inspection Report p/n 230-1946.

Maintenance Release

The aircraft and/or component(s) as listed above was repaired in accordance with current Federal Aviation Regulations. Pertinent details are on file at this repair station.

Signed:

CRS# BGSR439C

A.D./Bulletin/Letter Number Repairman and Station Certificate Numbers natures