



# TEXTRON AVIATION

Maintenance Transaction Record  
This Maintenance Report is To Be Used Solely For:

MTR ID # 8054057  
Page 1 of 1

Textron Aviation  
One Cessna Blvd.  
Wichita, KS 67215 U.S.A.  
Phone: +1(316)517-6000

Prop2 Serial No. 191193

### Aircraft Identification and Status

A/C Serial #	A/C Unit #	A/C Registration #	Date	City ID	Total A/C Hours	Total A/C Landings	Eng. 1 Ttl Hrs	Eng. 2 Ttl Hrs	Eng. 1 Ttl Cycles	Eng. 2 Ttl Cycles	Prop 1 Hrs	Prop 2 Hrs	Freon Hrs
TH-2535	2535	N993MW	24-Aug-20	KBEC	2.8	3	2.8	2.8	3	3	2.8	2.8	

### Component Changes, Inspections, Service Bulletins, or Airworthiness Directives Accomplished

Task/Item	Transaction No. Type	Item Name	Position	Part Number/Alternate Part	Mod Level	Part Serial	Removal Reason	Status	Installed Part TSN/TSO/TSR
NA	1 -	PROP RH							

Comment :

This prop model 3AF32C512/82NEA-5 has been installed on this aircraft as of 03 AUG 2020 with 0.0 hrs & 0 cycles.



Trans Type: 1-Component, 2-Inspection, 3-SB, 4-AD, -Misc Removal Reasons: WO-Worn to Limits, SC-Scheduled, UN-Unscheduled, CO-Convenience, N-Other(note in comments)

Installed Part Status: N-New, R-Repaired/Rebuilt, S-Serviceable, O-Overhauled, T-Tested, M-Modified, I-Inspected

Repair Facility Textron Aviation Inc. Certified Repair Station Number PC4 Work Order # \_\_\_\_\_  
 Work Performed By Textron Aviation Inc. Certificate No. PC4 Date 24-Aug-20


Federal Aviation Administration  Other (specify) \_\_\_\_\_  
 The aircraft identified above is presently airworthy & approved for service.

Work Inspected By Cary Klug Certificate No. PC4 Date 24-Aug-20  
 Pertinent details of this maintenance are on file at our facility under the above Work/Service Order Number as applicable.

Maintenance Log	
Section	Page
11	

# PROPELLER ASSEMBLY LOG

PAGE NUMBER \_\_\_\_\_

Date	Total Time	Time Since Overhaul	Aircraft Model & Registration Number	Maintenance Service History	Signature & Certificate Number
JAN 27 2020	0	3AF32C512	512-D 191193	<b>THIS PROPELLER WAS MANUFACTURED NEW AT MCCAULEY PROPELLER SYSTEMS. INSPECTED AND FOUND TO BE AIR- WORTHY ON THIS DATE.</b>	

PROP MODEL (R): 3AF32C512  
 PROP S/N (R): 191193  
 REG. NO: N993MW  
 WORK ORDER: 1059



1005 Sycolin Road Suite 106  
 Leesburg, VA 20175  
 Phone: 703-443-4739

DATE: 8/27/2021  
 A/C TSN: 125.5  
 PROP TT (R): 125.5  
 HOBBS: 125.5

### Right Prop Entries

Performed Annual inspection on propeller #2 IAW Beechcraft Baron G58 AMM 5-20-00 and FAR 43 Appendix D, and using McCauley Prop Operators Manual as reference. Inspected spinner, blades, hub, and mounting; no defects noted at this time. Dressed and cleaned prop as needed.

I certify this Propeller has been inspected IAW an Annual Inspection and was found to be in Airworthy Condition.

### Maintenance Release

The aircraft and/or component(s) on N993MW was repaired and inspected in accordance with current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of this maintenance are on file at our facility under the above work/service order number as applicable.

DATE: 8/27/2021

SIGNED: 

Work Order: 1059