PIPER PAZE-236 SIN: 28-7911310 ENGINE LOG#2



### Engine Record General Information

Manufacturer's Recommended Overhaul at \_\_\_\_\_

Manufacturer LYCOMING	Model 0-540	- T3A50	3
Serial <u>L-21831-40 A</u>	Type Certificate		
This engine is currently installed in	aircraft: N8083Y PA-2	8-236	
	(#)	*	1
Minimum Octane Fuel 100	Oil Grade Summer_50ωε.	Winter-	¥
Magneto Time	Point Setting	Firing Order	
Spark Plug Gap			

hours

YEAR RECORDING
TACH
TIME

TODAY'S FLIGHT

TOTAL
TIME IN
SERVICE

**Description of Inspections, Tests, Repairs and Alterations**Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)

# PERFORMANCE ABRO ENGINES

00 00 SMOH

Stage III engine overhaul O-540-J3A5D serial # L-21831-40A. Disassemble, clean, NDT & dimensionally inspect. Micropolish crankshaft std/std, SB530, SB505, SB475. Bush blades & counterweights. Modify crankshaft gear per SB475, torque 660 in lbs safety. Bush & bore connecting rods for center to center. Install new camshaft & lifters. Install & size new intake & exhaust guides. Three angle high performance valve job. Flow heads on SF600 flow bench. Surface & restud ports. Hone cylinders for ring finish. Bush size & ratio rocker arms. Complete engine blueprinted & balanced dynamically. Alodine alloy parts, paint engine. Assemble engine completed per manufacturers approved data. Engine must be functionally tested per SI1427 before return to service. See AD Compliance sheet. Other pertinent data on file at:

PERFORMANCE AERO ENGINES, INC.

RS#P6ER393N

Work Order #3736

Date: 4/9/0

Signed

lan Momo

#2540162

YEAR RECORDING TODAY'S TOTAL **Description of Inspections, Tests, Repairs and Alterations** OI FLIGHT TIME IN Entries must be endorsed with Name. Rating and Certificate Number of SERVICE Technician or Repair Facility. (See back pages for other specific entries.) DATE June 5 2001 Tac: 2348.24h TSMON: 000.00ha TSN: 2,348.24ha Lecus meled Engue stree noutral by Parformence New Engues of Loveine, CA. RS# PGER 393N. CUSINES EN ME THUSS, LASTRILED NEW VIBRATION ISOCATIONS Repensed sus printes sel Emme Baffel insmiles new Baffel seals, New En que Hoss / Hoss By AIN- Par of Como BERN, CA) AD JUSTED ENGINE CONTROLS for PAPEN OPE ATMIN. EXHAUST SYSTEM SENT OF THE REPORT, INSTALLES NEW ACTEMINATOR Drive Belt Tetimes WHEHETO to Engine ficiel En ine with Pressitell Sous. NOW DET. WILLIEL OIL FOR BAGAK-IN. ENGINE BREMC-IN PRICEDURES PEN Lycoming 35 1427B RECommendations. C/W All 100 hr Am Annual 12 spection Heres par Row Sauce Wanual All work Dinein recusance with Paper Suice Manuel Note: Clacato ofH'd 04-2001 00.0hr on alke @ E.ure of Kusmecanion NOTE: AD 00-18-53 OIC fecter Converter Plan Graker c/we 0/11 01-01 pur Run MB 5434 BME-GIME NOTE: AD 96-12-07 WASHETO IMPLISE Compline Due Every SUDA DESINO 2848246 C/W AD 76-07-12 WAGRETO Switch By function test Due Every 1 volum Hotin @ 2448.24hr c/w AD \$5-26-13- on Coolen Hosse New Hosse Due Every 100 la agrice 2448.246. 3348.246 I crutify THAT I HAVE CASPECTED THIS ENSINE in ACCORDENCE WITH A TOOK INISPRETION AND DETERMINED CT to BE in An AMMORTHY CONDITION THE DATE.

				5 9
YEAR O(  DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	<b>Description of Inspections, Tests, Repairs and Alterations</b> Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. ( <i>Seé</i> back pages for other specific entries.)
Lune	5 2001	THE: à	348.24h	- TSMOH: 000.00h TSN: 2,348.24km
	, ,	ucis	CE AD NO	TES THOM 01-08.
_ Z(	sectory 7	WEDE !	TIM SUD	Desgrained it to BE in An Ainwarry Condition
	is DHTE.	7	_	T. D. Wellen A) 12329157 IA
NOTE:	upDes	D H	Cost	BACK of LOG -
6/8/01	23 50,70		OIL &	FILTER CHANGED WITH A/S 1000 50WT.
			12 Q-	RUN, NO LEAKS: S.N. OWNER
7/23/01	237398		01- L 12 QT	FILTER CHANGED WITH AS 100 SOWT.  S CH 48103 FILTER, WASAED ENGINE,
000			TEST	RUN, NO LEAKS, S.N. OWNER

YEAR O ( DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	<b>Description of Inspections, Tests, Repairs and Alterations</b> Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. ( <i>See</i> back pages for other specific entries.)
11/21/01	2406.46		0162	FILTER CHANGED WITH A/S 100 W/50 W7
			12 QT	S CH 48103 FILTER WASHED ENGLIS
			TEST	RUN, NO LEAKS, SINI OWNER.
_,_,				
3/28/02	2452.00		OIL	FILTER CHANGED WITH A/S 100W/50 W
			12 979	, CH 48103 FILTER WASHED ENGINE
			TEST	RUN, NO LEAKS, SIN OWNER
		780		the state of the same
			1	· ·
			+35	
		5 75		
				and the second s
-5-14		e:		

YEAR 2002 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
July 2	2002	TAO!	2488.14/	- TSMOH: 139,90hm
TECH	(116ED) O	el ge	is filter	Agrositell Soure. DET. CHAMPION CHESTOS JULIA)
CHA	46ED AU	Lilfe	Elewen	BULLETT Phi 2905 CLESNED All puel Spell
SCA	sens in	mel	D NEW	iel Grecolin Barl Groket Withthe English
Au	conlin	n, C	FECKED, UM	HOURTO GO EJULUE TIMEN CONTILEMENTOESS-
#1	73/30 21	79/90	376/90 4	19/30 TI/85 "1/30 CHECKED All English Conthals
for	prose	gard	no sel	entralle sun achusi Compareta for sentale.
J	speles	New	BUSITH	Vine fla Hore MIL-H-6000-16 ADJUSTOME
X	reting 4	un to	· wasps	DAS CEDURED, XEMMED WITH SEAR.
E	welve Be	fel	carel.	prometer Alturnom feer free ment
	7 fres	1 /3	in P/N:	Savices 166 Classes
/	solfw.	dub)	Sinus	(maple tum tems) flu figar tenice wante
	selun	Dne	e in Ac	onbauce with figer surce wante
4	LED FAA	4243	13-1BA	A MAGRISTE.
	No. 12 2		a 1	Visual No 8 18 4 100 / 164 10 25381
C/W	AD 95-2	6-13	DIC Coole	1) Hose may betern by Ingraction all Way 100 hastern 435.
-c/w	HD 76-	0/1-12	- Dendus	Surremonifer of presentings ourself to
				Continued NexT/AGE

YEAR AND AND DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
Julya	2002	THe: a	488.146	TSWAH: 139.90 h
(Fren	a Previo	us /so	€) )	
1/2:	AD 96-12-	02 10	AGUETO IN	spulse Coupling Due Every 500 ha Alerin @ 2848,24ha
NOTE: 1	D 00-18-5	3 La	3 N Engine	oil supersever to AD 02-12-07
1/878. 1	0 02-12-		Went Los	a 1/ Enline oil P/c/w @ Enime, S/H 104-200/ #5434 1:110
		10		10.
I	Cartely	7/1/25	IHNE	inspected This Evene in Anna Dance, with
A	100 hr	Tres 29	chen &	us Defermined of to Be in an Anni order
C	un Tim	Thes	DATE.	1.2. alilla Ail 2325157
		55. 5		
$\sim$	/			V.
July	24200	2 7	c: 2498.	14km 18MOH: 139.90km
17	CHECKS	n de	deens	AD NOTES THUN 02-13.
Ĭ.	I Can	ile of	LATIA	THE CHERECTED THIS ENGER in LECADINES
	with a	Ada	nust To	s sertion des Attaluine 1 460 BE in de
	Luna	they &	motion	The Aste
	7,0000	/		10/1/// 1/2000

YEAR 02 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
11/14/02	2533.09		014	& FILTER CHANGED WITH AS 100W/50WT.
			10 Q	VARTS , CH 48103 FILTER , WASHED
			ENGIN	E, TEST RUN, NO LEAKS, S.N. OWNER
				the property of the families of the party of
3/24/03	2577.45		014	& FILTER CHANGED WITH A/S 100W/SOWT
44110	70 1110		10 Q	VARTS, CH 48103 FILTER, WASHED
		1	ENGU	WE TEST RUN, NO LEAKS SIN. OWNER
8.1.03	2617.35	T51	noH 2.6°	4.11 Persormed differential Compression
CHack	10 out	des	at lole	bus #1 1/2 #2 1/2 #3 1/2 #44 1/2 #5 1/6 #6/20
CHECK- U	Doill t	15//	ilter	Replaced All twelve Spark plage
CHARLE	el sil	128	to De	The None duy at this tim. I
C TI	TH	1100 7	NSDEEN	sel This Engine RAW A ANNOW!
I WSDE	72		Vaterna	instit to be in Ajawatly
Condition	7	Vin	Snewe	as Approved for Retur to Service
- mune			0	
				ASPTASE 2758645
-				1)0/

YEAR DATE	RECORDING TACH TIME	TODAY'S Flight	TOTAL TIME IN SERVICE	<b>Description of Inspections, Tests, Repairs and Alterations</b> Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. ( <i>See</i> back pages for other specific entries.)
8/1/03	2617.35	RE	PLACED ENGI	STAGTER DRIVE AIR FILTER NE HEAT SHROUD S.N. OWNER
12/4/03	2661.93		10 QT	FILTER CHANGED WITH A/S 100W RUS/SOWT CH 48103 FILTER, WASHED ENGINE, RUN, NO LEAKS, S.N.OWNER
7/5/04	2705,61		10 QT	FILTER CHANGED WITH A/S 100 PLUS/SOW S, CH 48103 FILTER, WASHED ENGINE, RUN, NO LEAKS, S.N. OWNER

Sept 13 2004

Tach 2712.52

Performed Differintial compression check all Cylinders as follows #1 75 /80 #2 76 /80 #3 77/80 #4 77/80 #5 77/80 #6 77 /80. Cleaned and gapped all twelve spark plugs.

I certify I have Inspected this Engine in accordance with a Annual Inspection and Determined to be in Airworthy. This Engine is approved for return to service.

L W Ziegler A&P, IA 2758645

/EAR DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
phos	2727.98			GERDES AVIATION SERVICES PROFESSIONAL AIRCRAFT SERVICES  Date: 6-1-05 N# 8083Y (act)/Hobbs: 2727.98 TT: 2727.98  (i) REMOVED & REPLACED 12 ENGINE EPARK PUGS WITH NEW PN# HMMHOE - CHAMPION: (ii) ALL PUGS INSTALLED / TORQUED / \$ WIRE NUTS TORQUE SEALED. (3) END.  Brian Gerdes P2804735
3-22-05	2 <b>750</b> .87			CHE OIL + FILTER, REFILL WITH 10 OTS AS 100+, ENGINE PUN, NO OIL LEARS NOTED. C.PSlemlin APSSB605989

YEAR	RECORDING TACH	TODAY'S FLIGHT	TOTAL TIME IN	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of
DATE	TIME		SERVICE	Technician or Repair Facility. (See back pages for other specific entries.)
	1. CV 2. AL 3. CC	PER PA2 V AD 02- 0 05-19-1 0 MPRES	26-01 BY IN 1 NA, ORIG SION CHEC	ER. NO: 28-7911310 SMOH: 413.25  NSPECTION F.I. LINES AND CLAMPS GINAL CRANKSHAFT  K. #1-78. #2-78. #3-78. #4-78. #5-78. #6.78. ALL OVER 20 PGV
	5. IN: 6. RE 7. CH 8. EN 9. PEI	STALL N SAFETY ECKED GINE GI RFORM	TEW INDUC ALT ADJU ALL CONTI ROUND RUI ALL REOD	TION FILTER, BA 2905
				DATE 10-10-05 AC N 86634  I CERTIFY THAT THIS SHAPE HAS  BEEN INSPECTED IN ACCORDANCE WITH  INSPECTION AND WAS  DETERMINED TO BE IN AN AIRWORTHY CONDITION  TOTAL TIME 2761, 19TACH 2761, 49  A & P 558605954

YEAR - US Date	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
2-10-05	2796.0			CITE OIL + FILTER REFILL WITH 10 GTS ALS 100+ ALC GROWD RIN, NO WALS NOTED C. Bliml AND 558605752
				10 GTS ALS 100+ ALC GROWD
×1				RUN. NO LEAKS NOTED
In the second				Co. Bliml A7PS58605952
.00				
				70 × V
				× 0
				Y
				8
				R 0 1 46 91

YEAR	RECORDING TACH	TODAY'S FLIGHT	TOTAL TIME IN	Description of Inspections, Tests, Repairs and Alteration Entries must be endorsed with Name, Rating and Certificate Number of
DATE	TIME		SERVICE	Technician or Repair Facility. (See back pages for other specific entries.
=:				AIRCRAFTERS, INC.
			FRENC	CH VALLEY AIRPORT BLD. 2 SUITE F
-				37552 WINCHESTER ROAD
			MUI	RRIETA CA. 92563 PH. 909-304-1292
ñ		DATE: 2/21	/06 MODEL	PA-28-236 REG#: N 8083Y TACH: 2809.3 W.O.: 062896
1 C/W	AD 2005-12-06	ON RENDE	Y MAG IMPLIT	SE COUPLING BY INSPECTION OF THE IMPULSE COUPLING, NO DEFECTS
NOT	TD "A" IN ON T	THE DATA	PLATE THE	NEXT INSPECTION DUE AT 3309.3 AIRCRAFT TOTAL TIME.
2 CON	PLETED A 500	HR INSPE	CTION ON TH	E MAG AS PER THE BENDIX MASTER SERVICE MANUAL.
3. INST	TALLED A NEW	CAPACITO	OR P/N 10-4005	76 FOR THE LEFT MAG.
THE AIR	CRAFT/COMPON	VENT IDEN	TIFIED ABOV	E WAS INSPECTED AND REPAIRED IN ACCORDANCE WITH APPLICABLE
FARS AN	D WAS FOUND	TO BE AIR	WORTHY FOR	R RETURN TO SERVICE.
			ILL DAILEDA	Bell Vaileda A&P1910299
7.				and the second of the second o

SkyBlueAir.nc. 50 Durley Ave. Camarillo, CA 93010 Phone: 805-987-7700 Work Order# M2287

Date: 03-20-2006

Tach Time: 2820.9

Hobbs N/A

Engine:
Serviced oil & filter (12qts Aeroshell 100 & CH48103-1 Filter) and checked fuel strainer.

Erik Keene

YEAR RECORDING TODAY'S TOTAL **Description of Inspections, Tests, Repairs and Alterations** RECORDING TODAY'S **Description of Inspections, Tests, Repairs and Alterations** TACH FLIGHT TIME IN Entries must be endorsed with Name, Rating and Certificate Number of TACH FLIGHT TIME IN Entries must be endorsed with Name, Rating and Certificate Number of SERVICE Technician or Repair Facility. (See back pages for other specific entries.) Page Fooility (See back names for other specific entries.) SkyBlueAirinc. 50 Durley Ave. Camarillo, CA 93010 Phone: 805-987-7700 SkyBlueAirınc. 50 Durley Ave. Camarillo, CA 93010 Phone: 805-987-7700 Page 1 of 1 Page 1 of 1 M2312 Time: Tach- 2844.84 Date: 06-05-2006 N8083Y PA-28-235 Hobbs- N/A Work Order# M2316 Time: Tach- 2856.4 N/A N8083Y Work Performed: Airframe PA28-236 Removed pilot side R/H brake master CYL. Replaced with new Cleveland P/N 10-30. Engine-Time: Total Time -Removed and replaced handbrake master CYL, installed new Cleveland P/N 10-22 gravity bled brake system. Work Performed: Engine Serviced oil and filter (12qts Aeroshell 100 & CH48103-1 filter) Leak check okay Erik Keene A&P# 3100387 FAA Authorization: Erike Keene A&P#3100384 SkyBlueAirinc. 50 Durley Ave. Camarillo, CA 93010 Phone: 805-987-7700 Work Order# M2320 Page 1 of 1 Time: Tach- 2592,03 Hobbs-N8083Y **PIPER** DAKOTA Work Performed: ENGINE: SkyBlueAirInc. 50 Durley Ave. Camarillo, CA 93010 Phone: 805-987-7700 Page 1 of 1 Removed and replaced Governor P/N: F-4-21Z S/N: EG14 and sent to SMP for leak repairs and bench checks. Installed Governor. Checked Mag timing and found to be accurate. Removed harness leads. Removed and inspected all plugs. Set Date: 05-11-2006 Work Order# M2303 gaps to mins(.16") Installed and torqued all plugs. Cleaned and stretched harness springs to reach plug depths. Installed all N8083Y Piper Dakota leads and secured. Adjusted carb mixture set screw to enrichen. All ops & leak checks good. Aircraft returned to service. Work Performed: Engine All work performed I/A/W 0-540 MM Cleaned and Re-Gapped All Plugs. FAA Authorization: **FAA Authorization:** John Kaness A&P#5640651131A Erik Keene A&P#3100384

AR TE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	<b>Description of Inspections, Tests, Repairs and Alterations</b> Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. ( <i>See</i> back pages for other specific entries.)
			1	
			CAMARI	LLO AIRCRAFT SERVICE
		375	Durley Ave.	• Camarillo, CA 93010 • (805) 388-1322
	Oct Tack	12, 20	006 0-1 11 q <sup>2</sup> 103 met	Changel all & filter. Added  Is Aeroshell woo plus & CH48  -1. Cut open filter. No al found. Cowled.  Rull N JLD  575661948 AAP
13				
		•		
				er e

YEAR	RECORDING	TODAY'S TOTAL	Description of Inspections, Tests, Repa	
DATE	TACH TIME		27552 Windhoster Dd	Partificate Number of her specific entries.)
		AIMEO, IOX French Valley Airpo	37552 Winchester Rd Murrieta, CA 92563 (Ph) 951-696-0160 (Fx) 951-698-0019	
( <b>3</b> ).		Date: 12/01/2006; Ai 2912.00; Total Time	ircraft: N8083Y; Type: DAKOTA; S/N: 7911310; Tach: : 0.00; Work Done At - Airframe Time: 2912.00,, Engine	e (8
		Time: 564.00, Shop Order #: 06-11 1. 100hr service and		
		2. Compression che	ck #1-78 #2-78 #3-78 #4-79 #5-78 #6-79 ilter. Cut filter no metal found. Serviced with PH20W50.	
		I certify I have insper inspection and found Brian Gallagher IA A	cted this engine in accordance with a 100 hr and annual dit to be in an airworthy condition.	
-13-07	2962		WIOD+ CUT OPEN FILTER NO	3103-1, SHELL
			TEST RUN. NO LEAKS. JOHN	METAL FOUND
			TEST NUM, THE LEARS. XXXXX	-1001316 60

			R 5			r.	x an harm	- V27		
YEAR RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	<b>Description of Inspections, Tests, Repairs and Alterations</b> Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)	. Y	Date: 01/04/2008 Model PA Tach Time: 3004.8	ළපළ A28-236 N7 <del>068</del> TT: 657.0		3		<b>***</b>
		Oil st (LWI Overl	Tach Time: 2983 TSMOH: 635.0  Jump gasket removed and replaced with new gasket, part #06B21326  13306) i.a.w. the Piper Service Manual, the Lycoming Direct Drive Model thaul Manual, and the AC 43.13. Engine test run, no leaks.  Jump gasket removed and replaced with new gasket, part #06B21326  13306) i.a.w. the Piper Service Manual, the Lycoming Direct Drive Model thaul Manual, and the AC 43.13. Engine test run, no leaks.  Jump gasket removed and replaced with new gasket, part #06B21326  13306) i.a.w. the Piper Service Manual, the Lycoming Direct Drive Model thaul Manual, and the AC 43.13. Engine test run, no leaks.	9/20/1	100 hour inspection. Spark plugs cleaned, gapped, a Changed oil & filter. Aeroshel Compression: #1: 78/80 #2: I certify that this engine has be to be in an airworthy condition.  Michael Piontek A&P 30916.  I certify that this engine has been be in an airworthy condition.  Richard D. Lewis A&P 8642.	Il W100 used. Cha 78/80 #3: 77/80 seen inspected in accent	ampion 48103-1 installe #4: 78/80 #5: 79/80 # ecordance with a 100 h	ed. Cut old filter, need: 79/80 our inspection and	o metal found. was determined as determined to	100 + 3 T

- 1 × 1	· · · · · · · · · · · · · · · · · · ·	y:		a			
YEAR DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)	/EAR	RECORDING TACH TIME	TODAY'S FLIGHT
Date	e: 02/11/200 Tach Tim		Model Pa TT: 729.		123/09	3108	
Spar	ual inspection rk plugs clear 3 deg.'), Fue	ned, gapp		talled with new gaskets M674-AN4027-1. Mag timing checked (set			F
Com Exha	npression: # aust gaskets	1: 77/80 replaced of	#2: 77/80 # on cylinders	3: 78/80 #4: 78/80 #5: 78/80 #6: 78/80.  1,3,5. (RA 77611)  king; N/A, ECI Cyl's not installed this A/C  ———————————————————————————————————		-2	
I ce be in	ertify that this in an airworth	s engine h y condition	as been inspo on,	ected in accordance with an annual inspection and was determined to			1/10/2010 ach Time
	hard D. Lew					Both ig	te igniti gnition c , Engin
9.10.09	3104			Oil changed, 10 ats Aeros HELL WIOO ADDED		Micha	el Piont
=			- 1	Champron Filter 48103-1 installed. Old Filter out open-No Foreign debris found.	- 1		- 1
				AIRCRAFT EXTERS LOW Oil Level Warning			
				SYSTEM INSTALLED I.A.W. MANUSACTURERS INST. GRD,			
	J			At P3091628	!	2	

YEAR DATE	RECORDING TACH TIME	TODAY'S Flight	TOTAL TIME IN SERVICE	<b>Description of Inspections, Tests, Repairs and Alterations</b> Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. ( <i>See</i> back pages for other specific entries.)
0/23/09	3108			Repaired RIGHT Magneto Capacitor
. /			-	WIRE WI NEW SPARE CONNECTOR Mag
				CHECK OK ON GROUND RON.
		1/10/2010 ach Time	1.104411	80837 PA28-236 N70686 SN#28-7911310
	Aero-li Both ig	ach Time te igniti gnition c	: 3115.0	RA28-236 N70686 SN#28-7911310  S #A64-10BS installed i.a.w. manufacturers instructions.  P/N ZM 10 - 400 576 replaced i.a.w. piper service
	Aero-li Both ig manual	te ignition c Engin	: 3115.0 on harness apacitors,	PA28-236 N70686 SN#28-7911310  S #A64-10BS installed i.a.w. manufacturers instructions.  P/N ZM 10 - 400 576 replaced i.a.w. piper service ck good.
	Aero-li Both ig manual	te ignition c Engin	on harness apacitors, ae ops chec	PA28-236 N70686 SN#28-7911310  S #A64-10BS installed i.a.w. manufacturers instructions.  P/N ZM 10 - 400 576 replaced i.a.w. piper service ck good.

YEAR DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	<b>Description of Inspections, Tests, Repairs and Alteration</b> Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.	
20	Date: 03/19/2	2 <mark>010 N</mark> ime: 311	4odel PA28-2 9.5 TT:	236 N7 <del>0686</del> SN#28-7911310 - 771.5 <sup>2023</sup> (	-
*				#	_
_	100 hour insp	ection.			
="				installed. Mag timing checked (23 deg.'), Fuel lines inspected.	_
-9				0 #3: 78/80 #4: 78/80 #5: 78/80 #6: 78/80. I certify that this engine	_
	200	ected in a	ccordance w	ith a 100 hour inspection and was determined to be in an airworthy	
	condition.	4-			_
	Michael Piont	tek A&P	3091628		-
	Translati i iom	1011 11001	3071020		=
	I certify that t	his engine	has been in	spected in accordance with an annual inspection and was determined to	
	be in an airwo				
	Reshar	d D	Jenes		
_	Richard D. L				
				9	

YEAR DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	<b>Description of Inspections, Tests, Repairs and Alterations</b> Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. ( <i>See</i> back pages for other specific entries.)
	Date: 04/01/2 Tach T	2011 L Time: 3		40-J3A5D N8083Y SN#2 <del>1831-40A</del> L - 21831-40 A : 814.4
_	Oil drained, 9 contaminants lines inspected	found. S	oshell W100 park plugs cl	added. New Champion 48103-1 installed. Old filter cut open, no leaned, gapped, and reinstalled. Mag timing checked (@23 deg.`), Fuel
<del>-</del>	I certify that	this engir	ie has been in	0 #3: 77/80 #4: 77/80 #5: 77/80 #6: 78/80.  Aspected in accordance with an annual inspection per the sal and was determined to be in an airworthy condition
<del>-</del>	Sechard D. L.	d2	Jewe	
				2
		-		

					a			e 15	
R E	RECORDING Tach Time	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)	YEAR J DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
	New Champ spark plugs p/n 10-3825 carb heat ca Compressio I certify that and detail of determined	ion 4810 nstalled. 85. Mag ble. Engin: #1:78 this aircr Part 43 a be in a cor, Loos	3-1 installed New capac timing set & ne washed, /80 #2: 75. raft has been Appendix D. n airworthy	Control Sleeve, N/A, HA-6 solid billet Carb. Not installed.	REMOVE WT DET	# 46 06-Fe S/N  D COWL - CERGENT OIL	PIPER  CHANGED  - WASH	OIL AND HED DOWN	FILTER - INSPECTED ENGINE - SERVICED WITH 11 QUARTS OF AI ENGINE - RUN CHECKED FOR LEAKS - RE-COWLED ENGINE -  Date
							7.1	V 13	First dark various
				3)	1				A
					4				V

No. of the last of

YEAR 2013	RECORDING Tach Time	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	<b>Description of Inspections, Tests, Repairs and Alterations</b> Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.).
14 Jun 13	TACH: 32	48,36		ENGINE TO TOTAL TIME! 3248,36 SPACE! 900,12
	11 1 1 1 1 m m l	oil 1	and eil S	TER, SERVICED WITH 11 QTS AEROSHELL 15W-50 Oil
	mud n el	111012	2-1 Nil 5	ITER REPLACED BRACKELL BH-2905 LNUMERION PAIR
g 1	S.ITED 1	15 AUE	Suc 1 50	RETENS AND CRAINED CARBURELOR 130WI: KEPIACED
L 15-50	Court	2 12	VET LUE	DIGATED ENCINE AND PROPERTER CONTROLS, INSTACTED
	_ 1 _	1 7	- 6 2 22	LOOPE MAIN LEADE PEAUEN GAPPIED TESTED AND KILLINSTPHILED
V	All LOADL	Pluns.	ENGINE C	014PRESSION! 1- 180 "2-1980 "3-14/80 "1-14/80 5-1780
	4/ 78/40	REPIAN	EN ENNI	IR shock Mounts AND BOLLS, KRPIACED OIL COURTE CHORES
	and fur	/ PRI	MER HOSE	· CLEANED ENGINE. RITH ENGINE FOR OPERATIONAL AND
	LEAK ch	ciks. E	PERATION	I chack Good, NO LEAKS NOTED AT This Time.
				July 82 AP18496682
	DATE/	4 Jun 1	3 TACH TI	ME3248,36 TOTAL TIME 3248,36 SMOH: 900.12
	I CERT	FY TH	T THIS	PENGINE HAS BEEN
-				NCE WITH WAN ANNUAL
· ·	INSPE	CTION A	ND WAS D	ETERMINED TO BE IN
	AIRWO	ORTHY	ONDITION	1/
	SIGNE	D //	Me Co	A+P18486682IA

YEAR DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
2/7/2014 Inspection Compressi Removed: Checked b systems. In mount for systems. A FAR43. A	on test: 78, 77, all sparkplugs, oth magnetos the aspected engine condition and all checks were opendix D and this engine is the	, 79, 78, 79 inspect, climing to 2 iming to 2 intake fil wear. Ran normal at AC43,131	8, 77/80 lean, gap and ro 3 degrees. Inspleter. Check all be engine to full parties that the control of the con	-945.85 100 hr/Annual  einstall all sparkplugs. pected intake and exhaust belts, hoses, and engine power and checked all work performed IAW licable maintenance is Schandelmeier,  HAS  BEEN INSPECTED IN ACCORDANCE WITH A  INSPECTION AND WAS FOUND  TO BE IN AIRWORTHY CONDITION.
8-29-14	3426			Charge oil & Si Her Cut Sitter no metal found. Returned to servered, Test Run re Leafes. IN Ward 3056883 Aug
37-15	353b	1	1188	I certify that this aircraft/ngme/prop has had a  100 hr inspec (Annual) per CFR 43.13 apend D and found in airworthy condition. All AD's 73 complied with.  Signed JD Ward JUCUL 79 Cert# 3056987 A & P/IA Date 2-2-7-(

#### FAA - PMA

YEAR  DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	This tag certifies that Sky-Tec Model No. 149-NL Serial No. FN-431466 was manufactured new on 27 0ct 2014 by Sky-Tec under the authority of FAA-PMA No. PQ0852SW
51515	354			Supplement No in accordance with Sky-Tec's  FAA-Approved Quality System (14CFR Part 21, Subpart K).
=			163	This article has been determined to be airworthy.  For installation eligibility see
				For installation eligibility see <a href="https://www.skytecair.com/eligibility.htm">www.skytecair.com/eligibility.htm</a> Starter Installed on N 3033 by
			o V	(Aircraft) (Mechanic) 305 6983 AP
		15 m	oH	
		120	14	Form CC1108-1
-	ventu	ne c	oldtach	
91015	86010	1	3592	new tack installed.
130-15	22		1266	Of Allerd CH Cub and
1 )0-13	<i>&gt;&gt;</i>		FUY	Noted The filled multiwt 20/50 Jest Rup no
				1 1 1 1 1 turn of the William IN Warters 1 P
	_			I certify that this aircreft engine prop has had a 100 hr inspec (Annual) per CFR 43.13 apend D
31/16	0045		1289	and found in airworthy condition. All AD's 28
			100	complied with.
				Cert# 3056983 A & P/IA 77 Date 3-1-16 76
				w 2 ,

## TT + 1244.0 = 7500

	-//	-	011.	0 - 100
YEAR DATE	RECORDING TACH TIME	TODAY'S FLIGHT		<b>Description of I</b> Entries must be end Technician or Repai
7-8-16	108			Fill with Phill
			w 11 90	7.00
	750		9 9	
	n (41)		€ €	
100	× = = = =		9	WAYNES
11.		2		111
3-10-17	177-5	E 10		AIRCRAFT MAINTGAMES SERVICES N80
		8.	æ	Date: 3/10/2
		34	. 4	Performed Ann Test With The I
		2. 25		6) 70/80. Clean alternator belt, Airframe Been
	9 1			(scope and det
		-		
F/				1
N	5 4	13	n	Allan Waley
				A3056984
	2 18		0	

#### Inspections, Tests, Repairs and Alterations dorsed with Name, Rating and Certificate Number of

air Facility. (See back pages for other specific entries.) 10 5 100 AN OK for Patern to 50 out tound 1 Word 3056883 AFR

> Wayne's Aircraft Maintenance 14300 SW 129th Street Hanger M7 Miami, FL 33186 305-238-0774

8083Y Model: Lycoming O-540-J3A5D S/N /2017 Tach: 177.5 SMOH: 1421.5 TTE: 3769.8

nnual Inspection I A.W. FAR 43 App 'D', Performed Compression Following Results: 1) 72/80 2) 70/80 3) 69/80 4) 72/80 5) 62/80 an and gapped plugs, Replace 7, Tighten oil return lines, Tighten Replace muffler and all exhaust gasket. I Certify That This Inspected In Accordance With F.A.R. Part 43 Appendix (D) etail of items) Annual, Inspection and Was Determined To Be in ndition.

wski


EAR RECORDING TACH TIME	TODAY'S TOTAL FLIGHT TIME IN SERVICE	Entries must be endorsed with	ns, Tests, Repairs and Alterations Name, Rating and Certificate Number of See back pages for other specific entries.)
4/17	3	3 4	
	N8083Y	TACH: 0208.9	DATE: 08/24/17
PHIL	LIPS 100AW ENGINE OIL.	CLEANED, TESTED, GAPPED & ROTA	FILTER P/N AA48103-2, SERVICED WITH 12QTS. TED LOWER SPARK PLUGS. WASHED ENGINE & T, HOSES, ENGINE MOUNTS & STRUCTURE.
	10111 -	7341 AHP	DIEGO CA
		AEROMECHANIX SAN	DIEGO, CA
	33Y TACH OIL, REPLACED FILTE CLEANED, GAPPED	:222.1 TSMO:1466.1 ER CH48103-1. SERVICED ENGI	DATE:04/16/18

		1 97450710
AER	OMECHANIX (KMYF) S.	A 2708500 AN DIEGO, CA
Nana	3Y TACH:249.7 DAT	
DRAIN	ED OIL, INSPECTED & CLEANED	TE:11/13/18
KEPLACED	OIL FILTER P/N CH48103-1 SF	RVICED WITH 12
Q15. PHIL	LIPS . CLEANED, TESTED. GAPE	PED & ROTATED
GASKETS	SPARK PLUGS. REPLACED LOWE 5 07-00877,OIL COOLER 80000	K SPARK PLUG 74-9 & TESTED
FUEL PR	ESSURE. WASHED ENGINE & CO	OMPARTMENT
INSPECT	ED ALL CONTROL CABLES, EXH ENGINE MOUNTS & STRUCTU	AUST, HOSES
500	AND 2708	KE
AERO	MECHANIX (KMYF) SAN D	IEGO, CA
· · · · · · · · · · · · · · · · · · ·		

ADJUSTED TO 75LBS. CLEANED OIL COOLER, REPLACED BAFFELING AS REQUIRED.

AEROMEĆHANIX (KMYF) SAN DIEGO, CA

N8086Y TACH:325.5 TSMO:1569.0 DATE:05/10/2020 N8083Y **TACH:256.7** TSMO:1500.7 DATE:04/05/19 DRAINED OIL. REPLACED FILTER AA48103-2. SERVICED ENGINE WITH 11 QTS PHILLIPS 100 CLEANED, GAPPED, TESTED & ROTATED SPARK PLUGS REPLACED SPARK PLUG GASKETS YEAR tions ations A/W OIL & CAM GUARD, INSTALLED SUCTION PUMP COVER PLATE & GASKET. CLEANED. 07-00877. CHECKED MAG TIMING, PERFORMED DIFF, COMPRESSION TEST, RESEALED er of per of GAPPED. TESTED & ROTATED SPARK PLUGS REPLACED SPARK PLUG GASKETS 07-00877. ENGINE BAFFLEING WITH SILICONE SEALER. "SEE ATACHED AD LIST" tries.) ntries.) CHECKED MAG TIMING, PERFORMED DIFF. COMPRESSION TEST. "SEE ATACHED AD LIST" DATE #1=72/80 #2=76/80 #3=76/80 #4=76/80 #5=78/80 #6=79/80 #1=71/80 #2=76/80 #3=74/80 #4=71/80 #5=76/80 #6=71/80 I CERTIFY THAT THIS ENGINE HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL I CERTIFY THAT THIS ENGINE HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION. AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION. INSPECTION. AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION. AND 2708 SOEA AEROMECHANIX (KMYF) SAN DIEGO, CA AEROMECHANIX (KMYF) SAN DIEGO, CA DATE:08/03/20 N8083Y **TACH:342.1** DATE: 7/9/2019 GARMIN Repair Station No. 9GTR079B REPLACED ALL INTAKE GASKETS P/N 71973, REPLACED #124&6 INTAKE **ENGINE MODEL** A/C TSN: 3860 2345 Turner Rd SE COUPLINGS P/N 69603. INSTALLED NEW GASCOLATOR P/N 3715-803. O-540-J3A5D ENG TT: 3860 Salem, OR 97302 ENGINE S/N: TSMOH: 1512 L-21831-40A 209 ASP 2708 STORA TACH: 268 REG, NO: N8083Y WORK ORDER: AEROMECHANIX (KMYF) SAN DIEGO, CA 17586 **Engine Entries** (11) Removed #3 cyl intake tube, cleaned and inspected and then re-installed #3 cyl intake pipe with new Gasket P/N 7193 and new Intake Hose P/N 69603. Re-installed #3 cyl Primer line and secured DATE:0108/21 N8083Y TACH:362.1 line to Intake tube IAW Lycoming OM 60294-7 Rev July 2011. DRAINED OIL, INSPECTED & CLEANED OIL SCREEN, (12) Removed #5 cyl intake tube, cleaned and inspected, re-installed #5 cyl intake pipe with new REPLACED OIL FILTER P/N AA48103-2, SERVICED WITH 12 Gasket P/N71973 and new Intake Hose P/N 69603 and re-installed #5 cyl Primer line and secured OTS, PHILLIPS X/P 20/50. CLEANED, TESTED, GAPPED & line to Intake tube IAW Lycoming OM 60294-7 Rev July 2011. ROTATED LOWER SPARK PLUGS. REPLACED LOWER SPARK I certify the article identified above has been inspected and determined to be airworthy with respect to PLUG GASKETS 07-00877. WASHED ENGINE & COMPARTMENT, INSPECTED ALL CONTROL CABLES, the work performed. cn=Mitchell Stoneberg, o=Garmin AT, EXHAUST, HOSES, ENGINE MOUNTS & STRUCTURE. email=mitchell.stoneberg@garmin.com, c=US Work Order: 17586 SIGNED 2019.07.09 16:24:48 -07'00' DATE: 7/9/2019 Printed by EBis 3 (datcomedia.com) StonebergM AEROMECHANIX (KNYF) SAN DIEGO, CA Certified Repair Station No. 9GTR079B



TACH:452.0 DATE:11/08/2022				ENGINE		1 34, 5, 12 5
DRAINED OIL & COLLECTED SAMPLE FOR LAB ANALYSIS.	nd Alterations	YEAR .	REC	Aeromechan		and Alteration
CLEANED & SERVICED OIL SCREEN REPLACED CRUSH CASKET ANDOO 20	cate Number of	TERM ,	TACI	3753 John J. Montgomery Drive, San Diego, CA 92123		ificate Number of
REPLACED OIL FILTER PIN AA48103-2 SERVICED WITH 12 OTS	specific entries.)	DATE	TIME	WO#: Y-2741 M&M: LYCOMING O-540J3A5D	Tach:489.6 Hobbs:	er specific entries
FRILLIPS VICTORY 20/50.		PATE	-	Reg#: N8083Y S/N L-21831-40A		1
CLEANED, TESTED, GAPPED & ROTATED LOWER SPARK PLUGS. REPLACED SPARK PLUG GASKETS 07-00877.	# <u>2</u>			INSTALLED NEW #6 INTAKE TUBE, FLANGE, COU	PLING & GASKET	1
INSTALLED NEW #6 INTAKE TUBE GASKET 71973	,			OVERHAULED PRIMER, GASCOLATOR & CLEAN		
WASHED ENGINE & COMPARTMENT, INSPECTED ALL CONTROL CABLES, EXHAUST,				SWAP MAP HOSE FROM #6 TO #4 & BACK. CHE		-
HOSES, ENGINE MOUNTS & STRUCTURE.				TEST SPARK PLUGS & REPLACE 5-EA		
VELLENOOUS COM				71973 GASKET (OSP	)	
- Soll MOSOCH				73346 FLANGE (OSP)	•	-
PERSONAL PLANE TECHNIC, DEA				70485 TUBE (OSP		1
AEROMECHANIX (KMYF)				99603 COUPLING (OSP)		
37 ENGINE				LW15592-8-28 CLAMP (OSP)	34	-
Aeromechanix				MS29513-012 "O" RING		i
3753 John J. Montgomery Drive, San Diego, CA 92123	2		100	URHM-40-E SPARK PLUG	14	1
WO#: Y-2473 M&M: LYCOMING O-540J3A5D Tach:473.6 Hobbs:N/A	7	-				
Reg#: N8083Y S/N L-21831-40A SMOH:1717.0			(	ou de:	·	14
I CERTIFY THAT THIS <b>ENGINE</b> HAS BEEN INSPECTED IN ACCORDANCE WITH AN			1.	F.R.S. #8PER976B Signature: David Long A&P IA	2708500 02/02/2024	
ANNUAL INSPECTION, AND WAS DETERMINED TO BE IN AIRWOOTHY CONDITION			1	T.M.S. HOT ENSTON SIGNATURE. DAVID EOILS AGE IA	02/02/2024	
MESCATED ENGINE BAFFELING AS REQ.		-		ENGINE	7	
RE-RIGRD MIXTURE CONTROL LINKAGE				Aeromechanix		
INSTALLED OIL PRESSURE SPRING & SET TO SPEC.				3753 John J. Montgomery Drive, S		
COMPRESSION TEST 1=73/80 2=77/80 3=75/80 4=77/80 5=76/80 6=78/80  BLACKSTONE OIL ANALYSIS				WO#: Y-2820 M&M: LYCOMING O-540J3A5D		
CHAMPION OIL FILTER CH48103-1				Reg#: N8083Y S/N L-21831-40A	Tach:498.2 Hobbs:	
COPPER SPARK PLUG GASKET M674					ETO A CARACITORS (VIIIs)	*
PHILLIPS 66 VICTORY AVIATION OIL 20W50		1		REMOVED MAGNETO & INSTALLED SPARE MAGN		
LW11713 OIL PRESSURE SPRING		_ ==		D6LN-2021 MAGNETO P/N 10-382560-00 S/N 204	191 (N/C)	
	0.00		1	300 S CM2		
David Long A&P IA 2708 00 -11-2073				F.R.S. #8PER976B David Long A&P IA 708500	04/05/2024	

je	1.474		El	9	
	T		Aeroi		
/EAR	RECORD		3753 John J. Montgomer	epairs and Alterations	
	TIME	WO#: Y-2939	WO#: Y-2939 M&M: LYCOMING O-540J3A5D Tach:503 Hobbs:		and Certificate Number of
DATE	IIIVIE	Reg#: N8083Y	S/N L-21831-40A	SMOH: 1747	s for other specific entries.)
	-		PECTION PERFORMED		-
			L & COLLECTED SAMPLE FO		
		•CLEANED & S	SERVICED OIL SCREEN, REF	PLACED CRUSH GASKET AN900-22	
		•REPLACED O	IL FILTER P/N AA48103-2, 9	W50	
		X/C.			
		<ul> <li>CLEANED, TE</li> </ul>	STED, GAPPED & ROTATED		
			PARK PLUG GASKETS 07-00	4	
		WASHED ENG	GINE & COMPARTMENT, IN	XHAUST,	
		HOSES, ENGIN	IE MOUNTS & STRUCTURE		
			PRESSURE TO SPEC.		
		BLACKSTONE (			
			C AVIATION OIL 20W50		
			8103-2 OIL FILTER		
			K PLUG GASKET M674		
		AN900-22 (MS	35769-35) COPPER GASKE		
		WASHERS: AN			
		WASHERS: AN			
		OIL RECYCLE F	EE		
		7	1 m		
		FRS #8PFR97	6B: David Long A&P IA 27	200500	
		1:11.5. #67 EK57	OB. David Long A&P IA 27	7/10	/2024
				3	
				8	
					-
	-				

EAR RECORDING						
		ENGINE Aeromechanix				
TACH	3753 .	airs and Alterations Certificate Number of				
DATE	WO#: Y-3027 M&M: LYCOMING O-540J3A5D Tach:506 Hobbs: Reg#: N8083Y S/N L-21831-40A SMOH: 1750			r other specific entries.)		
			SMOH: 1750			
	INSPECTION PERFOR					
		LUG GASKETS 07-00877.				
	I CERTIFY THAT THIS	<b>ENGINE</b> HAS BEEN INSPEC	CTED IN ACCORDANCE WITH AN			
	ANNUAL INSPECTION	N, AND WAS DETERMINED	TO BE IN AIRWORTHY CONDITION.			
	INSTALLED NEW CYLI	NDER OIL RETURN TUBES		1		
	INSTALLED NEW FUE	L CAP GASKETS, RE-RIG M	IXTURE, THROTTLE CONTROLS,			
1:	REINSTALL STAND-OF	F & SAFETY. RELIGNED EN	GINE AT MOUNT.	ж		
5 2	COMPRESSION TEST	1=75/80 2=76/80 3=78/	80 4=78/80 5=76/80 6=78/80	1		
	MIL 6000 OIL TRANSFER TUBING					
(H) (2)	COPPER SPARK PLUG					
	1					
	David Long A&P IA 2					
1	I David Lolig AQF IA 2	1		J=		
	33					
			.1.			
				`		
	$ \wedge$ $\bot$					
- 11 1						
				+		
				1		
-H		A				
			V	1		
_1						
	1					
			1	<b>-</b>		

YEAR	RECORDING TACH	TODAY'S FLIGHT	TOTAL TIME IN	Description Entries must l	n of Inspections, Tests, Repairs and Alteration he endorsed with Name, Rating and Certificate Number of
		ENGINE			epair Facility. (See back pages for other specific entries.
		Aeromechai			, ( and a second of the second
	3753 John J. Moi	ntgomery Drive	, San Diego, C	A 92123	
WO#: Y-357	2 M&M: Lycoming 0	D-540J3A5D	Tach:520.6	5 Hobbs:	
	SY S/N L-21831-40A		SMOH: 17	64.6	
	PERFORMED				
DRAINED C	IL & COLLECTED SAM	MPLE FOR LAB	ANALYSIS.		
•CLEANED 8	SERVICED OIL SCRE	EN, REPLACED	CRUSH GASKE	T AN900-16	
•REPLACED	OIL FILTER P/N AA48	103-2, SERVICE	D WITH 9 QTS	PHILLIPS 100A/W.	
	CAM GUARD.				
•CLEANED,	TESTED, GAPPED & R	OTATED LOWE	R SPARK PLUGS	S.	
•REPLACED	SPARK PLUG GASKET	S 07-00877.			8
I CERTIFY TH	HAT THIS <b>ENGINE</b> HA	S BEEN INSPEC	TED IN ACCOR	DANCE WITH AN	
ANNUAL IN	SPECTION, AND WA	S DETERMINED	TO BE IN AIRV	WORTHY CONDITION.	
Work Comp	leted on 10/2/2025				
	CARB TEMP PROBE.		S & PROGRAM	I TO SPEC.	
INSTALLED I	NEW #4 VALVE COVE	R GASKET.			
COMPRESSI	ON TEST 1=69/80	2=71/80 3=71/	80 4=72/80 5=	71/80 6=73/80	
	E OIL ANALYSIS				
100	A48103-2 OIL FILTER				
	ARK PLUG GASKET M				-
	X/C AVIATION OIL 2				
	AVIATION OIL ADD				
	ALVE COVER GASKE			4/	
400128 CAR	RB INLET TEMP. PROI	3E (J.P.I.)			10:
_ `_	2 000	0	)-CX	$\sim$	
David Long	A&P IA 2708500		-		
David solig	DES 1	î	·	i	

\* . . . | [e= | D