

SERVICEABLE

MAKE Hartzell MODEL No. BHCC2YF-1BF DATE 8-1-91

NEW ☐ OVERHAULED ☒ REPAIRED ☐ RESEALED ☐ OTHER ☐

SERIAL No. BLADES E22958 - D71950

BLADE DWG. F8459A-8R HUB SERIAL AM1872

Palm Beach Aircraft Propeller, Inc.

2633 Lantana Road
Suite 23, Bldg. 1501
Lantana, Florida 33462
(407) 965-7767

F.A.A. No. LU4R349M

Per Michael F. O'Neill A & P or
Repairman's Cert. No. 2348887



Installed 8-2-91 On Piper PA28R-201T
Carl Garlough
A & P. 50457-JA.
N2253M
HOBBS MTR 627-74

PLEASE SEE OTHER SIDE.

**EXPLANATION OF ALL MAINTENANCE
PERTAINING TO AIR WORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
MINOR ADJUSTMENTS & MAJOR OVERHAULS**

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
Aug 1, 1991	494.3	Overhauled	Palm Beach Propeller Inc.
11-22-96	TACH-909:96	Completed a 100 hour inspection this date.	Paul H Regelsperger CRS-BLBR505C
12-9-97	TACH-951.77	TSO-457:47 Completed a 100 hour inspection this date.	Paul H Regelsperger for CRS-BLBR505C
1-24-2000	TACH Reads 30.0hr	Completed Annual Inspection This Date.	Jull P. Bulow for 580648976 JA.



The Standard

PROPELLER LOG

ASA SP-1

Propeller Record General Information

Propeller Manufacturer

HATZELL

Model

PHC-C34F-1RF

Type

Hub Series #

EE3893B

Blade #

Date of Manufacture

INSTALLED 4-1-2002

Make/Model

Aircraft Installed On:

PIPER CHEROKEE
ARROW III

Serial #

PA28-R201T

☐ HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS

Year: <u>2015</u>	Total Time in Service <u>75N</u>	Description <u>No A.D.s due at this time</u> I certify that this <u>propeller</u> has been <u>Tach 553.9</u> inspected in accordance with <u>100HR</u> inspection and was determined to be <u>CONTENT Revision 9-11-15</u> in airworthy condition. <u>Done by AYP368544143TA</u> Mech. Cert. # or Repair Station # _____
Date: <u>9-20-15</u>	<u>511.8</u>	
Next Inspection Due:	Time Since Overhaul	

CAM CERTIFIED AIRCRAFT MAINTENANCE 12925 Wildcat Way, Burleson, TX, 76028		
PROP: Hartzell	MODEL: PHC-C34-1RF	S/N: EE3893B
	TACH: 885.2	HOBBS: 1959.9
DESCRIPTION OF WORK PERFORMED: Performed 100hr inspection IAW FAR 43, Appendix D checklist. Inspected bulkhead and spinner. I certify that this aircraft propeller has been inspected in accordance with a 100 hour inspection and has been determined to be in airworthy condition.		
DATE <u>7/1/17</u>	SIGNATURE <u>[Signature]</u> A&P	

Date:		
Next Inspection Due:	Time Since Overhaul	
Mech. Cert. # or Repair Station # _____		

HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS ☐

CAM CERTIFIED AIRCRAFT MAINTENANCE 12925 Wildcat Way, Burleson, TX, 76028		
PROP: Hartzell	MODEL: PHC-C34-1RF	S/N: EE3893B
	TACH: 1035.4	HOBBS: 148.9
DESCRIPTION OF WORK PERFORMED: Performed 100hr inspection IAW FAR 43, Appendix D checklist. Inspected bulkhead and spinner. I certify that this propeller has been inspected in accordance with a 100 hour inspection and has been determined to be in airworthy condition.		
DATE <u>July 27, 2018</u>	SIGNATURE <u>[Signature]</u> A&P	

CAM CERTIFIED AIRCRAFT MAINTENANCE 12925 Wildcat Way, Burleson, TX, 76028		
PROP: Hartzell	MODEL: PHC-C34-1RF	S/N: EE3893B
	TACH: 1076.5	PTSN: 1034.4
		HOBBS: 194.6
DESCRIPTION OF WORK PERFORMED: Inspected installation of prop for STC#SA01024CH conformity. Found prop installation to be correct in accordance with Hartzell Manual 115N Rev. 23 February 2018. STC Documentation and Permission letter (reproduced by stc holder) inserted in aircraft permanent records. Confirmed aircraft permanent records reflected changes. Work performed IAW manufacturers' technical publications. Form 337 filed, this date.		
DATE <u>March 27, 2019</u>	SIGNATURE <u>[Signature]</u> A&P	

Mech. Cert. # or Repair Station # _____		
---	--	--

☐ HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS

Year: _____
Date: _____
Next Insp Due: 09/03/19 1092.60 Tach 1050.50 Prop TSN Hartzell PHC-C3YF-1/RF S/N EE3893B

Propeller Log Entry

I certify that this propeller has been inspected in accordance with a 100 Hour Inspection and was determined to be in Airworthy Condition.

Year: _____
Date: _____
Signature: Mech. Overly A&P 3030006

Year: _____ Date: _____ Next Inspection Due: _____		Mech. Cert. # or Repair Station # _____
Year: _____ Date: _____ Next Inspection Due: _____	Total Time in Service	Description
	Time Since Overhaul	Mech. Cert. # or Repair Station # _____

HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS ☐

Precision Aircraft Maintenance - 4845 Lockheed Ln., Unit 102, Denton, TX, 76207 - 940.367.5988 - 409.767.1158
Ye N2253M Make: Piper Model: PA-28R-201T S/N: 28R-7803116 TACH: 1156.5 AFTT: 3857.55
Da Eng Make: Continental Eng Model: TSIO-360-FB15 Eng S/N: 299850-R Eng TTSMOH: 993.6
Ne Prop Make: Hartzell Prop Model: PHC-C3YF-1/RF Prop S/N: EE3893B Prop TTSN: 1114.4
Du 11/17/2020 PROPELLER

This propeller was inspected IAW an annual inspection per FAR 43 appendix (d). The following maintenance was performed.

I CERTIFY THIS PROPELLER HAS BEEN INSPECTED IAW AN ANNUAL INSPECTION AND WAS FOUND TO BE IN AN AIRWORTHY CONDITION AT THIS TIME.

Da Wesley Pearce AP 2729740 IA Wesley Pearce Date: 11/17/20

Year: _____ Date: _____ Next Inspection Due: _____		Mech. Cert. # or Repair Station # _____
Year: _____ Date: _____ Next Inspection Due: _____	Total Time in Service	Description
	Time Since Overhaul	Mech. Cert. # or Repair Station # _____

☐ HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS

Year: Precision Aircraft Maintenance – 4845 Lockheed Ln., Unit 102, Denton, TX, 76207 – 940.367.5988 – 409.767.1158
Date: N2253M Eng Make: Continental Prop Make: Hartzell DATE: 20DEC2021
A/C Make: Piper Eng Model: TSIO-360-FB15 Prop Model: PHC-C3YF-1/RF TACH: 1202.5
Next Due: A/C Model: PA-28R-201T Eng S/N: 299850-R Prop S/N: EE3893B AFTT: ~~3949.55~~
A/C S/N: 28R-7803116 Eng TTSMOH: 1085.6 Prop TTSN: 1206.4 3903.55 hr

PROPELLER


• This propeller was inspected IAW an annual/100HR inspection per FAR 43 appendix (d). The following maintenance was performed.
Year: I CERTIFY THIS PROPELLER HAS BEEN INSPECTED IAW AN ANNUAL/100HR INSPECTION AND WAS FOUND TO BE IN
Date: AN AIRWORTHY CONDITION AT THIS TIME.
Next Due: Wesley Pearce AP 2729740 IA 

		Mech. Cert. # or Repair Station #
Year:	Total Time in Service	Description
Date:		
Next Inspection Due:	Time Since Overhaul	
		Mech. Cert. # or Repair Station #

HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS ☐

Year: Precision Aircraft Maintenance – 5011 Sabre Ln., Denton, TX, 76207 – 940.367.5988 – 409.767.1158
Date: N2253M Eng Make: Continental Prop Make: Hartzell DATE: 17MAR2023
A/C Make: Piper Eng Model: TSIO-360-FB15 Prop Model: PHC-C3YF-1/RF TACH: 1245.10
Next Due: A/C Model: PA-28R-201T Eng S/N: 299850-R Prop S/N: EE3893B AFTT: 3946.15
A/C S/N: 28R-7803116 Eng TT: 1127.20 Prop TTSN: 1203.0

PROPELLER

• This propeller was inspected IAW an annual/100HR inspection per FAR 43 appendix (d).
Year: I CERTIFY THIS PROPELLER HAS BEEN INSPECTED IAW AN ANNUAL/100HR INSPECTION AND WAS FOUND TO BE IN
Date: AN AIRWORTHY CONDITION AT THIS TIME.
Next Due: Wesley Pearce AP 2729740 IA 

		Mech. Cert. # or Repair Station #
Year:	Total Time in Service	Description
Date:		
Next Inspection Due:	Time Since Overhaul	
		Mech. Cert. # or Repair Station #

☐ HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS

Ye Precision Aircraft Maintenance – 5011 Sabre Ln., Denton, TX, 76207 – 940.367.5988 – 409.767.1158

Da N2253M Eng Make: Continental Prop Make: Hartzell DATE: 18APR2024

Ne A/C Make: Piper Eng Model: TSIO-360-FB15 Prop Model: PHC-C3YF-1/RF TACH: 1262.80

Du A/C Model: PA-28R-201T Eng S/N: 299850-R Prop S/N: EE3893B AFTT: 3963.85

A/C S/N: 28R-7803116 Eng TT: 1144.9 Prop TTSN: 1220.7

PROPELLER

• This propeller was inspected IAW an annual/100HR inspection per FAR 43 appendix (d).

Da I CERTIFY THIS PROPELLER HAS BEEN INSPECTED IAW AN ANNUAL/100HR INSPECTION AND WAS FOUND TO BE IN AN AIRWORTHY CONDITION AT THIS TIME.

Wesley Pearce AP 2729740 IA

Wesley Pearce

Year:	Total Time in Service	Description
Date:		
Next Inspection Due:	Time Since Overhaul	
Mech. Cert. # or Repair Station #		

HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS ☐

Year

Date Precision Aircraft Maintenance – 5011 Sabre Ln., Denton, TX, 76207 – 940.367.5988 – 409.767.1158

Next N2253M Eng Make: Continental Prop Make: Hartzell DATE: 18JUN2025

Due: A/C Make: Piper Eng Model: TSIO-360-FB15 Prop Model: PHC-C3YF-1/RF TACH: 1282.50

A/C Model: PA-28R-201T Eng S/N: 299850-R Prop S/N: EE3893B AFTT: 3983.55

A/C S/N: 28R-7803116 Eng TT: 1164.60 Prop TTSN: 1240.40

PROPELLER

• This propeller was inspected IAW an annual/100HR inspection per FAR 43 appendix (d).

Da I CERTIFY THIS PROPELLER HAS BEEN INSPECTED IAW AN ANNUAL/100HR INSPECTION AND WAS FOUND TO BE IN AN AIRWORTHY CONDITION AT THIS TIME.

Wesley Pearce AP 2729740 IA

Wesley Pearce

Year:		
Date:		
Next Inspection Due:	Time Since Overhaul	
Mech. Cert. # or Repair Station #		