: Closed

ENCALL LOCAL

Engine Log TABLE OF CONTENTS

SECTION SEQUENCE		DESCRIPTION OF SECTION	PAGE NUMBER	
	1st SECTION	ENGINE DESCRIPTION		
	2nd SECTION	INSTALLATION RECORD	1	
	3rd SECTION	LIFE LIMITED PARTS OR OVERHAUL REQUIREMENTS	3	
	4th SECTION	AIRWORTHINESS DIRECTIVE OR FACTORY BULLETI COMPLIANCE RECORD	N 5	
	5th SECTION	INSPECTION AND MAINTENANCE RECORD	13	
	6th SECTION	PROPELLER OR ROTOR RECORD	67	
	7th SECTION	AIRWORTHINESS DIRECTIVE OR FACTORY BULLETI COMPLIANCE RECORD [Propeller or Rotor Only]	N 69	
	8th SECTION	REPAIR AND INSTALLATION RECORD [Propeller or Rotor Only]	71	

Aero Products Corporation
Copyright 1975 All Rights Reserved

ENGINE DESCRIPTION

MANUFACTURER _	PRATT & WHITNEY AVC OF CANADA	_MODELPT6A-42
SERIAL NUMBER	PCE-94363 DATE OF MANI	UFACTURE
RATED BHP	RPM	MANIFOLD PRESSURE
FUEL REQUIRED O	CTANE/PERFORMANCE	
REGISTERED OWN	ER	
STREET & NO		
CITY, STATE, ZII	P	
REGISTERED OWN	ER	
STREET & NO		
CITY, STATE, ZI	P	
	and the second s	

INSTALLATION RECORD

AIRPLANE	LOCATION	DATE INSTALLED	TOTAL HOURS AT INSTALLATION	DATE REMOVED	TOTAL HOURS AT REMOVAL	ACENCY CERT. NO.
BB-1368	LH.	4-11-90	0:00			
			000			ting and the second
				7-7		an and and
					The second second second	and the second s
						de la compania del compania de la compania de la compania del compania de la compania del la compania del la compania de la compania del la compania de la c
				The state of the s	terren kannen kanne Kannen kannen kanne	
				The same of the same state of		til der sterringsford forstation of the forestation and comments on the
		11-3				Aller or water the company of the company
	- Land	Description of the second		1	ende energia en	
		- Street Street			and Salaharan Pharmacolina	
					- or or or or or other supposed to the	
			Meson control of the second			and the second s
					and the state of t	Action of the second se
		Section 200				Security Control of the Control of t
and the second						

THINESS DIRECTIVE/FACTORY BULLETIN COMPLIANCE RECORD

M	DATE & HRS. AT COMP.	METHOD OF COMPLIANCE	TYPE OF A.D. 1 TIME/RECUR.	NEXT COMP. DATE/HRS./CYCLE	AUTHORIZED SIGNATURE CERTIFICATE NO.
		5584M 1) Complie	d with com	10-19- pressor wash	
		3/1	like A	HP4647	6705Z
				100	
				100	
				1/2/	
		- 30			
				200	

Complied with compressor wash. In AHP4C4767052 N5584M 62.2TT 09-07-90 C/W compressor wash. _DAPKC4767052 N5584M 09-21-90 3) Complied with compressor wash. N5584M 10-05-90 Complied with compressor wash. Melde ASP 464762057

N5584M

08-24-90

50.9TT

=	A/C: 20 S/N: BB		W.O.: 4939 ——————————————————————————————————
+	N#: N5 PT6A-42 S/N PCE94363	HEDRICK BEECHCRAFT-HOUSTON 8402 NELMS HOUSTON, TEXAS 77061-4110 FAA. APPROVED REPAIR STATION NO. XA1R6	HM. HOURS: 141.9 —
		P/N 101-590010-223C. pressor wash.	The second secon
	ACCORDANCE AN INSPECTION HAS BEEN FOU IS APPROVED INSPECTION 15 W/O #_4939 AUTHORIZED S	WITH THE INSTRUCTIONS AND PROCE N PROGRAM REQUIRED BY FAR 91.40 UND TO BE IN AN AIRWORTHY CONDITION FOR RETURN TO SERVICE. OF PROGRAM COMPLETED DATE 1/-9 AIRCRAFT TIME IN SERVICE 14/1. CHORAFT-HOUSTON 8402 NELMS ST.	EDURES FOR 9(F) DAND ITION, AND
1		N XA1R605K HOUSTON, TEXAS 770	

DATE	TOTAL	INSPECTION OR MAINTENANCE PERFORMED AGENCY & CERTIFICATE NO.
6-5-91	265.0 Hm	Complied with a 150 hz Primary inspection on this
		Engine as per Beech inspection from PN# 101-590010-2236
		This inspection is considered An Annual Type
		ingestion presumed in conjunction with A Centificate
		of pieuadiness inspedia for Export. Inspected
		oil & Hers for contamination, none rotal, inspectal
		Fred Purp Filler and replaced inter Filler, inspecded
		ignison plugs, in postal & lasted this detector, inspected
		inlest birdes, is pechal tubic blades, sodange
		rolla en producto vere abla on Engra Atlan
		Corondorus, 111 Edens inspected on Engine during
on Colors		inspection were fond sievoutly. Further dutails see
		on folo mi this age of indust 14091
		Stamped Entry next Page

rE	TOTAL TIME	INSPECTION OR MAINTENANCE PERFORMED . AGENCY & CERTIFICATE NO.
	Co.7>	Date 6-5-91 Work Order 14091 I Certify that this 4-4- has been inspected in accordance with the instructions and procedures of a current Manufacture's recom- mended program, approved for F. A. R. 91.409 F. 44
		Type of inspection 150 he 2000
	1044 SAN AN	ICK BEECHCRAFT 10 JOHN CAPE RD. 11 TONIO, TEXAS 78216 12 ORDER/INVOICE L.H. engine logbook attachment
	BB- 1368 Change	d oil. Serviced w/Exxon 2380.
	Pressur	e a Flow checked Fuel nozzles.
	Ground	l rang No leeks. W.O. 14091
		73 500

DATE	TOTAL	INSPECTION OR MAINTENANCE PERFORMED AGENCY & CERTIFICATE NO.
11-6-92	378.8 HLS	I CENTIFY THAT THIS ENFINE HAS BOW INSPECTED
	5700	I. A.W. The Instructions AND PROCEDURES FOR
		AN INSPORTION PROGRAM REQUIRED By FAR 91.409F(4)
		AND HAS FOUND to bE IN AN AIRVORTHY CONDITION.
		AND IS APPROVED SER RETURN to SERVICE. Informing
		150 HK Primary completed @ 11-6-92 (LONG FORM)
		(D) ENGINE OIL CHANGED (MOBIL JET II)
	-	D Full Wordes Romo Clomed, Flow Chaked AND
		RE-INSTALLED
		B) CW BORN SI 2432 (TRUSS BULTS)
		9) DUGINE LUNS CALLIOSON. NO DISCREPANCIUS NOTED
141		5) ALL ONG FILTERS REMO CLEANED AND RE-INSTALLED
		(Chip Deveron checked found good.
		12 STREETE Brushes checked and found satisfactory.
		BNM2 mil AP A 39648690
		Rocords of Insp can be checked at AMO 202
		Rocorde of Insp can be checked at AMO# 202 under who # 12153 @ West an arration Whidhock tambin
		Con't Nexpage >

DATE	TOTAL TIME	INSPECTION OR MAINTENANCE PERFORMED AGENCY & CERTIFICATE NO.
11-6-92	378.8 Hs.	all AD'S AND SB's checked and CW on this
	Section of the	date. Bom Donald AP# 396486680



N981GA PCE-94363 (LH) TT: 1422.5 DATE: 3/3/98

Completed a Phase 1 through Phase 4 Inspection iaw the Beechcraft Approved Inspection Program, form PN's 050010, 050020, 050030 & 050040. Completed a Hot Section Inspection iaw Pratt and Whitney M.M., removed fuel nozzles and flowed, inspected CT wheel; vane and large exit duct, inspected burner can, reinstalled with average tip clearance of .013"; replaced fuel filter; replaced both ignitors; washed down engine. The following items were previously CW by Beechcraft Augsburg, reinspected and found to be in compliance with Beechcraft M.M and conforms to U.S. MaintenenceStandards; oil filter replacement; P3 filter replacement; starter gen. O/H SN 19882. CW engine leak checks and performance runs.

DATE	TOTAL	INSPECTION OR MAINTENANCE PERFORMED AGENCY & CERTIFICATE NO.
	1	
	Cantt	Aviation Service Center inc
	Vallet	Aviation Service Center, inc.
		is Engine has been inspected and was found to be
a	irworthy. This	Engine is approved for return to socvice.
		ffely
		John R. Powe/IA 459044945
_		
_		
_		
_		
-		

	TOTAL TIME			NTENANCE PERFORMED ERTIFICATE NO.	
	Fa	ntt Aviatio	n Servi	ce Center	inc
		221 STEARMAN DRIVE G	SEORGETOWN, TEXAS		,
	N981GA		CRS# G1TR1440	Hoss not	1450.2
	PCE 94363	(LH)			E: 4/24/98
		121 -1 11011 63	I OT I	1.6	
		lit at "C" flange an Aero. Reinstalled w			
		gine amd performed p			FOW M.M.
	THIS	ENGINE APP	PROVED FOR RETUR	N TO SERVICE WITH	•
	RESPECT T	O WORK PERFORMED, ON FI	ILE AT THIS AGENC	, UNDER	
	WORK ORD	ER# 2971126 E	DATE 4-24-98	HRS 1450.2	
		MAZA Ba	lose		FOR
	SIGNED	1 piles			-OR
	Contt Avioti	on Service Center		REPAIR STATION G1TR	1440
3.5	221 STEAR	MAN DRIVE	AIR	FRAME/POWERPLANT LIM	ITED
-	GEORGET	OWN, TEXAS 78628			
T.					

DATE	TOTAL TIME	INSPECTION OR MAINTENANCE PERFORMED AGENCY & CERTIFICATE NO.
181X+398	1435:40	
2,0	Post IV	0.90
		, St. 14
	en e	July 30 08-14
		· · · · · · · · · · · · · · · · · · ·
	Control of the second	
		pool
		Service and the service and th
		Van de la company de la compan
		The state of the s
in the second		
_		
Salar Salar A	Service of the service of	