BOOK#3



3-32-7

Engine Record General Inform	nation		_
Manufacturer Textros Lice of Serial L - 23525 - 40 f	Model_ Mo	<u>D-640-よ3C5の</u> Type Certificate <u>N4716</u>	
Minimum Octane Fuel	Oil Grade: Summer_	Winter	_
Magneto Time	Point Setting	Firing Order	
Spark Plug Gap			_

Manufacturer's Recommended Overhaul at 75 mo. # 577.42 hours

2023	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)	YEAR 20 16 DATE	RECORDING TACH TIME	FLIGHT	TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
DATE		Ismoh	\$77.47		<u> </u>	13/2.16		579,86	Repair Facility. (See back pages for other specific entries.) Laspented Engine I as Tallier, I repeated Enhance System C/W BO NoTe 2023 - 07-08, Replaced Enhance Champ AT Tuluro changer with New Clamp At Tuluro changer with New Clamp AT Waste quite. Tall Pipe with Now Pipe Replaced Clamp AT waste quite. To Tail Pipe, Charled AD Wastes For Compliance i certify that this Engine has been inspected in accordance with an Annual inspection and was determined to be in
				and was determined to be in an airworthy condition.			25		an airworthy condition. /A2(74610